

ETSI TS 136 523-1 V16.12.0 (2023-01)



**LTE;
Evolved Universal Terrestrial Radio Access (E-UTRA)
and Evolved Packet Core (EPC);
User Equipment (UE) conformance specification;
Part 1: Protocol conformance specification
(3GPP TS 36.523-1 version 16.12.0 Release 16)**



Reference

RTS/TSGR-0536523-1v0c0

Keywords

LTE

ETSI

650 Route des Lucioles
F-06921 Sophia Antipolis Cedex - FRANCE

Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Siret N° 348 623 562 00017 - APE 7112B
Association à but non lucratif enregistrée à la
Sous-Préfecture de Grasse (06) N° w061004871

Important notice

The present document can be downloaded from:

<http://www.etsi.org/standards-search>

The present document may be made available in electronic versions and/or in print. The content of any electronic and/or print versions of the present document shall not be modified without the prior written authorization of ETSI. In case of any existing or perceived difference in contents between such versions and/or in print, the prevailing version of an ETSI deliverable is the one made publicly available in PDF format at www.etsi.org/deliver.

Users of the present document should be aware that the document may be subject to revision or change of status.

Information on the current status of this and other ETSI documents is available at

<https://portal.etsi.org/TB/ETSIDeliverableStatus.aspx>

If you find errors in the present document, please send your comment to one of the following services:

<https://portal.etsi.org/People/CommitteeSupportStaff.aspx>

If you find a security vulnerability in the present document, please report it through our
Coordinated Vulnerability Disclosure Program:

<https://www.etsi.org/standards/coordinated-vulnerability-disclosure>

Notice of disclaimer & limitation of liability

The information provided in the present deliverable is directed solely to professionals who have the appropriate degree of experience to understand and interpret its content in accordance with generally accepted engineering or other professional standard and applicable regulations.

No recommendation as to products and services or vendors is made or should be implied.

No representation or warranty is made that this deliverable is technically accurate or sufficient or conforms to any law and/or governmental rule and/or regulation and further, no representation or warranty is made of merchantability or fitness for any particular purpose or against infringement of intellectual property rights.

In no event shall ETSI be held liable for loss of profits or any other incidental or consequential damages.

Any software contained in this deliverable is provided "AS IS" with no warranties, express or implied, including but not limited to, the warranties of merchantability, fitness for a particular purpose and non-infringement of intellectual property rights and ETSI shall not be held liable in any event for any damages whatsoever (including, without limitation, damages for loss of profits, business interruption, loss of information, or any other pecuniary loss) arising out of or related to the use of or inability to use the software.

Copyright Notification

No part may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm except as authorized by written permission of ETSI.

The content of the PDF version shall not be modified without the written authorization of ETSI.

The copyright and the foregoing restriction extend to reproduction in all media.

© ETSI 2023.
All rights reserved.

Intellectual Property Rights

Essential patents

IPRs essential or potentially essential to normative deliverables may have been declared to ETSI. The declarations pertaining to these essential IPRs, if any, are publicly available for **ETSI members and non-members**, and can be found in ETSI SR 000 314: "*Intellectual Property Rights (IPRs); Essential, or potentially Essential, IPRs notified to ETSI in respect of ETSI standards*", which is available from the ETSI Secretariat. Latest updates are available on the ETSI Web server (<https://ipr.etsi.org/>).

Pursuant to the ETSI Directives including the ETSI IPR Policy, no investigation regarding the essentiality of IPRs, including IPR searches, has been carried out by ETSI. No guarantee can be given as to the existence of other IPRs not referenced in ETSI SR 000 314 (or the updates on the ETSI Web server) which are, or may be, or may become, essential to the present document.

Trademarks

The present document may include trademarks and/or tradenames which are asserted and/or registered by their owners. ETSI claims no ownership of these except for any which are indicated as being the property of ETSI, and conveys no right to use or reproduce any trademark and/or tradename. Mention of those trademarks in the present document does not constitute an endorsement by ETSI of products, services or organizations associated with those trademarks.

DECT™, **PLUGTESTS™**, **UMTS™** and the ETSI logo are trademarks of ETSI registered for the benefit of its Members. **3GPP™** and **LTE™** are trademarks of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners. **oneM2M™** logo is a trademark of ETSI registered for the benefit of its Members and of the oneM2M Partners. **GSM®** and the GSM logo are trademarks registered and owned by the GSM Association.

Legal Notice

This Technical Specification (TS) has been produced by ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities. These shall be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between 3GPP and ETSI identities can be found under <http://webapp.etsi.org/key/queryform.asp>.

Modal verbs terminology

In the present document "**shall**", "**shall not**", "**should**", "**should not**", "**may**", "**need not**", "**will**", "**will not**", "**can**" and "**cannot**" are to be interpreted as described in clause 3.2 of the [ETSI Drafting Rules](#) (Verbal forms for the expression of provisions).

"**must**" and "**must not**" are **NOT** allowed in ETSI deliverables except when used in direct citation.

Contents

| | |
|--|----------|
| Intellectual Property Rights | 2 |
| Legal Notice | 2 |
| Modal verbs terminology..... | 2 |
| Foreword..... | 4 |
| Introduction | 4 |
| 1 Scope | 5 |
| 2 References | 5 |
| 3 Definitions, symbols and abbreviations | 5 |
| 4 Overview | 6 |
| 4.1 Test methodology..... | 6 |
| 5 to 24 Void..... | 6 |
| Annex A (informative): Change history | 7 |
| History | 152 |

Foreword

This Technical Specification has been produced by the 3rd Generation Partnership Project (3GPP).

The contents of the present document are subject to continuing work within the TSG and may change following formal TSG approval. Should the TSG modify the contents of the present document, it will be re-released by the TSG with an identifying change of release date and an increase in version number as follows:

Version x.y.z

where:

- x the first digit:
 - 1 presented to TSG for information;
 - 2 presented to TSG for approval;
 - 3 or greater indicates TSG approved document under change control.
- y the second digit is incremented for all changes of substance, i.e. technical enhancements, corrections, updates, etc.
- z the third digit is incremented when editorial only changes have been incorporated in the document.

Introduction

The present document is the first part of a multi-part conformance specification. 3GPP TS 36.523-2 [18] contains a proforma for the Implementation Conformance Statement (ICS) and an applicability table, indicating the release from which each test case is applicable. 3GPP TS 36.523-3 [19] contains a TTCN-3 design frame work, test model and Test Suites (the detailed test specifications in TTCN-3).

For at least a minimum set of services, the prose descriptions of test cases will have a matching detailed test case implemented in TTCN [19].

The present document may contain descriptions of tests for additional services, but these tests may not have matching TTCN test cases.

The present document will not contain any tests on the USIM, or the interface between the UE and the USIM. These tests are documented elsewhere.

1 Scope

The present document specifies the protocol conformance testing for the 3rd Generation E-UTRAN User Equipment (UE).

This is the first part of a multi-part test specification. The following information can be found in this part:

- the overall test structure;
- the test configurations;
- the conformance requirement and reference to the core specifications;
- the test purposes; and
- a brief description of the test procedure, the specific test requirements and short message exchange table.

The following information relevant to testing could be found in accompanying specifications:

- the default setting of the test parameters [18];
- the applicability of each test case [19].

A detailed description of the expected sequence of messages could be found in the 3rd part of this test specification.

The Implementation Conformance Statement (ICS) pro-forma could be found in the 2nd part of the present document.

The present document is valid for UE implemented according to 3GPP releases starting from Release 8 up to the Release indicated on the cover page of the present document.

2 References

The following documents contain provisions which, through reference in this text, constitute provisions of the present document.

- References are either specific (identified by date of publication, edition number, version number, etc.) or non-specific.
- For a specific reference, subsequent revisions do not apply.
- For a non-specific reference, the latest version applies. In the case of a reference to a 3GPP document (including a GSM document), a non-specific reference implicitly refers to the latest version of that document in the same Release as the present document unless the context in which the reference is made suggests a different Release is relevant (information on the applicable release in a particular context can be found in e.g. test case title, description or applicability, message description or content).

[1] to [62] (void)

[63] 3GPP TS 36.523-1 Release 17: "Evolved Universal Terrestrial Radio Access (E-UTRA) and Evolved Packet Core (EPC); User Equipment (UE) conformance specification; Part 1: Protocol conformance specification"

3 Definitions, symbols and abbreviations

Void

4 Overview

4.1 Test methodology

The requirements of the present document are provided in 3GPP TS 36.523-1 Release 17 [63].

5 to 24 Void

Annex A (informative): Change history

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2007-08 | | R5-072514 | | | Initial version | | 0.0.1 |
| 2007-11 | | | | | Template updated | 0.0.1 | 0.0.2 |
| 2008-02 | | | | | Addition 6 new RRC test cases | 0.0.2 | 0.1.0 |
| 2008-04 | | | | | Addition of new RRC and PDCP test cases agreed in RAN5#39. Alignment with latest core specifications. | 0.1.0 | 0.2.0 |
| 2008-07 | | | | | Addition of new MAC, RLC, RRC and EMM test cases and corrections agreed in RAN5#39bis. Alignment with latest core specifications. | 0.2.0 | 0.3.0 |
| 2008-09 | | | | | Addition of new MAC, RLC, PDCP and RRC test cases and corrections agreed in RAN5#40. | 0.3.0 | 1.0.0 |
| 2008-10 | | | | | Addition of new test cases agreed by email after RAN5#40 and at RAN5#40bis. | 1.0.0 | 1.1.0 |
| 2008-11 | | | | | Addition of new test cases and test case corrections agreed at RAN5#41. | 1.1.0 | 2.0.0 |
| 2008-12 | RAN#42 | R5-080969 | | | Approval of version 2.0.0 at RAN#42, then put to version 8.0.0. | 2.0.0 | 8.0.0 |
| 2008-01 | | | | | Editorial corrections | 8.0.0 | 8.0.1 |
| 2009-03 | RAN#43 | R5-090102 | 0060 | - | Correction to E-UTRA RLC test case 7.2.3.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090103 | 0061 | - | Correction to E-UTRA RLC test case 7.2.3.2 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090124 | 0062 | - | Batch 2 -Update to test case 7.2.2.8 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090125 | 0063 | - | Batch 1B -Update to test case 7.2.2.9 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090128 | 0064 | - | Batch 1A -Update to test case 8.1.1.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090132 | 0065 | - | Batch 1A - Update to test case 8.2.4.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090133 | 0066 | - | Batch 2 - Update to test case 8.2.4.2 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090136 | 0067 | - | Batch 2 - Update to test case 8.2.4.6 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090137 | 0068 | - | Batch 2 - Update to test case 8.2.4.7 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090138 | 0069 | - | Batch 2 - Update to test case 8.2.4.9 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090144 | 0070 | - | Batch 2 - Addition of new test case 8.4.1.8 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090145 | 0071 | - | Batch 2 - Correction to Idle mode test method | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090146 | 0072 | - | Batch 1A - Update to test case 8.5.4.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090151 | 0073 | - | Batch 2 - Addition of new test case 9.2.3.2.10 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090153 | 0074 | - | Batch 2 - Addition of new test case 9.2.3.2.15 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090199 | 0075 | - | Removal of EMM test cases 9.2.2.2.4, 9.2.2.2.6, 9.2.2.2.7 and 9.2.2.2.8. | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090201 | 0076 | - | Batch 1:Corrections to MAC test case 7.1.2.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090203 | 0077 | - | Batch 1:Corrections to MAC test case 7.1.2.4 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090230 | 0078 | - | Batch 1:Corrections to MAC test case 7.1.2.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090235 | 0079 | - | Batch 1:Corrections to MAC test case 7.1.3.6 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090236 | 0080 | - | Batch 1:Corrections to MAC test case 7.1.4.11 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090347 | 0081 | - | Batch 2 - Update to MAC test case 7.1.4.3 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090453 | 0082 | - | Batch 1A - Update of E-UTRA RLC (AM) test case 7.2.3.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090455 | 0083 | - | Batch 2 - Update of E-UTRA RLC (AM) test case 7.2.3.16 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090498 | 0084 | - | Batch 1B: Correction to E-UTRA RLC test case 7.2.2.7 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090511 | 0085 | - | Addition of a new LTE test case" 7.3.3.2 Correct functionality of EPS UP encryption algorithms (SNOW 3G)" | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090512 | 0086 | - | Addition of a new LTE test case "7.3.3.1 Correct functionality of EPS AS encryption algorithms (SNOW 3G)" | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090513 | 0087 | - | Addition of a new LTE test case "7.3.3.3 Correct functionality of EPS AS encryption algorithms (AES)" | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090514 | 0088 | - | Addition of a new LTE test case "7.3.3.4 Correct functionality of EPS UP encryption algorithms (AES)" | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090552 | 0089 | - | Batch 1:Corrections to MAC test case 7.1.2.7 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090553 | 0090 | - | Batch 1:Corrections to MAC test case 7.1.2.8 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090554 | 0091 | - | .Batch 1:Corrections to MAC test case 7.1.3.4 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090555 | 0092 | - | Batch 1:Corrections to MAC test case 7.1.3.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090556 | 0093 | - | Batch 1:Corrections to MAC test case 7.1.4.15 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090557 | 0094 | - | Batch 1:Corrections to MAC test case 7.1.4.16 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090570 | 0095 | - | Update of 36.523-1 Reference list | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090605 | 0096 | - | Batch 2: Update of LTE TC 8.1.2.3 RRC - RRC Connection Establishment in RRC Idle state: return to idle state after T300 timeout | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090607 | 0097 | - | Batch 2: Addition of EMM TC 9.2.1.2.4 for Successful combined attach procedure, EPS service only / CS domain not available. | 8.0.1 | 8.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-03 | RAN#43 | R5-090611 | 0098 | - | Batch 1:Corrections to EMM test case 9.1.3.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090631 | 0099 | - | Batch 1B: Correction to E-UTRA RLC test case 7.2.2.3 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090645 | 0100 | - | Batch 1B: Update of E-UTRAN test case 6.1.1.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090649 | 0101 | - | Batch-1B: Introduction of a new EMM test case, 9.2.3.1.4 Normal tracking area update / list of equivalent PLMNs in the TRACKING AREA UPDATE ACCEPT message | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090651 | 0102 | - | Batch 1:Corrections to MAC test case 7.1.2.2 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090653 | 0103 | - | Batch 1: Addition of new MAC test case 7.1.3.9 : MAC reset | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090654 | 0104 | - | Batch 1: Addition of new MAC test case 7.1.4.12 : MAC reset | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090655 | 0105 | - | Batch 1A - Update of E-UTRA MAC test case: 7.1.3.3 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090656 | 0106 | - | Batch 2 - Update of E-UTRA MAC test case: 7.1.2.9 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090665 | 0107 | - | Batch 1B - New E-UTRA PDCP test case - 7.3.1.2 Maintenance of PDCP sequence numbers (user plane, RLC UM) | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090666 | 0108 | - | Batch 1B - Correction to E-UTRA PDCP test case 7.3.1.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090667 | 0109 | - | Batch 1B - New E-UTRA PDCP test case - 7.3.1.3 Maintenance of PDCP sequence numbers (user plane, RLC UM, long PDCP SN (12 bits)) | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090669 | 0110 | - | Batch 1B -Update to test case 7.2.2.4 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090670 | 0111 | - | Batch 1A -Update to test case 7.2.3.3 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090671 | 0112 | - | Batch 1A -Update to test case 7.2.3.4 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090672 | 0113 | - | Removal of TC 7.3.5.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090674 | 0114 | - | Batch 1A - Update of E-UTRA RLC (AM) test case 7.2.3.17 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090675 | 0115 | - | Batch 1A - Update of E-UTRA RLC (AM) test case 7.2.3.15 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090676 | 0116 | - | Batch 1B - Update of test case 8.2.2.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090677 | 0117 | - | Update of RRC batch 1B test case 8.2.2.2 RRC Connection Reconfiguration / SRB/DRB Reconfiguration: Success | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090678 | 0118 | - | Batch-1: Update to RRC part 3 test case 8.3.3.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090679 | 0119 | - | Batch 1A - TC 9.1.2.1 Authentication accepted - Update of conformance requirements | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090680 | 0120 | - | Batch 1A - TC 9.3.2.1 Paging procedure revisited | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090685 | 0121 | - | Batch 1A -Update to test case 6.1.2.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090688 | 0122 | - | Update of TC 7.3.6.1 PDCP Discard | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090689 | 0123 | - | Addition of new TC 7.3.5.4 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090690 | 0124 | - | Batch 2 - Update of LTE TC 8.5.1.3 RRC - RRC Connection Re-establishment: Failure: T311 Expiry | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090691 | 0125 | - | Batch 2 -Update to test case 8.1.2.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090692 | 0126 | - | Batch 1A -Update to test case 8.1.2.7 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090693 | 0127 | - | Batch 1A -Update to test case 8.1.3.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090694 | 0128 | - | Batch 2 - Update to test case 8.2.4.3 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090695 | 0129 | - | Batch 1B - Update to test case 8.2.4.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090707 | 0130 | - | Batch 1A - Update of test case 8.2.4.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090709 | 0131 | - | Batch 2: Update of RRC part1 TC 8.1.3.6 RRC Connection Release: redirection from E-UTRAN to UTRAN | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090710 | 0132 | - | Batch 2: Update of RRC part3 TC 8.3.1.7 Measurement configuration control and reporting / intra E-UTRAN measurements: blacklisting | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090711 | 0133 | - | Corrections to LTE idle mode test cases | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090712 | 0134 | - | Batch 1B: Update of test case 6.1.2.6 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090713 | 0135 | - | Batch 2: Update of LTE TC 8.1.2.2 RRC, Reject with wait time | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090714 | 0136 | - | Update to test case 8.1.3.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090715 | 0137 | - | Batch 1B: update of E-UTRA PDCP test case 7.3.6.1 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090716 | 0138 | - | Batch 1B: update of E-UTRA PDCP test case 7.3.6.1 | 8.0.1 | 8.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-03 | RAN#43 | R5-090717 | 0139 | - | Batch 2 - Update to test case 8.3.1.8 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090720 | 0140 | - | Batch-2: Update to RRC part 3 test case 8.3.1.3 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090721 | 0141 | - | Batch-2: Update to RRC part 3 test case 8.3.1.5 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090722 | 0142 | - | Batch 2: Addition of new EMM TC 9.2.1.2.3: Successful combined attach procedure, EPS service only / MSC temporarily not reachable | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090730 | 0143 | - | Batch 1:Corrections to MAC test case 7.1.2.3 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090732 | 0144 | - | Batch 2 - Addition of new test case 9.2.1.2.6 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090733 | 0145 | - | Batch 2 - Addition of new test case 9.2.3.2.6 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090734 | 0146 | - | Batch 1:Corrections to MAC test case 7.1.4.2 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090735 | 0147 | - | Batch 1:Corrections to MAC test case 7.1.3.2 | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090736 | 0148 | - | Batch 2: Update of RRC part1 TC 8.1.3.4 RRC Connection Release: redirection to another E-UTRAN frequency | 8.0.1 | 8.1.0 |
| 2009-03 | RAN#43 | R5-090740 | 0149 | 4 | Batch 1A - Update of E-UTRA RLC (AM) test case 7.2.3.18 | 8.0.1 | 8.1.0 |
| 2009-05 | RAN#44 | R5-092052 | 0150 | - | GCF Priority 1 - Update of 9.1.2.1 test procedure sequence and editorials | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092053 | 0151 | - | GCF Priority 2 - Update of TC 9.1.2.3 Authentication not accepted by the network, GUTI used, authentication reject and re-authentication | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092054 | 0152 | - | GCF Priority 2 - Update TC 9.1.2.4 Authentication not accepted by the UE MAC code failure | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092055 | 0153 | - | GCF Priority 2 - New TC 9.1.2.5 Authentication not accepted by the UE, SQN failure | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092061 | 0154 | - | GCF Priority 1 - Update of RRC test case 9.3.1.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092076 | 0155 | - | GCF Priority 2: First lu mode to S1 mode intersystem change after attach: go to E-UTRAN RRC idle: RAU to UTRAN (9.2.3.3.1) | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092077 | 0156 | - | Batch 2: Addition of 8.1.3.9 RRC Redirection from E-UTRAN to HRPD | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092078 | 0157 | - | Batch 2: Addition of 8.1.3.10 RRC Redirection from E-UTRAN to CDMA2000-1XRTT | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092107 | 0158 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.3.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092108 | 0159 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092109 | 0160 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.4 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092110 | 0161 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092112 | 0162 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.8 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092113 | 0163 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.10 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092114 | 0164 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.13 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092115 | 0165 | - | GCF Priority 1 - Proposal to remove E-UTRA RLC test case 7.2.3.19 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092181 | 0166 | - | GCF Priority 2 - Update of test case 8.5.1.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092185 | 0167 | - | GCF Priority 1 - Update of test case 8.2.3.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092190 | 0168 | - | GCF Priority 1 - Update of E-UTRA RLC (AM) test case 7.2.3.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092191 | 0169 | - | GCF Priority 1 - Update of E-UTRA RLC (AM) test case 7.2.3.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092192 | 0170 | - | GCF Priority 1 - Update of E-UTRA RLC (AM) test case 7.2.3.18 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092200 | 0171 | - | GCF Priority 1 - Update of E-UTRA RLC (AM) test case 7.2.3.18 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092213 | 0172 | - | Addition of new RRC test case 8.3.2.9 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092228 | 0173 | - | GCF Priority 2 - Update to test case 6.1.2.15 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092229 | 0174 | - | GCF Priority 1 - Update to test case 6.1.2.4 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092230 | 0175 | - | GCF Priority 2 - Update to test case 6.1.2.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092234 | 0176 | - | GCF Priority 1 - Update to test case 8.1.1.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092242 | 0177 | - | GCF Priority 2 - Update to test case 8.1.3.5 | 8.1.0 | 8.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-05 | RAN#44 | R5-092245 | 0178 | - | GCF Priority-2: A new EMM test case, 9.2.3.1.8 UE receives an indication that the RRC connection was released with cause 'load balancing TAU required' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092247 | 0179 | - | Introduction of new EMM test cases, 9.2.3.1.10 and 9.2.3.1.11 Normal tracking area update / Rejected | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092248 | 0180 | - | Introduction of 9.2.3.1.12 ' Normal tracking area update / rejected / EPS service not allowed' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092249 | 0181 | - | Introduction of 9.2.3.1.13 ' Normal tracking area update / rejected / UE identity cannot be derived by the network' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092250 | 0182 | - | GCF Priority 2 - Addition of a new test case 6.1.2.11 Inter-frequency cell reselection | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092251 | 0183 | - | Introduction of 9.2.3.1.14 ' Normal tracking area update / rejected / UE implicitly detached' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092252 | 0184 | - | Introduction of 9.2.3.1.15 ' Normal tracking area update / rejected / PLMN not allowed' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092253 | 0185 | - | Introduction of 9.2.3.1.16 ' Normal tracking area update / rejected / Tracking area not allowed' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092258 | 0186 | - | GCF Priority 2 - Update of RRC part1 TC 8.1.3.4 RRC Connection Release: redirection to another E-UTRAN frequency | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092260 | 0187 | - | GCF Priority 2 - Update of RRC part1 TC 8.1.3.6 RRC Connection Release: redirection from E-UTRAN to UTRAN | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092262 | 0188 | - | GCF Priority 2 - Correction to idle mode test cases 6.1.2.3 and 6.1.2.6 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092272 | 0189 | - | LTE-SIG:TDD related updates in RRC sections | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092276 | 0190 | - | "GCF priority 1 - Update of the LTE test cases 7.3.3.1 Correct functionality of EPS AS encryption algorithms (SNOW 3G)ö" | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092278 | 0191 | - | GCF priority 1 - Update of test cases 7.3.3.2 Correct functionality of EPS UP encryption algorithms (SNOW 3G)ö | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092280 | 0192 | - | GCF Priority 2 - Update to test case 8.2.4.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092281 | 0193 | - | GCF Priority 2 - Update to test case 8.2.4.3 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092283 | 0194 | - | GCF Priority 2 - Update to test case 8.2.4.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092284 | 0195 | - | GCF Priority 2 - Update to test case 8.2.4.6 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092285 | 0196 | - | GCF Priority 2 - Update to test case 8.2.4.7 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092288 | 0197 | - | GCF Priority 2 - Update to test case 8.3.1.8 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092295 | 0198 | - | Addition of new test case 9.2.1.2.8 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092296 | 0199 | - | Addition of new test case 9.2.1.2.9 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092297 | 0200 | - | Addition of new test case 9.2.1.2.10 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092299 | 0201 | - | Addition of new test case 9.2.3.2.12 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092300 | 0202 | - | Addition of new test case 9.3.1.4 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092301 | 0203 | - | Addition of new test case to test case 10.X.X | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092327 | 0204 | - | GCF Priority 1: Update E-UTRA PDCP TC 7.3.4.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092328 | 0205 | - | GCF Priority 1: Update E-UTRA PDCP TC 7.3.4.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092329 | 0206 | - | GCF Priority 2: Update E-UTRA PDCP TC 7.3.5.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092330 | 0207 | - | GCF Priority 2: Update E-UTRA PDCP TC 7.3.5.3 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092331 | 0208 | - | GCF Priority 2: Update E-UTRA PDCP TC 7.3.5.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092367 | 0209 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.6 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092396 | 0210 | - | GCF Priority 2 - Addition of new test case 6.2.2.3 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092397 | 0211 | - | GCF Priority 2 - Addition of new test case 6.2.3.7 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092398 | 0212 | - | GCF Priority 2 - Addition of new test case 6.2.3.8 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092406 | 0213 | - | "GCF Priority 2 - Addition of new LTE test case 7.2.2.11 UM RLC / RLC re-establishment procedure" | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092417 | 0214 | - | GCF Priority 2:Corrections to EMM test case 9.1.3.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092418 | 0215 | - | GCF Priority 1:Corrections to MAC test case 7.1.3.4 | 8.1.0 | 8.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2009-05 | RAN#44 | R5-092419 | 0216 | - | GCF Priority 1:Corrections to MAC test case 7.1.3.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092420 | 0217 | - | GCF Priority 1:Corrections to MAC test case 7.1.4.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092421 | 0218 | - | GCF Priority 2: Attach / Abnormal case / Access barred because of access class barring or NAS signalling connection establishment rejected by the network | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092422 | 0219 | - | GCF Priority 2: Corrections to EMM test case 9.4.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092423 | 0220 | - | GCF Priority 2:Corrections to EMM test case 9.4.3 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092430 | 0221 | - | GCF Priority 1:Corrections to MAC test case 7.1.1.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092451 | 0222 | - | Update of RSRP / RSRQ measurement result checking to the RRC part 3 test cases | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092471 | 0223 | - | GCF Priority 2-Correction of the EMM test case 9.2.3.1.4 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092480 | 0224 | - | GCF Priority 1:Corrections to MAC test case 7.1.2.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092481 | 0225 | - | GCF Priority 1:Corrections to MAC test case 7.1.2.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092484 | 0226 | - | GCF Priority 1:Corrections to MAC test case 7.1.2.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092485 | 0227 | - | GCF Priority 1:Corrections to MAC test case 7.1.2.7 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092486 | 0228 | - | GCF Priority 1:Corrections to MAC test case 7.1.2.8 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092500 | 0229 | - | GCF priority 2: Update of 10.2.1 for Dedicated EPS bearer context activation / Success | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092501 | 0230 | - | GCF priority 2: Addition of TC 10.4.1 for EPS bearer context deactivation / Success | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092502 | 0231 | - | GCF priority 2: Addition of TC 10.5.1 for UE requested PDN connectivity accepted by the network | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092504 | 0232 | - | GCF priority TBC: Addition of TC 10.5.2 for UE requested PDN connectivity accepted by the network / no PDN address allocated | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092505 | 0233 | - | GCF priority 3: Addition of TC 10.5.3 for UE requested PDN connectivity not accepted | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092506 | 0234 | - | GCF priority 2: Addition of ESM TC 10.6.1 for UE requested PDN disconnect procedure accepted by the network | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092507 | 0235 | - | GCF Priority 3: Addition of ESM TC 10.6.2 for UE requested PDN disconnect procedure not accepted by the network | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092510 | 0236 | - | GCF priority 2 - Update of 9.2.1.1.17 Attach / rejected / no suitable cells in tracking area | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092512 | 0237 | - | GCF priority 1: Update of EMM TC 9.3.1.2 Service Request initiated by UE for uplink signalling | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092513 | 0238 | - | GCF priority 2: Update of 9.2.1.1.17 Attach / rejected / no suitable cells in tracking area | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092514 | 0239 | - | GCF priority 1: Update of 9.2.1.1.1 Attach Procedure / Success (valid GUTI) | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092515 | 0240 | - | GCF priority 2: Update of 9.2.1.1.5 Attach Procedure/ Success / ATTACH ACCEPT includes the PDN address assigned to the UE | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092516 | 0241 | - | GCF priority 2: Update of 9.2.1.1.9 Attach / rejected / IMSI invalid | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092517 | 0242 | - | GCF priority 2: Update of 9.2.1.1.10 Attach / rejected / illegal ME | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092518 | 0243 | - | GCF priority TBC: Update of 9.2.1.1.12 Attach / rejected / GPRS services not allowed | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092539 | 0244 | - | GCF Priority 1 - Update of RLC section | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092567 | 0245 | - | GCF Priority 2 - Addition of a new test case 6.2.3.5 Inter-RAT Cell Reselection / from E-UTRA RRC_IDLE to UTRA_Idle | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092569 | 0246 | - | GCF Priority 2: Inter-RAT cell Selection / from E-UTRA RRC_IDLE to UTRA_Idle, serving cell becomes non-suitable (SServingCell<0,barred) | 8.1.0 | 8.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2009-05 | RAN#44 | R5-092570 | 0247 | - | GCF Priority 2: Inter-RAT cell Selection / from E-UTRA RRC_IDLE to GSM_Idle/GPRS Packet_idle, serving cell becomes non-suitable (SServingCell<0,barred) | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092571 | 0248 | - | GCF Priority 1 - New E-UTRA MAC test case - 7.1.7.1.1 DL-SCH Transport Block Size support / DCI format 1 / RA type 0 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092575 | 0249 | - | GCF Priority 1 - New E-UTRA MAC test case 7.1.7.1.2 - DL-SCH Transport Block Size selection / DCI format 1 / RA type 1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092577 | 0250 | - | GCF Priority 1 - New E-UTRA MAC test case 7.1.7.2.1 - UL-SCH Transport Block Size selection / DCI format 0 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092578 | 0251 | - | GCF priority 2: New MAC test case: 7.1.6.1 DRX Operation / (short cycle not configured) /Parameters configured by RRC (radio resource configuration) | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092579 | 0252 | - | GCF Priority 2 - New RRC part1 TC 8.1.3.8 RRC Connection Release: redirection from E-UTRAN to GERAN | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092580 | 0253 | - | GCF Priority 2 - Update of test case 8.2.1.3 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092583 | 0254 | - | GCF Priority 2: Attach Procedure / Success (last visited TAI, TAI list and equivalent PLMN list handling) 9.2.1.1.1a | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092584 | 0255 | - | GCF Priority 1 - Update of test case 8.2.1.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092589 | 0256 | - | GCF Priority 2 - Addition of new EMM test case 9.3.1.7a | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092593 | 0257 | - | GCF priority 2 - Update of 9.2.1.1.15 Attach / rejected / roaming not allowed in this tracking area | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092595 | 0258 | - | GCF Priority 1:Corrections to MAC test case 7.1.1.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092596 | 0259 | - | GCF Priority 1:Corrections to MAC test case 7.1.4.12 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092597 | 0260 | - | GCF Priority 1 - Update to test case 8.2.4.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092700 | 0261 | - | GCF Priority 2 - Addition of new test case 8.3.2.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092701 | 0262 | - | GCF Priority-1: Correction to 9.2.3.1.1 'Normal tracking area update / accepted' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092702 | 0263 | - | GCF Priority-1: Correction to 9.2.3.1.5'Periodic tracking area update / accepted' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092703 | 0264 | - | GCF Priority 2 - Addition of E-UTRAN test case 6.1.2.7 for Cell reselection: Equivalent PLMN | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092706 | 0265 | - | GCF Priority 1 - Update to RRC test cases | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092712 | 0266 | - | GCF Priority 2: New MAC test case 7.1.4.14 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092713 | 0267 | - | GCF Priority 2 - Update to test case 8.1.2.5 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092714 | 0268 | - | GCF Priority 2 - Update to test case 8.1.2.7 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092715 | 0269 | - | GCF Priority 2 - Addition of RRC test case 8.3.2.6 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092716 | 0270 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.4.7 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092717 | 0271 | - | GCF Priority 1 - New E-UTRA MAC test case 7.1.7.1.4 - DL-SCH Transport Block Size selection / DCI format 1A / RA type 2 / Distributed VRB | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092718 | 0272 | - | GCF Priority 1 - New E-UTRA MAC test case 7.1.7.1.3 - DL-SCH Transport Block Size selection / DCI format 1A / RA type 2 / Localised VRB | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092730 | 0273 | - | GCF priority 2: New MAC test case: 7.1.6.2 DRX Operation / Parameters (short cycle not configured) / DRX command MAC control element reception | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092731 | 0274 | - | GCF Priority 2 - Updates to E-UTRAN Idle Mode test case 6.1.2.9 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092732 | 0275 | - | GCF Priority 2 - Updates to E-UTRAN Idle Mode test case 6.1.2.8 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092741 | 0276 | - | GCF Priority 1 - Update to idle mode test cases | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092751 | 0277 | - | Addition of new idle mode test case for ignoring CSG cells in cell selection when Allowed CSG list is empty or not supported | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092752 | 0278 | - | GCF Priority 2: New idle mode test case 6.2.3.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092755 | 0279 | - | GCF Priority 2 - Update to test case 8.3.1.10 | 8.1.0 | 8.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-05 | RAN#44 | R5-092756 | 0280 | - | GCF Priority 2 - Update to test case 8.3.2.3 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092758 | 0281 | - | GCF Priority 2 - Updates to E-UTRAN test case 6.1.1.1 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092760 | 0282 | - | GCF Priority 2: New idle mode test case 6.2.3.2 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092761 | 0283 | - | Move common test procedure from sections 6.0.1, 6.0.2, 6.0.3 to TS 36.508 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092762 | 0284 | - | Batch 2 - Addition of new RRC test case 8.3.2.7 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092763 | 0285 | - | Batch 2 - Addition of new RRC test case 8.3.2.8 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092764 | 0286 | - | LTE-SIG:TDD related updates in MAC sections | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092768 | 0287 | - | GCF Priority-1: Correction to 9.2.2.2.1 'NW initiated detach / re-attach required' | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092784 | 0288 | - | GCF Priority 2 - Update to test case 8.3.1.9 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092483 | 0289 | - | GCF Priority 1:Corrections to MAC test case 7.1.2.4 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092528 | 0290 | 4 | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.2.3 | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092785 | 0291 | - | GCF priority 2: A/Gb mode READY state to S1 mode cell reselection and E-UTRAN - GERAN RAU (9.2.3.4.1, 9.2.3.4.2) | 8.1.0 | 8.2.0 |
| 2009-05 | RAN#44 | R5-092786 | 0292 | - | GCF Priority 2 - Update of TC 9.2.1.1.14 Attach / rejected / tracking area not allowed | 8.1.0 | 8.2.0 |
| - | - | - | - | - | Editorial corrections and split into sections | 8.2.0 | 8.2.1 |
| 2009-09 | RAN#45 | R5-094075 | 0293 | - | GCF Priority 1 - Update of MAC test case 7.1.2.6 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094076 | 0294 | - | GCF Priority 1 - Update of MAC test case 7.1.3.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094078 | 0295 | - | GCF Priority 1 - Update of MAC test case 7.1.3.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094079 | 0296 | - | GCF Priority 1 - Update of MAC test case 7.1.3.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094080 | 0297 | - | GCF Priority 1 - Update of MAC test case 7.1.3.5 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094081 | 0298 | - | GCF Priority 1 - Update of MAC test case 7.1.3.6 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094082 | 0299 | - | GCF Priority 1 - Update of MAC test case 7.1.3.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094083 | 0300 | - | GCF Priority 1 - Update of MAC test case 7.1.4.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094085 | 0301 | - | GCF Priority 1 - Update of MAC test case 7.1.4.6 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094086 | 0302 | - | GCF Priority 1 - Update of MAC test case 7.1.4.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094087 | 0303 | - | GCF Priority 1 - Update of MAC test case 7.1.4.8 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094088 | 0304 | - | GCF Priority 1 - Update of MAC test case 7.1.4.11 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094089 | 0305 | - | GCF Priority 1 - Update of MAC test case 7.1.4.13 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094090 | 0306 | - | GCF Priority 1 - Update of MAC test case 7.1.4.15 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094091 | 0307 | - | GCF Priority 1 - Update of PDCP test case 7.3.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094092 | 0308 | - | GCF Priority 1 - Update of RRC test case 8.2.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094093 | 0309 | - | GCF Priority 2 - Update of MAC test case 7.1.4.16 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094094 | 0310 | - | GCF Priority 2 - Update of Idle Mode test case 6.1.2.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094095 | 0311 | - | GCF Priority 2 - Update of RRC test case 8.1.3.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094096 | 0312 | - | GCF Priority 2 - Update of RRC test case 8.1.3.6 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094101 | 0313 | - | GCF Priority 2 - Addition of new test case 10.7.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094102 | 0314 | - | GCF Priority 2 - Addition of new test case 10.7.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094114 | 0315 | - | Addition of new test case 6.2.2.5 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094121 | 0316 | - | GCF Priority 2 - Update to test case 8.3.1.9 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094122 | 0317 | - | Remove TC 8.4.1.8 from TS 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094124 | 0318 | - | GCF Priority 2 - Addition of new test case 8.4.2.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094187 | 0319 | - | GCF Priority 2 - New EMM TC 9.1.4.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094189 | 0320 | - | GCF Priority 2 - Removal of EMM TC 9.1.2.2 | 8.2.1 | 8.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-09 | RAN#45 | R5-094195 | 0321 | - | GCF Priority 1 - Update of MAC test case 7.1.4.10 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094196 | 0322 | - | GCF Priority 2 - Update of RLC test case 7.2.3.21 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094201 | 0323 | - | GCF Priority 2 - Update of RRC test case 8.3.2.6 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094202 | 0324 | - | GCF Priority 2 - Add new RRC test case 8.4.1.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094203 | 0325 | - | GCF Priority 2 - Add new RRC test case 8.4.1.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094205 | 0326 | - | GCF Priority 3 - Remove RRC test case 8.1.3.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094284 | 0327 | - | Removal of the GUTI reallocation procedures test cases | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094289 | 0328 | - | GCF Priority 2 - TDD formulation update in 7.1.6.1 DRX Operation / (short cycle not configured) /Parameters configured by RRC (radio resource configuration) | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094290 | 0329 | - | GCF Priority 2 - TDD formulation update in 7.1.6.2 DRX Operation / Parameters (short cycle not configured) / DRX command MAC control element reception | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094366 | 0330 | - | GCF Priority 2 - Corrections to E-UTRAN test case 6.1.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094369 | 0331 | - | GCF Priority 2 - Updates to E-UTRAN test case 6.1.2.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094372 | 0332 | - | GCF Priority 2 - Corrections to E-UTRAN test cases 6.1.2.8 and 6.1.2.9 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094387 | 0333 | - | GCF Priority 2 - Update to test case 9.2.2.1.6 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094392 | 0334 | - | GCF Priority 2 - Correction of discard timer value to be consistent with test tolerances | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094399 | 0335 | - | GCF Priority 2 - Addition new test case 6.2.3.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094426 | 0336 | - | GCF Priority 1 - Corrections to MAC test case 7.1.4.6 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094428 | 0337 | - | GCF Priority 1 - Corrections to MAC test case 7.1.4.10 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094432 | 0338 | - | GCF Priority 2 - Corrections to MAC test case 7.1.4.16 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094520 | 0339 | - | GCF Priority 2 - Update of RRC test case 8.3.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094521 | 0340 | - | GCF Priority 2 - Update of RRC test case 8.3.1.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094523 | 0341 | - | GCF Priority 2 - Update of RRC test case 8.3.1.5 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094525 | 0342 | - | GCF Priority 1 - Update of RRC test case 8.3.3.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094577 | 0343 | - | GCF Priority 1 - Update of EMM part TC 9.1.3.1 NAS security mode command accepted by the UE | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094627 | 0344 | - | GCF Priority 2 - Update of MAC TC 7.1.3.2 DL SPS | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094628 | 0345 | - | GCF Priority 2 - Update of MAC TC 7.1.4.2 UL SPS | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094629 | 0346 | - | GCF Priority 1 - Corrections to MAC test case 7.1.3.9 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094635 | 0347 | - | GCF Priority 1 - Correction to E-UTRAN RLC test case 7.2.3.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094636 | 0348 | - | GCF Priority 1 - Adding Test Coverage for Verification of UE setting of the RRC Establishment Cause in EMM test case 9.2.1.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094660 | 0349 | - | GCF Priority 2 - Update of MAC test case 7.1.4.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094662 | 0350 | - | GCF Priority 1 - Corrections to RLC section | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094664 | 0351 | - | GCF Priority 1 - Update of RLC test case 7.2.3.9 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094666 | 0352 | - | GCF Priority 2 - Addition of new EMM test case 9.2.3.3.5 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094674 | 0353 | - | GCF Priority 2 - Update of RRC test case 8.3.2.8 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094676 | 0354 | - | GCF Priority 3 - Update of RRC test case 8.3.2.9 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094707 | 0355 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.2.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094762 | 0356 | - | GCF Priority 2 - Update of RRC test case 6.2.2.3 | 8.2.1 | 8.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-09 | RAN#45 | R5-094776 | 0357 | - | GCF Priority 2 - Update of RRC test case 6.2.3.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094788 | 0358 | - | GCF Priority 2 - Update of RRC test case 6.2.3.8 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094798 | 0359 | - | GCF Priority 2 - Update of RRC test case 8.1.3.9 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094814 | 0360 | - | GCF Priority 2 - Update of RRC test case 8.1.3.10 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094817 | 0361 | - | GCF Priority 2 - Update of RRC test case 8.3.2.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094823 | 0362 | - | GCF Priority 2 - Update of RRC test case 8.3.2.8 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094833 | 0363 | - | GCF Priority 2 - Correction of EMM TC 9.2.1.1.9 Attach / rejected / IMSI invalid | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094866 | 0364 | 2 | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094867 | 0365 | 2 | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094868 | 0366 | 2 | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094869 | 0367 | 2 | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-094876 | 0368 | - | GCF Priority 1 - Correction to E-UTRAN RLC test case 7.2.3.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095004 | 0369 | - | GCF Priority 2 - Update of 9.1.2.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095005 | 0370 | - | GCF Priority 2 - Update of 9.1.2.5 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095008 | 0371 | - | GCF Priority 2 - Update of MAC TC 7.1.4.14 TTI Bundling | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095028 | 0372 | - | GCF Priority 1 - Various corrections to RLC section of 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095032 | 0373 | - | GCF Priority 2 - Addition of new SMS over SGs test case 11.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095036 | 0374 | - | GCF Priority 2 - Correction to 9.2.2.2.2 NW initiated detach / IMSI detach | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095037 | 0375 | - | GCF Priority 2 - Correction of PDCP status report | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095038 | 0376 | - | GCF Priority 2 - Correction of PDCP handover test procedure | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095041 | 0377 | - | GCF Priority 2 - Update of 9.1.2.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095065 | 0378 | - | GCF Priority 2 - Adding Test Coverage for Verification of UE setting of the RRC Establishment Cause in EMM test case 9.2.2.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095066 | 0379 | - | GCF Priority 1 - Adding Test Coverage for Verification of UE setting of the RRC Establishment Cause in EMM test case 9.3.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095067 | 0380 | - | GCF Priority 1 - Adding Test Coverage for Verification of UE setting of the RRC Establishment Cause in EMM test case 9.3.1.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095069 | 0381 | - | GCF Priority 2 - Adding Test Coverage for Verification of UE setting of the RRC Establishment Cause in EMM test case 9.3.1.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095070 | 0382 | - | GCF Priority 2 - Adding Test Coverage for Verification of UE setting of the RRC Establishment Cause in EMM test case 9.3.2.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095073 | 0383 | - | GCF Priority 2 - Update of EMM test case 9.3.1.7a | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095075 | 0384 | - | GCF Priority 1 - Corrections to MAC test case 7.1.4.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095076 | 0385 | - | GCF Priority 1 - Corrections to MAC test case 7.1.4.8 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095077 | 0386 | - | GCF Priority 1 - Corrections to MAC test case 7.1.4.13 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095078 | 0387 | - | GCF Priority 1 - Corrections to MAC test case 7.1.4.5 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095086 | 0388 | - | GCF Priority 1 - Various corrections to RLC section of 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095087 | 0389 | - | GCF Priority 2 - New EMM TC 9.3.1.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095088 | 0390 | - | GCF Priority 1 - Update to test case 9.2.1.1.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095089 | 0391 | - | Update to GCF Priority 2 test case 9.2.1.1.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095090 | 0392 | - | GCF Priority 2 - Update to test case 9.2.2.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095094 | 0393 | - | Update to preamble in L2 UM test cases | 8.2.1 | 8.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2009-09 | RAN#45 | R5-095097 | 0394 | - | Add reference to test procedure for Idle Mode section | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095103 | 0395 | - | GCF Priority 1 - Update of MAC part TC 7.1.2.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095104 | 0396 | - | GCF Priority 1 - Corrections to MAC test case 7.1.4.11 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095105 | 0397 | - | Addition new test case 6.2.3.13 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095109 | 0398 | - | GCF Priority 1 - Update of 9.1.2.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095110 | 0399 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.3.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095112 | 0400 | - | GCF Priority 2 - Correction of EMM TC 9.2.1.1.12 Attach / rejected / EPS services not allowed | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095113 | 0401 | - | GCF Priority 2 - Corrections to test case 9.2.1.1.13 Attach / rejected / PLMN not allowed | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095116 | 0402 | - | GCF Priority 2 - Correction of EMM 9.2.1.1.17 TC Attach / rejected / no suitable cells in tracking area | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095118 | 0403 | - | GCF Priority 3 - Correction to EMM TC 9.2.1.2.3 Combined attach procedure / Success / EPS services only / MSC temporarily not reachable | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095120 | 0404 | - | GCF Priority 1 - Various corrections to other section of 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095121 | 0405 | - | GCF Priority 1 - Various corrections to RRC Part1 section of 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095125 | 0406 | - | GCF Priority 1 - Update of MAC TC 7.1.4.4 SR | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095126 | 0407 | - | GCF Priority 1 - Update of 9.3.2.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095127 | 0408 | - | Priority 2 - Update of test case 6.2.2.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095131 | 0409 | 2 | GCF Priority 1 - Addition of new Multi-layer Procedures test case 13.1.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095132 | 0410 | 2 | GCF Priority 1 - Addition of new Multi-layer Procedures test case 13.2.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095133 | 0411 | - | GCF Priority 1 - Correction to E-UTRAN RLC test case 7.2.3.5 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095135 | 0412 | - | GCF Priority 2 - Update of cell reselection test case 6.1.2.15 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095136 | 0413 | - | GCF Priority 2 - Update of PDCP test case handover / In-order delivery and duplicate elimination in the downlink | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095139 | 0414 | - | GCF Priority 2 - Addition of test case 11.1.3 MO-SMS over SGs in idle mode | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095140 | 0415 | - | GCF Priority 2 - Correction to 9.2.3.1.2 Normal tracking area update / accepted / 'Active' flag set | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095141 | 0416 | - | GCF Priority 2 - Correction of TC 9.2.1.1.14 Attach / rejected / tracking area not allowed | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095148 | 0417 | - | GCF Priority 2 - Correction of EMM TC 9.2.1.1.15 Attach / rejected / roaming not allowed in this tracking area | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095149 | 0418 | - | GCF Priority 2 - Addition of new test case 9.2.3.3.6 for E-UTRAN RRC connection failure / reselection of UTRAN cell / NAS signalling to release old S1 interface connection | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095150 | 0419 | - | GCF Priority 2 - Update to test case 10.8.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095151 | 0420 | - | GCF Priority 2 - Addition of new SMS over SGs test case 11.1.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095161 | 0421 | - | GCF Priority 1 - Various corrections to Idle Mode section of 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095164 | 0422 | - | GCF Priority 1 - Update of E-UTRA MAC test case 7.1.2.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095172 | 0423 | - | GCF Priority 4 - New TC 8.1.3.7 RRC Connection Release: redirection from UTRAN to E-UTRAN | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095173 | 0424 | 1 | GCF Priority 3 - Update to test case 9.2.2.1.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095175 | 0425 | 1 | GCF Priority 3 - Correction to 9.2.1.2.1 "Combined attach procedure / Success / EPS and non-EPS services" | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095177 | 0426 | - | GCF Priority 3 - CR to EMM TC 9.2.1.1.19 Attach / Abnormal case / Failure due to non integrity protection | 8.2.1 | 8.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|-----|--|-------------|-------------|
| 2009-09 | RAN#45 | R5-095178 | 0427 | - | GCF Priority 3 - New EMM TC 9.2.3.2.1a Combined tracking area update / successful / check of last visited TAI and handling of TAI list, LAI and TMSI | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095179 | 0428 | - | GCF Priority 3 - Addition of new test case 6.2.2.4 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095188 | 0429 | 3 | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.2.1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095207 | 0430 | - | GCF Priority 2 - Addition of new test case 8.4.2.2 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095208 | 0431 | - | GCF Priority 1 - Corrections to RLC test case 7.2.3.7 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095217 | 0432 | - | GCF Priority 1 - Corrections to PDCP test cases 7.5.3.2 and 7.5.3.3 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095219 | 0433 | - | GCF Priority 1 - Various corrections to RRC Part2 section of 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-09 | RAN#45 | R5-095220 | 0434 | - | GCF Priority 1 - Various corrections to RRC Part 3 section of 36.523-1 | 8.2.1 | 8.3.0 |
| 2009-10 | - | - | - | - | Minor CR 414 implementation corrections | 8.3.0 | 8.3.1 |
| 2009-10 | - | - | - | - | Minor CR 354 implementation corrections | 8.3.1 | 8.3.2 |
| 2009-11 | GERAN#44 | GP-092405 | 0435 | - | Addition of new Test Case 6.2.3.21 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095444 | 0436 | - | Removal of TC 8.1.2.10 from TS 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095446 | 0437 | - | GCF Priority 1 - Various corrections to RRC Part 2 section of 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095447 | 0438 | - | Removal of TC 8.2.1.2 from TS 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095448 | 0439 | - | Removal of TC 8.2.1.4 from TS 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095450 | 0440 | - | GCF Priority 2 - Update to test case 8.2.4.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095451 | 0441 | - | GCF Priority 3 - Update to test case 8.2.4.9 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095462 | 0442 | - | GCF Priority 3 - Addition of test case 9.2.3.1.9a | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095467 | 0443 | - | GCF Priority 3 - Addition of test case 9.3.1.16 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095505 | 0444 | - | GCF Priority 2 - Update test case 6.1.2.11 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095507 | 0445 | - | GCF Priority 2 - Correction for Measurement test cases | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095521 | 0446 | - | GCF Priority 1 - Update of RLC test case 7.2.3.14 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095524 | 0447 | - | GCF Priority 2 - Update of EMM test case 9.2.3.3.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095525 | 0448 | - | GCF Priority 2 - Update of EMM test case 9.3.1.7a | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095597 | 0449 | - | GCF Priority 3 - Addition of E-UTRAN test case 8.3.1.11 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095609 | 0450 | - | GCF Priority 1 - Update of EMM test case 9.2.3.1.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095621 | 0451 | - | GCF Priority 2 - Removal of TC 8.4.2.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095774 | 0452 | - | GCF Priority 2 - Correction to test case 6.1.1.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095783 | 0453 | - | GCF Priority 3 - Update to test case 9.2.1.1.25 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095784 | 0454 | - | GCF Priority 2 - Update to test case 9.2.2.1.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095785 | 0455 | - | GCF Priority 3 - Update to test case 9.2.2.1.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095786 | 0456 | - | GCF Priority 2 - Update to test case 9.2.2.1.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095795 | 0457 | - | Addition of new DSMIPv6 test case for Discovery of the Home Agent via DNS | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095796 | 0458 | - | Addition of new DSMIPv6 test case for Security association establishment without Home Agent reallocation procedure | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095802 | 0459 | - | GCF Priority 3 - Addition of new RRC test case 8.4.5.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095803 | 0460 | - | GCF Priority 3 - Addition of new RRC test case 8.4.7.3 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095804 | 0461 | - | GCF Priority 3 - Addition of new RRC test case 8.4.7.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095884 | 0462 | - | GCF Priority 1 - Correction of TC 9.2.1.1.1 Attach Procedure / Success (valid GUTI) | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095885 | 0463 | - | GCF Priority x - Proposed removal of TC 9.3.1.2 Service Request initiated by UE for uplink signalling | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095886 | 0464 | - | GCF Priority 2 - Proposed removal of TC 9.2.1.1.5 Attach Procedure / Success / ATTACH ACCEPT message includes the PDN address assigned to the UE | 8.3.2 | 8.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-12 | RAN#46 | R5-095901 | 0465 | - | GCF Priority 2 - Correction of TC 9.2.3.3.6 E-UTRAN RRC connection failure / reselection of UTRAN cell / NAS signalling to release old S1 interface connection | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095937 | 0466 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.4.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095963 | 0467 | - | GCF Priority 2 - Update of TC 9-1-2-5 for IP handling over U-plane | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095972 | 0468 | - | GCF Priority 1 - Update of TC 9-1-2-1 for IP handling over U-plane | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095976 | 0469 | - | GCF Priority 2 - Update of TC 9-3-1-7 for IP handling over U-plane | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095979 | 0470 | - | GCF Priority 2 - Update of TC 9-1-2-4 for IP handling over U-plane | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095980 | 0471 | - | GCF Priority 2 - Test Case 9.1.4.2 Clause title formatting error | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-095997 | 0472 | - | GCF Priority 2 - Correction to RRC test case 8.5.1.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096009 | 0473 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.2.3.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096024 | 0474 | - | GCF Priority 1: Cell number alignment in Test case 9.1.3.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096027 | 0475 | - | GCF Priority 2 - Cell number alignment in Test case 9.1.3.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096029 | 0476 | - | GCF Priority 2 - Cell number alignment in Test case 9.4.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096031 | 0477 | - | GCF Priority 2: Cell number alignment in Test case 9.4.3 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096034 | 0478 | - | GCF Priority 2: Correction to Test case 7.1.4.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096036 | 0479 | - | GCF Priority 2: Correction to Test case 7.1.4.14 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096149 | 0480 | - | GCF Priority 2 - update test case 8.5.1.3 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096156 | 0481 | - | GCF Priority 2 - Update of RLC test case 7.2.3.13 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096160 | 0482 | - | GCF Priority 2 - Update of TC 9-1-2-3 for IP handling over U-plane | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096161 | 0483 | - | GCF Priority 1 and Priority 2- EMM Successful Attach consistent description | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096178 | 0484 | - | GCF Priority 2 - Correction test cases 8.3.2.1, 8.3.2.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096192 | 0485 | - | GCF Priority 1 - Various editorial corrections to RLC section | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096193 | 0486 | - | GCF Priority 1 - Update to Idle Mode test case 6.1.2.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096194 | 0487 | - | GCF Priority 2 - Updated to test case 6.1.2.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096196 | 0488 | - | GCF Priority 2 - Correction to test case 6.3.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096197 | 0489 | - | GCF Priority 2 - Correction to test case 6.1.2.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096401 | 0490 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.2.9 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096414 | 0491 | - | GCF Priority 2 & 3 - Correction to test cases 9.2.1.1.9 and 9.2.1.1.12 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096421 | 0492 | - | GCF Priority 1: Update of MAC TC 7.1.7.1.1 DL-SCH TBS selection/DCI format 1/RA type0 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096422 | 0493 | - | GCF Priority 1: Update of MAC TC 7.1.7.1.2 DL-SCH TBS selection/DCI format 1/RA type1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096423 | 0494 | - | GCF Priority 1: Update of MAC TC 7.1.7.1.3 DL-SCH TBS selection/DCI format 1A/RA type2/Localized VRB | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096424 | 0495 | - | GCF Priority 1: Update of MAC TC 7.1.7.1.4 DL-SCH TBS selection/DCI format 1A/RA type2/Distributed VRB | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096425 | 0496 | - | GCF Priority 1: Update of MAC TC 7.1.7.2.1 UL-SCH TBS selection/DCI format 0 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096426 | 0497 | 1 | GCF Priority 1: Update of E-UTRA MAC test case 7.1.4.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096428 | 0498 | - | GCF Priority 1: Update of E-UTRA MAC test case 7.1.3.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096429 | 0499 | - | GCF Priority 2 - Update to test case 9.2.1.1.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096435 | 0500 | - | GCF Priority 3: Introduction of a new EMM test case 9.2.3.1.6' Normal tracking area update / UE with ISR active moves to E-UTRAN ' | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096436 | 0501 | - | GCF Priority 3: Introduction of 9.2.3.1.17 Normal tracking area update / rejected / Roaming not allowed in this tracking area | 8.3.2 | 8.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-12 | RAN#46 | R5-096437 | 0502 | - | GCF Priority 3: Introduction of 9.2.3.1.18 Normal tracking area update / rejected / EPS services not allowed in this PLMN | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096443 | 0503 | - | GCF Priority 3: Addition of new test case 9.2.1.1.24: Attach / Abnormal case / Change of cell into a new tracking area | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096444 | 0504 | - | GCF Priority 3: Addition of new test case 9.2.1.1.26: Attach / Abnormal case / Detach procedure collision | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096445 | 0505 | - | GCF Priority 2: Correction to Test case 7.1.3.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096446 | 0506 | - | GCF Priority 1: Correction to EMM test case 9.3.1.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096451 | 0507 | - | GCF Priority 2 - Correction of test cases 9.2.1.1.9, 9.2.1.1.10, 9.2.1.1.11 Attach / rejected / IMSI invalid / Illegal UE / EPS and non-EPS services not allowed | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096452 | 0508 | - | GCF Priority 2 - Correction of TC 9.2.3.2.1 Combined tracking area update / successful | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096454 | 0509 | - | GCF Priority 2 - Correction of TC 9.2.3.3.1 First lu mode to S1 mode intersystem change after attach: go to E-UTRAN RRC idle: RAU to UTRAN | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096459 | 0510 | - | Disabling PHR and periodic BSR for L2 test cases in 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096466 | 0511 | - | Correction of test case 6.1.2.13 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096467 | 0512 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.4.13 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096468 | 0513 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.4.10 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096470 | 0514 | - | GCF Priority 3 - Addition of E-UTRAN test case 8.3.3.3 for Measurement configuration control and reporting / SON / ANR: CGI reporting of GERAN cell | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096471 | 0515 | - | GCF Priority 3 - Addition of E-UTRAN test case 8.3.3.2 :Measurement configuration control and reporting / SON / ANR: CGI reporting of UTRAN cell | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096472 | 0516 | - | GCF Priority 1 - Update of Multi-layer Procedures part TC 13.1.1 Activation and deactivation of additional data radio bearer in E-UTRA | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096476 | 0517 | - | GCF Priority 3 - Update of RRC part TC 8.5.1.2 RRC Connection Re-establishment: Success (after Radio Link Failure) | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096479 | 0518 | - | GCF Priority 3 - Update of RRC test case 8.2.1.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096481 | 0519 | - | GCF Priority 1 - Update to test case 7.2.3.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096482 | 0520 | - | GCF Priority 1 - Correction of TC 8.5.4.1 UE capability transfer / Success | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096483 | 0521 | - | GCF Priority 1 - Update of PDCP test case 7.3.3.1 : Ciphering and Deciphering: Correct functionality of EPS AS encryption algorithms (SNOW 3G) | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096484 | 0522 | - | GCF Priority 1: Correction to RRC test case 8.2.1.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096485 | 0523 | - | GCF Priority 1 - Update of EMM test case 9.2.3.1.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096487 | 0524 | - | GCF Priority 1 - Various corrections to Idle Mode section of 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096488 | 0525 | - | GCF Priority 2 - Update to test case 8.1.2.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096489 | 0526 | - | GCF Priority 2 - Update to test case 8.1.2.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096491 | 0527 | - | GCF Priority 2 - Various corrections to RRC Part 3 section of 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096492 | 0528 | - | GCF Priority 1 - Correction to E-UTRA DRB test case 12.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096493 | 0529 | 3 | GCF Priority 1 - Update of Multi-layer Procedures part TC 13.2.1 RRC Connection Reconfiguration: E-UTRA to E-UTRA | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096494 | 0530 | - | GCF Priority 1 - Update of applicability entry for DRB test case 12.3 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096495 | 0531 | - | GCF Priority 2 - Update of the test case 6.2.3.3 | 8.3.2 | 8.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-12 | RAN#46 | R5-096496 | 0532 | - | GCF Priority 2 - Update of Idle Mode Operations test case 6.1.2.5 Cell reselection for inter-band operation | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096497 | 0533 | - | GCF Priority 2 - Update of Idle Mode Operations test case 6.6.2.3.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096502 | 0534 | - | GCF Priority 2 - Correction to the MAC DRX test cases preamble | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096505 | 0535 | - | GCF Priority 2 - Correction of TC 9.2.1.1.13 Attach / rejected / PLMN not allowed | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096506 | 0536 | - | GCF Priority 2 - Correction of TC 9.2.1.1.14 Attach / rejected / tracking area not allowed | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096507 | 0537 | - | GCF Priority 2 - Correction of TC 9.2.1.1.15 Attach / rejected / roaming not allowed in this tracking area | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096508 | 0538 | - | GCF Priority 3 - New TC 9.2.1.1.16 Attach / rejected / EPS services not allowed in this PLMN | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096509 | 0539 | - | GCF Priority 2 - Correction of TC 9.2.1.1.17 Attach / rejected / no suitable cells in tracking area | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096510 | 0540 | - | GCF Priority 2 - Correction of TC 9.2.1.2.4 Combined attach procedure / Success / EPS services only / MSC temporarily not reachable | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096511 | 0541 | - | GCF Priority 2 - Correction of TC 10.2.1 Dedicated EPS bearer context activation / Success | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096512 | 0542 | - | GCF Priority 2 - Correction of TC 10.3.1 EPS bearer context modification / Success | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096514 | 0543 | - | GCF Priority 2 - Correction of TC 10.6.1 UE requested PDN disconnect procedure accepted by the network | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096605 | 0544 | - | GCF Priority 2 - Update of RRC test case 8.3.2.7 : Measurement configuration control and reporting / inter-RAT measurements: event B2 (measurement HRPD cells) | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096606 | 0545 | - | GCF Priority 2 - Update of RRC test case 8.3.2.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096610 | 0546 | - | GCF Priority 2 - Update of RRC test case 8.4.1.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096611 | 0547 | - | GCF Priority 2 - Update of RRC test case 8.4.1.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096612 | 0548 | - | GCF Priority 2 - Update to test case 8.4.2.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096613 | 0549 | - | GCF Priority 2 - Update to test case 8.4.2.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096615 | 0550 | - | GCF Priority 3 - Addition of test case 6.2.3.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096616 | 0551 | - | GCF Priority 3 - Update to test case 8.1.1.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096617 | 0552 | - | GCF Priority 3 - Addition of test case 8.2.4.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096618 | 0553 | - | GCF Priority 2 - Update to test case 8.1.3.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096619 | 0554 | - | GCF Priority 2: Updates to TAU/RAU procedure for inter-system cell re-selection between A/Gb and S1 modes | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096620 | 0555 | - | GCF Priority 2: Updates to Attach Procedure / Success (last visited TAI, TAI list and equivalent PLMN list handling) | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096621 | 0556 | - | GCF Priority 2 - Correction to TC 8.1.3.8 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096622 | 0557 | - | GCF Priority 3 - Update test case 8.3.1.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096627 | 0558 | - | GCF Priority 1 - Update of RRC test case 8.2.2.1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096628 | 0559 | - | GCF Priority 1 - Update of RRC test case 8.2.2.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096629 | 0560 | - | GCF Priority 3 - Various corrections to EMM section of 36.523-1 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096630 | 0561 | - | GCF Priority 3 - Addition of new test case 9.2.1.2.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096631 | 0562 | - | GCF Priority 3 - Update to test case 9.2.1.2.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096632 | 0563 | - | GCF Priority 3 - Addition of test case 9.2.1.2.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096633 | 0564 | - | GCF Priority 3 - Addition of test case 9.2.1.2.11 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096634 | 0565 | 1 | GCF Priority 3 - Addition of test case 9.2.1.2.13 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096635 | 0566 | - | GCF Priority 3 - Addition of new test case 9.2.1.2.15 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096636 | 0567 | - | GCF Priority 3 - Addition of test cases 9.2.3.1.23 and 9.2.3.1.24 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096637 | 0568 | - | GCF Priority 3 - Addition of new test case 9.2.3.1.25 | 8.3.2 | 8.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-12 | RAN#46 | R5-096638 | 0569 | - | GCF Priority 3 - Addition of new test case 9.2.3.2.9 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096639 | 0570 | - | GCF Priority 3 - Update to test case 9.3.1.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096643 | 0571 | - | GCF Priority 1 - Update of RLC test case 7.2.3.9 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096645 | 0572 | - | GCF Priority 3 - Addition of new test case 8.3.3.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096646 | 0573 | - | GCF Priority 3 - Addition of new test case 8.3.3.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096647 | 0574 | - | GCF Priority 3 - Addition of new test case 10.7.3 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096648 | 0575 | - | GCF Priority 3 - Addition of new test case 10.7.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096649 | 0576 | - | GCF Priority TBC - Addition of new test case 10.7.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096650 | 0577 | - | GCF Priority 3 - Addition of new test case 10.8.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096651 | 0578 | - | GCF Priority 3 - Addition of new test case 10.8.3 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096652 | 0579 | - | GCF Priority TBC - Addition of new test case 10.8.4 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096653 | 0580 | - | GCF Priority 3 - Addition of new test case 10.8.5 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096654 | 0581 | - | GCF Priority 3 - Addition of new test case 10.8.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096655 | 0582 | - | GCF Priority 3 - Addition of new test case 10.8.7 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096656 | 0583 | - | GCF Priority 2 - Correction of TC 10.5.1 UE requested PDN connectivity procedure accepted by the network | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096657 | 0584 | - | GCF Priority 2 - Addition of test case 11.1.4 MO-SMS over SGs in active mode | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096658 | 0585 | - | GCF Priority 2 - Correction of TC 10.4.1 EPS bearer context deactivation / Success | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096660 | 0586 | - | GCF Priority 3 - Addition of EMM test case 9.1.2.6 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096661 | 0587 | - | GCF Priority 3 - Addition of new EMM test case 9.1.5.2 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096662 | 0588 | - | GCF Priority 3 - Addition of new EMM test case 9.2.1.1.18 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096663 | 0589 | - | GCF Priority 3 - Addition of EMM test case 9.2.1.2.12 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096665 | 0590 | - | GCF Priority 3 - Addition of EMM test case 9.2.2.2.14 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096666 | 0591 | - | GCF Priority 3 - Addition of EMM test case 9.2.3.1.26 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096667 | 0592 | - | GCF Priority 3 - Addition of EMM test case 9.2.3.1.27 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096668 | 0593 | - | GCF Priority 3 - Addition of EMM test case 9.2.3.1.28 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096669 | 0594 | - | GCF Priority 3 - Addition of EMM test case 9.3.1.15 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096670 | 0595 | - | GCF Priority 3 - Addition of new test case 9.3.1.17 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096671 | 0596 | - | GCF Priority 3 - Correction of TC 9.2.1.2.2 Combined attach procedure / Success / EPS services only / IMSI unknown in HSS | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096672 | 0597 | - | GCF Priority 3 - Correction of TC 9.2.1.2.3 Combined attach procedure / Success / EPS services only / MSC temporarily not reachable | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096673 | 0598 | - | GCF Priority 3: Introduction of 9.2.3.1.19 Normal tracking area update / rejected / No Suitable Cells in tracking Area | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096692 | 0599 | - | GCF Priority 3 - Update of E-UTRAN test case 9.2.1.1.20 | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096693 | 0600 | - | GCF Priority 3 - Correction of TC 9.2.1.1.19 Attach / Abnormal case / Failure due to non integrity protection | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096694 | 0601 | - | GCF Priority 3: Addition of new test case 9.2.1.1.21: Attach / Abnormal case / success after several attempts due to no network response | 8.3.2 | 8.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2009-12 | RAN#46 | R5-096695 | 0602 | - | GCF Priority 3: Addition of new test case 9.2.1.1.22: : Attach / Abnormal case / unsuccessful attach after 5 attempts | 8.3.2 | 8.4.0 |
| 2009-12 | RAN#46 | R5-096697 | 0603 | 1 | GCF Priority 3 - Addition of test case 13.3.1.1 | 8.3.2 | 8.4.0 |
| 2010-03 | RAN#47 | R5-100058 | 0604 | - | Addition of new DSMIPv6 test case for Registration of a new IPv6 CoA (Binding Update/Acknowledgment procedure in IPv6 network) | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100059 | 0605 | - | Addition of new DSMIPv6 test case for Re-registration of IPv6 CoA | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100060 | 0606 | - | Addition of new DSMIPv6 test case for Return to home link | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100061 | 0607 | - | Addition of new DSMIPv6 test case for Dual-Stack Mobile IPv6 detach in IPv6 network | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100089 | 0608 | - | GCF priority 2 - Correction of test case 10.5.1 for UE requested PDN connectivity accepted by the network | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100096 | 0609 | - | GCF priority 3 - Correction of test case 9.2.1.2.2 for Combined attach procedure / Success / EPS services only / IMSI unknown in HSS | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100100 | 0610 | - | GCF priority 2: correction of test case 9.2.3.3.1 First lu mode to S1 mode intersystem change after attach: go to E-UTRAN RRC idle: RAU to UTRAN | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100173 | 0611 | - | Update of test case 9.2.3.1.28 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100175 | 0612 | - | Update of test case 9.1.5.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100176 | 0613 | - | Update of test case 9.1.2.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100182 | 0614 | - | Priority 2-Update of the case 6.2.2.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100242 | 0615 | - | GCF Priority 1: Update of MAC TC 7.1.2.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100263 | 0616 | - | Correction to MAC TBS selection TCs not to use RS power boosting | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100270 | 0617 | - | GCF Priority 1 - Update to test case 7.2.2.9 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100271 | 0618 | - | GCF Priority 3 - Update to test case 8.1.1.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100274 | 0619 | - | GCF Priority 2 - Update to test case 8.2.4.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100275 | 0620 | - | GCF Priority 3 - Update to test case 8.2.4.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100276 | 0621 | - | GCF Priority 2 - Update to test case 8.2.4.5 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100277 | 0622 | - | GCF Priority 2 - Update to test case 8.2.4.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100278 | 0623 | - | GCF Priority 2 - Update to test case 8.2.4.7 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100279 | 0624 | - | GCF Priority 3 - Update to test case 8.2.4.9 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100281 | 0625 | - | GCF Priority 2 - Update to test case 8.3.1.9 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100283 | 0626 | - | GCF Priority 2 - Update to test case 8.3.2.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100284 | 0627 | - | GCF Priority 2 - Update to test case 8.4.2.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100285 | 0628 | - | GCF Priority 2 - Update to test case 8.4.2.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100287 | 0629 | - | GCF Priority 3 - Update to test case 9.2.1.2.5 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100288 | 0630 | - | GCF Priority 3 - Update to test case 9.2.1.2.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100289 | 0631 | - | GCF Priority 3 - Update to test case 9.2.1.2.7 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100290 | 0632 | - | GCF Priority 3 - Update to test case 9.2.1.2.8 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100293 | 0633 | - | GCF Priority 3 - Update to test case 9.2.3.2.9 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100294 | 0634 | - | GCF Priority 3 - Update to test case 9.3.1.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100383 | 0635 | - | GCF Priority 1- Update of MAC test cases 7.1.4.6, 7.1.4.7, 7.1.4.8 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100415 | 0636 | - | GCF Priority 2 - Correction to remark in 6.2.2.1, 6.2.2.2 and 6.2.3.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100416 | 0637 | - | GCF Priority 2 - Correction to test case 6.1.2.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100443 | 0638 | - | GCF Priority 2: Update to test case 9.2.3.1.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100462 | 0639 | - | Correction of test case 8.3.1.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100467 | 0640 | - | Addition of new DSMIPv6 test case for Registration of a new IPv4 CoA (Binding Update/Acknowledgment procedure in IPv4 network) | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100468 | 0641 | - | Addition of new DSMIPv6 test case for Re-registration of IPv4 CoA | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100469 | 0642 | - | Addition of new DSMIPv6 test case for Dual-Stack Mobile IPv6 detach in IPv4 network | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100470 | 0643 | - | GCF Priority 2 - Update to P2 EMM test case 9.2.2.1.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100471 | 0644 | - | Update to P3 EMM test case 9.2.2.1.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100472 | 0645 | - | GCF Priority 2 - Update to P2 EMM test case 9.2.2.1.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100475 | 0646 | - | Removal of TC 10.5.2 | 8.4.0 | 8.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2010-03 | RAN#47 | R5-100488 | 0647 | - | GCF priority 1 - Update of RRC test case 8.2.2.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100489 | 0648 | - | GCF priority 1 - Update of RRC test case 8.2.2.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100492 | 0649 | - | GCF priority 1 - Update of RRC test case 8.2.3.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100500 | 0650 | - | GCF Priority 1: Clarification to UE initial state for test case 7.1.2.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100501 | 0651 | - | GCF Priority 2 - Clarification to UE initial state | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100537 | 0652 | - | GCF Priority 1 - Correction to E-UTRA RLC test case 7.2.3.21 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100577 | 0653 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.2.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100582 | 0654 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.4.7 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100592 | 0655 | - | GCF Priority 3 - Correction to P3 EMM test case 9.2.1.2.12 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100625 | 0656 | - | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100638 | 0657 | - | GCF Priority 1 - Update of RLC test case 7.2.2.5.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100639 | 0658 | - | GCF Priority 1 - Update of RLC test case 7.2.2.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100642 | 0659 | - | GCF Priority 1 - Update of RLC test case 7.2.2.7 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100651 | 0660 | - | GCF Priority 1 - Update of RLC test case 7.2.3.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100652 | 0661 | - | GCF Priority 1 - Update of RLC test case 7.2.3.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100657 | 0662 | - | GCF Priority 1 - Update of RLC test case 7.2.3.5 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100659 | 0663 | - | GCF Priority 1 - Update of RLC test case 7.2.3.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100671 | 0664 | - | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100676 | 0665 | - | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100738 | 0666 | - | Priority 2 - Incorrect ATTACH procedure to UTRAN and GERAN cells | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100741 | 0667 | - | GCF Priority x - Clarification to E-UTRA Radio Bearer Tests section | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100742 | 0668 | - | Priority 3 - TC 9.2.3.1.15 Normal tracking area update / rejected / PLMN not allowed - problems with Test procedure sequence | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100745 | 0669 | - | GCF Priority 3 - Adding new TC 9.1.5.1 EMM Information Procedure | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-100777 | 0670 | - | GCF Priority 2 - Update of MAC test case 7.1.4.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101011 | 0671 | - | Priority ALL - Update of section 6 Idle Mode Operations to comply with RAN5 PRD13 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101012 | 0672 | - | Priority ALL - Update of section 9.1.x and 9.2.1.x to indicate on which cell events are to be observed in multi cell environment | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101013 | 0673 | - | GCF Priority 2 - Removal of test case 9.2.3.2.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101014 | 0674 | - | GCF Priority 2 - Update to test case 9.2.3.2.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101032 | 0675 | 2 | GCF Priority 2 - Correction of RRC test cases 8.3.1.3 and 8.3.1.5 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101033 | 0676 | 1 | GCF Priority 3 - Correction of RRC test cases 8.3.1.7 and 8.3.1.11 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101038 | 0677 | - | Correction of test case 6.2.3.13 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101039 | 0678 | - | Correction for Measurement related test cases | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101053 | 0679 | - | GCF priority 2 - Update of RRC test case 8.2.1.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101056 | 0680 | - | Priority ALL - Update of section 7 Layer 2 to comply with RAN5 PRD13 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101057 | 0681 | - | GCF Priority 1 - Various corrections to Idle Mode section 6.1 of 36.523-1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101062 | 0682 | - | GCF Priority 1 - Correction to E-UTRAN PDPC test case 7.1.4.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101063 | 0683 | - | GCF Priority 1: Update of MAC TC 7.1.2.5 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101064 | 0684 | - | GCF Priority 1: Update of MAC TC 7.1.2.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101065 | 0685 | - | GCF Priority 1: Update of MAC TC 7.1.2.9 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101066 | 0686 | - | GCF Priority 1: Update of MAC TC 7.1.3.9 | 8.4.0 | 8.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-03 | RAN#47 | R5-101067 | 0687 | - | GCF Priority 1: Update of MAC TC 7.1.4.8 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101068 | 0688 | - | GCF Priority 1: Update of MAC TC 7.1.4.11 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101069 | 0689 | - | GCF Priority 3 - Corrections to TC 8.5.1.2 RRC Connection Re-establishment: Success (after Radio Link Failure) | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101070 | 0690 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.4.13 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101074 | 0691 | - | New priority 3 test case: Periodic Location Updating Procedure (PLU Timer handling, non-cell reselection to GERAN) | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101075 | 0692 | - | GCF Priority 3 - Addition of new test case 9.2.3.3.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101076 | 0693 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.3.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101077 | 0694 | - | GCF Priority 1: Update of MAC TC 7.1.4.15 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101078 | 0695 | - | GCF Priority 1 - Update of MAC Procedures part TC 7.1.2.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101079 | 0696 | - | GCF Priority 1 - Correction to MAC test case 7.1.4.10 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101081 | 0697 | - | GCF Priority 1 - Update to test case 8.2.4.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101082 | 0698 | - | GCF Priority 2 - Update to test case 8.3.1.8 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101083 | 0699 | - | GCF Priority 2 - Update to test case 8.3.1.10 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101084 | 0700 | - | GCF Priority 1: Corrections to E-UTRA MAC test case 7.1.7.1.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101085 | 0701 | - | GCF Priority 1 - Update of Acknowledged Mode Procedures part TC 7.2.3.15 AM RLC / Re-ordering of RLC PDU segments" | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101086 | 0702 | - | GCF Priority 1 - Update of RLC test case 7.2.3.14 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101087 | 0703 | - | GCF Priority 1 - Update of RLC test case 7.2.3.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101088 | 0704 | - | GCF Priority 1 - Update of RLC test case 7.2.3.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101089 | 0705 | 1 | GCF Priority 1 - Update of RLC test case 7.2.3.7 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101090 | 0706 | 2 | GCF Priority 1 - Update of RLC test case 7.2.3.18 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101092 | 0707 | - | GCF priority 2 - EPS bearer context ID values and RRC messages carrying ESM messages for EPS bearer context (de)activation and modification | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101093 | 0708 | - | GCF priority 3 - Small correction to TC 9.2.1.1.11 Attach / rejected / EPS services and non-EPS services not allowed | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101094 | 0709 | - | GCF priority 2 - Correction of test case 9.2.1.1.15 for Attach / rejected / roaming not allowed in this tracking area | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101098 | 0710 | - | GCF Priority 2 - Update test case 8.5.1.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101105 | 0711 | - | GCF priority 1 - Update of RRC test case 8.2.1.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101108 | 0712 | - | GCF Priority 2 - Correction to EUTRAN RLC test case 7.2.2.10 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101110 | 0713 | - | GCF priority 2 - Correction of test case 9.2.1.2.4 for Successful combined attach procedure, EPS service only / CS domain not available | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101113 | 0714 | - | GCF Priority 1 - Correction to E-UTRA PDCP test case 7.3.4.1 and 7.3.4.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101114 | 0715 | - | GCF Priority 1 - Enhancement test case 8.1.2.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101117 | 0716 | - | GCF Priority 1 - Correction to EMM test cases to bring the UE to stable state at the end of expected sequence | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101118 | 0717 | - | GCF Priority 1 - Update of Multi-layer Procedures part TC 13.1.1 Activation and deactivation of additional data radio bearer in E-UTRA | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101119 | 0718 | - | GCF Priority 1 - Update of Multi-layer Procedures part TC 13.2.1 RRC Connection Reconfiguration: E-UTRA to E-UTRA | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101120 | 0719 | - | GCF Priority 2: Update of MAC TC 7.1.3.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101121 | 0720 | - | GCF Priority 1 - Correction to EPC test case 9.2.1.1.1 | 8.4.0 | 8.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2010-03 | RAN#47 | R5-101122 | 0721 | - | Priority 2 - section 9 alignment IP handling at wrong place - Missing security activation - Editorial changes | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101125 | 0722 | - | GCF Priority 1 - Correction to E-UTRAN RLC test case 7.2.3.15 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101126 | 0723 | - | GCF Priority 1 - Correction to E-UTRAN RLC test case 7.2.3.9 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101130 | 0724 | - | GCF Priority 1 - Correction of RRC test case 8.3.3.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101131 | 0725 | 1 | GCF Priority 1 - Correction to MAC test cases to bring the UE to stable state at the end of expected sequence | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101132 | 0726 | - | GCF Priority 1 - Correction to RRC test cases to bring the UE to stable state at the end of expected sequence | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101133 | 0727 | - | GCF Priority 2 - Update to test case 10.7.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101134 | 0728 | - | GCF Priority 2 - Update to test case 10.7.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101135 | 0729 | - | GCF Priority 2 - Update to test case 10.8.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101141 | 0730 | - | GCF Priority 4 - Addition of new RRC test case 8.4.7.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101142 | 0731 | - | GCF Priority 4 - Addition of new RRC test case 8.3.2.10 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101145 | 0732 | - | General note for test cases with statistical behaviour | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101148 | 0733 | - | GCF Priority 3 - Update to test case 10.7.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101149 | 0734 | - | GCF Priority 3 - Update to test case 10.7.4 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101151 | 0735 | - | GCF Priority 3 - Update to test case 10.8.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101152 | 0736 | - | GCF Priority 3 - Update to test case 10.8.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101154 | 0737 | - | GCF Priority 3 - Update to test case 10.8.5 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101155 | 0738 | - | GCF Priority 3 - Update to test case 10.8.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101156 | 0739 | - | GCF Priority 3 - Update to test case 10.8.7 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101158 | 0740 | - | GCF Priority 3: New PUSCH-Hopping test case 7.1.5.2:Predefined intra-TTI PUSCH hopping (N _{sb} =1) | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101160 | 0741 | - | GCF Priority 3: New PUSCH-Hopping test case 7.1.5.4: Predefined inter-TTI PUSCH hopping (N _{sb} =1) | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101162 | 0742 | 1 | GCF priority 3 - New test case 8.1.1.6 RRC / BCCH modification in connected mode | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101163 | 0743 | - | GCF Priority 3 - New TC 8.5.2.1 RRC Connection Reject: redirection from UTRAN to E-UTRAN | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101164 | 0744 | - | GCF Priority 3 - addition of new EMM test case 9.2.1.2.14 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101165 | 0745 | - | Update of test case 9.3.1.15 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101166 | 0746 | - | Update of test case 9.2.1.1.18 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101167 | 0747 | - | GCF Priority 3: Update to test case 9.2.3.1.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101168 | 0748 | - | GCF priority 3 - Correction of test case 10.5.3 for UE requested PDN connectivity procedure not accepted | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101169 | 0749 | - | GCF Priority 3 - Addition of new multi-layer test case 13.1.3 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101170 | 0750 | - | GCF Priority 3 - Addition of new test case 13.4.1.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101171 | 0751 | - | GCF Priority 3 - Update of Multi-layer Procedures part TC 13.3.1.1 Intra System Connection Reestablishment / Radio Link Recovery while T310 is running | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101172 | 0752 | - | GCF Priority 3 - update of test case 13.3.1.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101173 | 0753 | - | GCF Priority 2 : Correction to MAC test case 7.1.6.1 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101174 | 0754 | - | GCF Priority 2 : Correction to MAC test cases 7.1.6.2 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101175 | 0755 | 2 | GCF Priority 1 - Correction to E-UTRAN RLC test case 7.2.3.10 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101177 | 0756 | - | Update to GCF Priority 1 layer 2 UM test cases to increase the drx-Inactivity Timer to psf200 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101179 | 0757 | - | GCF Priority 1 - Enhancement and update to MAC test case 7.1.4.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101183 | 0758 | - | GCF Priority 1: Update of MAC TC 7.1.3.6 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101186 | 0759 | - | Update of test case and section titles | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101189 | 0760 | - | GCF Priority 2 - Update to test case 8.1.2.7 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101190 | 0761 | - | GCF Priority 2 - Update to test case 8.1.2.5 | 8.4.0 | 8.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|-----|--|-------------|-------------|
| 2010-03 | RAN#47 | R5-101191 | 0762 | - | Corrections related to UE mode of operation and UE capability for CS fallback and SMS over SGs | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | R5-101192 | 0763 | - | GCF priority 3 - Correction of test case 10.6.2 for UE requested PDN disconnect procedure not accepted by the network | 8.4.0 | 8.5.0 |
| 2010-03 | GERAN#45 | GP-100543 | 0605 | - | Addition of new Test Case 6.2.3.22 | 8.4.0 | 8.5.0 |
| 2010-03 | RAN#47 | - | - | - | Moved to v9.0.0 with no change | 8.5.0 | 9.0.0 |
| 2010-05 | GERAN#46 | GP-100625 | 0764 | - | New Test case 6.2.3.28- Inter-RAT Cell Reselection from GPRS Packet_transfer to E-UTRA Cell (Network Assisted Cell Change) | 9.0.0 | 9.1.0 |
| 2010-05 | GERAN#46 | GP-100626 | 0765 | - | New Test Case 6.2.3.30 - Inter-RAT Cell Reselection failure from GPRS Packet transfer to E-UTRA (Network Assisted Cell Change) | 9.0.0 | 9.1.0 |
| 2010-05 | GERAN#46 | GP-100649 | 0766 | - | New Test Case 6.2.2.6 - Inter-RAT Cell selection / From GSM_Idle/GPRS Packet_idle to E-UTRA_RRC_IDLE / Serving cell becomes non-suitable (ServingCell<0) | 9.0.0 | 9.1.0 |
| 2010-05 | GERAN#46 | GP-100650 | 0767 | - | New Test Case 6.2.2.7 - Inter-RAT Cell selection / From GSM_Idle/GPRS Packet_idle to E-UTRA_RRC_IDLE ,when the serving cell is barred. | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103077 | 0768 | - | GCF Priority 2 - Correction of Minimum Cell Configuration | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103086 | 0769 | - | GCF Priority 3: New TC 9.3.1.5 Service request / Rejected / Illegal ME | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103087 | 0770 | - | GCF Priority 1 - Correction to E-UTRAN MAC test case 7.1.2.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103088 | 0771 | - | GCF Priority 1 - Correction to MAC test case 7.1.4.10 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103089 | 0772 | - | GCF Priority 3 - Update of TC 9.1.5.1 EMM Information Procedure | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103090 | 0773 | - | GCF Priority 2 - Correction to TC 9.1.2.4 Authentication not accepted by the UE / MAC code failure | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103091 | 0774 | - | GCF Priority 2 - Correction to TC 9.1.2.5 Authentication not accepted by the UE / SQN failure | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103093 | 0775 | - | GCF Priority 2 - Correction of SIB in RRC TCs 8.4.2.2 and 8.4.2.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103130 | 0776 | - | GCF Priority 2 - Update to test case 6.1.2.6 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103131 | 0777 | - | GCF Priority 1 - Correction to PDSCH power allocation of MAC TBS selection TCs | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103132 | 0778 | - | GCF Priority 3 - Correction of test case 6.2.3.13 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103135 | 0779 | - | GCF Priority 4 - Addition of new test case 8.3.2.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103136 | 0780 | - | GCF Priority 4 - Update test case 8.3.2.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103137 | 0781 | - | GCF Priority 4 - Addition of new test case 8.3.2.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103139 | 0782 | - | GCF Priority 3 - Correction for test case 13.4.1.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103140 | 0783 | - | GCF Priority 3 - Addition of new test case 13.4.2.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103141 | 0784 | - | GCF Priority 2 - Update test case 6.1.2.11 & 6.1.2.15 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103144 | 0785 | - | GCF Priority 4 Addition of new test case 14.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103145 | 0786 | - | GCF Priority 4 Addition of new test case 14.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103157 | 0787 | - | GCF Priority 4: New MAC TBS test case 7.1.7.1.6:DCI format 2A / RA type 1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103158 | 0788 | - | GCF Priority 4: New MAC TBS test case 7.1.7.1.5:DCI format 2A / RA type 0 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103159 | 0789 | - | GCF Priority 4: Correction to E-UTRA DRB test case 12.3.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103160 | 0790 | - | GCF Priority 4: Correction to E-UTRA DRB test case 12.3.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103161 | 0791 | - | GCF Priority 4: Correction to E-UTRA DRB test case 12.3.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103162 | 0792 | - | GCF Priority 4: Correction to E-UTRA DRB test case 12.3.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103163 | 0793 | - | GCF Priority 4: Correction to generic test procedure 12.1.2 for E-UTRA DRB MIMO test cases | 9.0.0 | 9.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-06 | RAN#48 | R5-103228 | 0794 | - | GCF Priority 4: New PUSCH-Hopping test case 7.1.5.1: Inter-TTI PUSCH hopping by uplink grant | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103230 | 0795 | - | GCF Priority 4: New PUSCH-Hopping test case 7.1.5.3: Predefined intra-TTI PUSCH hopping (N_sb=2/3/4) | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103231 | 0796 | - | GCF Priority 4: New PUSCH-Hopping test case 7.1.5.5: Predefined inter-TTI PUSCH hopping (N_sb=2/3/4) | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103240 | 0797 | - | GCF Priority 2 - Update to test case 8.1.2.7 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103241 | 0798 | - | GCF Priority 3 - Update to test case 9.2.3.1.23 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103242 | 0799 | - | GCF Priority 1 - Clarification of the cells where the messages are observed in EMM test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103243 | 0800 | - | GCF Priority 4 - Update to test case 10.7.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103244 | 0801 | - | GCF Priority 4 - Update to test case 10.8.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103246 | 0802 | - | Applicability of new TC 13.1.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103271 | 0803 | - | GCF Priority 3 - Update of RRC part TC 8.5.1.2 Radio link failure / T301 expiry | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103272 | 0804 | - | GCF Priority 4 - Addition of new EPS mobility management procedure test case 9.2.3.2.7 Combined tracking area update / Rejected / EPS services and non-EPS services not allowed | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103273 | 0805 | - | GCF Priority 3 - Update Multi-layer test cases 13.3.1.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103276 | 0806 | - | GCF Priority 2 - Correct the Test Purpose 2 of PDCP part TC 7.3.1.2 and 7.3.1.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103277 | 0807 | - | GCF Priority 1 - Correct PDCP part TC 7.3.1.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103278 | 0808 | - | GCF Priority 4 - Addition of new EPS mobility management procedure test case 9.2.3.2.7 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103302 | 0809 | - | GCF Priority 1: Correction to test case 7.1.3.9 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103303 | 0810 | - | GCF Priority 1: Correction to E-UTRA MAC test case 7.1.2.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103304 | 0811 | - | GCF Priority 1: Correction to EMM test case 9.2.3.1.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103307 | 0812 | - | GCF Priority 1: Correction to EMM test case 9.2.1.1.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103308 | 0813 | - | GCF Priority 1: Correction to EMM test case 9.2.2.2.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103313 | 0814 | - | GCF Priority 1: Correction to EUTRA MAC test cases 7.1.7.1 test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103321 | 0815 | - | GCF Priority 2: Correction to EUTRA PDCP test case 7.3.6.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103323 | 0816 | - | GCF Priority 2: Correction to EUTRA RRC test case 8.5.1.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103327 | 0817 | - | GCF Priority 2: Correction to EPC test case 9.2.2.1.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103341 | 0818 | - | GCF Priority 2: Adding UE pre-conditions for UE to be configured for combined EPS/IMSI attach in 9.2.3.2.x combined TAU test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103364 | 0819 | - | GCF Priority 2 - Correction to generic test procedure reference in Idle mode section | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103365 | 0820 | - | GCF Priority 2 - Correction to TC 8.1.3.7 RRC connection release / Redirection from UTRAN to E-UTRAN | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103367 | 0821 | - | GCF Priority 3 - Correction to TC 8.5.2.1 RRC Connection Reject / Redirection from UTRAN to E-UTRAN | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103394 | 0822 | - | GCF Priority 4 - New TC 9.3.1.18 Service Reject CSG not authorized | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103413 | 0823 | - | GCF Priority 4 - Addition of new test case 8.4.3.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103414 | 0824 | - | GCF Priority 4 - Addition of new test case 8.4.3.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103416 | 0825 | - | Priority 4 - Addition of test case 9.2.3.2.17 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103418 | 0826 | - | Priority 4 - Addition of new test case 9.2.3.2.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103419 | 0827 | - | Priority 4 - Addition of new test case 9.2.3.2.14 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103420 | 0828 | - | Priority 4 - Addition of new test case 9.2.3.2.8 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103421 | 0829 | - | Priority 3 - update of test case 9.2.2.2.14 | 9.0.0 | 9.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-06 | RAN#48 | R5-103456 | 0830 | - | GCF Priority 4 - New TC 9.2.3.3.2 lu mode to S1 mode intersystem change / ISR is active / Expiry of T3312 in E-UTRAN or T3412 in UTRAN and further intersystem change | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103457 | 0831 | - | GCF Priority 4 - New test case 6.1.2.10 Cell reselection in shared network environment | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103458 | 0832 | - | GCF Priority 4 - New Test case 6.1.2.12 Cell reselection / Cell-specific reselection parameters provided by the network in a neighbouring cell list | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103459 | 0833 | - | GCF Priority 4 - addition of new test case 6.1.1.4: PLMN selection in shared network environment / Automatic mode | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103463 | 0834 | - | GCF Priority 3 - Addition of new EMM test case 9.2.2.1.7 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103464 | 0835 | - | GCF Priority 3 - Addition of new EMM test case 9.2.2.1.8 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103465 | 0836 | - | GCF Priority 3 - Addition of new EMM test case 9.2.2.1.9 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103486 | 0837 | - | GCF Priority 2 Correction to test case 6.1.2.3, 6.2.3.1 & 6.2.3.6 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103498 | 0838 | - | GCF Priority 2 to 3 - Correction to RRC part 3 test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103513 | 0839 | - | GCF Priority 2 - Update of RRC test case 8.2.4.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103514 | 0840 | - | GCF Priority 3 - New EMM test case 9.2.2.1.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103573 | 0841 | - | Addition of new DSMIPv6 test case for Discovery of the Home Agent address via DHCPv6 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103579 | 0842 | - | Addition of new DSMIPv6 test case for Security association establishment with Home Agent reallocation procedure | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103646 | 0843 | - | GCF Priority 2 - Corrections to C2K TCs 8.3.2.7, 8.3.2.8 and 8.3.2.9 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103649 | 0844 | - | Addition of new DSMIPv6 test case for Discovery of the Home Agent address via IKEv2 during tunnel setup to ePDG | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103676 | 0845 | - | GCF Priority 4 - Addition of test case 8.2.4.10 RRC Connection Reconfiguration / Handover (between FDD and TDD) | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103696 | 0846 | - | GCF Priority 1 - Correction to MAC, RRC and EMM test cases to bring the UE to stable state at the end of test | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103697 | 0847 | - | GCF Priority 1: Correction to EUTRA MAC test case 7.1.4.8 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103698 | 0848 | - | GCF Priority 1: Correction to test case 7.1.4.11 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103800 | 0880 | 1 | GCF Priority 1: Correction to EUTRA RLC test case 7.2.3.6 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103801 | 0881 | 1 | GCF Priority 1: Correction to EUTRA RLC test case 7.2.3.7 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103802 | 0849 | - | GCF Priority 1 - Update of RRC test cases 8.2.2.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103803 | 0850 | - | GCF Priority 1: Correction to EUTRA RLC test case 7.2.3.10 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103804 | 0851 | - | GCF priority 2 - Correction to test case 6.1.1.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103805 | 0852 | - | GCF Priority 2: Correction to EUTRA RLC test case 7.2.2.8 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103806 | 0853 | - | GCF Priority 2: Correction to EUTRA RLC test case 7.2.2.10 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103807 | 0854 | - | GCF Priority 2: Correction to EUTRA RLC test case 7.2.3.13 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103808 | 0855 | - | GCF Priority 2 - Update to test case 8.1.2.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103809 | 0856 | - | GCF Priority 2: Correction to EPC test case 9.1.3.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103810 | 0857 | - | GCF Priority 2: Adding UE pre-conditions for UE to be configured for EPS attach in 9.2.1.1.x EPS attach test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103811 | 0858 | - | GCF Priority 2: Adding UE pre-conditions for UE to be configured for EPS attach in 9.2.3.1.x TAU test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103814 | 0859 | - | GCF Priority 2: Adding UE pre-conditions for UE to be configured for EPS attach in 9.2.2.x detach test cases | 9.0.0 | 9.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-06 | RAN#48 | R5-103815 | 0860 | - | GCF Priority 2: Adding UE pre-conditions for UE to be configured for combined EPS/IMSI attach in 9.2.1.2.x combined attach test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103816 | 0895 | - | Correction to MAC and RLC handover test cases to set IE "statusReportRequired" to FALSE | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103817 | 0882 | 1 | GCF Priority 2: Correction to EMM test case 9.2.3.1.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103818 | 0861 | - | GCF Priority 2 - Correction to EPS test case 9.4.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103819 | 0883 | - | GCF Priority 2 - Update of General tests part TC 11.1.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103820 | 0862 | - | GCF Priority 2 - Correction to 'SMS over SGs' test case 11.1.1 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103821 | 0863 | - | GCF Priority 2 - Correction to 'SMS over SGs' test case 11.1.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103822 | 0864 | - | GCF Priority 2 - Correction to 'SMS over SGs' test case 11.1.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103823 | 0894 | - | GCF priority 3 - New test case 6.2.1.2 Inter-RAT PLMN Selection /Selection of correct RAT for UPLMN/Automatic mode | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103824 | 0884 | 1 | GCF priority 3 - Inter-RAT PLMN Selection/ Selection of correct PLMN and RAT in shared network environment, Automatic mode | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103825 | 0885 | 1 | GCF priority 4 - New test case 6.2.1.4 Inter-RAT PLMN Selection/ Selection of correct RAT from the OPLMN list/ Manual mode | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103826 | 0886 | - | GCF priority 3 - New test case 6.2.1.1 Inter-RAT PLMN Selection /Selection of correct RAT for OPLMN/Automatic mode | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103827 | 0887 | - | GCF Priority 3 - Update test case 8.2.4.8, 8.5.1.2 and 8.5.1.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103828 | 0865 | - | GCF Priority 3 - Update test case 8.3.3.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103829 | 0888 | - | GCF Priority 3 - Update RRC test case 8.3.1.4 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103830 | 0866 | - | GCF Priority 3: New EMM test case, 9.2.1.1.23: Attach / Abnormal case / Repeated rejects for network failures | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103831 | 0867 | - | GCF Priority 3: New TC 9.3.1.6 Service request / Rejected / EPS services not allowed | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103832 | 0868 | - | Priority 3 - update of test case 9.2.1.1.24 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103833 | 0889 | 1 | GCF Priority 2 - Correction of EMM test case 9.1.2.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103836 | 0869 | - | GCF Priority 3 - Addition of new test case 13.1.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103837 | 0889 | - | GCF Priority 3 - Update of Multilayer Procedures part TC 13.3.1.2 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103838 | 0870 | - | GCF Priority 3 - Update of Multilayer Procedures part TC 13.1.3 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103839 | 0891 | - | GCF Priority 4 - Update of RRC part TC 8.1.1.3 RRC / Paging for connection in idle mode /Multiple paging records | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103840 | 0871 | - | GCF Priority 4 - Addition of new test case 8.2.1.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103841 | 0872 | - | GCF Priority 4 - Addition of new test case 8.2.1.6 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103842 | 0873 | - | GCF Priority 4 - New TC 9.2.1.1.4 Attach Procedure Success Request for obtaining the IPv4 address of the home agent | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103843 | 0874 | - | Priority 4 - Addition of new test case 9.2.3.2.16 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103844 | 0892 | 1 | GCF Priority 4 - New TC 13.1.8 Connected CSFB to GSM with Redirection MO call | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103848 | 0875 | - | GCF Priority 2 - Update RRC test case 8.2.4.6 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103849 | 0876 | - | Addition of UE end state for 15 EMM test cases and termination of ongoing signalling procedure for 3 EMM test cases | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103872 | 0877 | - | GCF Priority 1 - Correction to MAC test case 7.1.4.5 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103873 | 0878 | - | GCF Priority 4 - Addition of Multi-layer Procedures part test case 13.1.7 | 9.0.0 | 9.1.0 |
| 2010-06 | RAN#48 | R5-103876 | 0879 | - | GCF Priority 4 - Addition of new test case 9.2.3.2.2 for combined tracking area update / successful for EPS services only / IMSI unknown in HSS | 9.0.0 | 9.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-06 | - | - | - | - | Typo correction of clause title 9.2.1.1.3.3 | 9.1.0 | 9.1.1 |
| 2010-09 | RAN#49 | GP-101502 | 0898 | - | CR 36.523-1-0898 New test case 6.2.3.14 Inter-RAT Cell Reselection / from GSM_Idle/GPRS Packet Idle to E-UTRA (priority of E-UTRA cells are higher than the serving cell) | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | GP-101503 | 0899 | - | CR 36.523-1-0899 New test case 6.2.3.15 Inter-RAT Cell Reselection / from GSM_Idle/GPRS Packet Idle to E-UTRA (priority of E-UTRA cells are lower than the serving cell) | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | GP-101510 | 0896 | - | CR 36.523-1-0896 6.2.3.19 : Redirection to E-UTRA upon the release of the CS connection | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | GP-101521 | 0897 | - | CR 36.523-1-0897 6.2.3.20: Redirection to E-UTRA upon the release of the CS connection and no suitable cell available | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | GP-101562 | 0902 | - | CR 36.523-1-0902 New Test case 6.2.3.27- Inter-RAT Cell selection from GPRS Packet_transfer to E-UTRA Cell (NC2 mode). | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | GP-101603 | 1016 | - | CR 36.523-1-1016 New Test Case 6.2.3.23 - Inter-RAT Cell Reselection from GPRS Packet transfer to E-UTRA in CCN mode (PACKET CELL CHANGE CONTINUE) | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104073 | 0903 | - | GCF Priority 2 - Corrections to EUTRA idle mode test cases | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104083 | 0904 | - | GCF Priority 2 - Review of detach at switch/power off procedure in EMM test cases | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104084 | 0905 | - | GCF Priority 2 - Review of switch/power off procedure | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104107 | 0906 | - | GCF Priority 1 - Correction to remove special configurations for UM Bearer test cases | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104130 | 0907 | - | GCF Priority 2 - Correction to EUTRA RRC test case 8.1.2.7 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104136 | 0908 | - | GCF Priority 2 - Correction to Generic E-UTRA radio bearer test procedure 12.1.1 and 12.1.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104142 | 0909 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.1.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104144 | 0910 | - | GCF Priority 1 - Correction to MAC test case 7.1.2.8 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104145 | 0911 | - | GCF Priority 2 - Correction to EUTRA RRC test case 8.1.2.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104147 | 0912 | - | GCF Priority 2 - Correction to EUTRA MAC test case 7.1.4.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104148 | 0913 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104149 | 0914 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.2.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104150 | 0915 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.3.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104157 | 0917 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.3.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104162 | 0918 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.4.11 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104168 | 0919 | - | GCF Priority 2 - Correction of ESM test case 10.8.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104173 | 0920 | - | GCF Priority 4 - Addition of new test case 6.1.2.14 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104178 | 0921 | - | GCF Priority 4 - Addition of new test case 9.2.3.2.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104182 | 0922 | - | GCF Priority 3 - Update to test case 13.1.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104238 | 0923 | - | GCF Priority 2 - Correction of EMM test case 9.2.1.1.17 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104265 | 0924 | - | GCF Priority 2 - Update of TC 8.1.2.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104283 | 0925 | - | GCF Priority 4 Update test case 8.3.2.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104286 | 0926 | - | GCF Priority 4 - Correction of test cases 14.1 & 14.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104287 | 0927 | - | GCF Priority 4 - Addition of new test case 14.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104389 | 0928 | - | Update of DSMIPv6 test cases | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104390 | 0929 | - | Removal of DSMIPv6 test case 15.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104399 | 0930 | - | GCF Priority 1 - update of test case 7.2.3.4 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104512 | 0931 | - | GCF Priority 2 - Update to EMM test case 9.2.2.1.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104535 | 0932 | - | GCF Priority 2 - Update of TC 7.1.4.16 | 9.1.1 | 9.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-09 | RAN#49 | R5-104632 | 0933 | - | GCF Priority 1 - Correction of RRC test case 8.5.4.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104637 | 0934 | - | GCF priority 4 - Addition of new test case 8.2.4.12 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104708 | 0935 | - | GCF Priority 1 - Correction to EUTRA MAC test cases 7.1.7.1.1, 7.1.7.1.2, 7.1.7.1.3, 7.1.7.1.4 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104709 | 0936 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.7.2.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104710 | 0937 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.3.4 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104711 | 0938 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.3.9 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104712 | 0939 | - | GCF Priority 1 - Correction to GCF WI-081 LTE Testcases 7.1.4.11, 7.1.4.14 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104713 | 0940 | - | GCF Priority 2 - Correction to EUTRA RRC test case 8.2.4.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104714 | 0941 | - | Correction to GCF WI-082 EMM Testcase 9.1.2.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104715 | 0942 | - | GCF Priority 2 - Corrections to EUTRA GERAN idle mode test cases | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104716 | 0943 | - | GCF Priority 2 - Corrections to idle mode test case 6.2.2.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104717 | 0944 | - | GCF Priority 2 - Review of detach at switch/power off procedure in Idle Mode test cases | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104718 | 0945 | - | GCF Priority 2 - Correction to Inter RAT HRPD test case 6.2.2.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104719 | 0946 | - | GCF Priority 2 - Correction to Inter RAT HRPD test case 6.2.3.7 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104720 | 0947 | - | GCF Priority 2 - Correction to Inter RAT HRPD test case 6.2.3.8 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104721 | 0948 | - | GCF Priority 2 - Addition of new test case 6.2.3.4 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104722 | 0949 | - | Addition of modified value tag after System Information modification | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104723 | 0950 | - | GCF Priority 2 - Correction to EUTRA RLC test case 7.2.3.21 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104724 | 0951 | - | GCF Priority 2 - Correction to GCF Priority 2 Inter RAT HRPD test case 8.1.3.9 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104725 | 0952 | - | GCF Priority 2 - Correction to TC 8.1.3.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104728 | 0953 | - | GCF Priority 2 - Correction of EMM test case 9.2.1.1.9 and 9.2.1.1.10 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104729 | 0954 | - | GCF Priority 2 - Correction of EMM test case 9.2.1.1.20 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104730 | 0955 | - | GCF Priority 2 - update of test case 9.2.3.1.8 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104731 | 0956 | - | GCF Priority 2 - Correction of EMM test case 9.2.1.2.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104732 | 0957 | - | GCF priority 2 - Correction of test case 9.2.1.1.1a about reference cell information | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104733 | 0958 | - | GCF Priority 2 - Correction of ESM test case 10.6.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104734 | 0959 | - | GCF Priority 2 - Correction to ESM test case 10.5.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104735 | 0960 | - | GCF Priority 2 - Correction to ESM test case 10.4.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104736 | 0961 | - | Add test case for RRC connection establishment of emergency call | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104742 | 0962 | - | GCF Priority 3: Correction to test case 7.1.5.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104743 | 0963 | - | GCF Priority 3 - Correction to test case 7.1.5.4 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104744 | 0964 | - | GCF priority 3: Correction to MAC TBS (MIMO configured) test case 7.1.7.1.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104745 | 0965 | - | GCF priority 3: Correction to MAC TBS (MIMO configured) test case 7.1.7.1.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104746 | 0966 | - | GCF Priority 3 - Addition of new EPS mobility management procedure test case 9.3.2.2a Paging for CS fallback / Connected mode | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104747 | 0967 | - | GCF Priority 3 - update of test case 9.2.1.1.12 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104748 | 0968 | - | GCF Priority 3 - update of test case 9.3.1.15 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104749 | 0969 | - | GCF Priority 3 - update of test case 9.2.3.1.23 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104750 | 0970 | - | GCF Priority 3 - Correction of ESM test case 10.5.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104751 | 0971 | - | GFC Priority 3 and 4: Correction of generic test procedure used in MIMO DRB test cases | 9.1.1 | 9.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-09 | RAN#49 | R5-104752 | 0972 | - | GCF Priority 3 - Addition of new Multilayer Procedures test case 13.1.4 Call setup from E-UTRAN RRC_IDLE / CS fallback to UTRAN with Handover / MT call | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104753 | 0973 | - | Addition of new LTE test case 13.1.2 CS fallback UTRAN with redirection / MO call | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104754 | 0974 | - | GCF Priority 3 - Addition of New TC for cell reselection when 1xRTT is higher priority | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104755 | 0975 | - | GCF Priority 3 - Addition of New TC for cell reselection when 1xRTT is lower priority | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104756 | 0976 | - | GCF Priority 4 - Addition of new test case 6.1.1.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104757 | 0977 | - | GCF Priority 4: Correction to test case 7.1.5.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104758 | 0978 | - | GCF Priority 4: Correction to test case 7.1.5.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104759 | 0979 | - | GCF Priority 4 - Correction to test case 7.1.5.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104760 | 0980 | - | GCF Priority 4 - Addition of new test case 8.1.2.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104761 | 0981 | - | GCF Priority 4 - Update of TC 8.2.1.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104762 | 0982 | - | GCF Priority 4 - Update of TC 8.2.1.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104763 | 0983 | - | GCF Priority 4 - Correction to TC 8.2.4.8 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104764 | 0984 | - | GCF Priority 4 - Update of TC 8.3.1.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104765 | 0985 | - | GCF Priority 2 - Correction to EUTRA RRC Test Case 8.2.4.7 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104768 | 0986 | - | GCF Priority 4 - Addition of new EMM test case 9.2.1.1.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104769 | 0987 | - | GCF Priority 4 - Addition of new test case 9.2.3.2.11 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104770 | 0988 | - | GCF Priority 4 - Update to test case 9.2.3.2.15 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104771 | 0989 | - | GCF Priority 4 - Addition of new test case 9.3.1.12a | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104773 | 0990 | - | GCF Priority X: Addition of New TC for Inter-RAT Cell reselection from E-UTRA idle non-CSG cell to a UTRA CSG cell | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104774 | 0991 | - | GCF Priority X: Addition of New TC for Inter-RAT CSG Cell Reselection from E-UTRA CSG cell to UTRA CSG cell | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104776 | 0992 | - | GCF Priority X: Introduction of new ESM test case 10.9.1 for UE routing of uplinks packets | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104777 | 0993 | - | GCF priority 2 - Cell detection timing related correction to test case 6.1.2.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104778 | 0994 | - | GCF priority 1 - Cell detection timing related correction to test case 6.1.2.4 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104779 | 0995 | - | GCF priority 2 - Cell detection timing related correction to test case 6.1.2.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104780 | 0996 | - | GCF priority 2 - Cell detection timing related correction to test case 6.1.2.11 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104781 | 0997 | - | GCF priority 1 - Cell detection timing related correction to test case 6.1.2.15 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104782 | 0998 | - | GCF priority 2 - Cell detection timing related correction to test case 6.2.2.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104783 | 0999 | - | GCF priority 2 - Cell detection timing related correction to test case 6.2.2.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104784 | 1000 | - | GCF priority 2 - Cell detection timing related correction to test case 6.2.3.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104785 | 1001 | - | GCF priority 2 - Cell detection timing related correction to test case 6.2.3.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104786 | 1002 | - | GCF priority 2 - Cell detection timing related correction to test case 6.2.3.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104787 | 1003 | - | GCF priority 2 - Cell detection timing related correction to test case 6.2.3.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104788 | 1004 | - | GCF priority 2 - Cell detection timing related correction to test case 8.1.2.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104789 | 1005 | - | GCF priority 2 - Cell detection timing related correction to test case 8.4.2.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104790 | 1006 | - | GCF priority 2 - Cell detection timing related correction to test case 8.4.2.4 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104791 | 1007 | - | GCF Priority 1 - Correction to test case 6.1.2.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104792 | 1008 | - | GCF Priority 2 - Correction to EUTRA Idle mode test case 6.1.2.6 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104793 | 1009 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.1.2.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104794 | 1010 | - | GCF Priority 2 - Correction to EUTRA PDCP test cases 7.3.5.2, 7.3.5.3, 7.3.5.4, 7.3.5.5 | 9.1.1 | 9.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2010-09 | RAN#49 | R5-104795 | 1011 | - | Correction to Generic E-UTRA radio bearer test procedure | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104797 | 1012 | - | GCF Priority 2 - Update test cases in clause 8.5.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-104798 | 1013 | - | GCF Priority 2 - Update of MAC test case 7.1.4.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105000 | 1014 | - | GCF Priority 3 - New TC 6.3.3 Inter-RAT cell reselection / From UTRA_Idle to E-UTRA RRC_IDLE CSG cell | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105001 | 1015 | - | GCF Priority 1 - Correction to GCF Priority 1 MAC test cases for AP#47.05 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105002 | 1017 | - | GCF Priority 1 - Correction of new test cases in 8.3.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105004 | 1018 | - | GCF Priority 4 - Update to test case 8.1.2.9 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105005 | 1019 | - | 36523-1: Update of attach procedure specification | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105006 | 1020 | - | GCF Priority 4 - Update of TC 8.1.2.8 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105007 | 1021 | - | GCF Priority 1 - Correction of EUTRA MAC test case 7.1.4.5 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105009 | 1022 | - | GCF Priority 2 - Correction of EUTRA test case 8.5.1.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105010 | 1023 | - | GCF Priority 2 - Correction to ETURA RRC test case 8.5.1.1 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105011 | 1024 | - | GCF Priority 2 - Correction of EUTRA test case 8.3.1.3 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105012 | 1025 | - | GCF Priority 2 - Correction to ESM test case 10.7.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105014 | 1027 | - | GCF Priority 3 - update of test case 9.2.3.2.9 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105015 | 1028 | - | GCF Priority 2 - update of test case 9.2.3.1.2 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105016 | 1029 | - | GCF Priority 1+2: Correction to RLC test cases for AP#47.05 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105054 | 1031 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.18 | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105070 | 1026 | - | Harmonising EMM test case pre-test conditions specification | 9.1.1 | 9.2.0 |
| 2010-09 | RAN#49 | R5-105071 | 1030 | - | GCF Priority x - Correction to 36.523-1 Test Case 8.3.1.5 | 9.1.1 | 9.2.0 |
| 2010-12 | RAN#50 | R5-106062 | 1133 | - | GCF Priority 2 - Correction of ESM test case 10.3.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106094 | 1134 | - | GCF Priority 1 - Update of RRC test case 8.2.2.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106107 | 1135 | - | GCF Priority 1 - Correction to EMM test case 9.2.3.1.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106108 | 1136 | - | GCF Priority 2 - Correction to ESM test case 10.4.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106109 | 1137 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.1.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106111 | 1138 | - | GCF Priority 2 - Correction to ESM test case 10.7.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106114 | 1032 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.13 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106156 | 1033 | - | GCF Priority 1 - Correction to TC 7.2.3.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106160 | 1034 | - | GCF Priority 1 - Correction to TC 9.2.3.1.5 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106164 | 1035 | - | GCF Priority 2 - Correction to TC 7.3.5.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106177 | 1036 | - | GCF Priority 2 - Correction of test cases in 6.2.3.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106182 | 1037 | - | GCF Priority 2 - Correction of test cases in 8.3.2.1, 8.3.2.3, 8.3.2.5 and 8.3.2.6 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106183 | 1038 | - | GCF Priority 3 - Correction of test cases in 8.3.3 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106186 | 1039 | - | GCF Priority 3 - Corrections to test case 9.2.1.2.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106187 | 1040 | - | GCF Priority 3 - Corrections to test case 9.2.2.1.7 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106188 | 1041 | - | GCF Priority 1 - Corrections to test case 9.2.2.2.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106189 | 1042 | - | GCF Priority 4 - Corrections to test case 9.2.3.2.2. | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106190 | 1043 | - | GCF Priority 4 - Corrections to test case 9.3.1.17 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106204 | 1044 | - | GCF Priority 1 - Corrections to test case 7.1.4.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106214 | 1045 | - | GCF Priority 2 - Correction to EMM test cases 9.2.1.1.13, 9.2.1.1.15 and 9.2.1.1.17 | 9.2.0 | 9.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2010-12 | RAN#50 | R5-106216 | 1046 | - | GCF Priority 2 - Correction to EMM test case 9.2.1.1.7 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106226 | 1047 | - | GCF Priority 2 - Correction to EMM test case 9.2.1.2.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106227 | 1048 | - | GCF Priority 2 - Correction to EMM test case 9.2.1.2.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106229 | 1049 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.1.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106268 | 1050 | - | GCF Priority 4 - Editorial correction to test case 6.1.1.6 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106269 | 1051 | - | GCF Priority 3 - Update to test case 6.2.2.5 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106274 | 1052 | - | GCF Priority 4 - Update to test case 8.1.2.6 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106275 | 1053 | - | GCF Priority 4 - Update to test case 8.1.2.8 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106276 | 1054 | - | GCF Priority 4 - Update to test case 8.1.2.9 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106277 | 1055 | - | GCF Priority 2 - Update to test case 8.1.3.5 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106280 | 1056 | - | GCF Priority 3 - Update to test case 9.2.1.2.15 and 9.3.1.12a | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106284 | 1057 | - | GCF Priority 3 - Update to test cases 10.8.2, 10.8.4 and 10.8.6 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106294 | 1058 | - | CR to 36.523-1: Correction to UTRA cell minimum power level | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106326 | 1059 | - | GCF Priority 3 - Corrections to ESM test case 10.6.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106333 | 1060 | - | GCF Priority 2 - Corrections to RRC test case 8.2.4.6 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106335 | 1061 | - | GCF Priority 1-4 - Editorial corrections to EUTRA RRC test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106336 | 1062 | - | GCF Priority 1-4 - Editorial corrections to EMM test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106524 | 1063 | - | Update test case 8.1.2.11 with IMS emergency session setup | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106525 | 1064 | - | Update references with IMS | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106555 | 1065 | - | GCF Priority 1 - Correction of test cases in 6.1.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106556 | 1066 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.2.8 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106557 | 1067 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.4.12 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106558 | 1068 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.4.13 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106559 | 1069 | - | GCF Priority 2 - Making compressed mode configuration optional for FDD and removal of compressed mode requirement for TDD for InterRAT HO test cases 8.4.2.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106560 | 1070 | - | GCF Priority 2 - Making compressed mode configuration optional for FDD and removal of compressed mode requirement for TDD for InterRAT HO test cases 8.4.2.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106563 | 1071 | - | GCF Priority 1 - Update of MAC test case 7.1.4.13 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106564 | 1072 | - | Resolve timing issue in P1 RLC TCs | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106565 | 1073 | - | GCF Priority 1 - Correction to TC 7.2.3.9 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106566 | 1074 | - | GCF Priority 1 - Update of Radio Bearer test procedure used by TC 12.2.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106567 | 1075 | - | GCF Priority 2 - Correction to Idle mode test case 6.1.2.7 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106568 | 1076 | - | GCF Priority 2 - Correction of test cases in 6.1.2.8 and 6.1.2.9 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106569 | 1077 | - | GCF Priority 2 - Correction of test cases in 6.2.2.1 and 6.2.2.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106570 | 1078 | - | GCF Priority 2 - Correction to EUTRA RRC test case 8.1.3.5 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106572 | 1079 | - | GCF Priority 2 - Correction of test cases in 8.3.1.8 ~ 8.3.1.11 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106573 | 1080 | - | GCF Priority 2 - Update to test case 8.4.2.2 and 8.4.2.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106574 | 1081 | - | GCF Priority 2 - Correction to contents for message Extended Service Request | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106575 | 1082 | - | GCF Priority 2 - Correction to EMM test case 9.1.2.3 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106595 | 1083 | - | Add test case for RRC connection establishment of emergency call / Limited Service | 9.2.0 | 9.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2010-12 | RAN#50 | R5-106598 | 1084 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.2.4.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106600 | 1085 | - | GCF Priority 2 - Correction to EMM test case 9.2.2.2.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106601 | 1086 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.2.1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106602 | 1087 | - | GCF Priority 3 - Corrections to test case 7.1.5.1 and 7.1.5.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106603 | 1088 | - | GCF Priority 3 - Addition new test case 6.1.2.13 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106604 | 1089 | - | GCF Priority 2 - Correction to EMM test case 9.2.1.1.1a | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106605 | 1090 | - | GCF Priority 3 - Various corrections to EMM section 9 of 36.523-1 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106607 | 1092 | - | GCF Priority 3: Correction to multi-layer test cases 13.1.4 and 13.1.5 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106608 | 1093 | - | GCF Priority 4 - Update to test case 8.1.1.3 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106619 | 1094 | - | GCF Priority 1 - Correction to TC 7.3.3.1, 7.3.3.2, 7.3.3.3 and 7.3.3.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106621 | 1095 | - | GCF Priority 4 - Update to test case 8.1.1.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106622 | 1096 | - | GCF Priority 4 - Correction of test cases in 8.3.1.6 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106623 | 1097 | - | GCF Priority 4 - Update to test case 9.2.3.2.5, 9.2.3.2.11, and 9.3.1.12a | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106624 | 1098 | - | Attach GCF Priority 4 - Addition of new test case 9.2.3.2.13 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106625 | 1099 | - | GCF Priority 4: Addition of a new test case 9.2.3.2.1b | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106626 | 1100 | - | Addition of system information combination in Idle Mode test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106627 | 1101 | - | Addition of system information combination in EMM test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106628 | 1102 | - | Addition of system information combination in RRC test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106629 | 1103 | - | Addition of system information combination in Multilayer test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106630 | 1104 | - | Clarification of measurements requirements for Inter-RAT | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106631 | 1105 | - | GCF Priority X - Addition new test case 6.2.3.31 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106632 | 1106 | - | GCF Priority 1 – Correction to EUTRA MAC test case 7.1.4.8 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106635 | 1107 | - | GCF Priority TBD - Addition of new idle mode test case for inter-freq cell reselection based on CSG autonomous search | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106636 | 1108 | - | GCF Priority TBD - Correction to TC 16.1.1.1 Inter-RAT Cell reselection from E-UTRA idle non-CSG cell to a UTRA CSG cell | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106637 | 1109 | - | GCF Priority TBD - Movement of TC 16.1.1.2 to section 6.3.8 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106638 | 1110 | - | GCF Priority 4 - Addition of new TC 6.3.4 Inter-RAT cell reselection / From UTRA CELL_PCH state to E-UTRA RRC_IDLE CSG cell | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106641 | 1112 | - | GCF Priority 4 -Making measurement and reporting optional for FDD and removal compressed mode requirement for TDD for Redirection test cases 8.1.3.7 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106642 | 1113 | - | Periodic RI Reporting using PUCCH / Category 1 UE / Transmission mode 3/4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106647 | 1116 | - | GCF Priority X - Addition of new test case 13.1.X | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106655 | 1117 | - | GCF Priority 4 - New test case 6.1.1.2 PLMN selection of 'Other PLMN/access technology combinations' / Automatic mode | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106657 | 1119 | - | GCF Priority 1 - Correction to TC 7.2.3.10 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106659 | 1120 | - | GCF Priority 1 - Corrections and enhancements to EUTRA PDCP test cases 7.3.3.1, 7.3.3.3, 7.3.4.1 and 7.3.4.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106660 | 1121 | - | GCF Priority 3 - Correction to test case 8.1.2.2 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106661 | 1122 | - | GCF Priority 2 - Corrections to E-UTRA RRC test case 8.1.2.7 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106662 | 1123 | - | GCF Priority 4: Addition of a new test case 9.2.1.2.1b | 9.2.0 | 9.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|-----|---|-------------|-------------|
| 2010-12 | RAN#50 | R5-106666 | 1124 | - | GCF Priority 2 - Correction to EUTRA MAC test case 7.1.4.16 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106676 | 1125 | - | GCF Priority 1-4 - Editorial corrections to various ESM test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106678 | 1126 | - | GCF Priority 1-4 - Editorial corrections to EUTRA Idle Mode test cases | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106679 | 1127 | - | GCF Priority 2 - Corrections to E-UTRA PDCP test case 7.3.5.5 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106680 | 1128 | - | GCF Priority 2 - Correction to EUTRA RLC test case 7.2.3.16 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106681 | 1129 | - | GCF Priority 2 - Update to test case 9.2.3.3.1 and 9.2.3.3.4 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106707 | 1131 | - | GCF priority X: New test case 9.2.3.2.1c Combined tracking area update / Success / CS Fallback not preferred | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106875 | 1114 | - | GCF Priority X - Addition of new test case 8.1.2.10 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106876 | 1118 | - | Cell detection timing related correction to test case 6.2.2.3, 6.2.2.4, 6.2.3.7 and 6.2.3.8 | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | R5-106877 | 1115 | - | GCF priority X: New test case 9.2.1.2.1c Combined attach procedure / Success / EPS and CS Fallback not preferred | 9.2.0 | 9.3.0 |
| 2010-12 | RAN#50 | RP-101255 | 1132 | - | GCF Priority 2 - Correction to EUTRA RLC test case 7.2.3.21 | 9.2.0 | 9.3.0 |
| 2011-03 | GERAN#49 | GP-110046 | 1142 | - | CR 36.523-1-1142 New test case 6.2.3.16 Inter-RAT Cell Reselection / from GSM_Idle to E-UTRAN /based on H_Prio criteria | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110047 | 1143 | - | CR 36.523-1-1143 Modifications to test case 6.2.2.6 and 6.2.2.7 | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110048 | 1144 | - | CR 36.523-1-1144 New Test Case 6.2.1.6 - Inter-RAT Background HPLMN Search/Search for correct RAT for HPLMN/Automatic Mode. | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110049 | 1145 | - | CR 36.523-1-1145 New Test Case 6.2.3.24 - Inter-RAT Cell Reselection from GPRS Packet transfer to E-UTRA in CCN mode (PACKET CELL CHANGE ORDER) | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110050 | 1146 | - | CR 36.523-1-1146 New Test Case 6.2.3.26 - Inter-RAT Autonomous Cell Reselection GPRS Packet_transfer to E-UTRA (NC1 mode) | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110051 | 1147 | - | CR 36.523-1-1147 Correction to GERAN-EUTRAN Inter-RAT testcases 6.2.3.19,6.2.3.21 and 6.2.3.22 | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110107 | 1149 | 1 | CR 36.523-1-1149 Addition of new Test case 8.4.4.1 Inter-RAT PS Handover / from GPRS Packet_transfer to E-UTRA cell | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110108 | 1150 | 1 | CR 36.523-1-1150 Addition of new Test case 8.4.4.2 Inter-RAT PS Handover failure from GPRS Packet_transfer to E-UTRA cell | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110405 | 1148 | 1 | CR 36.523-1-1148 Allow test cases 6.2.3.21 and 6.2.3.22 to be implemented in the TTCN | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110417 | 1139 | 1 | CR 36.523-1-1139 New test case 6.2.3.17 Inter-RAT Cell Reselection / from GSM_Idle/GPRS Packet_Idle to E-UTRA (priority E-UTRA cells) | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110418 | 1140 | 1 | CR 36.523-1-1140 New test case 6.2.3.18 Inter-RAT Cell Reselection / from GSM_Idle/GPRS Packet_Idle to E-UTRA (blacklisted E-UTRA cells) | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110419 | 1141 | 1 | CR 36.523-1-1141 New Test Case 6.2.3.29 - Inter-RAT cell Reselection from GPRS packet_transfer to E-UTRA in CCN mode (PACKET MEASUREMENT ORDER) | 9.3.0 | 9.4.0 |
| 2011-03 | GERAN#49 | GP-110420 | 1151 | 1 | CR 36.523-1-1151 Correction to GERAN-EUTRAN Inter-RAT cell reselection testcases 6.2.3.28 and 6.2.3.30. | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110137 | 1152 | - | GCF Priority 2 - Correction to system information in 6.1.2.7 and 6.1.2.11 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110156 | 1153 | - | GCF priority 3: Correction of UTRA cell in Idle and EMM test cases | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110192 | 1154 | - | GCF Priority 2 - Correction to EUTRA test case 8.3.2.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110194 | 1155 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.12 | 9.3.0 | 9.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-03 | RAN#51 | R5-110205 | 1156 | - | GCF Priority 2 Correction of test case in 6.2.3.4 and 6.3.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110207 | 1157 | - | GCF Priority 3 Correction of test case in 8.1.1.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110208 | 1158 | - | GCF Priority 3 Correction of test case in 8.1.2.2 and 8.1.2.8 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110209 | 1159 | - | GCF Priority 2 Correction of test case in 8.1.3.4, 8.1.3.6 and 8.1.3.8 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110211 | 1160 | - | GCF Priority 3 Correction of test case in 8.3.1.11 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110220 | 1161 | - | GCF Priority 1 - Enhancement to EUTRA MAC test case 7.1.4.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110223 | 1162 | - | GCF Priority 1 - Correction to EUTRA PDCP test cases 7.3.4.1 and 7.3.4.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110230 | 1163 | - | GCF Priority 4 - Update to test cases 8.1.2.6 and 8.1.2.9 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110231 | 1164 | - | GCF Priority 4 - Correction on TC numbering and update to test case 8.1.2.10 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110232 | 1165 | - | GCF Priority 2 - Update to test cases 8.4.2.2 and 8.4.2.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110234 | 1166 | - | GCF Priority 3 - Update to test case 9.2.1.2.11 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110273 | 1167 | - | Correction to TC 6.2.1.1 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110274 | 1168 | - | Correction to TC 6.2.1.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110277 | 1169 | - | Correction to TC 8.1.3.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110280 | 1170 | - | Correction to TC 9.2.3.3.1 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110305 | 1171 | - | GCF Priority 3 - Correction to TC 9.2.1.1.26 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110329 | 1172 | - | GCF Priority 2 - Update of EMM test case 9.3.1.7a | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110341 | 1173 | - | Addition of new test case on Service request for mobile originating 1xCS fallback emergency call | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110342 | 1174 | - | Addition of new test case on emergency call in non-allowed CSG cell | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110386 | 1175 | - | GCF Priority 3 - Correction to EUTR-1XRTT test case 6.2.2.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110387 | 1176 | - | GCF Priority 3 - Correction to EUTR-1XRTT test case 6.2.3.9 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110388 | 1177 | - | GCF Priority 3 - Correction to EUTR-1XRTT test case 6.2.3.10 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110389 | 1178 | - | GCF Priority 3 - Correction to EUTR-1XRTT test cases 8.4.7.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110390 | 1179 | - | GCF Priority 3: Correction to EUTR-1XRTT test cases 8.4.7.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110392 | 1180 | - | GCF priority 3: Correction to MAC TBS (MIMO configured) test case 7.1.7.1.5 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110393 | 1181 | - | GCF priority 3: Correction to MAC TBS (MIMO configured) test case 7.1.7.1.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110400 | 1182 | - | GCF Priority 1 - Correction to EMM test case 9.2.1.1.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110440 | 1183 | - | Addition of new test case 11.2.5 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110442 | 1184 | - | Addition of new test case 11.2.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110450 | 1185 | - | GCF Priority 4 - Addition of new Multilayer Procedures test case 13.4.1.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110477 | 1186 | - | New TC 11.2.6 Normal tracking area update for emergency bearer services Local emergency list sent | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110486 | 1187 | - | GCF Priority 1..4 - Editorial corrections to EMM test cases | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110504 | 1188 | - | GCF P3 : Corrections to DL and UL SPS grant test cases | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110514 | 1189 | - | Correction to GCF WI-081 MAC test case 7.1.4.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110602 | 1190 | - | GCF Priority 2 - Correction of Idle testcase 6.2.3.5 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110603 | 1191 | - | GCF Priority 3 - Correction of Idle testcase 6.2.3.13 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110604 | 1192 | - | GCF Priority 9 - Correction of Idle testcase 6.2.3.31 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110677 | 1193 | - | GCF Priority 2 - Correction to GCF WI-081 UTRAN - LTE Testcase 6.2.3.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110711 | 1194 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.4.1 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110712 | 1195 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.4.5 | 9.3.0 | 9.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-03 | RAN#51 | R5-110713 | 1196 | - | GCF Priority 1 - Correction to E-UTRA MAC test case 7.1.3.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110717 | 1197 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.3.3.1 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110718 | 1198 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.10 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110719 | 1199 | - | GCF Priority 1 Correction of test cases in 8.3.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110721 | 1200 | - | GCF Priority 2 - Correction to EUTRA Idle Mode test case 6.2.3.5 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110722 | 1201 | - | GCF Priority 2 - Correction to Idle mode test cases | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110723 | 1202 | - | GCF Priority 2 - Update of idle mode TC 6.1.2.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110724 | 1203 | - | GCF Priority 2 - Correction to EUTRA PDCP test cases 7.3.5.2 and 7.3.5.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110725 | 1204 | - | GCF Priority 2 - Correction to EUTRA RRC test case 8.1.2.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110726 | 1205 | - | GCF priority 2: Correction of sysinfo combination in EMM and ESM test cases | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110728 | 1206 | - | GCF Priority 2-Correction to TC-9.2.1.1.1a | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110730 | 1207 | - | GCF Priority 3 - Addition of new TC 6.3.2 Inter-RAT cell reselection / From GSM_Idle/GPRS Packet_Idle to E-UTRA idle CSG cell | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110731 | 1208 | - | GCF Priority 3 - Update to test case 6.3.3 and 6.3.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110732 | 1209 | - | GCF Priority 3 - Addition of new test case 6.2.2.x for Inter-RAT Cell Selection | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110733 | 1210 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.1.1.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110734 | 1211 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.3.2.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110735 | 1212 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.3.1.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110737 | 1213 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.3.1.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110738 | 1214 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.23 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110739 | 1215 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.9 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110740 | 1216 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.25 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110741 | 1217 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.16 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110742 | 1218 | - | GCF Priority 3 - Correction to EMM test cases 9.3.2.2 and 9.3.2.2a | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110751 | 1219 | - | GCF Priority 3 - Correction to EMM test case 9.3.1.15 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110752 | 1220 | - | GCF Priority 3 - Correction to EMM test case 9.3.1.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110753 | 1221 | - | Correction to TC 9.2.1.1.25 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110754 | 1222 | - | GCF Priority 3 - Correction to test case 9.3.1.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110755 | 1223 | - | GCF Priority 3- TC 9.2.3.2.1a | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110756 | 1224 | - | GCF Priority 3-Correction to TC 13.1.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110758 | 1225 | - | GCF Priority 3 - Correction to MultiLayer test case 13.3.1.1 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110760 | 1226 | - | GCF Priority 3 - Correction to Multilayer test case 13.1.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110764 | 1227 | - | GCF Priority 4 - Addition of E-UTRAN test case 6.1.1.3 for Cell reselection of ePLMN in manual mode | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110765 | 1228 | - | GCF Priority 4 - Addition of E-UTRAN test case 6.1.2.1 for Cell selection in forbidden Tracking Area | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110767 | 1229 | - | GCF Priority 4 - Correction to test case 6.2.1.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110768 | 1230 | - | GCF Priority 4 - Update to test case 6.3.7 and 6.3.8 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110769 | 1231 | - | GCF Priority 4 Correction of test case in 8.1.3.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110770 | 1232 | - | GCF Priority 4 - Correction to EUTRA RRC test case 8.1.2.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110771 | 1233 | - | Correction to TC 9.2.3.2.1c | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110772 | 1234 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.10 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110773 | 1235 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.9 | 9.3.0 | 9.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-03 | RAN#51 | R5-110774 | 1236 | - | GCF Priority 2 - Correction to EMM test case 9.3.1.7a | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110775 | 1237 | - | GCF Priority 2 - Correction to EMM test case 9.3.1.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110776 | 1238 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.14 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110777 | 1239 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.13 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110778 | 1240 | - | GCF Priority 4: Correction test case 9.2.1.2.1b, 9.2.1.2.1c and 9.2.3.2.1b to check the signalled MS Radio Access capability | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110779 | 1241 | - | GCF Priority 4: Correction to ESM test case 10.9.1 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110781 | 1242 | - | GCF Priority 4: New TC 13.1.9 Call setup from E-UTRA RRC_IDLE - CS fallback to GSM with CCO without NACC - MO call | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110783 | 1243 | - | GCF Priority 2 - Correction to TCs 9.2.1.2.1 and 13.1.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110790 | 1244 | - | Priority X Addition new test case 6.2.3.32 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110791 | 1245 | - | Correction to TC 6.3.7 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110792 | 1246 | - | GCF Priority 1 - Update to EUTRA RLC test cases 7.2.3.6, 7.2.3.7, 7.2.3.8 and 7.2.3.17 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110793 | 1247 | - | GCF Priority 2 - Correction to EMM test case 9.2.2.2.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110794 | 1248 | - | GCF Priority 2 - Update of EMM test case 9.2.3.3.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110796 | 1249 | - | GCF Priority X: Adding test case 9.2.1.2.1d Combined attach procedure / Success / EPS and CS Fallback not preferred/data centric UE | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110797 | 1250 | - | GCF Priority X - Update to test case 13.1.15 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110798 | 1251 | - | Update to chapter '4.3 Repetition of tests' to clarify re-testing in test cases, where HARQ retransmissions are not tolerated | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110813 | 1252 | - | Introduction of new test case 11.2.1 for CT1 aspects of emergency calls | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110830 | 1254 | - | GCF Priority 2 - Correction to SMS test cases 11.1.1, 11.1.2, 11.1.3, 11.1.4 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110876 | 1255 | - | GCF Priority 2 - Correction to E-UTRA RLC test case 7.2.3.16 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110877 | 1253 | - | Priority 2 -4: Adjusting the power levels of multiple cell, multiple RAT EMM test cases | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110062 | 1256 | - | GCF Priority 2 - Correction to EUTRA IDLE MODE test case 6.1.2.9 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110072 | 1257 | - | GCF Priority 3 - Correction to MultiLayer test case 13.4.1.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110077 | 1258 | - | GCF Priority 3 - Correction to EMM test case 9.1.2.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110078 | 1259 | - | GCF Priority 3 - Correction to ESM test case 10.8.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110081 | 1260 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.1.2.3 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110083 | 1261 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.3.9 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110085 | 1262 | - | GCF Priority 3 - Correction to EMM test case 9.2.2.1.9 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110086 | 1263 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.24 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110087 | 1264 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.3.1.11 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110091 | 1265 | - | GCF Priority 3 - Correction to MultiLayer test case 13.3.1.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110097 | 1266 | - | CGF Priority 4 - Correction to EUTRA DRB test case 12.3.2 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110122 | 1267 | - | GCF Priority 4 - Correction of cell number description for test case 6.1.1.6 | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110133 | 1268 | - | GCF priority 2-4: correction of EMM, RRC, Idle mode TC postamble in connected mode | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110814 | 1269 | - | Addition of new idle mode test case for manual CSG ID selection across PLMNs | 9.3.0 | 9.4.0 |
| 2011-03 | RAN#51 | R5-110815 | 1270 | - | Addition of new idle mode test case for inter-freq cell reselection to hybrid cell based on CSG autonomous search | 9.3.0 | 9.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2011-06 | RAN#52 | R5-112079 | 1277 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.2.4.7 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112080 | 1278 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.1.1.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112082 | 1279 | - | GCF Priority 2 - Correction to EUTRA Idle mode test case 6.1.1.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112083 | 1280 | - | GCF Priority 1 - Correction to EUTRA PDCP test cases 7.3.4.1 and 7.3.4.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112085 | 1281 | - | GCF Priority 4 - Correction to EUTRA RRC test case 8.5.1.4 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112088 | 1283 | - | GCF Priority 2 - Correction to EUTRA Idle mode test case 6.1.2.6 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112089 | 1284 | - | GCF Priority 2 - Correction to EMM test case 9.2.1.1.1a | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112090 | 1285 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112093 | 1286 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.15 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112094 | 1287 | - | GCF Priority 1 - Correction to EMM test case 9.2.3.1.5 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112095 | 1288 | - | GCF Priority 2 - Correction to EMM test case 9.2.1.1.12 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112096 | 1289 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112097 | 1290 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.13 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112098 | 1291 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.4 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112105 | 1292 | - | GCF Priority 2 - Correction to EMM test cases 9.2.1.2.1, 9.2.2.2.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112106 | 1293 | - | GCF Priority 2 - Correction to ESM test case 10.3.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112107 | 1294 | - | Removal of ESM test case 10.6.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112109 | 1295 | - | GCF Priority 2 - Correction to EMM test case 9.3.1.7 and 9.3.1.7a | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112118 | 1296 | - | GCF Priority 2 - Correction to update reference to 36.508 table 6.4.2.7A-1 and 6.4.2.7A-2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112121 | 1297 | - | GCF Priority 4 - Correction to EMM test cases 9.2.3.2.5, 9.2.3.2.6 and 9.2.3.2.7 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112122 | 1298 | - | GCF Priority 2 - Correction to specific message content for RRC Connection Reconfiguration message (Handover test cases) | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112145 | 1299 | - | GCF Priority 1 - Correction to GCF WI-081 MAC Testcase 7.1.2.9 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112162 | 1300 | - | GCF Priority 4 - remove the message contents from 14.1, 14.2 and 14.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112205 | 1301 | - | GCF Priority 2 - Correction to EUTRA RLC test case 7.2.2.10 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112208 | 1302 | - | GCF priority 4: Correction of UTRA cell in EMM test case 9.2.3.2.8 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112257 | 1303 | - | GCF Priority 2 - Correcting usage of generic test procedure 36.508 cl. 6.4.2.8 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112262 | 1304 | - | GCF Priority 4 - Correction to Multilayer test cases 13.2.1, 13.4.1.2, 13.4.1.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112266 | 1305 | - | GCF priority 1 - Correction to EUTRA MAC test case 7.1.4.13 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112276 | 1306 | - | GCF Priority 4 - Update of EMM test case 9.2.1.1.4 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112287 | 1307 | - | GCF Priority 3 - Editorial correction to EMM test case 9.2.1.1.26 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112304 | 1308 | - | GCF Priority 4 - Correction to TC 8.1.3.7 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112351 | 1309 | - | GCF Priority 3 - Update of EMM TC 9.2.1.2.13 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112390 | 1310 | - | Update of HeNB enhancements test case 6.3.9 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112391 | 1311 | - | Update of HeNB enhancements test case 6.4.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112392 | 1312 | - | Update of idle mode section Table 6.0.1-2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112434 | 1313 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.2.5 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112483 | 1314 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.2.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112534 | 1315 | - | GCF Priority 3: Update of TC 8.3.1.4 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112569 | 1316 | - | GCF Priority 3 – Correction to test case 9.2.3.1.25 | 9.4.0 | 9.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-06 | RAN#52 | R5-112594 | 1318 | - | New TC 6.4.6 Inter-RAT cell reselection / From UTRA CELL_PCH to E-UTRA RRC_IDLE member hybrid cell | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112595 | 1319 | - | New TC 6.4.7 Inter-RAT cell reselection / From GERAN to E-UTRA RRC_IDLE member hybrid cell | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112602 | 1320 | - | GCF priority 4 - Addition of Multi-layer Procedures test case 13.1.13 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112603 | 1321 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.6 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112604 | 1322 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.6 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112605 | 1323 | - | GCF priority 1 - Modification to EUTRA RLC test case 7.2.3.9 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112606 | 1324 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.18 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112607 | 1325 | - | GCF Priority 2 Correction of CSG test cases | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112608 | 1326 | - | GCF Priority 2 - Correction to EUTRA PDCP test cases 7.3.5.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112610 | 1327 | - | GCF Priority 2 - Review of detach at switch/power off procedure in EMM test cases and Emergency calls over IMS test case 11.2.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112611 | 1328 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.1.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112614 | 1329 | - | GCF Priority 3 Correction of Measurement configuration test cases | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112615 | 1330 | - | GCF Priority 3 - Correction to EMM test cases 9.2.1.2.5, 9.2.1.2.6 and 9.2.1.2.7 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112616 | 1331 | - | GCF Priority 3 - Correction to EMM test cases 9.3.1.4 & 9.3.1.5 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112617 | 1332 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.14 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112618 | 1333 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.15 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112619 | 1334 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.2.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112620 | 1335 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.2.9 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112622 | 1337 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.8 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112623 | 1338 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.9 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112624 | 1339 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.2.12 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112625 | 1340 | - | GCF Priority 3 - Correction to time requirements at cell reselection in EMM test cases | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112626 | 1341 | - | GCF Priority 3 - Addition of new test case 9.2.3.1.22 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112628 | 1342 | - | Addition of GCF Priority 3 EMM test case 9.2.2.1.4 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112629 | 1343 | - | GCF Priority 3 - Correction to Multilayer test case 13.1.3 and 13.1.15 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112630 | 1344 | - | GCF Priority 3 - New Multi Layer TC 13.4.2.4 Inter-system mobility / Service based redirection from UTRA to E-UTRA | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112631 | 1345 | - | GCF Priority 3 - Addition of new test case 13.4.2.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112632 | 1346 | - | GCF Priority 3 - Correction to test case 13.1.4 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112634 | 1347 | - | GCF Priority 3 - Addition of new test case 8.4.3.1 Inter-RAT handover / From E-UTRA to GPRS / PS HO | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112636 | 1348 | - | GCF Priority 3 - Addition of new test case 13.3.2.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112638 | 1349 | - | Correction to EMM test case to allow execution of all RAT specific branches using a single MRAT device | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112639 | 1350 | - | GCF Priority 4 Addition new test case 9.2.3.1.9 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112640 | 1351 | - | GCF Priority 4 - Corrections to Extended Service Request message in 9.2.3.2.1b and 13.1.8 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112641 | 1352 | - | GCF priority 4 - Addition of EMM test case 9.2.3.1.20 | 9.4.0 | 9.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|-----|--|-------------|-------------|
| 2011-06 | RAN#52 | R5-112642 | 1353 | - | GCF Priority 4 - Add new test case 13.4.3.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112643 | 1354 | - | GCF Priority 1 - Correction to EMM test case 9.2.1.1.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112654 | 1355 | - | Add new test case 11.2.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112657 | 1356 | - | Addition of new test case on Attach for emergency bearer services / Rejected / No suitable cells in tracking area / Emergency call using the CS domain | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112658 | 1357 | - | Update of IMS Emergency TC 11.2.6 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112659 | 1358 | - | New TC for IMS Emergency 11.2.7 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112660 | 1359 | - | GCF Priority 4 - Update of TC 13.1.9 MO call CS fallback to GSM with CCO without NACC | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112661 | 1360 | - | GCF Priority 4 - New TC 13.1.10 MT call CS fallback to GSM with CCO without NACC PS service suspension | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112666 | 1361 | - | GCF Priority X Correction of test case in 6.2.2.8 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112667 | 1362 | - | GCF Priority X - Addition of new test case 13.1.2a | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112668 | 1363 | - | GCF Priority X - Addition of new test case 13.1.16 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112671 | 1364 | - | Update test case 8.1.2.11 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112672 | 1365 | - | Update test case 8.1.2.12 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112678 | 1366 | - | GCF Priority X Addition new test case 6.4.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112679 | 1367 | - | GCF Priority X Addition new test case 6.4.4 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112680 | 1368 | - | GCF Priority X Addition new test case 6.4.5 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112682 | 1369 | - | Addition of new HeNB test case for intra-frequency SI acquisition | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112687 | 1372 | - | GCF priority 4 - Update Multi-layer Procedures test case 13.1.7 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112688 | 1373 | - | GCF priority 4 - Addition of Multi-layer Procedures test case 13.1.11 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112689 | 1374 | - | GCF priority 4 - Addition of Multi-layer Procedures test case 13.1.12 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112690 | 1375 | - | GCF Priority 2 - Correction to EUTRA Idle mode test case 6.3.6 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112693 | 1376 | - | Addition of a new TC for MCCH information acquisition/UE is switched on | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112695 | 1378 | - | Addition of a new TC for MCCH information acquisition/ UE handover to a cell in a new MBMS area | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112701 | 1379 | - | GCF Priority 3 - Correction to test case 13.1.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112703 | 1381 | - | GCF priority 4 - Update Multi-layer Procedures test case 13.3.1.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112705 | 1382 | - | GCF Priority 2 - Corrections to EUTRA RRC test case 8.4.1.2 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112720 | 1385 | - | GCF Priority 2: Update of test case 9.2.3.4.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112749 | 1377 | - | Addition of a new TC for MCCH information acquisition/ when cell reselection to a cell in a new MBMS area | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112750 | 1370 | - | GCF Priority X - Addition of new test case 6.4.1 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112753 | 1317 | - | GCF priority 1 – Correction to EUTRA MAC test case 7.1.4.10 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112754 | 1336 | - | GCF Priority 2 - Correction to EUTRA MAC test case 7.1.4.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112755 | 1383 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.17 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112756 | 1380 | - | GCF priority 4 - Addition of EMM test case 9.2.3.3.3 | 9.4.0 | 9.5.0 |
| 2011-06 | RAN#52 | R5-112757 | 1371 | - | GCF Priority X - Add new test case 9.2.2.1.10 | 9.4.0 | 9.5.0 |
| 2011-06 | GERAN#50 | GP-110571 | 1274 | - | CR 36.523-1-1274 Removal of LTE TC 6.2.3.2 specification due to duplication | 9.4.0 | 9.5.0 |
| 2011-06 | GERAN#50 | GP-110575 | 1275 | - | CR 36.523-1-1275 Removal of Test Case 8.4.4.2 | 9.4.0 | 9.5.0 |
| 2011-06 | GERAN#50 | GP-110831 | 1386 | - | CR 36.523-1-1386 Addition of new Test case 8.4.4.2 Inter-RAT PS Handover / from GPRS Packet_transfer to E-UTRA cell (CCN mode) | 9.4.0 | 9.5.0 |
| 2011-06 | GERAN#50 | GP-110832 | 1387 | - | CR 36.523-1-1387 Addition of new Test case 8.4.4.3 Inter-RAT PS Handover / from GPRS Packet_transfer to E-UTRA cell (NC2 mode) | 9.4.0 | 9.5.0 |
| 2011-06 | GERAN#50 | GP-110839 | 1273 | 1 | CR 36.523-1-1273 Modification of tc 6.2.3.19 | 9.4.0 | 9.5.0 |
| 2011-09 | GERAN#51 | GP-111104 | 1386 | 1 | CR 36.523-1-1386 Corrections to GERAN – LTE Tests | 9.5.0 | 9.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-09 | RAN#53 | R5-113031 | 1389 | - | GCF Priority 3: Correction of EMM TC 9.2.3.2.1a | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113101 | 1390 | - | GCF Priority 4 - Correction to Idle mode test case 6.2.2.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113102 | 1391 | - | GCF Priority 2 -Correction to EUTRA RRC test case 8.1.3.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113104 | 1392 | - | GCF Priority 1 - Correction to EUTRA RRC test cases 8.2.4.1, 8.2.4.4 and 8.2.4.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113105 | 1393 | - | GCF Priority 4 - Correction to EUTRA RRC test case 8.3.1.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113106 | 1394 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.3.1.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113107 | 1395 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.3.3.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113108 | 1396 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.2.4.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113110 | 1397 | - | GCF Priority 1 - Correction to ESM test cases 10.2.1 and 10.4.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113111 | 1398 | - | GCF Priority 4 - Correction to ESM test cases 10.8.5 and 10.8.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113113 | 1399 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.11 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113114 | 1400 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.16 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113115 | 1401 | - | GCF Priority 3 - Correction to EMM test cases 9.2.3.1.9a and 9.2.3.1.23 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113116 | 1402 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.2 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113117 | 1403 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113118 | 1404 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.11 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113121 | 1405 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.25 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113124 | 1406 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.12 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113129 | 1407 | - | GCF Priority 1 - Correction to several EUTRA RLC test cases | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113131 | 1408 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.9 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113170 | 1409 | - | GCF Priority TBD - Update of test case 6.3.1 Inter-frequency cell reselection / From E-UTRA RRC_IDLE non-CSG cell to E-UTRA RRC_IDLE CSG cell | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113188 | 1410 | - | GCF Priority 2 - Correction to ESM test case 10.4.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113189 | 1411 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113190 | 1412 | - | GCF Priority 3 - Correction to Multilayer test case 13.3.1.2 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113240 | 1413 | - | GCF Priority 3 - Update of EMM test case 9.2.2.1.9 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113270 | 1414 | - | Update of IMS emergency test case 11.2.3 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113293 | 1415 | - | Update of the case 11.2.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113294 | 1416 | - | Update of test case 11.2.5 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113300 | 1417 | - | GCF Priority 2 - Update test case 9.1.2.3, 9.2.1.1.9, 9.2.1.1.11, 9.2.1.1.25, 9.2.1.2.12, 9.2.2.1.2, 9.2.2.1.3, 9.2.2.1.8, 9.2.2.1.9, 9.2.3.2.4, 9.3.1.6 and 9.3.1.16 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113325 | 1418 | - | GCF Priority 3 - Correction to testcase 13.3.2.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113331 | 1420 | - | GCF Priority 3 - Corrections to TC 6.3.2 Inter-RAT reselection from GERAN to E-UTRA CSG cell | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113332 | 1421 | - | Corrections to TC 6.4.7 Inter-RAT reselection from GERAN to E-UTRA Hybrid cell | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113333 | 1422 | - | Corrections to HeNB Section 6.3 TCs | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113360 | 1423 | - | Priority 4: Correction to TC 13.1.9 MO call CS fallback to GSM with CCO without NACC | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113364 | 1424 | - | GCF Priority 3 - Correction to test case 9.3.1.17 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113374 | 1425 | - | GCF priority 3 - Update to Multi Layer Procedure test case 13.3.1.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113482 | 1426 | - | GCF Priority 3 - Correction to test case 9.2.1.2.5 | 9.5.0 | 9.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-09 | RAN#53 | R5-113539 | 1427 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.15 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113573 | 1428 | - | GCF Priority 4 - Editorial correction to EUTRA RRC test case 8.3.2.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113575 | 1429 | - | GCF Priority 3 / 4 - Editorial corrections to EUTRA MAC test cases 7.1.5.x | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113672 | 1430 | - | GCF Priority 1 - Correction to GCF WI-091 MAC Testcase 7.1.4.15 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113673 | 1431 | - | GCF Priority 1: Correction to RLC AM test case 7.2.3.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113674 | 1432 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.5.4.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113675 | 1433 | - | GCF Priority 1 & 3 :Corrections to test cases 9.2.3.1.1, 9.2.3.1.9a & 9.2.3.1.27, to make suitable for single frequency operation | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113676 | 1434 | - | GCF Priority 2 - Correction to Idle mode test case 6.1.2.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113677 | 1435 | - | GCF Priority 2 Complete SIBs Reading for TC 6.2.2.1_2_3_4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113678 | 1436 | - | GCF Priority 2 Complete SIBs Reading for TC 6.2.3 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113679 | 1437 | - | GCF Priority 2: Correction to DRX test cases 7.1.6.1 and 7.1.6.2 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113680 | 1438 | - | GCF Priority 2 Complete SIBs Reading for TC 8.4.2.2.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113681 | 1439 | - | GCF Priority 2 & 3: Update of EMM test cases to cater for bands with single frequency operation | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113682 | 1440 | - | GCF Priority 2 - Update of EMM test cases 9.2.1.2.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113685 | 1441 | - | GCF Priority 2 - Correction to GCF WI-082 EMM LTE MRAT Testcase 9.2.3.1.18/ | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113687 | 1442 | - | GCF Priority 3 Complete SIBs Reading for TC 6.3.2.3.7.8 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113688 | 1443 | - | GCF Priority 3 - Update of test case 6.2.1.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113689 | 1444 | - | GCF Priority 3 - Update of test case 6.2.3.32 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113690 | 1445 | - | GCF Priority 3 - Correction to EUTRA MAC test case 7.1.4.14 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113691 | 1446 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.2.4.12 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113692 | 1447 | - | GCF Priority 3 - Correction to EMM test case 9.1.5.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113693 | 1448 | - | GCF Priority 3 - Correction to EMM test cases 9.3.1.4 and 9.3.1.5 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113694 | 1449 | - | GCF Priority 3 - Correction of test case 9.2.3.1.9a | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113695 | 1450 | - | GCF Priority 3 - Correction to location update message contents | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113696 | 1451 | - | GCF Priority 3 - Update of EMM test cases to cater for bands with single frequency and LTE only operation | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113699 | 1452 | - | GCF Priority 3 - Correction to the value of timer T3402 in EMM test case 9.2.3.1.26 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113701 | 1453 | - | GCF Priority 3 - Correction to ESM test cases 10.7.3 and 10.8.3 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113702 | 1454 | - | GCF Priority 4 - Correction to GCF WI-081 Idle Mode Testcase 6.1.1.2 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113703 | 1455 | - | GCF Priority 4: Correction to Rank Indication test case 7.1.8.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113704 | 1456 | - | GCF Priority 4 - Correction to EUTRA RRC test case 8.1.2.8 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113705 | 1457 | - | GCF Priority 4 - Correction to 8.1.2.13 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113706 | 1458 | - | GCF Priority 4 – Update to test cases 8.2.1.5 and 8.2.1.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113707 | 1459 | - | GCF Priority 4 - Correction to EUTRA RRC Test Case 8.4.3.3 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113708 | 1460 | - | GCF Priority 4 - Addition of EUTRA RRC Test Case 8.4.1.5 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113709 | 1461 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.17 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113710 | 1462 | - | GCF Priority 4: Correction test case 9.2.1.2.1b to check the signalled MS Radio Access capability | 9.5.0 | 9.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-09 | RAN#53 | R5-113711 | 1463 | - | GCF Priority 4 - Correction to GCF WI-082 ESM Testcase 10.8.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113713 | 1465 | - | GCF Priority 4 - Correction to ESM test case 10.9.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113714 | 1466 | - | GCF Priority 4 - Correction to ESM test case 10.3.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113715 | 1467 | - | GCF Priority 4 - Update to test case 13.1.15 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113716 | 1468 | - | GCF Priority 4 - Update of test case 13.1.11 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113717 | 1469 | - | GCF Priority 4 - Update of test case 13.1.12 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113718 | 1470 | - | GCF Priority 4 - Update of test case 13.1.13 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113719 | 1471 | - | GCF Priority 4 - Update of test case 13.1.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113720 | 1472 | - | GCF Priority 4 - Update of test case 13.1.8 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113721 | 1473 | - | GCF Priority 4 - Add new test case 13.4.3.2 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113722 | 1474 | - | GCF Priority 4 - Update test case 13.4.3.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113723 | 1475 | - | GCF Priority 4 - Add new test case 13.4.3.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113728 | 1477 | - | Update test case 8.1.2.12 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113729 | 1478 | - | Addition of new test case for e1xCsFB / MT call | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113730 | 1479 | - | Addition of new test case for e1xCsFB / MO call | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113754 | 1480 | - | GCF Priority X - Update to test case 6.4.1 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113755 | 1481 | - | Various updates to Rel-9 HeNB enhancements test cases | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113756 | 1482 | - | GCF Priority X Correction of TC 6.4.3.4.5.6.7 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113757 | 1483 | - | GCF Priority X Addition new test case 8.3.4.2 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113758 | 1484 | - | GCF Priority X Addition new test case 8.3.4.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113759 | 1485 | - | Addition of new HeNB test case for Inter-frequency SI acquisition member Hybrid Cell | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113762 | 1486 | - | Addition of a new eMBMS test case 17.2.1: UE Acquire the MBMS data based on the SIB13 and MCCH message /MCCH and MTCH are on the same MCH | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113763 | 1487 | - | Addition of a new eMBMS test case 17.2.2: UE Acquire the MBMS data based on the SIB13 and MCCH message /MCCH and MTCH are on different MCHs | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113764 | 1488 | - | Addition of a new eMBMS test case 17.2.3: UE Acquire the MBMS data based on the SIB13 and MCCH message /MCCH and MTCH are on different MCHs | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113765 | 1489 | - | Addition of a new eMBMS test case 17.2.4: Reception of PDCCH DCI format 0 and PHICH in MBSFN subframes | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113766 | 1490 | - | Addition of a new TC for MCCH information acquisition/ UE is receiving an MBMS service | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113767 | 1491 | - | Addition of a new TC for MCCH information acquisition/ UE is not receiving MBMS data | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113783 | 1492 | - | GCF Priority X - Addition of new test case 8.2.1.8 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113792 | 1493 | - | GCF Priority 2 - Correction to GCF WI-081 Idle Mode Interband Testcase 6.1.2.5 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113793 | 1494 | - | GCF Priority 2 - Correction to GCF WI-091 MAC Testcase 7.1.4.16 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113805 | 1496 | - | Clarification of LTE only branch in EMM TCs | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113806 | 1497 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.2.3 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113807 | 1498 | - | GCF Priority 2 & 3 - Update of EMM test cases 9.2.2.1.6, 9.2.2.1.7, 9.2.2.1.8 and 9.2.2.1.9 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113808 | 1499 | - | GCF Priority 3 - Correction to EMM test case 9.3.1.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113809 | 1500 | - | GCF Priority 2 - Correction to GCF WI-082 EMM Testcase 9.2.3.3.5 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113810 | 1501 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113811 | 1502 | - | GCF Priority 2, 3 & 4 - Update of EMM test cases 9.2.2.2.2, 9.3.1.3, 9.3.1.12a, 9.3.2.2 and 9.3.2.2a | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113812 | 1503 | - | GCF Priority 3 - Addition of new test case 13.3.2.2 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113813 | 1504 | - | GCF Priority 1 & 2 - Update of LTE-C2k test cases 8.4.5.4, 8.4.7.3 and 8.4.7.4 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113836 | 1505 | - | GCF Priority 3 - Correction to WI-082 EUTRA EMM Testcase 9.2.3.1.22 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113848 | 1476 | - | New E-UTRA MAC test case for padding BSR | 9.5.0 | 9.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|-----|--|-------------|-------------|
| 2011-09 | RAN#53 | R5-113849 | 1464 | - | GCF Priority 3 - Correction to EUTRA MAC test cases 7.1.7.1.5 and 7.1.7.1.6 | 9.5.0 | 9.6.0 |
| 2011-09 | RAN#53 | R5-113850 | 1495 | - | GCF Priority 2 - Correction to EMM test cases | 9.5.0 | 9.6.0 |
| 2011-12 | GERAN#52 | GP-111502 | 1506 | - | CR 36523-1-1506 Correction to 6.2.3.22 | 9.6.0 | 9.7.0 |
| 2011-12 | GERAN#52 | GP-111525 | 1507 | - | CR 36523-1-1507 Addition of new Test case 13.4.2.5 Inter-system mobility / Service based redirection from GSM/GPRS to E-UTRA | 9.6.0 | 9.7.0 |
| 2011-12 | GERAN#52 | GP-111539 | 1509 | - | CR 36523-1-1509 Moving the TCs under section 8.4.4 to void | 9.6.0 | 9.7.0 |
| 2011-12 | GERAN#52 | GP-111540 | 1510 | - | CR 36523-1-1510 Addition of new Test case 13.4.2.6 to 13.4.2.8 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115138 | 1511 | - | GCF Priority U2 - Correction to EUTRA RRC test case 8.3.3.2 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115164 | 1512 | - | GCF Priority 3 - Correction to test case 6.1.2.13 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115167 | 1513 | - | GCF Priority g1 - Correction to GERAN CSFB test cases | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115176 | 1514 | - | GCF Priority 4 - Removal of test case 14.3 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115228 | 1515 | - | GCF Priority 4 - Correction to Idle Mode Testcase 6.1.1.4 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115230 | 1516 | - | GCF Priority 3: Correction to EMM test cases 9.2.2.2.2, 9.3.1.3, 9.3.2.2, 9.3.2.2a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115239 | 1517 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.3.1.7 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115244 | 1518 | - | Correction to parameter 'sf-AllocEnd-r9' in MBMS test cases | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115245 | 1519 | - | Editorial correction to test case 8.1.3.10 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115272 | 1520 | - | Update of test cases 8.4.7.3, 8.4.7.4, 8.4.7.5 and 8.4.7.6 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115305 | 1521 | - | GCF Priority X Addition new test case 6.1.2.2a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115311 | 1522 | - | GCF Priority X Correction for test cases 8.3.4.1_2_3_4 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115314 | 1523 | - | Update of TC 11.2.6 IMS Emergency CT1 aspects | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115355 | 1524 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.25 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115361 | 1525 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.3.5 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115370 | 1526 | - | Correction to GCF P3 EMM test case 9.3.1.17 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115448 | 1527 | - | GCF Priority 4 - Correction to EUTRA Idle Mode test case 6.1.1.3 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115455 | 1528 | - | GCF Priority 4 - Removal of test case 6.1.2.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115511 | 1529 | - | GCF Priority X: Addition of new test case 8.3.1.9a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115532 | 1530 | - | Update of TC 11.2.4 IMS Emergency CT1 aspects | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115539 | 1531 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.4.10 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115547 | 1532 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.3.3 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115560 | 1533 | - | GCF Priority 2 (and lower) - Corrections to various EMM test cases | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115561 | 1534 | - | GCF Priority 2 (and lower) - Corrections to ESM test cases 10.3.1 and 10.9.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115564 | 1535 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.3.9 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115576 | 1536 | - | GCF Priority 2 - Editorial Correction to EUTRA RLC test case 7.2.3.13 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115620 | 1537 | - | CGF Priority 1 - Correction to EUTRA MAC test case 7.1.7.2.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115622 | 1538 | - | GCF Priority 1 - Correction to RRC test case 8.5.4.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115624 | 1539 | - | GCF Priority 2 Correction for test cases 6.1.2.13 and 6.1.2.15 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115625 | 1540 | - | GCF Priority 2 - Correction to Idle Mode test case 6.1.1.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115626 | 1541 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.3.5 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115627 | 1542 | - | GCF Priority 2: Corrections to equivalent PLMN test case 9.2.3.1.4 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115628 | 1543 | - | GCF Priority 2: Corrections to test case 9.2.3.1.16 | 9.6.0 | 9.7.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2011-12 | RAN#54 | R5-115629 | 1544 | - | GCF Priority 3 - Corrections to Idle mode Shared network test cases | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115630 | 1545 | - | GCF Priority 3: Addition of new idle mode test case for Manual support for CSG ID selection | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115631 | 1546 | - | GCF Priority 3 - Correction to test case 6.2.3.13 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115634 | 1547 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.2.1a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115635 | 1548 | - | GCF Priority 3 - Correction to EMM test case 9.1.5.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115636 | 1549 | - | GCF Priority 3 - Update of EMM test case 9.3.1.15 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115637 | 1550 | - | GCF Priority 3 - Update to test case 9.2.3.1.23 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115638 | 1551 | - | GCF Priority 3 - Correction to ESM test cases 10.8.5 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115639 | 1552 | - | GCF Priority 4 - Update to test case 6.1.2.14 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115640 | 1553 | - | GCF Priority 4 - Correction to GCF WI-081 Idle Mode Testcase 6.1.1.3 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115642 | 1554 | - | Removal of TC 11.2.9 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115644 | 1555 | - | GCF Prio 3: Corrections to TC 8.4.3.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115645 | 1556 | - | GCF Priority 4 Correction for test cases 6.2.3.13 and 6.2.3.31 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115646 | 1557 | - | GCF Priority 4 - Update to EUTRA RRC test case 8.3.1.6 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115647 | 1558 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.1.17 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115648 | 1559 | - | GCF Priority 4 - Correction to EMM test cases 9.3.1.12a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115649 | 1560 | - | GCF Priority 4: Correction to test case 9.2.1.2.1d | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115650 | 1561 | - | GCF priority 4: Minor correction to test case 9.2.1.2.1c | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115651 | 1562 | - | GCF Priority 4 - Add new test case 13.4.3.3 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115652 | 1563 | - | GCF Priority 4 - Add new test case 13.4.3.5 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115653 | 1564 | - | GCF Priority 4 - Update test case 13.4.3.2 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115654 | 1565 | - | GCF Priority 4 - Update test case 13.4.3.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115655 | 1566 | - | GCF Priority 4 - Update test case 13.4.3.4 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115656 | 1567 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.3.5a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115792 | 1568 | - | GCF priority X - new test case 6.1.1.3a for Cell reselection of ePLMN in manual mode / between FDD and TDD | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115662 | 1569 | - | GCF Priority 4 - Correction to EUTRA RRC test case 8.2.4.8 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115672 | 1570 | - | Update of TC 11.2.7 IMS Emergency CT1 aspects | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115673 | 1571 | - | Update of test case 11.2.1 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115675 | 1572 | - | Update of test case 11.2.3 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115676 | 1573 | - | Update of test case 11.2.4 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115677 | 1574 | - | GCF Priority U1: Correction to TC 6.3.7 Inter-RAT Cell reselection from E-UTRA idle non-CSG cell to a UTRA CSG cell | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115678 | 1575 | - | GCF Priority U1 - Correction to EUTRA RRC testcase 8.4.1.4 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115680 | 1576 | - | Addition of new Rel-9 test case 6.2.3.7a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115681 | 1577 | - | Addition of new Rel-9 test case 6.2.3.8a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115682 | 1578 | - | Addition of new Rel-9 test case 6.2.3.9a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115683 | 1579 | - | Addition of new Rel-9 test case 6.2.3.10a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115684 | 1580 | - | GCF Priority X Addition new test case 6.1.2.3a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115685 | 1581 | - | GCF Priority X Addition new test case 6.1.2.17 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115686 | 1582 | - | GCF Priority X Addition new test case 6.1.2.18 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115687 | 1583 | - | GCF Priority U2: Correction to TC 6.3.3 Inter-RAT cell reselection / From UTRA_Idle to E-UTRA RRC_IDLE CSG cell | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115794 | 1584 | - | GCF priority x - Add new test case 6.1.1.1a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115691 | 1585 | - | GCF Priority X - Addition of new test case 8.5.1.x | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115692 | 1586 | - | GCF Priority X - Addition of new test case 8.1.2.x | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115693 | 1587 | - | GCF Priority X: Addition of new test case 8.3.1.11a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115709 | 1588 | - | GCF Priority 4 - Update of test cases 13.1.11 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115710 | 1589 | - | GCF Priority 4 - Update of test cases 13.1.12 | 9.6.0 | 9.7.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2011-12 | RAN#54 | R5-115711 | 1590 | - | GCF Priority 4 - Update of test cases 13.1.13 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115712 | 1591 | - | Addition of new test case for e1xCsFB emergency call | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115713 | 1592 | - | Addition of new test case for 1xCsFB emergency call | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115720 | 1593 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.26 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115722 | 1594 | - | Maximum bandwidth config for MAC TBS test cases in band 25 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115726 | 1595 | - | GCF Priority 1 - Correction to EUTRA MAC test case 7.1.4.5 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115793 | 1596 | - | Addition of a new TC for Cell reselection / interband operation / Between FDD and TDD | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115753 | 1597 | - | Update of test case 6.2.3.8 and 6.2.3.10 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115795 | 1598 | - | PLMN selection in shared network environment / Automatic mode / between FDD and TDD | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115796 | 1599 | - | Inter-frequency cell reselection according to cell reselection priority provided by SIBs / Between FDD and TDD | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115797 | 1600 | - | Addition of new test case 6.2.3.1a | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115763 | 1602 | - | GCF Priority 4: Modification on the Event A3 timeToTrigger value in TC 8.3.1.6 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115798 | 1603 | - | GCF Priority 2 - Update of EMM test case 9.2.2.1.7 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115766 | 1604 | - | GCF Priority 3 - Correction to EMM test cases 9.2.3.1.22 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115767 | 1605 | - | GCF Priority 3 - Update of EMM test cases 9.2.3.1.26 Preamble | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115768 | 1606 | - | GCF Priority 2 - Update of EMM test cases 9.2.3.2.3 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115769 | 1607 | - | GCF Priority 2 - Update test case 9.2.3.1.6 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115771 | 1608 | - | Update test case 11.2.2 | 9.6.0 | 9.7.0 |
| 2011-12 | RAN#54 | R5-115774 | 1609 | - | GCF Priority 2 - Correction to Idle mode test case 6.2.2.5 | 9.6.0 | 9.7.0 |
| 2012-03 | RAN#55 | R5-120125 | 1610 | - | GCF Priority 1 - Correction of test case 7.1.2.6 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120156 | 1611 | - | GCF Priority X Correction of test case 6.1.2.2a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120158 | 1612 | - | GCF Priority X Correction of test case 6.1.2.18 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120174 | 1613 | - | GCF Priority 2: Modification on TC 8.1.3.4 RRC connection release / Redirection to another E-UTRAN frequency | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120236 | 1614 | - | GCF priority c1: Correction of measurement gap offset | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120265 | 1615 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.1.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120267 | 1616 | - | GCF Priority 2 - Correction to EUTRA Idle mode testcase 6.1.2.13 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120268 | 1617 | - | GCF Priority 3 - Correction to EUTRA MAC testcase 7.1.3.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120269 | 1618 | - | GCF Priority 4 - Correction to EUTRA MAC testcase 7.1.4.7a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120270 | 1619 | - | GCF Priority 1 - Correction to EUTRA RLC testcase 7.2.3.8 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120271 | 1620 | - | GCF Priority 3 - Correction to EUTRA testcase 8.3.1.11 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120272 | 1621 | - | GCF Priority u1 - Correction to EUTRA RRC test case 8.3.3.2 and 8.3.3.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120273 | 1622 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.1.6 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120356 | 1623 | - | GCF Priority 3 - Correction to EUTRA RRC test case 8.3.1.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120357 | 1624 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.23 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120398 | 1625 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.16 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120400 | 1626 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.23 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120403 | 1627 | - | Update of IMS emergency call test case 11.2.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120440 | 1628 | - | GCF Priority X - Update to test case 8.2.1.8 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120441 | 1629 | - | GCF Priority X - Addition of new test case 8.3.1.3a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120482 | 1630 | - | Clarification on specifying parameter values without taking into account uncertainties | 9.7.0 | 9.8.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2012-03 | RAN#55 | R5-120490 | 1631 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.13 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120494 | 1632 | - | GCF Priority X Correction of test case 6.1.2.17 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120528 | 1633 | - | GCF Priority 2 - Correction to EUTRA RRC test case 8.3.2.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120541 | 1634 | - | GCF Priority 4: Correction to ESM test case 10.3.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120542 | 1635 | - | GCF Priority 4: Correction to ESM test case 10.9.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120584 | 1636 | - | GCF Priority U1 - Correction to EUTRA Idle Mode test case 6.2.1.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120622 | 1637 | - | GCF Priority 2 : Update of inter band cell reselection test case 6.1.2.5 to cater for bands with single frequency operation | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120623 | 1638 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.1.6 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120624 | 1639 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.2.1a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120625 | 1640 | - | GCF Priority 2 (and lower) - Correction of TAI list fields in EMM test cases | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120627 | 1641 | - | GCF Priority 3 : Update of EMM test cases 9.2.3.1.17 and 9.2.3.1.19 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120628 | 1642 | - | GCF Priority 3 : Update of EMM authentication test case 9.1.2.6 to cater for bands with single frequency operation | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120629 | 1643 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.26 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120630 | 1644 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.3.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120633 | 1646 | - | GCF Priority 4 - Correction to EMM test case 9.2.1.1.18 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120635 | 1647 | - | GCF Priority 4 - Update to test case 13.4.3.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120636 | 1648 | - | GCF Priority 4 - Update to test case 13.4.3.5 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120637 | 1649 | - | GCF Priority 4 - Update test case 13.4.3.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120638 | 1650 | - | GCF Priority 4 - Update to test case 14.1 and 14.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120639 | 1651 | - | GCF Priority u1 Correction of test case 6.2.3.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120640 | 1652 | - | GCF Priority U1 - update of E-UTRA Idle mode test case 6.2.2.5 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120641 | 1653 | - | GCF Priority U1 - update of E-UTRA RRC test case 8.1.3.7 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120642 | 1654 | - | GCF Priority U1 - update of E-UTRA RRC test case 8.3.2.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120643 | 1655 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.3.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120644 | 1656 | - | GCF Priority u1 - Correction to EMM test case 9.2.1.2.1b | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120645 | 1657 | - | GCF Priority U1 - update of E-UTRA Multi-Layer test case 13.4.2.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120646 | 1658 | - | GCF Priority U1 - update of E-UTRA Multi-Layer test case 13.4.2.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120647 | 1659 | - | GCF Priority u1 - Correction to Multilayer test case 13.1.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120649 | 1660 | - | GCF Priority U2 - update of E-UTRA RRC test case 8.3.2.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120650 | 1661 | - | 8.1.3.12a RRC connection release / Success / With priority information / Inter-band / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120651 | 1662 | - | 8.1.3.11a RRC connection release / Redirection to another E-UTRAN band / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120652 | 1663 | - | 8.2.4.13a RRC connection reconfiguration / Handover / Success (with measurement) / Inter-band / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120653 | 1664 | - | 8.2.4.14a RRC connection reconfiguration / Handover / Failure / Re-establishment successful / Inter-band / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120654 | 1665 | - | 8.2.4.15a RRC connection reconfiguration / Handover / Failure / Re-establishment failure / Inter-band / Between FDD and TDD | 9.7.0 | 9.8.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2012-03 | RAN#55 | R5-120657 | 1666 | - | 8.3.1.14a Measurement configuration control and reporting / Intra E-UTRAN measurements / Two simultaneous events A2 and A3 (inter-band measurements) / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120658 | 1667 | - | 8.3.1.15a Measurement configuration control and reporting / Intra E-UTRAN measurements / Inter-band handover / IE measurement configuration not present / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120659 | 1668 | - | 8.3.1.16a Measurement configuration control and reporting / Intra E-UTRAN measurements / Continuation of the measurements after RRC connection re-establishment / Inter-band / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120660 | 1669 | - | GCF Priority u2 - Correction to EUTRA RRC test case 8.3.3.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120661 | 1670 | - | GCF Priority U2 - update of E-UTRA RRC test case 8.4.2.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120662 | 1671 | - | GCF Priority U2 - update of E-UTRA RRC test case 8.4.2.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120663 | 1672 | - | GCF Priority U2 - update of E-UTRA Multi-Layer test case 13.1.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120664 | 1673 | - | GCF Priority U2 - update of E-UTRA Multi-Layer test case 13.1.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120665 | 1674 | - | GCF Priority U2 - update of E-UTRA Multi-Layer test case 13.1.15 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120666 | 1675 | - | GCF Priority U2 - update of E-UTRA Multi-Layer test case 13.4.3.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120667 | 1676 | - | GCF Priority U2 - update of E-UTRA Multi-Layer test case 13.4.3.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120668 | 1677 | - | GCF Priority U2 - update of E-UTRA Multi-Layer test case 13.4.3.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120669 | 1678 | - | GCF Priority M1 - update of E-UTRA RRC test case 8.3.2.5 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120670 | 1679 | - | GCF Priority M1 - update of E-UTRA RRC test case 8.3.2.6 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120671 | 1680 | - | GCF Priority g1 - Correction to EUTRA Idle mode test case 6.2.3.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120673 | 1681 | - | GCF Priority X Correction of test case 6.1.2.3a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120674 | 1682 | - | GCF Priority X Addition of new test case 6.2.3.3a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120675 | 1683 | - | GCF Priority X Addition of new test case 6.2.3.5a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120676 | 1684 | - | GCF Priority X - Addition of new test case 6.2.3.x | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120695 | 1685 | - | Update of test case 11.2.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120696 | 1686 | - | Update of test case 11.2.5 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120697 | 1687 | - | GCF Priority X - Update of TC 11.2.8 to include IMS procedures | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120698 | 1688 | - | Update test case 11.2.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120699 | 1689 | - | GCF Priority x - Update test case 8.1.2.11 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120700 | 1690 | - | GCF Priority x - Update test case 8.1.2.12 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120701 | 1691 | - | GCF Priority x : Update of titles of test cases 8.3.1.9a and 8.3.1.11a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120703 | 1693 | - | Addition of new test 11.2.10 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120705 | 1694 | - | GCF Priority X - Addition of new test case 8.3.2.3a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120707 | 1695 | - | GCF Priority 4 (and higher) - Editorial corrections to various EMM test cases | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120708 | 1696 | - | Addition of new Rel-9 test case 13.4.4.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120709 | 1697 | - | Addition of new Rel-9 test case 13.4.4.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120710 | 1698 | - | GCF Priority X - update of E-UTRA Multi-Layer test case 13.1.2a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120711 | 1699 | - | Modification of TC 8.4.7.1: Inter-RAT handover / SRVCC from E-UTRA to 1xRTT(CS) / Speech | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120712 | 1700 | - | Addition for new 13.4.4.3 LTE-CDMA2000-HRPD interworking test case | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120713 | 1701 | - | Addition for new 13.4.4.4 LTE-CDMA2000-HRPD interworking test case | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120714 | 1702 | - | 8.3.1.12a Measurement configuration control and reporting / Intra E-UTRAN measurements / Two simultaneous events A3 (inter-band measurements) / Between FDD and TDD | 9.7.0 | 9.8.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2012-03 | RAN#55 | R5-120715 | 1703 | - | 8.3.1.13a Measurement configuration control and reporting / Intra E-UTRAN measurements / Periodic reporting (intra-frequency and inter-band measurements) / Between FDD and TDD | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120741 | 1716 | - | GCF Priority X - Addition of new test case 8.6.4.y | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120742 | 1717 | - | GCF Priority X - Addition of new test case 8.6.4.z | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120743 | 1718 | - | GCF Priority X - Addition of new test case 8.6.x.y | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120744 | 1719 | - | GCF Priority X - Addition of new test case 8.6.x.z | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120751 | 1720 | - | Addition of new Rel-9 test case 18.1.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120757 | 1721 | - | GCF Priority 2 : Introduction of new equivalent , 6.1.2.x test cases to cater for bands with single frequency operation | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120758 | 1722 | - | GCF Priority 2 : Introduction of new equivalent 6.1.1.x test cases to cater for bands with single frequency operation | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120760 | 1723 | - | GCF Priority U1 - Correction to EUTRA RRC test case 8.1.3.7 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120764 | 1724 | - | GCF Priority U1 - Correction to EUTRA RRC test cases 8.4.1.2 and 8.4.1.4 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120765 | 1725 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.2.1 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120766 | 1726 | - | GCF Priority u1 - Update to test case 9.2.3.3.2 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120767 | 1727 | - | GCF Priority u1 - Update to test case 9.2.3.3.3 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120768 | 1728 | - | GCF Priority u1 - Update to test case 9.2.3.3.5 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120769 | 1729 | - | GCF Priority X - Update of test cases 6.2.2.3, 6.2.3.7, 6.2.3.7a, 6.2.3.8, 6.2.3.8a, 6.2.3.9, 6.2.3.9a, 6.2.3.10, 6.2.3.10a | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120771 | 1731 | - | GCF Priority 3 - Correction to Idle Mode test case 6.1.2.13 | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120776 | 1732 | - | GCF Priority UX – Correction to EUTRA to UTRA Handover testcases | 9.7.0 | 9.8.0 |
| 2012-03 | RAN#55 | R5-120631 | 1645 | - | Addition of new MDT test case for 'Logged MDT / Intra-frequency measurement, logging and reporting / E-UTRA handover' | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120724 | 1704 | - | Addition of a new TC 17.3.1 for MBMS Counting / UE not receiving MBMS service | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120727 | 1705 | - | CA / RRC connection reconfiguration / Carrier Aggregation / SCell addition/ modification/release / Success | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120728 | 1706 | - | CA / RRC connection reconfiguration / Carrier Aggregation / SCell SI change / Success | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120729 | 1707 | - | CA / RRC connection reconfiguration / SCell addition without UL | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120730 | 1708 | - | CA / RRC connection reconfiguration / Handover / Success / SCell addition | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120731 | 1709 | - | CA / RRC connection reconfiguration / Handover / Success / SCell becomes PCell | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120732 | 1710 | - | CA / Measurement configuration control and reporting / Intra E-UTRAN measurements / Event A6 | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120733 | 1711 | - | CA / Measurement configuration control and reporting / Intra E-UTRAN measurements / Additional measurement reporting | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120734 | 1712 | - | Addition of new Rel-10 test case 7.1.3.11 CA / Correct HARQ process handling / DCCH and DTCH / Pcell and Scell | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120738 | 1713 | - | Addition of new MDT test case for 'Logged MDT / Intra-frequency measurement, logging and reporting / Limiting area scope' | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120739 | 1714 | - | New Logged MDT test case 8.6.2.1 (Intra-frequency measurement, logging and reporting) | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120740 | 1715 | - | New Logged MDT test case 8.6.2.2 (Inter-frequency measurement, logging and reporting) | 9.8.0 | 10.0.0 |
| 2012-03 | RAN#55 | R5-120770 | 1730 | - | Addition of a new Rel-10 test case 17.3.2 | 9.8.0 | 10.0.0 |
| 2012-06 | RAN#55 | R5-120638 | 1650 | - | GCF Priority 4 - Update to test case 14.1 and 14.2 (addition in Table 14.2.3.2-1 of forgotten Step 5 alert check and Note) | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121080 | 1738 | - | GCF Priority m1: Optimisation of frequency allocation | 10.0.0 | 10.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2012-06 | RAN#56 | R5-121081 | 1739 | - | GCF Priority P2: Optimisation of frequency allocation | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121087 | 1740 | - | GCF Priority U1 - Correction to EUTRA RRC test case 8.1.3.7 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121099 | 1741 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.3.6 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121106 | 1742 | - | GCF Priority U1 - Correction to test EUTRA-UTRA test case 13.3.2.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121108 | 1743 | - | GCF Priority C1 - Correction to test cases 6.2.3.8 and 6.2.3.8a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121142 | 1744 | - | GCF priority 3 - Correction to idle mode test case 6.1.2.13 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121158 | 1745 | - | GCF Priority X - corrections to TC 13.4.4.3 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121159 | 1746 | - | GCF Priority X - corrections to TC 13.4.4.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121202 | 1747 | - | GCF priority x - Update of test case 6.1.1.1a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121275 | 1748 | - | GCF Priority 2 - Update of test cases 9.3.1.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121278 | 1749 | - | GCF Priority X - Update of Inter-system session management test case 13.4.4.1 and 13.4.4.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121289 | 1750 | - | GCF Priority X - Update to test case 8.6.6.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121293 | 1751 | - | GCF Priority X - Addition of new test case 8.2.4.13 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121295 | 1752 | - | GCF Priority X - Addition of new test case 8.2.4.15 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121296 | 1753 | - | GCF Priority X - Addition of new test case 8.3.1.15 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121297 | 1754 | - | GCF Priority X - Addition of new test case 8.3.1.16 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121394 | 1755 | - | GCF Priority 4 Correction of test case 8.2.4.10 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121411 | 1756 | - | GCF Priority 4 - Update test case 8.1.2.6 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121412 | 1757 | - | GCF Priority 4 - Update test case 8.1.2.9 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121419 | 1758 | - | GCF Priority 2 and 3 - Removal of 'Active' flag test cases | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121426 | 1759 | - | Changing to Void of GERAN to E-UTRAN section 8.4.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121437 | 1760 | - | GCF Priority g1 - Correction to EUTRA test case 8.1.3.8 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121450 | 1761 | - | GCF Priority 3 - Correction to EUTRA MAC testcase 7.1.4.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121465 | 1762 | - | GCF Priority 1 and 3 - Correction to EMM test cases 9.2.1.1.2 and 9.2.2.1.8 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121466 | 1763 | - | GCF Priority U1 - Correction to multi-layer test case 13.1.5 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121504 | 1764 | - | GCF priority 2: Correction to test case 9.2.1.17 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121505 | 1765 | - | GCF priority G1: Correction to test case 13.4.2.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121511 | 1766 | - | Introduction of new PWS test case 18.1.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121517 | 1767 | - | Introduction of new Rel10 CA test case 7.1.4.21 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121541 | 1768 | - | GCF Priority 1, 2, 3, 4 and U1 - Correction to EMM test cases to use new PICS | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121548 | 1769 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.5.4.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121550 | 1770 | - | GCF Priority 4 - Correction to ESM test case 10.8.7 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121623 | 1771 | - | Radio Link Failure logging / Reporting at GERAN Inter-RAT handover | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121632 | 1772 | - | GCF Priority 4 - Update test case 13.4.3.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121666 | 1773 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.17 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121703 | 1774 | - | GCF Priority u1 - Correction to Multilayer test case 13.4.2.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121738 | 1775 | - | GCF Priority 1 and 3 - Correction to EUTRA MAC test cases 7.1.7.1.1, 7.1.7.1.2, 7.1.7.1.3, 7.1.7.1.4, 7.1.7.1.5, 7.1.7.1.6 and 7.1.7.2.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121739 | 1776 | - | GCF Priority 1 - Correction to EMM test case 9.2.3.1.5 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121740 | 1777 | - | GCF Priority 2: Addition of equivalent EMM test cases for single frequency operation | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121742 | 1778 | - | GCF Priority 2: Corrections to EMM test cases to enable single frequency operation | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121743 | 1779 | - | GCF Priority 2 - Update to test case 10.4.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121744 | 1780 | - | GCF Priority 3 - Correction to EUTRA MAC testcase 7.1.3.2 | 10.0.0 | 10.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2012-06 | RAN#56 | R5-121746 | 1781 | - | GCF Priority 4 - Correction to EMM CSG test case 9.3.1.18 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121747 | 1782 | - | GCF Priority 3 Update of TC 9.2.3.1.23 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121748 | 1783 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.23, 9.2.3.2.4, 9.2.3.2.14, 9.2.3.2.2, 9.2.3.2.17 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121749 | 1784 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121750 | 1785 | - | GCF Priority 3 - Correction to EMM test case 9.2.2.1.7 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121753 | 1786 | - | GCF Priority 4 - Correction to EUTRA Idle Mode test cases 6.1.1.6 and 6.1.1.6a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121754 | 1787 | - | GCF priority 4 - Correction to Idle Mode test case 6.1.2.12 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121755 | 1788 | - | GCF Priority 4 - Correction to Idle mode test case 6.1.1.6a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121756 | 1789 | - | GCF Priority 4 - Editorial corrections to some EMM test cases | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121757 | 1790 | - | GCF Priority 4 - Update test case 13.4.3.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121758 | 1791 | - | GCF Priority 4 - Update test case 13.4.3.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121759 | 1792 | - | GCF Priority 4 - Update to test case 14.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121760 | 1793 | - | GCF Priority u1 - Update to EUTRA Idle Mode test case 6.2.1.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121761 | 1794 | - | GCF Priority u1 - Correction to EUTRA Idle Mode test case 6.2.1.3 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121762 | 1795 | - | GCF Priority u1 - Correction to EMM test case 9.2.1.2.11 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121763 | 1796 | - | GCF Priority u1 - Correction to EMM test case 9.2.1.2.15 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121764 | 1797 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.3.5 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121765 | 1798 | - | GCF Priority u1 - Correction to EMM test case 9.2.1.2.1d | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121766 | 1799 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.2.1c | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121767 | 1800 | - | GCF Priority U1 - Correction to EUTRA Multi-Layer test case 13.1.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121768 | 1801 | - | GCF Priority U1 - Correction to multi-layer test case 13.4.2.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121771 | 1802 | - | GCF Priority g1 - Correction to EUTRA test case 6.2.2.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121772 | 1803 | - | GCF Priority g1 - Correction to EUTRA test case 6.2.3.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121773 | 1804 | - | GCF Priority g1 - Correction to EUTRA test case 8.3.2.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121774 | 1805 | - | GCF Priority g1 - Update to test case 9.2.3.3.5a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121775 | 1806 | - | GCF Priority g1 - Correction to EMM test case 9.2.3.4.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121776 | 1807 | - | GCF Priority g2 Correction of test case 8.4.3.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121780 | 1808 | - | GCF Priority X - Update to test case 6.2.3.33 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121781 | 1809 | - | GCF Priority X - Addition of new test case 8.1.3.12 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121782 | 1810 | - | GCF Priority X - Addition of new test case 8.1.3.11 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121783 | 1811 | - | GCF Priority X - Addition of new Rel-9 EUTRA RRC test case 8.1.3.6a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121784 | 1812 | - | GCF Priority X - Addition of new test case 8.2.4.14 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121785 | 1813 | - | GCF Priority X - Addition of new test case 8.3.1.12 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121786 | 1814 | - | GCF Priority X - Addition of new test case 8.3.1.13 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121787 | 1815 | - | GCF Priority X - Addition of new test case 8.3.1.14 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121788 | 1816 | - | GCF Priority C2 - Correction to test case 8.4.5.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121789 | 1817 | - | Addition of new e1xCSFB Rel-9 test case 8.4.7.7 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121790 | 1818 | - | Addition of new e1xCSFB Rel-9 test case 8.4.7.8 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121791 | 1819 | - | Addition of new e1xCSFB Rel-9 test case 8.4.7.9 | 10.0.0 | 10.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2012-06 | RAN#56 | R5-121792 | 1820 | - | Addition of new Rel-9 SRVCC test case 13.4.3.6 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121793 | 1821 | - | GCF Priority X - Addition of new test case 13.4.1.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121794 | 1822 | - | GCF Priority X Addition of new test case 13.3.1.3 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121807 | 1823 | - | GCF Priority X - Update of IMS test case 11.2.8 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121808 | 1824 | - | Add new test case 11.2.11 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121826 | 1825 | - | New UTRAN ANR/E-UTRAN test case 8.7.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121828 | 1826 | - | Update of MDT test case 8.6.2.3 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121829 | 1827 | - | Update of MDT test case 8.6.2.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121830 | 1828 | - | Addition of new MDT test case 8.6.2.5 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121831 | 1829 | - | Addition of new MDT test case 8.6.2.6 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121832 | 1830 | - | Addition of new MDT test case 8.6.2.7 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121833 | 1831 | - | Addition of new MDT test case 8.2.6.8 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121834 | 1832 | - | GCF Priority X - Addition of new test case 8.6.4.5 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121836 | 1833 | - | GCF Priority X - Addition of new test case 8.6.4.6 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121837 | 1834 | - | GCF Priority X - Addition of new test case 8.6.5.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121839 | 1835 | - | GCF Priority X - Addition of new test case 8.6.6.3 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121840 | 1836 | - | GCF Priority X - Addition of new test case 8.6.7.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121841 | 1837 | - | New Logged MDT test case 8.6.3.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121843 | 1838 | - | Radio Link Failure logging / Reporting at RRC connection establishment and reestablishment | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121844 | 1839 | - | Radio Link Failure logging / Reporting at E-UTRA handover | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121848 | 1840 | - | Correction to UE Pre-test condition for TS 36.523-1 Test Case 6.4.7 (Inter-RAT cell reselection / From GSM_Idle/GPRS Packet_Idle to E-UTRA RRC_IDLE member hybrid cell) | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121849 | 1841 | - | Correction of E-UTRAN<->GERAN test cases for Classmark Change | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121855 | 1842 | - | Addition of new PWS Rel-9 test case 18.1.7 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121857 | 1843 | - | Correction of CA TC 8.2.2.3 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121858 | 1844 | - | Correction of CA TC 8.2.2.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121859 | 1845 | - | Correction of CA TC 8.2.2.5 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121860 | 1846 | - | Correction of CA TC 8.2.4.17 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121861 | 1847 | - | Removal of CA TC 8.2.4.16 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121862 | 1848 | - | Correction of CA TC 8.3.1.17 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121863 | 1849 | - | Correction of CA TC 8.3.1.18 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121865 | 1850 | - | GCF Priority X - Addition of new CA test case | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121869 | 1851 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.10 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121870 | 1852 | - | GCF Priority 1 - Correction to EUTRA RLC test case 7.2.3.13 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121889 | 1853 | - | Update to TC 6.1.1.3a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121890 | 1854 | - | Update to TC 6.1.1.4a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121891 | 1855 | - | Update to TC 6.1.2.15a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121892 | 1856 | - | Update to TC 6.1.2.16 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121893 | 1857 | - | GCF Priority X Correction of test cases 6.2.3.3a and 6.2.3.5a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121894 | 1858 | - | GCF Priority 4: Modification on TC 8.1.2.9 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121895 | 1859 | - | Update to TC 8.1.3.11a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121896 | 1860 | - | Update to TC 8.1.3.12a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121897 | 1861 | - | Update to TC 8.2.4.13a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121898 | 1862 | - | Update to TC 8.2.4.14a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-121899 | 1863 | - | Update to TC 8.2.4.15a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122008 | 1864 | - | Introduction of new Rel10 CA test case 7.1.9.1 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122009 | 1865 | - | Radio Link Failure logging / Reporting at CDMA2000 Inter-RAT handover | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122010 | 1866 | - | Immediate MDT / Reporting / Location information | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122011 | 1867 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.3.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122012 | 1868 | - | GCF Priority X - Update of EMM test case 9.2.1.2.1b | 10.0.0 | 10.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2012-06 | RAN#56 | R5-122013 | 1869 | - | GCF Priority X - Update of EMM test case 9.2.1.2.1c | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122016 | 1870 | - | Addition of new e1xCsFB Rel-9 test case 13.4.4.5 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122100 | 1871 | - | Update to TC 8.3.1.12a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122101 | 1872 | - | Updates to TC 8.3.1.13a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122102 | 1873 | - | Update to TC 8.3.1.14a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122103 | 1874 | - | Update to TC 8.3.1.15a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122104 | 1875 | - | Update to TC 8.3.1.16a | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122105 | 1876 | - | GCF Priority U1 - Correction to EUTRA RRC test case 8.4.2.2 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122107 | 1877 | - | GCF Priority U1 - Correction to EMM test case 9.2.1.2.13 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122108 | 1878 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.2.9 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122113 | 1879 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.4 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122114 | 1880 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.3.3 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122115 | 1881 | - | GCF Priority U1: Modification on TC 9.2.3.2.13 | 10.0.0 | 10.1.0 |
| 2012-06 | RAN#56 | R5-122119 | 1882 | - | GCF priority 3: Correction to EMM TC 9.2.3.1.17 | 10.0.0 | 10.1.0 |
| 2012-09 | RAN#57 | R5-123079 | 1887 | - | GCF Priority u1: Optimisation of test frequency allocation of UTRA cell | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123099 | 1888 | - | GCF Priority 2 - Correction to test case 9.2.3.2.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123102 | 1889 | - | GCF Priority X - Corrections of test case 8.1.3.12 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123119 | 1890 | - | GCF Priority u1 - Correction to EUTRA RRC test case 8.3.2.5 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123120 | 1891 | - | GCF Priority u1 - Correction to EMM test case 9.2.1.2.13 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123124 | 1892 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.3.5a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123126 | 1893 | - | GCF Priority g1 - Correction to multilayer test case 13.1.7 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123131 | 1894 | - | GCF Priority g1 - Correction to EMM test case 9.2.3.4.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123132 | 1895 | - | GCF Priority 3 - Correction to EUTRA MAC test case 7.1.3.2 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123202 | 1896 | - | GCF Priority X - Update to test case 6.2.3.33 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123203 | 1897 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.3.2 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123247 | 1898 | - | GCF Priority C1 - Correction to Rel9 EUTRA-1xRTT test case 6.2.3.10a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123248 | 1899 | - | GCF Priority C1 - Correction to Rel9 EUTRA-HRPD test case 6.2.3.7a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123251 | 1900 | - | GCF Priority C1 - Correction to Rel9 EUTRA-1xRTT test case 6.2.3.9a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123254 | 1901 | - | GCF Priority U1 - Correction to EMM test case 9.2.1.2.13 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123325 | 1902 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.5.4.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123415 | 1903 | - | GCF Priority 4: Correction to test case 6.1.2.8a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123423 | 1904 | - | Enhancements to LTE CA test case 7.1.9.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123424 | 1905 | - | Update PWS Rel-9 test case 18.1.4 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123432 | 1906 | - | GCF Priority 1- Correction to RRC test case 8.1.3.12a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123433 | 1907 | - | GCF Priority 4 - Correction to Idle Mode test case 6.1.1.3b | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123474 | 1909 | - | GCF Priority g1: Correction to EMM TC 9.2.3.4.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123475 | 1910 | - | Corrections of measGapConfig IE definitions in CDMA2000 related test cases | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123476 | 1911 | - | GCF Priority 2: Update MAC TC 7.1.4.16 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123496 | 1912 | - | Update MDT TC 8.6.5.3 title | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123536 | 1913 | - | Update of References to specs and Releases in 36.523-1 v990 (pointer) | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123539 | 1914 | - | Update of References to specs and Releases in 36.523-1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123541 | 1915 | - | Add missing PLMN and TAC | 10.1.0 | 10.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2012-09 | RAN#57 | R5-123550 | 1916 | - | GCF Priority 3 - Correction to test cases 9.3.1.4, 9.3.1.5 and 9.3.1.6 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123554 | 1917 | - | Correction to UTRAN ANR E-UTRAN Inter-RAT test case 8.7.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123565 | 1918 | - | GCF priority b1: Correction to test case 6.1.2.5 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123586 | 1919 | - | GCF Priority U1 - Update of EMM TC 9.2.3.2.3 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123637 | 1920 | - | GCF priority 1 - Correction of test case 8.5.4.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123638 | 1921 | - | GCF Priority 1..4 - Editorial Corrections to EMM test cases | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123640 | 1922 | - | GCF Priority 3 - Update of EMM test case 9.2.2.1.2 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123641 | 1923 | - | GCF Priority 3 - Correction to EUTRA Idle Mode test case 6.1.1.4 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123642 | 1924 | - | GCF Priority u1 - Correction to Idle mode test case 6.2.1.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123643 | 1925 | - | GCF Priority u1 - Correction to Idle mode test case 6.2.3.13 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123644 | 1926 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.2.9 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123645 | 1927 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.2.14 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123646 | 1928 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.3.2 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123647 | 1929 | - | GCF Priority u1 - Correction to EMM test case 9.3.1.6 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123648 | 1930 | - | GCF Priority u1 - Correction to EMM test cases 9.2.1.2.1b and 9.2.1.2.1.c | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123649 | 1931 | - | GCF Priority u1 Update of TC 9.2.3.3.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123650 | 1932 | - | GCF Priority U1 - Correction to EMM test case 9.2.1.2.9 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123651 | 1933 | - | GCF Priority U1 - Update of EMM test case 9.2.3.2.1b | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123655 | 1934 | - | GCF Priority U2 - Correction to UTRA-EUTRA test case 8.4.2.4 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123656 | 1935 | - | GCF Priority C1 - Correction to test cases 8.3.2.8 and 8.3.2.10 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123657 | 1936 | - | GCF Priority C1 - Correction to test case 6.2.3.9 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123659 | 1937 | - | GCF Priority g1 - Correction to multilayer test case 13.1.10 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123660 | 1938 | - | GCF Priority g1 - Correction to multilayer test case 13.1.8 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123661 | 1939 | - | GCF Priority g1 - Correction to multilayer test case 13.1.9 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123665 | 1940 | - | GCF Priority 3 - Correction to EUTRA MAC test cases 7.1.3.2, 7.1.4.2 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123666 | 1941 | - | Correction to Rel-9 EUTRA-HRPD Idle Mode test case 6.2.3.8a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123667 | 1942 | - | GCF Priority X: Addition of New Inter band test case 6.1.2.15b | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123668 | 1943 | - | Correction to EUTRA Idle Mode test case 6.1.1.4a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123669 | 1944 | - | GCF Priority X - Update of test case 6.1.2.2a | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123671 | 1945 | - | GCF Priority X - Addition of new test case 8.4.7.11 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123672 | 1946 | - | GCF Priority X: Correction to test case 13.4.4.1 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123673 | 1947 | - | GCF Priority X - Update of 13.4.4.5 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123674 | 1948 | - | GCF Priority X - Update of 8.4.7.x test cases | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123680 | 1949 | - | GCF Priority x - Addition of new test case 6.2.3.4a : Inter-RAT cell reselection / From UTRA_CELL_PCH state to E-UTRA RRC_IDLE based on RSRQ+RSRP evaluation | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123685 | 1950 | - | Update PWS Rel-9 test case 18.1.7 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123708 | 1951 | - | GCF Priority X - Addition of New Rel-10 eICIC test case | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123709 | 1952 | - | Addition of new Rel-10 eICIC test case 8.3.1.19 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123732 | 1957 | - | GCF Priority g1 - Correction to EUTRA test cases 8.4.3.2 and 8.4.3.3 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123735 | 1958 | - | Correction to EUTRAN-GERAN test cases for classmark change | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123736 | 1959 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.3.4 | 10.1.0 | 10.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|-----|---|-------------|-------------|
| 2012-09 | RAN#57 | R5-123790 | 1960 | - | GCF Priority 3 - Correction to EMM test case 9.2.2.1.3 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123738 | 1961 | - | GCF Priority X Addition of new test case 13.4.1.5 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123739 | 1962 | - | GCF Priority u1 - Correction to SRVCC test cases 13.4.3.1, 13.4.3.2, 13.4.3.4 and 13.4.3.6 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123749 | 1963 | - | Update test case 11.2.11 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123753 | 1964 | - | Update of CA TC 7.1.3.11 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123754 | 1965 | - | GCF Priority X - Addition of New Carrier Aggregation test case | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123755 | 1966 | - | Correction of CA test case 8.2.2.3 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123756 | 1967 | - | Addition of new TC 7.1.4.19 CA / UE power headroom reporting / SCell activation and DL pathloss change reporting / Extended PHR | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123794 | 1968 | - | Addition of new TC 7.1.4.23 CA / Correct handling of MAC control information / Buffer status | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123758 | 1969 | - | Correction of CA test case 8.2.2.4 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123759 | 1970 | - | Correction of CA test case 8.2.2.5 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123760 | 1971 | - | Correction of CA test case 8.2.4.17 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123761 | 1972 | - | Correction of CA test case 8.2.4.18 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123762 | 1973 | - | Correction of CA test case 8.3.1.17 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123763 | 1974 | - | Correction of CA test case 8.3.1.18 | 10.1.0 | 10.2.0 |
| 2012-09 | GERAN#56 | GP-120868 | 1886 | - | CR 36.523-1-1886 GCF Priority g1 - Correction to Idle mode test case 6.2.3.19 | 10.1.0 | 10.2.0 |
| 2012-09 | GERAN#56 | GP-121042 | 1884 | 1 | CR 36.523-1-1884 GCF priority g1 - Correction to Idle Mode test case 6.2.3.24 | 10.1.0 | 10.2.0 |
| 2012-09 | GERAN#56 | GP-121043 | 1975 | - | CR 36.523-1-1975 GCF Priority g1 - Deletion of Idle mode test case 6.2.3.20 | 10.1.0 | 10.2.0 |
| 2012-09 | RAN#57 | R5-123436 | 1908 | - | Addition of new TC9.4.5 Integrity protection / Correct functionality of EPS NAS integrity algorithm / ZUC | 10.2.0 | 11.0.0 |
| 2012-09 | RAN#57 | R5-123721 | 1953 | - | Addition of Test Case 7.3.4.3 Integrity protection Correct functionality of EPS AS integrity algorithms ZUC | 10.2.0 | 11.0.0 |
| 2012-09 | RAN#57 | R5-123722 | 1954 | - | Addition of new ZUC test case 7.3.3.6 correct functionality of EPS UP encryption algorithms | 10.2.0 | 11.0.0 |
| 2012-09 | RAN#57 | R5-123723 | 1955 | - | Addition of new TC7.3.3.5 Ciphering and deciphering / Correct functionality of EPS AS encryption algorithms / ZUC | 10.2.0 | 11.0.0 |
| 2012-09 | RAN#57 | R5-123724 | 1956 | - | Addition of new TC 9.4.6 Ciphering and deciphering / Correct functionality of EPS NAS encryption algorithm / ZUC | 10.2.0 | 11.0.0 |
| 2012-12 | RAN#58 | R5-125074 | 1978 | - | GCF P3: Update of TC 9.2.1.1.19 to apply to all types of attach | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125080 | 1980 | - | GCF WI-151 - Correction to LTE FDD-TDD Inter-mode test case 6.1.1.1a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125087 | 1981 | - | GCF Priority 3: Correction to EMM test case 9.2.3.1.16 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125126 | 1982 | - | GCF Priority 4 - Correction to EUTRA Idle Mode test case 6.1.1.6a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125130 | 1983 | - | Split of CA TC 7.1.3.11 to Intra-band contiguous CA and Inter-band CA | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125132 | 1984 | - | GCF Priority 3 - Update to Multilayer procedure test cases 13.1.3, 13.3.2.1 and 13.3.2.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125154 | 1985 | - | GCF Priority X - Corrections_TC_s_8.4.7.x | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125155 | 1986 | - | GCF Priority X - Renumbering test case 8.4.7.11 to 8.4.7.10 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125172 | 1987 | - | Correction of RSRQ EUTRA 6.1.2.18 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125173 | 1988 | - | Correction of RSRQ EUTRA-GERAN 6.2.3.1a | 11.0.0 | 11.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2012-12 | RAN#58 | R5-125200 | 1989 | - | GCF Priority 3 - Editorial correction for test case 9.2.1.1.25 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125204 | 1990 | - | GCF Priority 3 - Update test case 9.2.1.1.26 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125207 | 1991 | - | Correction to ANR for UTRAN IRAT (E-UTRAN) test case 8.7.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125232 | 1992 | - | GCF Priority 1 - Correction to Idle Mode test case 6.2.3.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125233 | 1993 | - | GCF Priority u1: Correction to RRC test case 8.1.3.7 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125234 | 1994 | - | GCF Priority u1: Correction to RRC test case 8.4.2.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125235 | 1995 | - | GCF Priority u2: Correction to RRC test case 8.4.2.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125272 | 1996 | - | Correction to CA test case 8.2.2.4.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125274 | 1997 | - | GCF Priority U1 - Update test case 6.2.3.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125276 | 1998 | - | Clarification to Local Emergency list provided by the NWK and more | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125317 | 1999 | - | GCF Priority 1 - Correction to PDCP test cases 7.3.4.1 and 7.3.4.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125333 | 2000 | - | GCF Priority 3 - Update of TC 9.2.3.1.27 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125525 | 2001 | - | Addition of new MDT test case 8.6.7.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125526 | 2002 | - | Addition of new MDT test case 8.6.7.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125532 | 2003 | - | Update to GCF P3 TCs 9.2.2.1.3 and 9.2.2.1.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125584 | 2004 | - | GCF Priority G1 - Update test case 13.4.3.5 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125633 | 2005 | - | GCF Priority U2 - Correction to UTRA-EUTRA test case 8.4.2.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125634 | 2006 | - | GCF Priority U2 - Correction to EMM test case 9.2.3.2.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125640 | 2007 | - | GCF WI-151 - Correction to LTE FDD-TDD Inter-mode test case 6.1.1.4a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125657 | 2008 | - | Editorial corrections to some EMM test cases | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125662 | 2009 | - | GCF Priority X - Correction to Rel-10 eICIC test case 8.3.1.20 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125663 | 2010 | - | Removal of technical content in 36.523-1 v10.2.0 and substitution with pointer to the next Release | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125683 | 2011 | - | GCF Priority 4 - Correction to EMM test case 9.2.3.2.13 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125685 | 2012 | - | Split of CA TC 7.1.9.1 to Intra-band contiguous CA and Inter-band CA | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125697 | 2013 | - | GCF Priority 4: Update of EMM test cases 9.2.1.1.1b, 9.2.1.1.15a, 9.2.1.1.16a, 9.2.3.1.15a and 9.2.3.1.18a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125702 | 2014 | - | GCF Priority 1 - Correction to PDCP test case 7.3.3.1, 7.3.3.2, 7.3.3.3 and 7.3.3.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125703 | 2015 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.5.4.1 | 11.0.0 | 11.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2012-12 | RAN#58 | R5-125704 | 2016 | - | GCF Priority 1 - Correction to EMM test case 9.2.3.3.5a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125705 | 2017 | - | GCF Priority 2 - Correction to Idle Mode testcases referring to 36.508 6.4.2.7A-2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125707 | 2018 | - | GCF Priority 2 - Update test case 9.2.2.2.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125708 | 2019 | - | GCF Priority 3 - Correction to EMM test case 9.3.1.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125710 | 2020 | - | GCF Priority 3 - Correction to EMM test case 9.2.2.1.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125711 | 2021 | - | GCF Priority 3 - Update test case 9.2.1.1.24 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125712 | 2022 | - | GCF Priority 3 - update of TC 9.2.1.1.24 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125713 | 2023 | - | GCF Priority 3: Modification of TC 6.1.2.13 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125714 | 2024 | - | GCF priority 3: Modification of TC 8.3.1.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125715 | 2025 | - | GCF priority 3: Modification of TC 8.3.2.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125716 | 2026 | - | GCF Priority 2: Modification of EMM TC 9.2.2.1.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125717 | 2027 | - | GCF priority 2: Modification of TC 8.3.1.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125718 | 2028 | - | GCF priority 2: Modification of TC 8.3.1.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125720 | 2029 | - | GCF Priority 4 - Corrections to Single Frequency EUTRA Idle Mode test cases | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125721 | 2030 | - | GCF Priority 4 - Correction to EUTRA Idle Mode test case 6.1.2.9a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125722 | 2031 | - | Correction of Rel-9 inter-band test case 8.3.1.16 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125723 | 2032 | - | Correction to Rel-9 EUTRA FDD-TDD test case 8.2.4.14a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125724 | 2033 | - | Correction to Rel-9 EUTRA FDD-TDD test case 8.2.4.15a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125725 | 2034 | - | GCF Priority 4: Update of EMM test case 9.2.3.2.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125726 | 2035 | - | GCF Priority 4: Corrections to user PLMN reselection test cases | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125728 | 2036 | - | GCF Priority 4 - Correction to test case 6.3.5 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125729 | 2037 | - | GCF Priority U1 - Update test case 6.2.3.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125730 | 2038 | - | GCF Priority u1 - Correction to preamble in 6.2.2.8/6.2.3.3/6.2.3.3a/6.4.5 test cases | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125731 | 2039 | - | GCF Priority u1: Modification of TC 6.2.3.13 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125732 | 2040 | - | GCF Priority u1: Modification of TC 6.2.3.32 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125733 | 2041 | - | GCF Priority u1 - Update to RRC test case 8.3.2.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125734 | 2042 | - | GCF Priority u1 - Update to RRC test case 8.3.2.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125735 | 2043 | - | GCF priority u1: Modification of TC 8.3.2.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125736 | 2044 | - | GCF priority u1: Modification of TC 8.3.2.4 | 11.0.0 | 11.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2012-12 | RAN#58 | R5-125738 | 2046 | - | GCF Priority u1: Modification of EMM TC 9.2.3.2.1a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125740 | 2047 | - | GCF Priority u1 - Update to SRVCC test cases 13.4.3.1, 13.4.3.2, 13.4.3.4 and 13.4.3.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125741 | 2048 | - | GCF Priority U1 - Update test case 13.4.3.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125742 | 2049 | - | GCF Priority U1 - Update test case 13.4.3.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125743 | 2050 | - | GCF Priority U1 - Update test case 13.4.3.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125744 | 2051 | - | GCF Priority u2 - Update to RRC test case 8.3.3.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125747 | 2052 | - | GCF P4: Update of TC 9.2.1.1.3 to clarify applicability of all types of attach and more | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125748 | 2053 | - | GCF P4: Update of TC 9.2.1.1.4 to clarify applicability of all types of attach and more | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125749 | 2054 | - | GCF priority g1: Modification of TC 8.3.2.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125750 | 2055 | - | GCF priority g2: Modification of TC 8.3.2.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125753 | 2058 | - | GCF Priority m1 - Update of RRC test cases 8.3.2.5 and 8.3.2.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125754 | 2059 | - | GCF Priority i1 - Correction to LTE FDD-TDD Inter-mode test case 13.4.1.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125756 | 2060 | - | Correction to test cases 6.1.2.15, 6.1.2.15a and 6.1.2.15b | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125757 | 2061 | - | Correction to EUTRANFeatureGroupIndicators in EMM test cases | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125758 | 2062 | - | Correction to TS 36.523-1 TC 9.2.3.1.5 "Periodic tracking area update / Accepted" | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125759 | 2063 | - | Correction to Multi-layer test cases 13.1.7,13.1.8,13.1.9,13.1.10 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125761 | 2064 | - | Correction of RSRQ EUTRA-UTRAN 6.2.3.33 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125762 | 2065 | - | Correction of RSRQ EUTRA-UTRAN 8.3.2.3a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125763 | 2066 | - | Update of test case 11.2.11 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125764 | 2067 | - | GCF WI-154 - Correction to IMS Emergency Call test case 11.2.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125765 | 2068 | - | GCF WI-151 - Correction to LTE FDD-TDD Inter-mode test case 8.3.1.13a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125766 | 2069 | - | GCF Priority X - Updates of e1xCsFB TC_13.1.17 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125767 | 2070 | - | Correction of RSRQ EUTRA-UTRAN 6.2.3.3a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125768 | 2071 | - | Correction of RSRQ EUTRA-UTRAN 6.2.3.4a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125769 | 2072 | - | Correction of RSRQ EUTRA-UTRAN 6.2.3.5a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125770 | 2073 | - | GCF Priority 1 - Update of test case 8.5.4.1 to Clarify FGI 33 - 36 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125775 | 2074 | - | Update PWS Rel-9 test case 18.1.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125776 | 2075 | - | Correction to PWS Rel-9 test case 18.1.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125781 | 2076 | - | GCF Priority X - Addition of New Rel-10 H(e)NB test case 6.3.10 | 11.0.0 | 11.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2012-12 | RAN#58 | R5-125782 | 2077 | - | GCF Priority X - Addition of new Rel-10 H(e)NB test case 6.3.12 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125783 | 2078 | - | GCF Priority X - Addition of New Rel-10 H(e)NB test case 6.3.11 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125785 | 2079 | - | Location stimulus clarification for MDT test cases | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125786 | 2080 | - | New E-UTRAN MDT test case 8.6.2.9 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125787 | 2081 | - | New E-UTRAN MDT test case 8.6.4.7 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125788 | 2082 | - | New E-UTRAN MDT test case 8.6.6.4 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125789 | 2083 | - | Update of MDT test cases 8.6.5.1 and 8.6.7.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125790 | 2084 | - | Addition of new TC 7.1.4.22: Correct HARQ process handling / UL MIMO | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125793 | 2085 | - | GCF Priority X - Addition of new test case 13.4.3.7 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125794 | 2086 | - | GCF Priority X - Addition of new test case 13.4.3.8 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125795 | 2087 | - | GCF Priority X - Addition of new test case 13.4.3.9 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125796 | 2088 | - | GCF Priority X - Addition of new test case 13.4.3.10 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125797 | 2089 | - | GCF Priority X - Addition of new test case 13.4.3.11 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125798 | 2090 | - | GCF Priority X - Addition of new test case 13.4.3.12 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-125799 | 2091 | - | GCF Priority X - Addition of new test case 13.4.3.13 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126000 | 2092 | - | Add aSRVCC test case 13.4.3.14 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126001 | 2093 | - | Add aSRVCC test case 13.4.3.16 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126006 | 2094 | - | Splitting of CA test case 7.1.4.19 to Intra-band Contiguous CA and Inter-band CA | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126007 | 2095 | - | Renumbering TC 7.1.4.23 and Splitting it to intra-band contiguous CA and inter-band CA | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126008 | 2096 | - | GCF Priority X - Update of Carrier Aggregation test case 8.4.2.7 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126019 | 2097 | - | GCF Priority U1 - Update test case 6.2.1.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126021 | 2098 | - | GCF Priority 1 - Correction to EUTRA MAC test cases 7.1.7.1.1, 7.1.7.1.2, 7.1.7.1.3, 7.1.7.1.4, 7.1.7.1.5, 7.1.7.1.6 and 7.1.7.2.1 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126022 | 2099 | - | GCF Priority g1: Correction to EUTRA to GERAN HO test case 8.4.3.3 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126023 | 2100 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.3.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126024 | 2101 | - | GCF Priority 3 - Correction to EMM test case 9.3.1.6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126026 | 2102 | - | Correction of RSRQ EUTRA 8.3.1.3a | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126028 | 2103 | - | Correction of RSRQ EUTRA 6.1.2.3a | 11.0.0 | 11.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|-----|--|-------------|-------------|
| 2012-12 | RAN#58 | R5-126029 | 2104 | - | Correction of RSRQ EUTRA 6.1.2.17 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126030 | 2105 | - | Addition of new CA related test case: CA / Correct handling of MAC control information / Buffer Status / UL data arrive in the UE Tx buffer / Extended buffer size | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126067 | 1979 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.3.2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126068 | 2045 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.3.5 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126070 | 2106 | - | GCF Priority 1 - Update of test case 8.5.4.1 to add Carrier Aggregation IEs | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126071 | 2107 | - | Addition of New Carrier Aggregation test case for A5 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126073 | 2108 | - | Addition of New Carrier Aggregation test case for PCell Change SCell no Change | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126074 | 2109 | - | Addition of New Carrier Aggregation test case for Event A6 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126075 | 2110 | - | Addition of New Carrier Aggregation test case for Event A1 and Event A2 | 11.0.0 | 11.1.0 |
| 2012-12 | RAN#58 | R5-126076 | 2111 | - | Addition of New Carrier Aggregation test case for RLF | 11.0.0 | 11.1.0 |
| 2012-12 | GERAN#56 | GP-121233 | 1976 | - | Addition of New Carrier Aggregation test case for RLF | 11.0.0 | 11.1.0 |
| 2012-12 | GERAN#56 | GP-121234 | 1977 | - | Addition of New Carrier Aggregation test case for RLF | 11.1.0 | 11.1.1 |
| 2013-03 | RAN#59 | R5-130079 | 2115 | - | GCF Priority 4 - Correction to EMM tc 9.2.3.2.1c | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130081 | 2116 | - | GCF Priority 3 - Correction to Multi-Layer test case 13.1.3 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130088 | 2117 | - | Update to test case 8.3.1.3a | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130159 | 2118 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.24 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130178 | 2119 | - | GCF Priority u1 - Correction to EMM test case 9.2.3.2.1c | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130207 | 2120 | - | GCF Priority 4 - Correction to RRC test case 8.1.2.6 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130208 | 2121 | - | GCF Priority X - Correction to RRC test case 8.2.4.14 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130209 | 2122 | - | GCF Priority U1 - Correction to EMM test case 9.2.1.2.13 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130212 | 2123 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.3.5 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130312 | 2124 | - | GCF Priority u1 - Update test case 13.4.3.2 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130313 | 2125 | - | Update test case 13.4.3.14 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130314 | 2126 | - | Update test case 13.4.3.16 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130316 | 2127 | - | GCF Priority 3 - Update test case 9.2.3.1.27 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130317 | 2128 | - | GCF Priority 3 - Update test case 9.2.3.1.28 | 11.1.1 | 11.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-03 | RAN#59 | R5-130340 | 2129 | - | Correction of MDT test case 8.6.7.1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130341 | 2130 | - | Addition of new MO SMS test cases 11.1.5 and 11.1.6 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130355 | 2131 | - | GCF Priority g1 - Update to EUTRA Idle Mode test case 6.2.3.1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130356 | 2132 | - | GCF Priority 2 - Correction to EMM test case TC9.4.4 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130357 | 2133 | - | GCF Priority 4 - Correction to Idle Mode test case TC6.2.3.19 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130369 | 2134 | - | Update to test cases 13.4.3.8, 13.4.3.9, 13.4.3.11 and 13.4.3.13 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130454 | 2135 | - | GCF Priority g1 - Update to Inter-RAT measurements test case 8.3.2.5 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130455 | 2136 | - | GCF Priority g2 - Update to Inter-RAT measurements test case 8.3.3.3 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130527 | 2137 | - | Correction to test case 11.1.1 & 11.1.4 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130539 | 2138 | - | Updating of EMM cause of test case 11.2.6 and 11.2.7 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130558 | 2139 | - | GCF Priority 1 - Corrections to MAC TC 7.1.4.10 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130560 | 2140 | - | Corrections to TC 13.4.3.3 "Inter-system mobility / E-UTRA voice to GSM CS voice / SRVCC" | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130562 | 2141 | - | Correction to Table 13.4.3.2.3.3-6: HANDOVER TO UTRAN COMMAND (step 32, Table 13.4.3.2.3.3-5) to include new handover condition defined in TS 36.508 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130586 | 2142 | - | Correction to MDT test case 8.6.3.1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130624 | 2143 | - | Correction to preamble for TC 6.2.3.4a | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130625 | 2144 | - | GCF Priority X - Correction to RSRQ test case 6.1.2.17 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130626 | 2145 | - | Correction to RSRQ test case 6.1.2.18 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130627 | 2146 | - | Correction to RSQR test case 6.2.3.3a | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130628 | 2147 | - | GCF Priority u1 - Correction to EUTRA RRC Test Case 8.4.2.2 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130629 | 2148 | - | GCF Priority u2 - Correction to EUTRA RRC Test Case 8.4.2.4 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130630 | 2149 | - | Update of 8.4.5.4 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130631 | 2150 | - | Update of 8.4.7.3 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130632 | 2151 | - | Update of 8.4.7.4 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130633 | 2152 | - | Update of 8.4.7.5 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130634 | 2153 | - | Update of 8.4.7.6 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-03 | RAN#59 | R5-130635 | 2154 | - | Update of 8.4.7.7 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130636 | 2155 | - | Update of 8.4.7.8 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130637 | 2156 | - | Update of 8.4.7.9 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130639 | 2158 | - | GCF Priority c1 - Correction to title of EUTRA-1xRTT test cases 8.4.7.3 and 8.4.7.4 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130641 | 2159 | - | GCF Priority g1 - Correction to EUTRA RRC Test Cases 8.4.3.2 and 8.4.3.3 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130642 | 2160 | - | GCF Priority 4 - Correction to EMM tc 9.2.3.1.17 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130644 | 2162 | - | GCF Priority 2 - Correction to EMM test case 9.2.3.1.4 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130645 | 2163 | - | GCF Priority U1 - Correction to EMM test case 9.2.3.2.13 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130646 | 2164 | - | GCF Priority U1 - Correction to EMM test case 9.2.1.2.5 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130647 | 2165 | - | GCF Priority 4 - Correction to EMM tc 9.2.3.3.5a | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130649 | 2166 | - | New LTE Rel-9 TC for UE rejection of NAS security mode command with EIA0 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130650 | 2167 | - | GCF Priority 1 - Update test case 9.1.3.1 to test not null and null ciphering algorithms | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130651 | 2168 | - | Correction to GCF P3 EMM test case 9.2.2.1.8 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130652 | 2169 | - | Update of 11.2.8 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130653 | 2170 | - | GCF Priority 3 - Correction to Multi-layer test cases 13.1.x | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130654 | 2171 | - | GCF Priority u1 - Update test case 13.1.2 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130655 | 2172 | - | GCF Priority u1 - Update test case 13.1.2a | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130656 | 2173 | - | GCF Priority u1 - Update test case 13.1.5 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130657 | 2174 | - | GCF Priority g1 - Update test case 13.1.9 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130658 | 2175 | - | Update of 13.1.17 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130659 | 2176 | - | Update of 13.1.18 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130660 | 2177 | - | Update of 13.4.4.1 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130661 | 2178 | - | Update of 13.4.4.2 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130662 | 2179 | - | Update of 13.4.4.4 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130663 | 2180 | - | Update of 13.4.4.5 - Addition of C2K checking parameters | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130664 | 2181 | - | Update of 13.4.4.3 - C2K messages contents for checking parameters | 11.1.1 | 11.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2013-03 | RAN#59 | R5-130665 | 2182 | - | GCF Priority 3 - Correction to EMM test case 9.1.5.1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130669 | 2183 | - | Addition of new Inter-RAT measurement test case for event B1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130697 | 2184 | - | New aSRVCC TC 13_4_3_15 MO call voice-data SRVCC HO cancelled | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130698 | 2185 | - | New aSRVCC TC 13_4_3_17 MT call voice-data SRVCC HO cancelled | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130699 | 2186 | - | Update of eICIC test case 8.3.1.20 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130701 | 2187 | - | Update of Carrier Aggregation test case 8.2.4.19.1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130703 | 2188 | - | Editorial Corrections to Carrier Aggregation Radio Resource Reconfiguration test cases | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130704 | 2189 | - | Modification on CA radio resource reconfiguration related test cases | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130705 | 2190 | - | Editorial Corrections to Carrier Aggregation Handover Test cases | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130707 | 2191 | - | Modification of CA TC 8.2.4.17 and 8.2.4.18 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130720 | 2192 | - | New NIMTC test case 6.1.1.7 PLMN selection / Periodic reselection / MinimumPeriodicSearchTimer | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130722 | 2193 | - | New NIMTC test case 9.2.1.1.27 Attach / Abnormal case / Network reject with Extended Wait Timer | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130723 | 2194 | - | New NIMTC test case 10.5.4 UE requested PDN connectivity not accepted / Network reject with Extended Wait Timer | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130729 | 2195 | - | Addition of new MDT test case 8.6.3.2 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130730 | 2196 | - | Addition of New MDT test case for Logged MDT | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130733 | 2198 | - | Addition of new test case 8.3.1.bb | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130734 | 2199 | - | Addition of new test case 8.3.1.cc | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130735 | 2200 | - | Addition of new test case 8.3.1.dd | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130739 | 2202 | - | GCF Priority 3 - Corrections to EMM TC 9.2.1.1.12, 9.2.3.1.12, 9.2.3.1.18 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130740 | 2203 | - | GCF Priority U1 - Correction to EMM test case 9.2.1.2.8 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130741 | 2204 | - | GCF Priority g1 - Update test case 13.1.8 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130742 | 2205 | - | GCF Priority g1 - Update test case 13.1.12 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130746 | 2206 | - | GCF Priority i1 - Correction to LTE FDD-TDD Inter-mode test case 8.3.1.15a | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130747 | 2207 | - | GCF Priority i1 - Correction to LTE FDD-TDD Inter-mode test case 8.3.1.16a | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130748 | 2208 | - | GCF Priority 1 - Correction to EUTRA RRC test case 8.5.4.1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130752 | 2209 | - | Modification of CA TC 8.2.4.19 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130753 | 2210 | - | Modification of CA TC 8.2.4.20 | 11.1.1 | 11.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|------------|-----------|------|-----|--|-------------|-------------|
| 2013-03 | RAN#59 | R5-130754 | 2211 | - | Modification of CA TC 8.2.4.21 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130755 | 2212 | - | Modification of CA TCs 8.3.1.17 and 8.3.1.18 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130756 | 2213 | - | Modification of CA TC 8.3.1.22 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130757 | 2214 | - | Modification of CA TC 8.4.2.7 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130758 | 2215 | - | Update of Carrier Aggregation test case 8.2.4.20.1 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130762 | 2216 | - | GCF Priority 3 – Corrections to EMM tcs 9.2.3.2.1a and 9.2.3.3.4 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130778 | 2161 | - | GCF Priority 3 - Update test case 9.3.1.3 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130784 | 2217 | - | GCF Priority ee1 - Corrections to Emergency Call over IMS test cases | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130785 | 2218 | - | GCF Priority c1 - Correction to EUTRA-HRPD test case 8.3.2.8 | 11.1.1 | 11.2.0 |
| 2013-03 | RAN#59 | R5-130786 | 2219 | - | GCF Priority c1 - Correction to EUTRA-1xRTT test case 8.3.2.10 | 11.1.1 | 11.2.0 |
| 2013-03 | GERAN3 #57 | GP-130307 | 2112 | - | GCF Priority g1 - Correction to EUTRA Idle Mode test case 6.2.3.23 | 11.1.1 | 11.2.0 |
| 2013-06 | RAN#60 | GP-130357 | 2220 | - | CR 36.523-1-2220 GCF Priority 1 - Correction to EUTRA Idle Mode Test Case 6.2.3.15 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | GP-130358 | 2221 | - | CR 36.523-1-2221 GCF priority g1 - Correction to Idle Mode test case 6.2.1.6 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | GP-130371 | 2222 | - | CR 36.523-1-2222 Removal of TC 6.2.3.22 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131066 | 2224 | - | Update of CDMA2000 specification references: Clause 2 of TS 36.523-1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131071 | 2225 | - | Update of CDMA2000 specification references for UE Capability Transfer | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131072 | 2226 | - | Update of CDMA2000 specification references for Inter-RAT Handover | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131073 | 2227 | - | Update of CDMA2000 specification references of Inter-system session management | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131077 | 2228 | - | Update of LTE MDT test case 8.6.3.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131087 | 2229 | - | Editorial Remove square bracket in TC 8.3.2.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131088 | 2230 | - | Editorial Remove square bracket and FFS in TCs 13.4.2.2, 13.4.3.3, 13.4.3.5 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131091 | 2231 | - | Editorial TC 12.1.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131128 | 2232 | - | Correction of description on 36523-3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131142 | 2233 | - | GCF Priority X - Correction to Idle Mode test case 6.3.11 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131143 | 2234 | - | GCF Priority X - Correction to Idle Mode test case 6.3.10 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131169 | 2235 | - | Update to test function Update UE Location Information | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131215 | 2236 | - | GCF Priority u1 - Update to EMM test case 9.2.3.2.9 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131255 | 2237 | - | GCF Priority 3 - Correction to EUTRA MAC test case 7.1.4.2 | 11.2.0 | 11.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2013-06 | RAN#60 | R5-131294 | 2238 | - | Update test case 13.1.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131295 | 2239 | - | Update test case 13.1.7 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131296 | 2240 | - | Update test case 13.1.10 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131298 | 2241 | - | Update test case 13.1.15 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131299 | 2242 | - | Update test case 13.1.11 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131300 | 2243 | - | Update test case 13.1.13 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131301 | 2244 | - | Update test case 13.1.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131302 | 2245 | - | Update test case 13.1.16 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131314 | 2246 | - | Correction to RSRQ test case 8.3.2.3a | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131316 | 2247 | - | Correction to EUTRA-HRPD test case 8.3.3.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131317 | 2248 | - | Correction to EMM test case 9.2.1.2.8 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131318 | 2249 | - | Correction to EMM test case 9.2.2.1.8 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131324 | 2250 | - | Correction to CA test cases 8.3.1.18.1 and 8.3.1.18.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131366 | 2251 | - | Update test case 13.4.2.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131367 | 2252 | - | Update test case 13.4.3.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131368 | 2253 | - | Update test case 13.4.3.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131369 | 2254 | - | Update test case 13.4.3.7 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131370 | 2255 | - | Update test case 13.4.3.8 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131371 | 2256 | - | Update test case 13.4.3.9 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131372 | 2257 | - | Update test case 13.4.3.10 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131373 | 2258 | - | Update test case 13.4.3.11 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131375 | 2259 | - | Update test case 13.4.3.12 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131376 | 2260 | - | Update test case 13.4.3.13 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131377 | 2261 | - | Update test case 13.4.3.14 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131378 | 2262 | - | Update test case 13.4.3.16 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131441 | 2263 | - | Correction to test case 8.3.1.26 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131470 | 2264 | - | Update IMS emergency call pre-test condition | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131480 | 2265 | - | Adding a new TC 9.2.3.1.5a for NIMTC conformance testing | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131485 | 2266 | - | Splitting TC 11.2.8 in two TCs one for UTRA/GERAN and one for 1xRTT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131496 | 2367 | - | Correction to generic MO CSFB procedures | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131504 | 2267 | - | Editorial update of test case 13.1.5 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131557 | 2268 | - | Update of 8.4.7.10 - Addition of C2K checking parameters | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131626 | 2269 | - | Addition of new test case for PLMN change in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131633 | 2270 | - | Addition of new test case for EventB2 reporting in eMDT | 11.2.0 | 11.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-06 | RAN#60 | R5-131635 | 2271 | - | Addition of new test case for RACH reporting in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131675 | 2272 | - | Correction to EMM Test Case 9.2.3.1.19 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131693 | 2273 | - | GCF Priority 2 / 3 - Editorial corrections to EMM test cases 9.2.1.1.1a and 9.2.3.1.17 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131708 | 2274 | - | GCF Priority 2 - Corrections to SMS over SGs test cases | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131713 | 2275 | - | Editorial correction to TC 9.2.1.1.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131733 | 2276 | - | Correction to LTE-A test case 8.2.2.5.1/8.2.2.5.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131810 | 2277 | - | CSG reselection requirements correction in TC 6.3.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131811 | 2278 | - | CSG reselection requirements correction in TC 6.3.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131812 | 2279 | - | CSG reselection requirements correction in TC 6.3.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131813 | 2280 | - | CSG reselection requirements correction in TC 6.3.7 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131814 | 2281 | - | CSG reselection requirements correction in TC 6.3.8 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131815 | 2282 | - | Correction to EUTRA Idle mode Test case 6.1.2.13 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131816 | 2283 | - | Correction to EUTRA Idle mode test case 6.2.3.1a | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131817 | 2284 | - | Correction to MAC test case 7.1.1.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131818 | 2285 | - | Update of test case 8.5.4.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131819 | 2286 | - | Correction to EUTRA-1xRTT test case 8.3.2.10 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131820 | 2287 | - | Correction to EUTRA-HRPD test case 8.3.2.8 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131821 | 2288 | - | New TC 8.3.4.5 Inter-frequency E-UTRAN FDD - FDD / CSG Proximity Indication | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131822 | 2289 | - | Addition of new test case 8.3.1.23 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131823 | 2290 | - | Addition of new test case 8.3.1.27 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131824 | 2291 | - | GCF Priority 1 - Correction to EUTRA RRC Test Case 8.3.2.2. | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131825 | 2292 | - | GCF Priority x - Correction to EUTRA test case 8.3.1.13 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131826 | 2293 | - | Editorial Remove square bracket in TC 8.4.3.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131827 | 2294 | - | Update to test case 9.2.1.2.3 and 9.2.3.2.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131828 | 2295 | - | GCF Priority 3 - Corrections to EMM TC 9.2.1.1.12, 9.2.3.1.12, 9.2.3.1.18 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131829 | 2296 | - | Correction to EMM test case 9.2.3.2.1a | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131830 | 2297 | - | Correction to EMM test case 9.2.3.3.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131831 | 2298 | - | GCF Priority 2 - Correction to EUTRA EMM Test Case 9.2.3.2.3 | 11.2.0 | 11.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-06 | RAN#60 | R5-131832 | 2299 | - | GCF Priority 2: Extending the scope of TC 9.1.4.2 to verify IMEISV | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131833 | 2300 | - | GCF G2: Corrections to EMM test case 9.2.3.4.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131834 | 2301 | - | GCF Priority U1: Correction to EMM test case 9.2.3.3.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131835 | 2302 | - | 9.2.3.1.8 'Load Balancing TAU' does not test the main requirement | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131836 | 2303 | - | Correction to EMM test case 9.1.3.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131837 | 2304 | - | Update to test case 11.2.6 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131838 | 2305 | - | Update test case 11.2.11 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131839 | 2306 | - | Update of test case 8.3.3.5 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131840 | 2307 | - | Correction to EUTRA Multi-layer Test Case 13.3.1.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131841 | 2308 | - | Corrections to eMBMS test case 17.1.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131842 | 2309 | - | Corrections to eMBMS test case 17.1.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131843 | 2310 | - | Corrections to eMBMS test case 17.1.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131844 | 2311 | - | Corrections to eMBMS test case 17.1.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131845 | 2312 | - | Corrections to eMBMS test case 17.1.5 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131846 | 2313 | - | Corrections to eMBMS test case 17.2.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131847 | 2314 | - | Corrections to eMBMS test case 17.2.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131848 | 2315 | - | Corrections to eMBMS test case 17.2.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131849 | 2316 | - | Corrections to eMBMS test case 17.2.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131850 | 2317 | - | Correction to PWS(CMAS) test case 18.1.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131851 | 2318 | - | Corrections to eMBMS test case 17.3.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131852 | 2319 | - | Corrections to eMBMS test case 17.3.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131853 | 2320 | - | Correction to E-UTRA MDT test case 8.6.2.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131854 | 2321 | - | Correction to E-UTRA MDT test case 8.6.2.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131855 | 2322 | - | Correction to E-UTRA MDT test case 8.6.2.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131856 | 2323 | - | Correction to E-UTRA MDT test case 8.6.2.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131857 | 2324 | - | Correction to E-UTRA MDT test case 8.6.2.5 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131858 | 2325 | - | Correction to E-UTRA MDT test case 8.6.2.8 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131859 | 2326 | - | Correction to E-UTRA MDT test case 8.6.3.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131860 | 2327 | - | Correction to E-UTRA MDT test case 8.6.3.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131861 | 2328 | - | Correction to E-UTRA MDT test case 8.6.3.3 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131879 | 2330 | - | Correction to MAC LTE CA test case 7.1.3.11 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131880 | 2331 | - | Correction to MAC LTE CA test case 7.1.4.18 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131881 | 2332 | - | Correction to MAC LTE CA test case 7.1.9.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131882 | 2333 | - | Correction to MAC LTE CA test case 7.1.4.20.1 | 11.2.0 | 11.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-06 | RAN#60 | R5-131883 | 2334 | - | Correction to MAC LTE CA test case 7.1.4.19.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131886 | 2335 | - | Update of eICIC test case 8.3.1.20 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131892 | 2336 | - | Adding a new TC 9.2.1.1.2a for NIMTC conformance testing | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131894 | 2337 | - | Addition of new test case for TDD additional special subframe configuration with CRS based transmission scheme | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131895 | 2338 | - | Addition of new test case for TDD additional special subframe configuration with UE-specific reference signals based transmission scheme | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131898 | 2339 | - | Correction to EUTRA EMM Test Case 9.2.3.2.1b | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-131899 | 2340 | - | Correction to EUTRA EMM Test Case 9.2.1.2.1b | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132003 | 2341 | - | Update to test case 8.2.4.17.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132005 | 2342 | - | Correction to RRC test case 8.2.4.14 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132018 | 2343 | - | New Carrier Aggregation test case on MIMO | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132019 | 2344 | - | Correction to usage of cells in Inter-band LTE CA test case 8.2.4.19.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132020 | 2345 | - | Correction to usage of cells in Inter-band LTE CA test case 8.2.4.20.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132021 | 2346 | - | Correction to usage of cells in Inter-band LTE CA test case 8.2.4.21.2 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132022 | 2347 | - | Addition of SCell configuration type to CA test cases | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132024 | 2348 | - | Correction to eICIC test case 8.3.1.19 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132032 | 2349 | - | Correction to idle mode test case 6.1.2.17 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132033 | 2350 | - | Correction to LTE FDD-TDD Inter-mode test case 8.1.3.12a | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132034 | 2351 | - | GCF Priority 1 - Update of EUTRA RRC test case 8.5.4.1 to handle Rel-11 IEs | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132035 | 2352 | - | Correction to EMM test case 9.2.3.3.4 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132042 | 2353 | - | GCF Priority 2 - Corrections to ESM test case 10.3.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132043 | 2354 | - | GCF Priority 2 - Corrections to ESM test case 10.9.1 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132044 | 2355 | - | Addition of new test case for T300 expiry in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132045 | 2356 | - | Addition of new test case about TAC and PLMN id in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132046 | 2357 | - | Addition of new test case about PLMN list in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132047 | 2358 | - | Addition of new test case about Location information for eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132048 | 2359 | - | Addition of new test case for inter-frequency measurements report in eMDT | 11.2.0 | 11.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2013-06 | RAN#60 | R5-132049 | 2360 | - | Addition of new test case for inter-RAT measurements report in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132054 | 2361 | - | Addition of new test case for reporting reestablishment in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132056 | 2362 | - | Addition of new test case for EventA2 reporting in eMDT | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132058 | 2363 | - | GCF Priority X - Correction to Idle Mode test case 6.3.12 | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132067 | 2364 | - | GCF Priority ee1 - Update of Emergency Call over IMS test cases | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132069 | 2365 | - | GCF Priority i1 - Correction to LTE FDD-TDD Inter-mode test case 6.1.1.4a | 11.2.0 | 11.3.0 |
| 2013-06 | RAN#60 | R5-132084 | 2366 | - | Update of TC 11.2.7 to consider document C1-131732 | 11.2.0 | 11.3.0 |
| 2013-09 | RAN#61 | R5-133081 | 2368 | - | Correction to CA test case 8.2.4.21.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133082 | 2369 | - | GCF Priority 3 - Correction to EMM test case 9.2.1.1.11 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133093 | 2370 | - | Correction to EMM test case 9.2.3.4.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133114 | 2371 | - | Clarification for handling of differences between conformance requirements in different releases of core specifications | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133128 | 2372 | - | Correction to CA Test Case 8.2.2.5.1 and 8.2.2.5.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133145 | 2373 | - | Correction to EMM test case 9.2.1.1.1b | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133167 | 2374 | - | Editorial update of TC 9.2.3.3.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133184 | 2375 | - | Update of text for Update UE Location Information | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133322 | 2376 | - | Addition of new eMDT test case 8.6.7.4 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133323 | 2377 | - | Addition of new eMDT test case 8.6.4.8 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133324 | 2378 | - | Addition of new eMDT test case 8.6.4.9 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133325 | 2379 | - | Addition of new eMDT test case 8.6.4.10 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133326 | 2380 | - | Addition of new eMDT test case 8.6.8.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133327 | 2381 | - | Addition of new eMDT test case 8.6.8.5 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133328 | 2382 | - | Addition of new eMDT test case 8.6.9.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133342 | 2383 | - | Correction to test case 8.4.3.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133362 | 2384 | - | Correction of ESM test cases 10.3.1 and 10.9.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133483 | 2385 | - | GCF Priority 4: Modification to TC 6.1.2.12 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133486 | 2386 | - | Modification to TC 8.3.1.13a | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133510 | 2387 | - | Update to test case 9.2.1.1.18 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133585 | 2388 | - | GCF Priority 3 - Correction to 6.1.2.9a test cases | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133586 | 2389 | - | Define new TC 6.1.2.19 for Intra-frequency cell reselection with MFBI support | 11.3.0 | 11.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2013-09 | RAN#61 | R5-133587 | 2390 | - | Define new TC 6.1.2.21 for Inter-band cell reselection with MFBI support | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133589 | 2391 | - | GCF priority 4 - Correction to EUTRA RRC test cases 8.2.1.5 and 8.2.1.6 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133590 | 2392 | - | Correction to FDD-TDD test case 8.3.1.15a | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133591 | 2393 | - | GCF Priority 4 - Corrections to EUTRA-GERAN Test Case 8.4.3.3 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133592 | 2394 | - | GCF Priority 3 - Correction to test case 9.2.3.1.18a | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133593 | 2395 | - | GCF Priority 2 - Correction to test case 9.2.3.3.6 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133594 | 2396 | - | Correction to EMM TC 9.2.2.1.3 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133595 | 2397 | - | GCF Priority 2 - Correction to test case 9.2.1.2.4 and 9.2.3.2.4 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133596 | 2398 | - | Correction to EUTRA test case 9.2.1.2.1b | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133597 | 2399 | - | Correction to EMM Test Case 9.2.3.1.6 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133598 | 2400 | - | Clarification of EMM Test case 9.2.2.2.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133599 | 2401 | - | Add test case Attach / Success / IMS | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133600 | 2402 | - | GCF Priority U1 – Correction to EMM test case 9.2.1.2.13 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133602 | 2403 | - | Add test case EPS bearer context deactivation / Re-establishment | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133603 | 2404 | - | Corrections to allow both ISIM or USIM to be used in test cases using IMS | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133604 | 2405 | - | Correction to SRVCC test case 13.4.3.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133605 | 2406 | - | Correction to eMBMS test case 17.3.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133606 | 2407 | - | Correction to eMBMS test case 17.3.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133610 | 2408 | - | GCF Priority 4: Modification to TC 6.1.2.14 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133611 | 2409 | - | Modification to TC 8.3.1.13 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133613 | 2410 | - | Update of test case 8.3.3.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133617 | 2412 | - | Correction to CA Test Case 8.3.1.22.1 and 8.3.1.22.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133618 | 2413 | - | Correction to CA Test Case 8.3.1.17.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133619 | 2414 | - | Correction to CA Test Case 8.2.2.3.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133620 | 2415 | - | Correction to CA Test Case 8.2.4.21.1 and 8.2.4.21.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133621 | 2416 | - | Update of CA Test Case 8.2.2.3.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133622 | 2417 | - | Correction to CA test case 8.5.1.7 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133623 | 2418 | - | Correction to EUTRA CA RRC test cases 8.2.4.17.1 and 8.2.4.17.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133624 | 2419 | - | Correction to EUTRA CA RRC test cases 8.2.4.19.1 and 8.2.4.19.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133646 | 2420 | - | Update of Test Case 8.3.1.20 | 11.3.0 | 11.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-09 | RAN#61 | R5-133648 | 2422 | - | Correction of eICIC TC 8.3.1.19 & 8.3.1.20 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133660 | 2423 | - | Addition of new eMDT test case 8.6.9.3 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133663 | 2424 | - | New eMBMS service continuity test case 17.4.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133664 | 2425 | - | New eMBMS service continuity test case 17.4.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133665 | 2426 | - | New TC 17.4.7 MBMS Interest Indication after Radio Link Failure | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133666 | 2427 | - | Introduction of New eMBMS Service Continuity Improvements test case 17.4.4 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133667 | 2428 | - | Addition of new TC 8.6.2.11 Logged MDT / Logging and reporting / Reporting at intra LTE handover / PLMN list | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133668 | 2429 | - | Addition of new TC 8.6.2.12 Logged MDT / Logging and reporting / Reporting at RRC connection re-establishment / PLMN list | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133669 | 2430 | - | Addition of new TC 8.6.3.4 Logged MDT / Logging and reporting / Reporting at UTRAN Inter-RAT handover / PLMN list | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133670 | 2431 | - | Addition of new TC 8.6.6.5 Handover Failure logging / Logging and reporting / Reporting at RRC connection establishment / PLMN list | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133671 | 2432 | - | Addition of new TC 8.6.6.6 Handover Failure logging / Logging and reporting / Reporting at intra LTE handover / PLMN list | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133672 | 2433 | - | Addition of new TC 8.6.6.7 Handover Failure logging / Logging and reporting / Reporting at RRC connection re-establishment / PLMN list | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133673 | 2434 | - | Addition of new TC 8.6.9.4 Connection Establishment Failure logging / Logging and reporting / Reporting of CDMA2000 Inter-RAT measurements | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133675 | 2435 | - | Introduction of New LTE RAN Enhancements for Diverse Data Applications test case 8.2.2.6.2 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133676 | 2436 | - | New test case 8.2.2.6.1 RRC connection reconfiguration/ UE Assistance Information/power preference indication setup and release | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133677 | 2437 | - | New test case 8.2.2.6.3 RRC connection reconfiguration/ UE Assistance Information/T340 running | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133679 | 2438 | - | Addition of new TC 7.1.3.X Correct handling of DL assignment / Dynamic case / EPDCCH | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133680 | 2439 | - | Addition of new TC 7.1.3.Y Correct handling of DL assignment / Semi-persistent case / EPDCCH | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133692 | 2441 | - | Define new TC 6.1.2.20 for Inter-frequency cell reselection with MFBI support. | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133695 | 2443 | - | Addition of new MFBI test case: 8.2.4.22 RRC connection reconfiguration / Handover / MFBI / target cell broadcasting information disregarded by the UE | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133696 | 2444 | - | Update of Emergency Call over IMS test case 11.2.7 | 11.3.0 | 11.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-09 | RAN#61 | R5-133699 | 2445 | - | New eMBMS service continuity test case 17.4.6 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133700 | 2446 | - | New eMBMS service continuity test case 17.4.8 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133707 | 2447 | - | Addition of new Rel-10 eICIC test case 8.3.1.21 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133723 | 2440 | - | Update of TC 6.2.1.1 Inter-RAT PLMN Selection for OPLMN Automatic mode | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133725 | 2448 | - | Correction of EUTRA RRC test case 8.5.4.1 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133730 | 2421 | - | Addition of new eICIC Test Case 8.3.1.27 | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133732 | 2442 | - | Update of Test Case 8.2.4.13a | 11.3.0 | 11.4.0 |
| 2013-09 | RAN#61 | R5-133733 | 2411 | - | Correction to CA Test Case 8.3.1.18.1 and 8.3.1.18.2 | 11.3.0 | 11.4.0 |
| 2013-12 | RAN#62 | R5-134077 | 2449 | - | Correction to MDT test case 8.6.4.3 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134079 | 2450 | - | Correction to SRVCC test cases | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134081 | 2451 | - | Update of E-UTRA Inter-RAT test case 6.2.1.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134082 | 2452 | - | Correction to E-UTRA Idle Mode Test Case 6.1.1.4a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134083 | 2453 | - | Correction to E-UTRA MAC test case 7.1.4.7a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134084 | 2454 | - | Correction to LTE UL MIMO Test Case 7.1.4.22 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134110 | 2455 | - | Correction to test case 8.1.3.12 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134111 | 2456 | - | Introduction of new test case 8.1.3.12b | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134229 | 2457 | - | Correction to IRAT RRC test case 8.3.2.5 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134239 | 2458 | - | Corrections to eMBMS SC test case 17.4.6 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134241 | 2459 | - | Corrections to eMBMS SC test case 17.4.8 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134248 | 2460 | - | Correction to EUTRA IRAT RRC test case 8.3.2.11 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134259 | 2461 | - | Update of EMM Test Case 9.2.3.3.5a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134262 | 2462 | - | GCF Priority 2 - Removal of EMM test case 9.2.3.3.6 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134318 | 2463 | - | GCF P2 - Update of TC 9.2.2.2.2 verdicts message content PRD13 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134355 | 2464 | - | Update of RRC Measurement Test Case 8.3.1.12a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134358 | 2465 | - | Correction to EPS mobility management test cases 9.2.3.1.13, 9.2.3.1.14, 9.2.3.2.9, 9.2.3.2.10, 9.3.1.7, 9.3.1.7a and 9.3.1.17 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134398 | 2466 | - | Corrections to EUTRA Idle Mode test case 6.1.1.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134399 | 2467 | - | Corrections to EUTRA Idle Mode test case 6.1.1.2a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134407 | 2468 | - | Update Test Purpose of TC 6.1.1.7 PLMN selection Periodic reselection MinimumPeriodicSearchTimer | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134450 | 2469 | - | Correction to LTE-A CA RRC test case 8.2.2.3.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134457 | 2470 | - | Correction to EUTRA RRC test case 8.3.1.3a | 11.4.0 | 11.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-12 | RAN#62 | R5-134506 | 2471 | - | Correction of eMDT Test Cases 8.6.6.5, 8.6.6.6 and 8.6.6.7 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134523 | 2472 | - | Correction of eMDT test case 8.6.8.6 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134561 | 2473 | - | Correction to EMM test case 9.2.3.2.1b | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134564 | 2474 | - | Correction to EMM test case 9.2.3.3.2, 9.2.3.3.3 and 9.2.3.3.5 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134565 | 2475 | - | Correction of CSG Test cases 6.3.4, 6.3.6, 6.4.1, 6.4.2, 6.4.3, 6.4.4, 6.4.5, 6.4.6, 6.4.7, 9.2.1.1.18, 9.2.1.2.14, 9.2.3.1.20, 9.2.3.2.16, 9.3.1.18 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134569 | 2476 | - | GCF Priority 3 - Correction to EMM test case 9.2.3.1.12 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134638 | 2477 | - | Correction to EUTRA NIMTC test cases 9.2.3.1.5a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134679 | 2478 | - | Update of CA Test Case 8.2.4.21.1 and 8.2.4.21.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134682 | 2479 | - | Correction to E-UTRA Inter-RAT ANR for UTRAN test case 8.7.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134731 | 2480 | - | Corrections to Idle mode operations TC 6.1.1.7 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134732 | 2481 | - | GCF Priority 3 Correction to test case 6.1.2.13 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134735 | 2483 | - | Correction to E-UTRA Idle Mode Test Cases 6.1.1.3, 6.1.1.3a and 6.1.1.3b | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134736 | 2484 | - | Correction to LTE-UTRA test case 6.2.3.33 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134737 | 2485 | - | Correction to LTE-A Carrier Aggregation RRC test case 8.2.4.21.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134738 | 2486 | - | Correction of Rel-9 EUTRA RRC Measurement test case 8.3.1.26 and 8.3.1.27 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134739 | 2487 | - | Corrections to test cases 9.2.1.2.1c and 9.2.3.2.1b | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134742 | 2488 | - | Correction to GCF P3 EMM test case 9.2.3.1.17 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134743 | 2489 | - | GCF P3 - Update of TC 9.2.2.1.3 TP message sequence message contents PRD 13 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134744 | 2490 | - | Correction to test case 9.2.1.2.8 and 9.2.3.2.8 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134745 | 2491 | - | GCF Priority U1 - Correction to EMM test case 9.2.1.2.13 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134746 | 2492 | - | Correction to EMM test case 9.2.3.1.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134747 | 2493 | - | Correction to EUTRA NIMTC test cases 9.2.1.1.2a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134748 | 2494 | - | Correction to EUTRA NIMTC test cases 9.2.1.1.27 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134749 | 2495 | - | New test case: 9.2.1.1.7b Attach / Success / native GUMMEI | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134750 | 2496 | - | Addition of new test case: 9.2.3.1.20a Normal tracking area update / Rejected / Congestion | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134751 | 2497 | - | Correction to E-UTRA ESM test case 10.8.7 | 11.4.0 | 11.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-12 | RAN#62 | R5-134752 | 2498 | - | Correction of E-UTRA RRC Radio Link Failure Test Case 8.5.1.3 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134753 | 2499 | - | Correction to EUTRA NIMTC test cases 10.5.4 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134754 | 2500 | - | Correction to E-UTRA Multi-Layer test case 13.1.2a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134755 | 2501 | - | Correction to SRVCC test case 13.4.3.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134756 | 2502 | - | Addition of test case 'Inter-system mobility / E-UTRA voice to GSM CS voice / aSRVCC / MO call' | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134757 | 2503 | - | Addition of test case 'Inter-system mobility / E-UTRA voice to GSM CS voice / aSRVCC / MT call' | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134758 | 2504 | - | Addition of test case "Inter-system mobility / E-UTRA voice to GSM CS voice / aSRVCC / MO call / SRVCC HO failure" | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134759 | 2505 | - | Addition of test case "Inter-system mobility / E-UTRA voice to GSM CS voice / aSRVCC / MT call / SRVCC HO failure" | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134760 | 2506 | - | Correction to E-UTRA MDT test case 8.6.2.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134761 | 2507 | - | Correction to E-UTRA MDT test case 8.6.2.5 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134762 | 2508 | - | Correction of eMBMS test case 17.1.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134764 | 2509 | - | Correction of eMBMS test case 17.1.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134766 | 2510 | - | Correction of eMBMS test case 17.1.3 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134768 | 2511 | - | Correction of eMBMS test case 17.1.4 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134769 | 2512 | - | Correction of eMBMS test case 17.1.5 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134771 | 2514 | - | Correction to E-UTRA MDT Test Case 8.6.4.8 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134775 | 2515 | - | Correction of IMS Emergency call over EPS test case 11.2.6 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134776 | 2516 | - | Corrections to eMBMS rel9 test case 17.2.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134777 | 2517 | - | Corrections to eMBMS rel9 test case 17.2.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134778 | 2518 | - | Corrections to eMBMS rel9 test case 17.2.3 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134779 | 2519 | - | Corrections to eMBMS rel9 test case 17.2.4 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134780 | 2520 | - | Corrections to eMBMS rel10 test case 17.3.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134781 | 2521 | - | Corrections to eMBMS rel10 test case 17.3.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134782 | 2522 | - | Update of CA Measurement Test Cases 8.3.1.18.1 and 8.3.1.18.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134788 | 2523 | - | Addition of new CA TC 7.1.2.11 CA / Maintenance of uplink time alignment / Multiple TA | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134914 | 2524 | - | Corrections to Rel-10 eICIC test case 8.3.1.20 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134932 | 2525 | - | Optimise UTRA test frequency allocation in 8.6.3.4 and 8.6.7.4 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134933 | 2526 | - | Addition of eMDT test case 8.6.5.1a | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134934 | 2527 | - | Addition of eMDT test case 8.6.5.4 | 11.4.0 | 11.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2013-12 | RAN#62 | R5-134935 | 2528 | - | correction to 36.523-1 TC 8.6.7.4 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134936 | 2529 | - | Correction of eMDT conformance requirement | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134937 | 2530 | - | Corrections to eMBMS SC test case 17.4.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134938 | 2531 | - | Corrections to eMBMS SC test case 17.4.2 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134939 | 2532 | - | Corrections to eMBMS SC test case 17.4.4 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134940 | 2533 | - | Corrections to eMBMS SC test case 17.4.7 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134941 | 2534 | - | New eMBMS service continuity test case 17.4.3 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134942 | 2535 | - | New eMBMS Service Continuity Improvements test case 17.4.5 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134945 | 2536 | - | New SIMTC test case 8.1.1.7 RRC / Paging / EAB active | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134946 | 2537 | - | New SIMTC test case 9.2.3.1.8a Normal tracking area update / low priority override | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134947 | 2538 | - | New SIMTC test case 10.5.1a Dedicated EPS bearer context activation / Dual priority / T3396 override | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134948 | 2539 | - | New SIMTC test case 10.8.8 UE requested bearer resource modification / Dual priority / low priority override | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134950 | 2540 | - | Add test case 6.2.4.1 for inter-RAT cell reselection | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134951 | 2541 | - | Add test case 6.2.4.3 for inter-RAT cell reselection | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134953 | 2542 | - | GCF Priority 4 - Correction to Single Frequency EMM test cases | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135001 | 2546 | - | Correction of IMS Emergency call over EPS test case 11.2.7 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135005 | 2513 | - | Removal of TC 6.3.10, 6.3.11, 6.3.12 from TS 36.523-1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135008 | 2547 | - | Addition of new CA TC 7.1.2.10 CA / Random access procedure / Scell | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135010 | 2548 | - | Addition of new CA TC 8.2.2.6 CA / RRC connection reconfiguration / sTAG addition/modification/release / Success | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135024 | 2550 | - | Update to Test Case 9.2.3.1.6 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135028 | 2554 | - | Update to Test Case 9.2.3.3.1 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135071 | 2482 | - | Correction of GCF WI-154 IMS Emergency Call over EPS test case 11.2.4 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135073 | 2549 | - | Update to Test Case 9.2.2.1.10 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135074 | 2551 | - | Update to Test Case 6.2.3.13 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135075 | 2552 | - | Update to Test Case 6.2.3.31 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-135076 | 2553 | - | Update to test case 6.2.3.21 | 11.4.0 | 11.5.0 |
| 2013-12 | RAN#62 | R5-134963 | 2543 | - | Addition of new test case 13.4.3.18 | 11.5.0 | 12.0.0 |
| 2013-12 | RAN#62 | R5-134964 | 2544 | - | Addition of new test case 13.4.3.19 | 11.5.0 | 12.0.0 |
| 2013-12 | RAN#62 | R5-134965 | 2545 | - | Addition of new bSRVCC test case 13.4.3.20 | 11.5.0 | 12.0.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2014-03 | RAN#63 | R5-140073 | 2555 | - | New SIMTC TC 9.2.3.2.4a Combined tracking area update - Successful for EPS services only - Congestion | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140074 | 2556 | - | Adding normative reference for 3GPP TS 24.368 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140141 | 2558 | - | Correction to E-UTRA EMM test case 9.2.3.2.1b | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140181 | 2559 | - | Addition of test case ' Inter-system mobility / E-UTRA PS voice to GSM CS voice / bSRVCC / MO call / SRVCC HO cancelled' | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140182 | 2560 | - | Addition of test case ' Inter-system mobility / E-UTRA voice to GSM CS voice / bSRVCC / MO call / SRVCC HO failure' | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140344 | 2561 | - | Correction to GCF WI-162 LTE-A Carrier Aggregation Test Case 8.3.1.22.1 and 8.3.1.22.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140419 | 2562 | - | Correction to GCF U1 EMM TC 9.2.3.3.4 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140449 | 2563 | - | New eMBMS service continuity inter-band test case 17.4.2a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140450 | 2564 | - | New eMBMS service continuity inter-band test case 17.4.3a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140473 | 2565 | - | Update to Test Case 9.2.2.1.10 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140482 | 2566 | - | Update to Test Case 6.2.3.31 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140519 | 2567 | - | Update of 1xCS fallback Test Case 13.1.18 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140522 | 2568 | - | Correction to eMBMS test case 17.2.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140529 | 2569 | - | Update of CSG Test Case 8.3.4.5 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140537 | 2570 | - | Correction to IMS Emergency Call over EPS test case 11.2.6 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140551 | 2571 | - | Correction to EMM test case 9.2.3.1.9 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140573 | 2572 | - | Correction to Home eNB Enhancements test case 6.4.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140576 | 2573 | - | Addition of test case 6.2.4.4 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140580 | 2574 | - | Addition of test case 6.2.4.6 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140582 | 2575 | - | GCF Priority 1 - Update to EUTRA RRC test case 8.5.4.1 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140623 | 2576 | - | Correction of the reference to the procedure for IMS call release | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140748 | 2577 | - | Correction to EUTRA Idle Mode Test case 6.2.3.31 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140749 | 2578 | - | Correction to E-UTRA Inter-RAT test case 6.2.3.3a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140751 | 2579 | - | Correction to EUTRA Idle Mode Test case 6.1.1.1 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140755 | 2580 | - | Update to test case 6.2.3.1 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140756 | 2581 | - | Correction to GCF WI-162 LTE-A Carrier Aggregation Test Case 8.2.4.18.1 and 8.2.4.18.2 | 12.0.0 | 12.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2014-03 | RAN#63 | R5-140757 | 2582 | - | Correction to E-UTRA RRC Test Case 8.3.1.16a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140761 | 2584 | - | Update to Test Case 9.2.3.3.1 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140762 | 2585 | - | Correction to EMM test case 9.2.1.2.14 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140763 | 2586 | - | Correction to EMM test case 9.2.1.1.7b | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140764 | 2587 | - | Update of test case 9.2.3.1.20a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140765 | 2588 | - | Correction to GCF WI-154 IMS Emergency Call testcase 11.2.5 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140766 | 2589 | - | Update of IMS Emergency TC 11.2.4 to verify Permanently stored in the UE ENs requirements | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140769 | 2592 | - | Corrections to MultiLayer SRVCC test case 13.4.3.4, 13.4.3.5 and 13.4.3.6 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140770 | 2593 | - | Addition of test case ' Inter-system mobility / E-UTRA voice to GSM CS voice / aSRVCC / MO call / Forked responses' | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140773 | 2594 | - | Reconfirmation of voided section | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140776 | 2597 | - | Optimise UTRA test frequency allocation in 8.6.5.1a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140777 | 2598 | - | Correction to EUTRA MDT test case 8.6.6.3 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140778 | 2599 | - | Correction to EUTRA MDT test case 8.6.2.8 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140779 | 2600 | - | Correction to GCF WI-162 LTE-A Carrier Aggregation Test Case 8.2.4.19.1 and 8.2.4.19.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140780 | 2601 | - | Correction to NIMTC test case 9.2.3.1.5a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140791 | 2602 | - | Update to Test Case 6.2.3.13 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140792 | 2603 | - | Update to Test Case 6.2.3.21 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140925 | 2604 | - | Correction to EMM TC 9.2.3.4.1 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140927 | 2605 | - | Correction of Rel-11 MDT parameter | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140933 | 2606 | - | Correction of Test case 8.3.1.20 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140934 | 2607 | - | Correction of Test case 8.3.1.21 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140935 | 2608 | - | Correction of Test case 8.3.1.28 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140936 | 2609 | - | New eMBMS service continuity test case 17.4.9.1 and 17.4.9.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140937 | 2610 | - | New eMBMS service continuity test case 17.4.10.1 and 17.4.10.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140938 | 2611 | - | New eMBMS service continuity CA test cases 17.4.11.1 and 17.4.11.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140940 | 2612 | - | Addition of test case 'eICIC/ RRC connection reconfiguration / SIB1 information / Success' | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140955 | 2613 | - | New SIMTC TC 9.2.1.1.27a Attach procedure - EAB broadcast handling | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140956 | 2614 | - | New SIMTC TC 9.2.3.1.8b TAU procedure - EAB broadcast handling | 12.0.0 | 12.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2014-03 | RAN#63 | R5-140957 | 2615 | - | New SIMTC TC 9.2.1.2.4a Successful combined attach procedure - EPS service only - Congestion | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140958 | 2616 | - | Corrections to EUTRA SIMTC TC9.2.3.18a,TC8.5.1a and TC10.8.8 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140959 | 2617 | - | Corrections to EUTRA SIMTC TC8.1.1.7 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140960 | 2618 | - | Addition of SIMTC Test Case 10.5.1b | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-140965 | 2619 | - | Addition of test case ' Inter-system mobility / E-UTRA PS voice to GSM CS voice / bSRVCC / MO call' | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141052 | 2622 | - | Correction of TC 9.2.1.2.1c | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141053 | 2624 | - | Update to Test Case 9.2.3.1.6 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141056 | 2629 | - | Correction to EUTRA RRC Measurements of CSG cells test case 8.3.4.1 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141101 | 2620 | - | Update test case 8.5.1.1 Radio link failure / RRC connection re-establishment success | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141102 | 2621 | - | Correction to RRC Inter-RAT Measurements test case 8.3.2.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141104 | 2623 | - | Correction to GCF WI-086 EUTRA EMM Test Case 9.2.3.3.5a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141106 | 2625 | - | GCF priority 2 Correction to EMM TCs 9.2.1.1.1a and 9.2.1.1.1b | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141107 | 2626 | - | Addition of test case ' Inter-system mobility / E-UTRA voice to GSM CS voice / aSRVCC / MT call / User answers in CS domain' | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141108 | 2627 | - | Addition of test case ' Inter-system mobility / E-UTRA voice to GSM CS voice / aSRVCC / MT call / User answers in CS domain/ SRVCC HO cancelled' | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141109 | 2628 | - | Correction to EMM test case 9.2.1.1.2a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141127 | 2630 | - | Update of PDCP test case 7.3.6.1 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141129 | 2596 | - | Correction to Multilayer aSRVCC test case 13.4.3.13 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141131 | 2583 | - | Update of RRC Test Case 8.3.1.13a | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141132 | 2595 | - | Correction to Multilayer aSRVCC test case 13.4.3.12 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141133 | 2590 | - | Update of IMS Emergency Call over EPS test case 11.2.2 | 12.0.0 | 12.1.0 |
| 2014-03 | RAN#63 | R5-141134 | 2591 | - | Update of IMS Emergency Call over EPS test case 11.2.4 | 12.0.0 | 12.1.0 |
| 2014-06 | RAN#64 | R5-142131 | 2633 | - | Correction to EUTRA Idle Mode Test case 6.2.3.31 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142140 | 2634 | - | Correction to eMBMS test case 17.3.1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142225 | 2635 | - | Adding TC 8.5.1.7.3 to TS 36.523-1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142229 | 2636 | - | Adding TC 8.2.2.5.3 to TS 36.523-1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142238 | 2637 | - | New eMBMS test case 17.4.1a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142259 | 2638 | - | Correction to eMBMS test case 17.4.5 | 12.1.0 | 12.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2014-06 | RAN#64 | R5-142260 | 2639 | - | Correction to eMBMS test case 17.4.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142261 | 2640 | - | Correction to eMBMS test case 17.4.7 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142280 | 2641 | - | Correction to EUTRA CSG Test Case 8.3.4.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142281 | 2642 | - | Correction to GCF WI-086 EUTRA EMM Test Case 9.2.3.3.5a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142282 | 2643 | - | Correction to GCF WI-172 EUTRA<->UTRA aSRVCC Testcase 13.4.3.11 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142283 | 2644 | - | Correction to GCF WI-159 Pre-registration at 1xRTT testcase 13.4.4.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142285 | 2645 | - | Correction to GCF WI-159 Enhanced CSFB test case 8.4.7.10 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142313 | 2646 | - | Update of reference list and list of abbreviations for eMBMS testing purposes | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142326 | 2647 | - | Correction to E-UTRA Inter-RAT test case 6.2.3.1a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142338 | 2648 | - | Correction to test case 8.6.3.4. | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142364 | 2649 | - | Editorial CR removing white spaces from title of test case 6.2.4.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142409 | 2650 | - | Update of test case 8.2.2.8 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142416 | 2651 | - | Addition of test case ' Authentication not accepted by the UE/ non-EPS authentication unacceptable' | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142423 | 2652 | - | Correction to NIMTC test case 10.5.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142440 | 2653 | - | Correction of measObjectId in Several SRVCC Test Cases | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142445 | 2654 | - | Addition of Close Down Procedure for bSRVCC Test Cases | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142454 | 2655 | - | Correction to eMDT Test Case 8.6.7.4 and Update to 8.6.5.1, 8.6.5.1a and 8.6.5.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142456 | 2656 | - | Correction to EUTRA Idle Mode Test Cases 6.2.2.6 and 6.2.3.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142457 | 2657 | - | Correction to LTE-A Carrier Aggregation Test Case 8.2.4.21.1 and 8.2.4.21.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142458 | 2658 | - | Corrections to TC 8.2.2.5.2, 8.3.1.17.2, 8.5.1.7.2 in TS 36.523-1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142461 | 2659 | - | Correction to EUTRA Idle mode Test case 6.1.2.12 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142463 | 2660 | - | Update to EUTRA Idle Mode Test Case 6.1.1.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142489 | 2661 | - | Correction to GCF WI-087 EUTRA<->GERAN SRVCC Testcase 13.4.3.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142513 | 2662 | - | Update of CGI reporting test case 8.3.3.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142525 | 2663 | - | Update of test case 8.2.4.14 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142556 | 2664 | - | Correction to EUTRA EMM Test case 9.2.3.1.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142563 | 2665 | - | Correction to SRVCC and bSRVCC Test Cases to Avoid Unexpected Cell Reselection from GERAN to EUTRAN | 12.1.0 | 12.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2014-06 | RAN#64 | R5-142580 | 2666 | - | Resubmission: Removal of TC 6.3.10, 6.3.11, 6.3.12 from TS 36.523-1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142633 | 2667 | - | Editorial correction for test case 6.2.4.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142635 | 2668 | - | Correction to LTE-GERAN SRVCC test case 13.4.3.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142669 | 2669 | - | Update of E-UTRA DL-SCH one layer transport block size selection test cases 7.1.7.1.1, 7.1.7.1.2, 7.1.7.1.3 and 7.1.7.1.4 for higher UE categories | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142681 | 2670 | - | Update of E-UTRA DL-SCH two layer transport block size selection test cases 7.1.7.1.5 and 7.1.7.1.6 for higher UE categories | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142690 | 2671 | - | Update of E-UTRA UL-SCH transport block size selection test case 7.1.7.2.1 for higher UE categories | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142691 | 2672 | - | Correction to EMM test cases 9.2.1.1.1a and 9.2.1.1.1b | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142700 | 2673 | - | Correction to ESM test case 10.4.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142724 | 2674 | - | Correction to RRC test case 8.5.4.1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142736 | 2675 | - | Correction to LTE InterRAT (UTRA CELL_FACH) test cases 6.2.4.1 and 6.2.4.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142765 | 2676 | - | Correction to RRC test case 8.5.1.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142776 | 2677 | - | Correction to SRVCC Test Case 13.4.3.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142777 | 2678 | - | Addition of new Intra-band non-Contiguous CA test case 7.1.4.20.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142795 | 2679 | - | Correction to RRC Measurement test case 8.3.4.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142797 | 2680 | - | Correction to GCF WI-159 Enhanced CSFB test case 8.4.7.8 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142847 | 2681 | - | Correction to EUTRA Idle Mode Test case 6.1.1.1b | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142848 | 2682 | - | Correction to E-UTRA Inter-RAT test case 6.2.3.5a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142849 | 2683 | - | Correction to EUTRA Idle Mode CSG test case 6.3.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142850 | 2684 | - | Update to EUTRA Idle Mode Test Case 6.1.1.3a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142851 | 2685 | - | Update of MFBI test case 6.1.2.19 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142853 | 2687 | - | Split of TDD special subframe MAC test cases 7.1.3.12 and 7.1.3.13 into separate test cases for ssp7 and ssp9. | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142854 | 2688 | - | Correction to LTE-A CA MAC test case 7.1.4.19.x | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142855 | 2689 | - | Update of RRC test case 8.1.3.7 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142857 | 2690 | - | Update of test case 8.2.4.14a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142858 | 2691 | - | Addition of new TC 8.2.4.23 CA / RRC connection reconfiguration / Handover / Failure / Re-establishment successful | 12.1.0 | 12.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2014-06 | RAN#64 | R5-142859 | 2692 | - | Correction to EUTRA CSG Testcases 8.3.4.1, 8.3.4.3, 8.3.4.4, 8.3.4.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142860 | 2693 | - | Correction to EUTRA CSG test case 8.3.4.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142861 | 2694 | - | Addition of test mode procedure to the E-UTRAN Inter-frequency CSG proximity indication test case 8.3.4.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142863 | 2695 | - | Correction to LTE MDT test case 8.6.4.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142864 | 2696 | - | Correction to GCF WI-181 Rel-10 EPS Enhancements EPS FDD <>UTRAN Test Case 8.6.5.1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142865 | 2697 | - | Correction to MDT Test Case 8.6.3.1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142866 | 2698 | - | Correction to test case 8.6.4.1, 8.6.4.2 and 8.6.4.4. | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142867 | 2699 | - | Correction to test case 8.2.2.6.2. | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142868 | 2700 | - | Update of EMM test case 9.2.3.1.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142869 | 2701 | - | Correction to test case 9.1.5.1, Table 9.1.5.1.3.3-1: EMM INFORMATION (step 1, Table 9.1.5.1.3.2-1) | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142870 | 2702 | - | Addition of test case ' Attach / Rejected / IMEI not accepted' | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142871 | 2703 | - | Addition of test case ' Attach / Abnormal case / ESM failure' | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142872 | 2704 | - | Correction to test case 8.6.3.1. | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142873 | 2705 | - | Correction to Test Case 9.2.3.2.8 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142874 | 2706 | - | Update of ESM test case 10.5.1b | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142875 | 2707 | - | Correction to ESM test case 10.8.8 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142876 | 2708 | - | Removal of GCF WI-172 EUTRA<>UTRA aSRVCC Testcase 13.4.3.12 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142877 | 2709 | - | Correction to GCF WI-172 EUTRA<>UTRA aSRVCC Testcases 13.4.3.x | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142878 | 2710 | - | Correction to Multilayer Test Case 13.4.1.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142879 | 2711 | - | Correction to EUTRA to UTRA SRVCC and aSRVCC Test Cases to Avoid Unexpected Cell Reselection | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142880 | 2712 | - | Correction to cs-FallbackIndicator in LTE SRVCC test cases 13.4.3.x | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142881 | 2713 | - | Correction to Band Indicator in LTE-GERAN SRVCC test cases 13.4.3.3 and 13.4.3.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142882 | 2714 | - | Correction for ATTACH REQUEST contents in aSRVCC and bSRVCC test cases | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142883 | 2715 | - | Correction to GCF WI-159 Pre-registration at 1xRTT test case 13.4.4.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142887 | 2716 | - | Correction to eMBMS test case 17.1.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142888 | 2717 | - | New MTC test case 6.1.1.7a PLMN selection / Periodic reselection / ExtendedWaitTimer / Single Frequency operation | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142889 | 2718 | - | Update to SIMTC test case 10.5.1b | 12.1.0 | 12.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2014-06 | RAN#64 | R5-142890 | 2719 | - | Update to SIMTC test case 10.5.1a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142902 | 2720 | - | Correction to eMBMS test case 17.1.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142903 | 2721 | - | Correction to eMBMS test case 17.1.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142904 | 2722 | - | Correction to eMBMS test case 17.1.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142905 | 2723 | - | Correction to eMBMS test case 17.3.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142906 | 2724 | - | Correction to eMBMS test case 17.4.1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142907 | 2725 | - | Correction to eMBMS test cases 17.4.2 and 17.4.2a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142908 | 2726 | - | Correction to eMBMS test cases 17.4.3 and 17.4.3a | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142909 | 2727 | - | Correction to eMBMS test case 17.4.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142910 | 2728 | - | Correction to eMBMS test case 17.4.8 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142911 | 2729 | - | Correction to eMBMS test cases 17.4.9.1 and 17.4.9.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142912 | 2730 | - | Correction to eMBMS test cases 17.4.10.1 and 17.4.10.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142913 | 2731 | - | Correction to eMBMS test case 17.4.11.1 and 17.4.11.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142914 | 2732 | - | Adding general information for the eMBMS service continuity test cases | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142920 | 2733 | - | Correction to Emergency Call over IMS test case 11.2.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142921 | 2734 | - | Addition of test case "CA / RRC connection reconfiguration / Handover / Success / PCell change and SCell addition / Intra-Band non-contiguous CA" and CA / RRC connection reconfiguration / Handover / Success / PCell Change / SCell no Change / lbnCCA | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142922 | 2735 | - | New Intra-band non-Contiguous CA MAC test case 7.1.9.1.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142923 | 2736 | - | Correction to CA Enhancements test case 7.1.2.10 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142924 | 2737 | - | Correction to CA Enhancements test case 7.1.2.11 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142925 | 2738 | - | Addition of new Intra-band non-Contiguous CA test case 7.1.3.11.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142926 | 2739 | - | Addition of new Intra-band non-Contiguous CA test case 7.1.4.19.3 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142931 | 2740 | - | Adding TC 8.3.1.17.3 to TS 36.523-1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142933 | 2741 | - | Adding new test case 6.2.4.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142934 | 2742 | - | Adding new test case 6.2.4.7 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142938 | 2743 | - | Correction to Test Case 9.1.2.6 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142965 | 2744 | - | GCF Priority 2 - Update to EMM test cases 9.2.3.3.2, 9.2.3.3.3 and 9.2.3.3.5 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142974 | 2745 | - | Update of MFBI test case 6.1.2.20 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142975 | 2746 | - | Update of MFBI test case 6.1.2.21 | 12.1.0 | 12.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------|------|------|---|-------------|-------------|
| 2014-06 | RAN#64 | R5-142976 | 2747 | - | Update to the title of 7.1.4.18 and 7.1.4.21 to non-CA test cases | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142977 | 2748 | - | Update to EUTRA MDT Test Case 8.6.2.8 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142978 | 2749 | - | Correction of LTE IRAT EMM test case 9.2.1.2.1b and 9.2.1.2.1c | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142979 | 2750 | - | Correction to GCF WI-154 IMS emergency Testcase 11.2.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142988 | 2751 | - | GCF Priority 1 - Update to EUTRA RRC test case 8.5.4.1 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-142998 | 2753 | - | GCF Priority 3 - Update to EMM test case 9.2.3.3.4 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-143212 | 2686 | - | Correction to Test Case 6.2.2.2 | 12.1.0 | 12.2.0 |
| 2014-06 | RAN#64 | R5-143213 | 2632 | - | Correction to test case 10.5.4, Table 10.5.4.3.2-1: Main behaviour | 12.1.0 | 12.2.0 |
| 2014-09 | GERAN#63 | GP-140521 | 2755 | - | CR 36.523-1-2755 Correction in Idle mode test cases 6.2.3.26, 6.2.3.27, 6.2.3.28, 6.2.3.30 | 12.2.0 | 12.3.0 |
| 2014-09 | GERAN#63 | GP-140531 | 2754 | 1 | CR 36.523-1-2754 Correction to WI-87 LTE GERAN test case 6.2.3.23 | 12.2.0 | 12.3.0 |
| 2014-09 | GERAN#63 | GP-140534 | 2756 | - | CR 36.523-1-2756 Resubmission of the Correction to WI-87 LTE GERAN Test cases 6.2.3.23,6.2.3.26,6.2.3.27,6.2.3.28,6.2.3.29 and 6.2.3.30 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144164 | 2757 | 2757 | Correction to GCF WI-172 EUTRA<->UTRA aSRVCC Testcase 13.4.3.17 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144190 | 2758 | 2758 | Correction to LTE-CA MAC Test case 7.1.3.11.1 and 7.1.3.11.2 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144230 | 2759 | 2759 | Editorial correction to LTE CA MAC test cases | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144231 | 2760 | 2760 | Editorial correction to LTE CA test cases 8.5.1.7.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144233 | 2761 | 2761 | Editorial - rewording in eMBMS test cases 17.1.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144236 | 2762 | 2762 | Correction to LTE eMBMS TestCases 17.1.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144252 | 2763 | 2763 | Remove LTE MDT Test cases on PLMN change | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144298 | 2764 | 2764 | Update of TC 6.3.8 Inter-RAT CSG Cell Reselection from E-UTRA CSG cell to UTRA CSG cell | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144307 | 2765 | 2765 | Addition of new TC 8.2.2.4.3 Intra-band non-contiguous CA | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144345 | 2766 | 2766 | Updates to EMM TC 9.1.3.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144368 | 2767 | 2767 | Correction to test case 6.2.4.5 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144369 | 2768 | 2768 | Correction to test case 6.2.4.7 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144374 | 2769 | 2769 | Editorial correction of test case - Attach / Rejected / IMEI not accepted | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144376 | 2770 | 2770 | Remove test case 13.4.3.29 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144401 | 2771 | 2771 | Correction to EMM Test case 9.2.1.1.27 | 12.2.0 | 12.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|------|--|-------------|-------------|
| 2014-09 | RAN#65 | R5-144405 | 2772 | 2772 | Add test case 6.2.4.2 for inter-RAT cell reselection | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144406 | 2773 | 2773 | Correction to LTE eMBMS TestCases 17.2.4 for TDD | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144442 | 2774 | 2774 | Correction to EMM Test Case 9.1.2.6 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144517 | 2775 | 2775 | Addition of new Intra-band non-Contiguous CA test case 8.2.4.21.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144519 | 2776 | 2776 | Addition of new Intra-band non-Contiguous CA test case 8.3.1.18.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144520 | 2777 | 2777 | Addition of new Intra-band non-Contiguous CA test case 8.4.2.7.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144592 | 2778 | 2778 | Correction to EUTRA MAC test case 7.1.4.2 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144593 | 2779 | 2779 | Correction to EMM test case 9.1.2.7 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144596 | 2780 | 2780 | Correction to EMM test case 9.2.1.1.23 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144604 | 2781 | 2781 | Update of EMM test case 9.2.1.1.28 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144624 | 2782 | 2782 | Correction to eICIC test case 8.3.1.19 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144625 | 2783 | 2783 | Correction to GCF WI-87 SRVCC<->UTRA Testcases 13.4.3.5 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144645 | 2784 | 2784 | Correction to EUTRA Idle Mode Test case 6.1.2.8a | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144646 | 2785 | 2785 | Correction to EUTRA Idle Mode CSG test case 6.3.5 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144647 | 2786 | 2786 | Update of MFBI test cases 6.1.2.19, 6.1.2.20 and 6.1.2.21 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144648 | 2787 | 2787 | Update of IDLE mode test case 6.1.2.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144649 | 2788 | 2788 | Correction to EUTRA Idle Mode test case 6.2.1.4 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144651 | 2789 | 2789 | Addition of Inter-RAT Cell reselection EUTRAN to UTRAN MFBI test case 6.2.3.34 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144653 | 2790 | 2790 | Correction of EUTRA test case 7.1.4.20 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144654 | 2791 | 2791 | Update of MFBI test case 8.2.4.22 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144655 | 2792 | 2792 | Update of EUTRA test case 8.2.4.20.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144656 | 2793 | 2793 | Update of EUTRA test case 8.2.4.20.2 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144657 | 2794 | 2794 | Correction to EUTRA RRC HeNB Testcase 8.3.4.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144658 | 2795 | 2795 | Editorial update of TC 8.3.1.22.2 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144659 | 2796 | 2796 | Correction to EUTRA RRC handover Test Cases 8.4.1.2, 8.4.1.4, 8.4.1.5 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144660 | 2797 | 2797 | Correction of LTE-A Minimization of Drive Tests (MDT) Testcase 8.6.3.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144661 | 2798 | 2798 | Correction to GCF WI-181 EUTRA EPS FDD <->UTRAN test Case 8.6.5.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144662 | 2799 | 2799 | Update EMM 9.2.3.4.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144663 | 2800 | 2800 | Correction to ESM test case 10.5.4 | 12.2.0 | 12.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|------|--|-------------|-------------|
| 2014-09 | RAN#65 | R5-144664 | 2801 | 2801 | Correction for IMS Emergency Call test case 11.2.5 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144665 | 2802 | 2802 | Corrections to IMS Emergency Call over EPS test cases 11.2.8 and 11.2.8a | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144666 | 2803 | 2803 | Correction to GCF WI-167 SRVCC<>UTRA Testcases 13.4.3.6 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144667 | 2804 | 2804 | Correction to GCF WI-086 EUTRA<>UTRA SRVCC Testcase 13.4.3.2 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144668 | 2805 | 2805 | Correction to GCF WI-086 SRVCC<>UTRA Testcase 13.4.3.4 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144670 | 2806 | 2806 | Correction to GCF WI-172 EUTRA<>UTRA aSRVCC Testcase 13.4.3.16 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144671 | 2807 | 2807 | Correction to GCF WI-172 EUTRA<>UTRA aSRVCC Testcase 13.4.3.9 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144672 | 2808 | 2808 | Correction to GCF WI-172 EUTRA<>UTRA aSRVCC Testcase 13.4.3.11 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144673 | 2809 | 2809 | Correction to GCF WI-172 EUTRA<>UTRA aSRVCC Testcase 13.4.3.13 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144674 | 2810 | 2810 | Correction to GCF WI-172 EUTRA<>UTRA aSRVCC Testcase 13.4.3.15 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144675 | 2811 | 2811 | Corrections for EUTRA<>GERAN aSRVCC test cases | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144676 | 2812 | 2812 | Corrections to eMBMS test case 17.2.4 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144679 | 2813 | 2813 | Correction to EMM test case 9.2.1.1.28 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144680 | 2814 | 2814 | Addition of test case - CA / RRC connection reconfiguration | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144683 | 2815 | 2815 | Addition of new TC 8.2.2.3.3 Intra-band non-contiguous CA | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144684 | 2816 | 2816 | Addition of new TC 8.3.1.22.3 Intra-band non-contiguous CA | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144724 | 2817 | 2817 | Addition of new UL CoMP TC 7.1.10.1 Sending SR on PUCCH with DMRS generated by using virtual cell identity / nPUCCH-Identity | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144725 | 2818 | 2818 | Addition of new TC 7.1.10.2 Transmitting data on PUSCH with DMRS generated by using virtual cell identity / nPUSCH-Identity | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144728 | 2819 | 2819 | Update to test case 9.2.3.3.4 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144731 | 2820 | 2820 | Correction to Multi-layer test cases 13.1.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144734 | 2821 | 2821 | Correction to EMM Test cases 9.2.3.3.2 and 9.2.3.3.3 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144741 | 2822 | 2822 | Correction of EUTRA test case 11.2.10 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144742 | 2823 | 2823 | Correction to EMM test case 9.1.5.1 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144743 | 2824 | 2824 | Correction to SRVCC emergency call test case 11.2.11 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144744 | 2825 | 2825 | Correction to Emergency calls over IMS test cases 11.2.2 and 11.2.4 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144745 | 2826 | 2826 | Correction to GCF WI-172 EUTRA<>UTRA aSRVCC Testcase 13.4.3.14 | 12.2.0 | 12.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|------|--|-------------|-------------|
| 2014-09 | RAN#65 | R5-144756 | 2827 | 2827 | Clarification of security protection for EMM cause #25 in test cases 9.2.1.1.18, 9.2.1.2.14, 9.2.3.1.20, 9.2.3.2.16 and 9.3.1.18 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144769 | 2828 | 2828 | Correction to WI-156 EUTRA RRC test case 8.2.4.14 | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144770 | 2829 | 2829 | Correction to WI-151 EUTRA RRC test case 8.2.4.14a | 12.2.0 | 12.3.0 |
| 2014-09 | RAN#65 | R5-144776 | 2830 | 2830 | Correction of the ePDCCH TCs for applying default parameter | 12.2.0 | 12.3.0 |
| 2014-12 | RAN#66 | R5-145113 | 2833 | - | Correction to EUTRA RRC Test Case 8.3.2.4 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145115 | 2834 | - | Correction for IMS Emergency Call test case 11.2.10 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145117 | 2835 | - | Correction to Multi-layer test case 13.1.3 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145118 | 2836 | - | Correction for multilayer bSRVCC test case 13.4.3.22 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145119 | 2837 | - | Correction to eMBMS test case 17.3.1 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145122 | 2838 | - | Editorial Correction to eMBMS-SC test cases 17.4.3 and 17.4.3a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145123 | 2839 | - | Correction to eMBMS-SC test case 17.4.6 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145124 | 2840 | - | Correction to eMBMS-SC test case 17.4.8 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145131 | 2841 | - | Remove Inter-RAT CSG test case 6.3.8 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145146 | 2842 | - | Correction to GCF WI-178 eMBMS-SC test cases 17.4.2 and 17.4.2a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145148 | 2843 | - | Correction to GCF WI-081 EUTRA RRC handover Test Cases 8.4.1.2, 8.4.1.4, 8.4.1.5 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145162 | 2844 | - | Correction to GCF WI-150 MFBI test case 6.1.2.20 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145163 | 2845 | - | Correction to GCF WI-159 EUTRA<>1xRTT testcase 13.4.4.2 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145166 | 2846 | - | Correction to GCF WI-081 EUTRA RRC testcase 8.1.1.2 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145170 | 2847 | - | Correction to TC 6.2.3.34 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145202 | 2848 | - | Correction for multilayer bSRVCC test case 13.4.3.19 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145220 | 2849 | - | Correction to EMM Test cases 9.2.3.3.5 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145312 | 2850 | - | Correction to eMDT Test Case 8.6.8.1 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145313 | 2851 | - | Editorial Correction to eMDT Test Case 8.6.8.2 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145332 | 2852 | - | Addition of short DRX test case 7.1.6.3 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145333 | 2853 | - | Addition of short DRX test case 7.1.6.4 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145335 | 2854 | - | Update of test case 8.2.2.8 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145340 | 2855 | - | Update of aSRVCC to GSM test case 13.4.3.28 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145415 | 2856 | - | Correction to GCF WI-179 NIMTC testcase 6.1.1.7a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145500 | 2857 | - | Correction to eMBMS multiband test cases | 12.3.0 | 12.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2014-12 | RAN#66 | R5-145549 | 2858 | - | Correction to eMDT Test Case 8.6.2.11 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145551 | 2859 | - | Correction to bSRVCC test case 13.4.3.18 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145552 | 2860 | - | Correction to eMDT Test Case 8.6.4.9 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145553 | 2861 | - | Correction to eMDT Test Case 8.6.6.6 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145554 | 2862 | - | Correction to bSRVCC test case 13.4.3.20 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145555 | 2863 | - | Correction to bSRVCC test case 13.4.3.21 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145583 | 2864 | - | Correction to EUTRA RRC test case 8.5.4.1 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145585 | 2865 | - | Correction to EMM test case 9.2.1.2.14 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145611 | 2866 | - | Addition of Idle mode test case 6.1.1.9 PLMN selection of RPLMN or (E)HPLMN: Manual mode | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145637 | 2867 | - | Correction to GCF WI-159 Pre-registration at 1xRTT testcase 13.1.18 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145664 | 2868 | - | Addition of new test case 6.1.1.8 PLMN selection of RPLMN or (E)HPLMN: Automatic mode | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145665 | 2869 | - | Corrections to Idle mode test case 6.1.1.1a and 6.1.1.4a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145667 | 2870 | - | Correction to GCF WI-168 EUTRA Idle Mode Testcase 6.2.3.1a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145668 | 2871 | - | Correction to GCF WI-087 EUTRA CSG Testcase 6.3.2 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145669 | 2872 | - | Correction to EUTRA HomeNB Testcase 6.4.7 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145670 | 2873 | - | Add new test case Inter-RAT cell reselection from UTRA to E-UTRA / MFBI | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145671 | 2874 | - | Correction to EUTRA Idle Mode test case 6.1.1.3a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145672 | 2875 | - | Editorial correction to test case 7.1.4.20.3 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145673 | 2876 | - | Correction to GCF WI-154 IMS emergency call test case 8.1.2.12 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145674 | 2877 | - | Correction to GCF WI-154 IMS Emergency Call test case 8.1.2.11 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145676 | 2878 | - | Correction to GCF WI-159 EUTRA<>1xRTT Testcase 8.4.7.8 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145677 | 2879 | - | Correction to eMDT Test Case 8.6.2.3a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145678 | 2880 | - | Correction to eMDT test case 8.6.4.10 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145679 | 2881 | - | Correction to eMDT Test Case 8.6.6.5 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145680 | 2882 | - | Correction to eMDT Test Case 8.6.6.7 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145681 | 2883 | - | Correction to eMDT Test Case 8.6.2.12 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145682 | 2884 | - | Update to EMM Test case 9.2.1.2.1b and 9.2.1.2.1c | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145684 | 2885 | - | Correction for IMS Emergency Call test case 11.2.11 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145685 | 2886 | - | Correction to GCF WI-154 IMS Emergency Call test case 11.2.4 | 12.3.0 | 12.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2014-12 | RAN#66 | R5-145687 | 2887 | - | Update of bSRVCC handover failure test case 13.4.3.20 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145688 | 2888 | - | Update of bSRVCC handover failure test case 13.4.3.23 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145689 | 2889 | - | Update of aSRVCC handover failure test cases 13.4.3.26 and 13.4.3.28 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145690 | 2890 | - | Update of aSRVCC handover failure test cases 13.4.3.9 and 13.4.3.11 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145691 | 2891 | - | Corrections for EUTRA<>GERAN aSRVCC test cases 13.4.3.26 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145693 | 2892 | - | Corrections for EUTRA<>GERAN aSRVCC test cases 13.4.3.28 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145694 | 2893 | - | Corrections for GCF WI-086 EUTRA<>GERAN SRVCC test cases 13.4.3.5 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145695 | 2894 | - | Corrections for GCF WI-172 EUTRA<>GERAN aSRVCC test cases 13.4.3.30 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145696 | 2895 | - | Corrections for EUTRA<>GERAN bSRVCC test case 13.4.3.22 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145697 | 2896 | - | Corrections for EUTRA<>GERAN bSRVCC test case 13.4.3.23 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145698 | 2897 | - | Correction to bSRVCC test case 13.4.3.23 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145699 | 2898 | - | Handling Signalling Connection Release Indication | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145700 | 2899 | - | Updating dataCodingScheme of CMAS TC in 36.523-1 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145701 | 2900 | - | Correction to eMBMS-SC test case 17.4.5 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145702 | 2901 | - | Correction to GCF WI-178 eMBMS-SC test case 17.4.7 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145740 | 2902 | - | New TC 13.4.3.32 Inter-system mobility / UTRA CS voice to E-UTRA voice / rSRVCC | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145741 | 2903 | - | New TC 13.4.3.34 Inter-system mobility / UTRA CS voice to E-UTRA voice / alerting / rSRVCC / MO call | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145742 | 2904 | - | New TC 13.4.3.36 Inter-system mobility / UTRA CS voice to E-UTRA voice / alerting / rSRVCC / MT call | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145743 | 2905 | - | New TC 13.4.3.38 Inter-system mobility / UTRA CS voice to E-UTRA voice / rSRVCC / HO cancelled | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145773 | 2906 | - | Update 8.2.1.8 of SN length for ROHC config test | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145775 | 2907 | - | Corrections for test case 9.2.3.1.8b | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145776 | 2908 | - | Correction to EMM test case 9.2.1.1.28 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145790 | 2909 | - | Add new EMM test case 9.2.1.1.28a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145791 | 2910 | - | Correction to IMS Emergency Call test case 11.2.5 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145794 | 2911 | - | Update of EPS test case 10.4.2 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145795 | 2912 | - | Update of eICIC test case 8.3.1.20 | 12.3.0 | 12.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2014-12 | RAN#66 | R5-145950 | 2913 | - | Update to test case 6.2.4.5 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145951 | 2914 | - | Correction to test case 6.2.4.7 | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145952 | 2915 | - | Correction to eMBMS-SC test cases 17.4.1 and 17.4.1a | 12.3.0 | 12.4.0 |
| 2014-12 | RAN#66 | R5-145953 | 2916 | - | Correction for IMS Emergency Call test case 11.2.8 | 12.3.0 | 12.4.0 |
| 2015-03 | RAN#67 | R5-150062 | 2839 | - | Correction of Idle mode test case 6.1.1.2 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150063 | 2840 | - | Correction of Idle mode test case 6.1.1.9 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150068 | 2841 | - | Forgotten removal of TC 6.3.12 from TS 36.523-1 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150089 | 2842 | - | Correction to eMDT test case 8.6.4.5 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150090 | 2843 | - | Correction to eMDT test case 8.6.6.6 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150100 | 2844 | - | Correction to MFBI test case 6.1.2.20 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150101 | 2845 | - | Correction to test case 6.2.4.3 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150151 | 2846 | - | Update of Idle mode test case 6.2.3.35 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150270 | 2847 | - | Correction of EUTRA<->UTRA bSRVCC Testcase 13.4.3.20 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150271 | 2848 | - | Correction to GCF WI-082 EUTRA ESM test case 10.4.1 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150277 | 2849 | - | Correction the parameter in TC 13.4.3.28 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150321 | 2850 | - | Correction to CA intra band non-contiguous clause 7.1 rel-11 test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150322 | 2851 | - | Correction to CA intra band non-contiguous clause 7.1 rel-12 test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150323 | 2852 | - | Correction to CA intra band non-contiguous clause 8.2 rel-11 test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150329 | 2853 | - | Correction to CA intra band non-contiguous clause 8.2 rel-12 test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150330 | 2854 | - | Correction to CA intra band non-contiguous clause 8.3 rel-11 test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150331 | 2855 | - | Correction to CA intra band non-contiguous clause 8.4 rel-11 test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150332 | 2856 | - | Correction to CA intra band non-contiguous clause 8.5 rel-11 test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150339 | 2857 | - | Correction to ESM test case 10.4.2 test case | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150340 | 2858 | - | Correction to IMS Emergency Call test case 11.2.4 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150341 | 2859 | - | Correction to IMS Emergency Call test case 11.2.5 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150342 | 2860 | - | Correction to IMS Emergency Call test case 11.2.8 and 11.2.8a | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150348 | 2861 | - | Correction to LTE-A Carrier Aggregation test cases 8.2.4.23.x | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150362 | 2862 | - | Updates to MDT test case 8.6.5.1 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150397 | 2863 | - | Update of SRVCC test case 13.4.3.2 | 12.4.0 | 12.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2015-03 | RAN#67 | R5-150398 | 2864 | - | Update of aSRVCC test case 13.4.3.14 and 13.4.3.16 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150399 | 2865 | - | Update of bSRVCC test case 13.4.3.18 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150401 | 2866 | - | Update of EMM test case 9.1.5.1 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150426 | 2867 | - | New TC 13.4.3.31 Inter-system mobility / GERAN CS voice to E-UTRA voice / rSRVCC | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150427 | 2868 | - | New TC 13.4.3.33 Inter-system mobility / GERAN CS voice to E-UTRA voice / alerting / rSRVCC / MO call | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150428 | 2869 | - | New TC 13.4.3.35 Inter-system mobility / GERAN CS voice to E-UTRA voice / alerting / rSRVCC / MT call | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150429 | 2870 | - | New TC 13.4.3.37 Inter-system mobility / GERAN CS voice to E-UTRA voice / rSRVCC / HO cancelled | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150934 | 2871 | - | Correction to IMS Emergency Call test case 11.2.7 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150589 | 2872 | - | Updates to TC 13.4.3.32 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150590 | 2873 | - | Updates to TC 13.4.3.34 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150591 | 2874 | - | Updates to TC 13.4.3.36 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150592 | 2875 | - | Updates to TC 13.4.3.38 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150599 | 2876 | - | Remove of test case 8.2.4.22 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150600 | 2877 | - | Correction to eMBMS-SC test case 17.4.2 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150607 | 2878 | - | Correction to RFT-117 EUTRA MFBI Testcase 6.2.3.35 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150648 | 2879 | - | Correction to EUTRA Idle Mode test cases 6.1.1.8 and 6.1.1.9 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150649 | 2880 | - | Correction to short DRX cycle test case 7.1.6.3 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150650 | 2881 | - | Correction to UL-Comp test case 7.1.10.1 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150651 | 2882 | - | Correction to UL-Comp test case 7.1.10.2 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150652 | 2883 | - | Correction to ePDCCH test case 7.1.3.14 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150653 | 2884 | - | Correction to ePDCCH test case 7.1.3.15 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150654 | 2885 | - | New test case 8.5.4.2 for Network-requested CA Band Combination Capability Signalling | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150655 | 2886 | - | New test case 8.5.4.3 for Network-requested CA Band Combination Capability Signalling | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150656 | 2887 | - | Correction to EUTRA RRC test case 8.5.4.1 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150657 | 2888 | - | Correction to CA test case 8.2.4.16.x | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150658 | 2889 | - | Correction to CA test case 8.2.4.20.x | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150659 | 2890 | - | Update of eICIC test case 8.3.1.20 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150660 | 2891 | - | Correction to eMDT test case 8.6.2.3a | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150661 | 2892 | - | Correction to eMDT test case 8.6.2.10 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150662 | 2893 | - | Correction to eMDT test case 8.6.2.11 | 12.4.0 | 12.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2015-03 | RAN#67 | R5-150663 | 2894 | - | Correction to test cases 8.6.4.9 and 8.6.8.2 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150664 | 2895 | - | Correction to test cases 8.6.5.2, 8.6.5.3 and 8.6.6.2 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150666 | 2896 | - | Correction to GCF WI-086 EUTRA EMM test case 9.2.1.2.1b | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150668 | 2897 | - | Correction to aSRVCC test case 13.4.3.28 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150669 | 2898 | - | Correction of Multilayer bSRVCC TC 13.4.3.19 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150670 | 2899 | - | New test case "Inter-system mobility / E-UTRA PS voice to GSM CS voice / HO cancelled / Notification procedure / SRVCC" | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150671 | 2900 | - | Correction to eMBMS test case 17.3.2 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150673 | 2901 | - | Correction to eMBMS-SC test case 17.4.2 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150932 | 2902 | - | up of IE 'cs-FallbackIndicator' value in clause 13 xSRVCC handover test cases | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150715 | 2903 | - | Addition of Test case - "Inter-system mobility / UTRA CS voice + PS data to E-UTRA voice + PS data / rSRVCC" to rSRVCC Work Plan | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150718 | 2904 | - | Update of IDLE mode test case 6.2.2.5 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150730 | 2905 | - | Correction to test Case 8.3.1.19 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150731 | 2909 | - | Update of Test Case 9.1.5.1 | 12.0.0 | 12.1.0 |
| 2015-03 | RAN#67 | R5-150732 | 2906 | - | Correction to IMS Emergency Call test case 11.2.3 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150733 | 2907 | - | Correction to IMS Emergency Call test case 11.2.6 | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150740 | 2908 | - | Addition of Test Case - Intersystem mobility / UTRA CS voice to E-UTRA voice / rSRVCC / Multiple voice calls with mid-call feature | 12.4.0 | 12.5.0 |
| 2015-03 | RAN#67 | R5-150746 | 2910 | - | Correction to EMM test case 9.2.1.1.28a | 12.4.0 | 12.5.0 |
| 2015-06 | RAN#68 | R5-151110 | 2921 | - | Correction to test case 6.2.2.8 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151142 | 2925 | - | Update to IRAT PLMN selection test case 6.2.1.4 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151146 | 2929 | - | Correction to EMM test case 9.2.3.3.1 and 9.2.3.3.4 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151148 | 2930 | - | Update to EUTRAN measurement test case 8.3.1.12a | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151175 | 2935 | - | New MAC test case 7.1.1.1a for Low Cost MTC | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151349 | 2946 | - | Corrections to eMDT test case 8.6.6.6 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151381 | 2949 | - | Corrections to MDT test case 8.6.3.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151383 | 2951 | - | Correction to MDT test case 8.6.5.3 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151413 | 2953 | - | Update of DL-SCH transport block size selection test case 7.1.7.1.1 for UE Cat 0 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151414 | 2954 | - | Update of DL-SCH transport block size selection test case 7.1.7.1.2 for UE Cat 0 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151415 | 2955 | - | Update of DL-SCH transport block size selection test case 7.1.7.1.3 for UE Cat 0 | 12.5.0 | 12.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2015-06 | RAN#68 | R5-151416 | 2956 | - | Update of DL-SCH transport block size selection test case 7.1.7.1.4 for UE Cat 0 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151417 | 2957 | - | Update of UL-SCH transport block size selection test case 7.1.7.2.1 for UE Cat 0 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151471 | 2959 | - | Correction to LTE-GERAN SRVCC test case 13.4.3.41 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151472 | 2960 | - | Correction to EMM test case 9.2.2.1.3 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151473 | 2961 | - | Correction to test cases 8.6.7.1, 8.6.7.2 and 8.6.7.3 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151474 | 2962 | - | Correction to Measurements for self optimized networks test case 8.3.3.x | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151475 | 2963 | - | Correction to test case 8.3.4.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151493 | 2969 | - | Update of Section 9's text for call to generic procedure 6.4.2.5 of 36.508 to reflect what the generic procedure does | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151494 | 2970 | - | Update of TC 8.1.2.11 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151532 | 2977 | - | Addition of new TC 7.1.4.24 Correct HARQ process handling / TTI bundling without resource allocation restriction | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151636 | 3001 | - | Corrections for bSRVCC test cases 13.4.3.22 and 13.4.3.23 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151739 | 2932 | 2 | Correction of idle mode test case 6.1.1.2a | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151740 | 2964 | 1 | Corrections for use of EFloci field in USIM configurations for Idle Mode test cases | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151741 | 2983 | 1 | Correction to remark of message content of TC 6.2.3.34 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151742 | 3007 | 1 | Update of WI-087 Inter-RAT Cell Reselection test case 6.2.3.17 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151743 | 2944 | 1 | Correction of DL SPS test case 7.1.3.2 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151744 | 2945 | 1 | Correction of UL SPS test case 7.1.4.2 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151745 | 3016 | 1 | Correction to EUTRA MAC test case 7.1.3.13a | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151746 | 2917 | 1 | Correction to RRC test case 8.1.2.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151747 | 2918 | 1 | Editorial correction in RRC test case 8.1.2.3 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151748 | 2947 | 1 | Add pre-test steps to check the band capability of UE in MFBI protocol test cases | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151749 | 2920 | 1 | Upgrade of TC 8.5.4.1 to Rel-12 ASN.1 baseline | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151750 | 3017 | 1 | Correction to EUTRA RRC test case 8.5.4.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151751 | 2940 | 1 | Update of eICIC test case 8.3.1.20 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151752 | 2941 | 1 | Update of eICIC test case 8.3.1.21 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151753 | 2942 | 1 | Update of eICIC test case 8.3.1.28 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151754 | 3025 | 1 | Update of SI acquisition measurement test cases 8.3.4.x | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151756 | 2985 | 1 | Correction to eMDT test case 8.6.11.1 – RACH optimization | 12.5.0 | 12.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2015-06 | RAN#68 | R5-151758 | 2939 | 1 | Correction in EMM test cases 9.2.3.1.15 and 9.2.3.1.15a | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151759 | 2943 | 1 | Update of EMM information procedure test case 9.1.5.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151760 | 2971 | 1 | Editorial changes to 9.1.3.3 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151761 | 2968 | 1 | Update of TC 9.2.1.1.1a | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151762 | 2973 | 1 | Correction to WI-82 EUTRA EMM Testcases for IMS capable UE | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151763 | 3005 | 1 | Correction to WI-82 EUTRA EMM Testcase 9.2.1.2.2 for IMS capable UE | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151764 | 3006 | 1 | Correction to WI-82 EUTRA EMM Testcase 9.3.1.12a for IMS capable UE | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151765 | 3015 | 1 | Correction to Test Case 9.2.1.2.4 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151766 | 2919 | 1 | Correction to NAS test case 10.4.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151767 | 3014 | 1 | Correction to WI-103 EPS Testcase 10.4.2 for IMS capable UE | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151768 | 2991 | 1 | New TC 11.2.12 LIMITED-SERVICE / Inter-system mobility / E-UTRA to GSM CS / SRVCC Emergency Call Handover to GERAN | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151771 | 3018 | 1 | Correction to IMS Emergency Call test case 11.2.5 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151772 | 3021 | 1 | Correction to IMS Emergency Call test case 11.2.3 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151773 | 2926 | 1 | Correction to Multi-layer test case 13.1.3 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151774 | 2931 | 1 | Corrections to rSRVCC test cases | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151775 | 2972 | 1 | Editorial changes to WI-086 EUTRA<->UTRAN SRVCC Testcase 13.4.3.2 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151776 | 2993 | 1 | Updates to 13.4.3.36 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151777 | 2996 | 1 | Updates to references to annex C.39 for rSRVCC test cases | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151778 | 3004 | 1 | Correction to GCF WI-159 Pre-registration at 1xRTT testcase 13.4.4.2 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151779 | 2927 | 1 | Correction to eMBMS test case 17.4.7 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151780 | 2928 | 1 | Correction to eMBMS test case 17.2.4 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151781 | 2974 | 1 | Correction to eMBMS-SC-CA test case 17.4.10.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151782 | 2975 | 1 | Correction to eMBMS-SC-CA test case 17.4.11.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151783 | 3027 | - | Correction to TS 36.523-1 Rel-10 pointer | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151784 | 3028 | - | Correction to TS 36.523-1 Rel-11 pointer | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151972 | 2938 | 1 | Addition of new test case TC 8.5.4.4 - UE Capability Transfer/ Success/ UE Cat 0/ UE Paging Info | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151973 | 2934 | 1 | New idle mode test case 6.1.2.2b for Low Cost MTC | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151986 | 2976 | 1 | Correction to TS 36.523-1 Rel-8 pointer | 12.5.0 | 12.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2015-06 | RAN#68 | R5-151987 | 3020 | 1 | Correction to TS 36.523-1 Rel-9 pointer | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151989 | 2998 | 1 | New test case "Correct HARQ process handling / TTI bundling with enhanced HARQ pattern" | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-151999 | 2948 | 1 | Addition of new test case TC 8.4.8.3 - WLAN Offload/ Offload Success/ EUTRA RRC_CONNECTED to/from WLAN (Qqualmeas, BeaconRSSI) | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152053 | 2958 | 1 | Add test case 8.4.8.1 for WLAN Offload | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152054 | 2992 | 1 | New test case 6.5.3 WLAN Offload / Cell Selection / EUTRA RRC_Idle to/from WLAN (Qqualmeas, BackhaulRateUIWLAN) | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152055 | 3002 | 1 | Addition of Test Case - WLAN Offload / Cell Selection / EUTRA RRC_Idle to/from WLAN (Qrxlevmeas, BeaconRSSI) - 3GPP/WLAN Work Plan | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152056 | 3003 | 1 | Addition of Test Case - WLAN Offload / Offload Success / EUTRA RRC_Connected to/from WLAN (Qrxlevmeas , ChannelUtilizationWLAN) - 3GPP/WLAN Work Plan | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152060 | 2937 | 1 | Addition of new D2D test case for Successful Announce Request Procedure/Direct discovery | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152062 | 2986 | 1 | Addition of new SCM TC 13.5.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152063 | 3026 | 1 | Addition of a new TC for SCM, 13.5.2 MTSI MO video call / SCM / 0% access probability skip for MTSI MO video call | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152070 | 2924 | 1 | Correction to EUTRA Idle Mode test case 6.1.1.8 and 6.1.1.9 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152072 | 2987 | 1 | Correction to SIMTC test case 9.2.3.1.8b | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152073 | 2988 | 1 | Correction to SIMTC test case 9.2.1.1.27a | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152075 | 2999 | 1 | New test case "cell reselection / MFBI/UE does not support multiBandInfoList" | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152076 | 3009 | 1 | Correction to Idle Mode test cases 6.1.1.1a and 6.1.1.4a | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152077 | 2989 | 1 | Correction to SIMTC test case 8.1.1.7 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152078 | 3000 | 1 | Correction to MDT test cases 8.6.4.4 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152082 | 2990 | 1 | Correction to SIMTC test cases 10.5.1a and 10.5.1b | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152083 | 2994 | 1 | Updates to 13.4.3.37 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152084 | 2995 | 1 | Updates to 13.4.3.38 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152098 | 2981 | 1 | Addition of new test case of FDD-TDD CA / Correct HARQ process handling / PUSCH / FDD PCell and TDD SCell | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152099 | 2982 | 1 | Addition of new test case of FDD-TDD CA / Correct HARQ process handling / PUSCH / TDD PCell and FDD SCell | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152105 | 2952 | 1 | Introduction of New TC 8.2.4.24.1 - CA / RRC connection reconfiguration / SCell Addition / Success /RRC Processing Delay/Intra-Band Contiguous CA | 12.5.0 | 12.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2015-06 | RAN#68 | R5-152107 | 3022 | 1 | Correction to LTE-UTRA FE-FACH test cases 6.2.4.x | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152108 | 3008 | 1 | Update of EMM Test Case 9.1.5.1 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152138 | 3010 | 2 | Correction to IMS Emergency Call test case 11.2.6 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152139 | 3012 | 2 | Correction to IMS Emergency Call test case 11.2.7 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152142 | 2978 | 2 | Addition of new TC 7.1.2.11.3 CA / Maintenance of uplink time alignment / Multiple TA / TDD-FDD CA | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152143 | 2979 | 2 | Addition of new test case of FDD-TDD CA / Correct HARQ process handling / Dynamic case / FDD PCell and TDD Scell | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152144 | 2980 | 2 | Addition of new test case of FDD-TDD CA / Correct HARQ process handling / Dynamic case / TDD PCell and FDD Scell | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152145 | 3029 | 1 | Correction to Test Case 13.4.3.39 | 12.5.0 | 12.6.0 |
| 2015-06 | RAN#68 | R5-152148 | 3023 | 2 | Correction to ESM test case 10.2.1 | 12.5.0 | 12.6.0 |
| 2015-09 | RAN#69 | R5-153102 | 3034 | - | Introduction of TC 8.8.1.4 Successful Acceptance/Rejection of Direct Communication announcements | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153139 | 3039 | - | Correction to EUTRA idle mode test case 6.1.2.17 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153212 | 3042 | - | Correction to D2D test case 19.2.1 for Successful Announce Request Procedure/Direct discovery | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153227 | 3048 | - | New E-UTRA MAC test case 7.1.2.24a TTI bundling without resource allocation restriction for Category 0 UE | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153228 | 3049 | - | Correction of E-UTRA RLC test case 7.2.3.1 for Category 0 UE | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153229 | 3050 | - | Correction of E-UTRA RLC test case 7.2.3.5 for Category 0 UE | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153234 | 3053 | - | Editorial correction to E-UTRA MAC test case 7.1.3.3 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153276 | 3055 | - | Void 1x SRVCC test case 8.4.7.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153278 | 3056 | - | Void eCIC test case 8.3.1.20 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153312 | 3062 | - | Update of EMM Test Case 9.2.1.2.1b | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153314 | 3063 | - | Update of eMDT test case 8.6.4.9 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153385 | 3073 | - | Correction to GCF WI-159 Pre-registration at 1xRTT testcase 13.1.18 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153399 | 3081 | - | Correction to EMM test case 9.2.1.1.30 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153401 | 3082 | - | Correction to Test Case 10.8.8 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153405 | 3086 | - | Correction to eMDT test case 8.6.5.1a | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153406 | 3087 | - | Correction to CA test cases 8.3.1.18.1, 8.3.1.18.2 and 8.3.1.18.3 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153489 | 3098 | - | Updates to TC 13.4.3.31 | 12.6.0 | 12.7.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2015-09 | RAN#69 | R5-153490 | 3099 | - | Updates to TC 13.4.3.33 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153491 | 3100 | - | Updates to TC 13.4.3.35 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153549 | 3104 | - | Correction to LTE-A eCIC test case 8.3.1.21 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153550 | 3105 | - | Correction to eMDT test case 8.6.10.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153555 | 3107 | - | Correction to GCF WI-222 Test Cases 8.5.4.2 and 8.5.4.3 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153558 | 3108 | - | Correction to WI-082 Test Cases 9.2.2.1.1, 9.2.2.1.6, 9.2.2.1.7, 9.2.2.1.8, 9.2.2.1.9 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153563 | 3109 | - | Update test case 8.4.8.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153568 | 3111 | - | Update of test case 8.6.4.5 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153570 | 3112 | - | Addition of D2D ProSe test case 19.1.3 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153578 | 3116 | - | Correction to LTE IRAT testcase 6.3.3 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153602 | 3124 | - | [PTCO] Implicit testing: Update of 11.2.1 due to removal of 8.1.2.11 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153632 | 3128 | - | Editorial correction for chapter 6.5 title - 3GPP/WLAN Work Plan | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153640 | 3129 | - | Correction to LTE IRAT testcase 6.3.4 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153667 | 3131 | - | Correction to LTE-A eCIC test case 8.3.1.28 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153668 | 3132 | - | Correction to eMBMS test case 17.3.2 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153681 | 3135 | - | Corrections to test cases 13.1.9 and 13.1.10 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153691 | 3136 | - | Correction to MDT Inter-RAT Logged Handover Failure test case 8.6.7.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153719 | 3090 | 1 | Updates to 7.1.7.1 and 7.1.7.2 about DL-SCH and UL-SCH TBS selection | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153720 | 3060 | 1 | Update of RLC test case 7.2.2.5.2 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153721 | 3117 | 1 | Update of TC 8.1.2.1 RRC connection establishment / Ks=1.25 / Success to reflect its original intention | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153722 | 3091 | 1 | Updates to 8.2.2.3 and Deletion of 8.2.4.24 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153724 | 3137 | - | Editorial correction to DL-SCH SCH transport block size selection test cases 7.1.7.1.3 and 7.1.7.1.4 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153725 | 3074 | 1 | Update of test case 8.4.2.7.x | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153726 | 3067 | 1 | Correction to EUTRA eMDT test case 8.6.11.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153727 | 3072 | 1 | Correction to eMDT test case 8.6.2.11 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153728 | 3083 | 1 | Correction to eMDT test case 8.6.3.4 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153729 | 3085 | 1 | Correction to MDT test case 8.6.4.4 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153730 | 3092 | 1 | Correction to test case 8.6.7.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153731 | 3064 | 1 | Update of ANR test case 8.7.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153733 | 3118 | 1 | Update of TC 9.2.2.1.3 for dynamic change of GERAN Release | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153734 | 3119 | 1 | Reduction of the value of the T3402 used in TC 9.2.1.1.22 | 12.6.0 | 12.7.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2015-09 | RAN#69 | R5-153736 | 3120 | 1 | Moving the MTSI SSAC access probability TCs from 34.229 into 36.523 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153737 | 3130 | 1 | Correction to Test Case 10.5.1b | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153738 | 3106 | 1 | Correction to IMS Emergency Call test case 11.2.12 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153739 | 3079 | 1 | Correction to Multilayer Procedures test case 13.4.2.4 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153740 | 3054 | 1 | Correction to eMBMS test case 17.4.5 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153741 | 3078 | 1 | Correction to eMBMS test cases 17.4.3 and 17.4.3a | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153747 | 3138 | - | Correction to test case 6.2.2.2 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153757 | 3140 | - | Adding new TC 13.5.6 MTSI MO SMS / SCM / 0% access probability skip for MTSI MO SMS over IP | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153776 | 3065 | 1 | Addition of new EUTRAN-WLAN interworking test case 6.5.5 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153777 | 3066 | 1 | Addition of new EUTRAN-WLAN interworking test case 6.5.6 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153779 | 3142 | - | [PTCO] Implicit Testing: Update of 8.2.1.1 due to removal of TC 8.1.3.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153783 | 3122 | 1 | [PTCO] Implicit Testing: Removal of TC 9.2.1.1.21 update of 9.2.1.1.22 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153784 | 3141 | 1 | [PTCO] Implicit Testing: Removal of TC 9.1.2.1 and update of 9.1.2.3 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153785 | 3125 | 1 | [PTCO] Implicit testing: Update of 11.2.2 due to removal of 8.1.2.12 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153786 | 3126 | 1 | [PTCO] Implicit testing: Update of 9.3.2.1 due to removal of 8.1.1.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153787 | 3127 | 1 | [PTCO] Implicit testing: Removal of 8.1.2.11, 8.1.2.12, 8.1.3.1 and 8.1.1.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153792 | 3035 | 1 | Addition of TC 8.8.2.4 D2D test case for successful acceptance/rejection of Direct Discovery announcements | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153793 | 3043 | 1 | Addition of a new D2D test case for Successful Reception and Transmission/ProSe Direct Discovery | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153794 | 3044 | 1 | Addition of a new D2D test case for RRC Reconfiguration/Direct Discovery | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153795 | 3103 | 1 | Addition of new D2D test case for Successful EPC-LEVEL ProSe Discovery | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153954 | 3045 | 1 | New E-UTRA MAC test case 7.1.3.3a for DL MAC PDU header handling for Category 0 UE | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153955 | 3046 | 1 | New E-UTRA MAC test case 7.1.4.3a for logical channel prioritization handling for Category 0 UE | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153956 | 3047 | 1 | Correction of E-UTRA MAC test case 7.1.4.13 for Category 0 UE | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153957 | 3051 | 1 | Correction of E-UTRA RLC test case 7.2.3.9 for Category 0 UE | 12.6.0 | 12.7.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|----------|-----------------------|------|-----|--|-------------|-------------|
| 2015-09 | RAN#69 | R5-153958 | 3052 | 1 | Correction of DRB generic test procedure in clause 12.1.1 for Category 0 UE | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153959 | 3030 | 1 | Extension of SCM test case 13.5.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153960 | 3031 | 1 | Correction to SCM test case 13.5.2 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153973 | 3088 | 1 | Update of Latency check test case 8.2.1.5 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153975 | 3068 | 1 | Correction to EMM Test Case 9.1.5.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153976 | 3059 | 2 | Update of test case 9.1.5.1 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153977 | 3084 | 1 | Correction to Test Case 9.2.3.1.8a | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153978 | 3033 | 1 | Updates to rSRVCC test case 13.4.3.40 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153979 | 3080 | 1 | Correction to Multilayer Procedures test case 13.4.2.5 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153980 | 3134 | 1 | Resubmission: Corrections to rSRVCC test cases 13.4.3.x | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153982 | 3093 | 1 | Addition of new TC 7.1.7.1.7 SCE-L1 / DL-SCH transport block size selection / DCI format 1 / RA type 0 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-153990 | 3077 | 1 | Addition of Test Case - WLAN Offload / Cell Selection / EUTRA RRC_Idle to/from WLAN (Qualmeas, ChannelUtilizationWLAN) - 3GPP/WLAN Work Plan | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154036 | 3113 | 1 | Addition of D2D ProSe test case 19.1.4 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154037 | 3114 | 1 | Addition of D2D ProSe test case 19.1.5 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154038 | 3058 | 2 | Correction to Cell selection test case 6.1.2.3 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154039 | 3069 | 1 | Correction to Cell reselection test case 6.1.2.6 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154040 | 3110 | 2 | Correction to LTE-UTRA FE-FACH test case 6.2.4.7 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154041 | 3057 | 1 | Correction to Measurement reporting test case 8.3.1.4 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154042 | 3071 | 1 | Correction to GCF WI-151 EUTRA FDD-TDD Testcase 8.3.1.13a | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154043 | 3139 | 1 | Correction to test cases 13.4.2.5, 13.4.2.6, 13.4.2.7, 13.4.2.8 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154047 | 3143 | 1 | Correction to xSRVCC test cases 13.4.3.2, 13.4.3.14, 13.4.3.16 and 13.4.3.18 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | R5-154048 | 3038 | 1 | Correction to EUTRA measurement test case 8.3.1.13 | 12.6.0 | 12.7.0 |
| 2015-09 | RAN#69 | - | - | - | update of the "non-specific references" in section 2 according to the approved R5-153582 and an action point on ETSI MCC | 12.6.0 | 12.7.0 |
| 2015-12 | GERAN#69 | GP-151053 / R5-155019 | 3144 | - | CR 36.523-1-3144 Correction to GCF WI-087 EUTRA EMM Testcases 6.2.3.28, 6.2.3.30 | 12.7.0 | 12.8.0 |
| 2015-12 | GERAN#69 | GP-151062 / R5-155080 | 3147 | - | CR 36.523-1-3147 Correction to GCF WI-87 GERAN-LTE cell reselection test cases 6.2.3.27 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155357 | 3177 | - | [PTCO] Implicit testing: Test title corrections for Clause 8 | 12.7.0 | 12.8.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2015-12 | RAN#70 | R5-155358 | 3178 | - | [PTCO] Implicit testing: Test title corrections for Clause 9 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155433 | 3189 | - | Adding main clause 8.8, 8.8.1 for Direct Communication and 8.8.2 for Direct Discovery | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155455 | 3190 | - | Correction to RRC CA test case 8.2.4.16.1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155487 | 3191 | - | Correction to EMM test case 9.2.3.1.8a | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155488 | 3192 | - | Correction to various ESM test cases for IP address allocation | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155492 | 3195 | - | Correction to SIMTC test case 10.5.1b | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155494 | 3197 | - | Correction to eMBMS test case 17.2.4 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155495 | 3198 | - | AP#68.02: Correction to Rel-11 eMBMS test cases | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155522 | 3202 | - | Correction to Cell selection test case 6.1.2.3 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155525 | 3204 | - | Correction to Cell reselection test case 6.1.2.6 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155526 | 3205 | - | Correction to Measurement reporting test case 8.3.1.4 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155527 | 3206 | - | Correction to EUTRA measurement test cases 8.3.1.13 and 8.3.1.13a | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155533 | 3209 | - | Moving Rel-9 SSAC test descriptions into 36.523-1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155534 | 3210 | - | Moving Rel-12 SSAC test descriptions into 36.523-1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155620 | 3220 | - | Correction to LTE-A MAC test cases 7.1.3.11.x | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155624 | 3221 | - | Update of IMS Emergency Call test case 11.2.6 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155638 | 3227 | - | Correction to ESM test case 10.2.1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155661 | 3238 | - | Correction to test case 7.1.7.1.6 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155683 | 3244 | - | Editorial Correction of clause 8.4 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155684 | 3245 | - | Editorial Correction of clause 6.5 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155781 | 3145 | 1 | Corrections to MFBI test case 6.1.2.22 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155782 | 3199 | 1 | Correction to MAC CA test cases 7.1.3.11.1, 7.1.3.11.4 and 7.1.3.11.5 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155783 | 3235 | 1 | Update 7.1.7.x test cases with UE Category 11 and 12 information | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155784 | 3217 | 1 | Correction to the testcase 8.2.4.20.x | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155785 | 3223 | 1 | Corrections to eDDA testcases 8.2.2.6.1 and 8.2.2.6.2 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155786 | 3168 | 1 | Corrections to LTE CSG test case 8.3.4.2 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155787 | 3211 | 1 | Correction to SI acquisition TCs | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155789 | 3194 | 1 | Correction to MDT test case 8.6.4.4 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155790 | 3196 | 1 | Correction to MDT test case 8.6.2.3a | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155791 | 3219 | 1 | Correction to eMDT testcase 8.6.7.1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155792 | 3254 | 1 | Corrections to eMDT test case 8.6.5.1a | 12.7.0 | 12.8.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2015-12 | RAN#70 | R5-155793 | 3255 | 1 | Corrections to eMDT test case 8.6.7.4 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155794 | 3148 | 1 | Update test case 9.2.1.1.28 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155795 | 3149 | 1 | Update test case 9.2.1.1.28a | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155798 | 3150 | 1 | Correction to Table 9.2.1.2.4.3.3-5: Message ATTACH REQUEST of Test Case 9.2.1.2.4 to reflect TS 24.008 Rel-11 changes | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155799 | 3167 | 1 | Correction to LTE CSG test case 9.2.3.1.9 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155902 | 3234 | 1 | Correction to GCF WI-087 EUTRA EMM testcase 9.2.3.3.5 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155904 | 3166 | 1 | Correction to LTE CSG testcase 11.2.3 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155905 | 3212 | 1 | Update eMBMS test case 17.3.2 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155923 | 3187 | 1 | Addition of new D2D test case 8.8.1.5 for successful monitoring for SyncRef UE/Direct Communication | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155924 | 3188 | 1 | Addition of new D2D test case 8.8.2.5 for successful monitoring for SyncRef UE/Direct Discovery | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155925 | 3203 | 1 | Correction to TC8.8.2.1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155926 | 3229 | 1 | Addition of ProSe Direct Communication test case 19.1.6 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155927 | 3230 | 1 | Addition of ProSe Direct Communication test case 19.1.10 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155929 | 3231 | 1 | Correction to ProSe Direct Communication test case 19.1.4 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155930 | 3232 | 1 | Correction to ProSe Direct Communication test case 19.1.5 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155932 | 3236 | 1 | Correction to testcase 19.2.4 Successful EPC-LEVEL ProSe Discovery | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155933 | 3253 | 1 | Addition of new D2D test case for Successful ProSe Direct Communication/Limited Service state | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155935 | 3152 | 1 | Update of MAC test case 7.1.4.15 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155936 | 3153 | 1 | Update of MAC test case 7.1.4.16 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155937 | 3154 | 1 | Update of MAC test case 7.1.4.21 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155938 | 3161 | 1 | Update of MAC test case 7.1.4.7a for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155939 | 3171 | 1 | Update to title of MAC MTC test case 7.1.1.1a | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155940 | 3173 | 1 | Update to title of MTC test case 7.1.1.1a in 36.523-2 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155942 | 3163 | 1 | Update of MAC test case 7.1.7.2.1 for LTE 64QAM UL | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155944 | 3214 | 1 | [PTCO] Implicit Testing: Removal of TC 8.1.2.1 update of 8.1.1.3 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155947 | 3162 | 1 | New Dual Connectivity test case 7.3.7.1 for PDCP Uplink Routing / Split DRB | 12.7.0 | 12.8.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2015-12 | RAN#70 | R5-155948 | 3179 | 1 | Addition of TC 8.2.2.9.5 Dual Connectivity test case for RRC connection reconfiguration / SCG change without handover / Split DRB modification within the same PSCell | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155949 | 3224 | 1 | Addition of Dual Connectivity RRC test case | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155950 | 3228 | 1 | Addition of Dual Connectivity RRC test case 8.2.4.25.2 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155951 | 3239 | 1 | Add test case 8.2.2.9.1 for dual connectivity | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155952 | 3241 | 1 | Add test case 8.2.2.9.2 for dual connectivity | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155955 | 3249 | 1 | New UEPCOP test case 9.2.1.1.7c Attach / Success / PSM | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155963 | 3169 | 1 | Correction 3GPP-WLAN interworking test case 6.5.5 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155964 | 3170 | 1 | Correction of Beacon RSSI parameters in test case 6.5.6 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155965 | 3172 | 1 | Correction of Beacon RSSI parameters in test case 8.4.8.3 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155966 | 3174 | 1 | Addition of new WLAN interworking test case for RRC Idle Mode | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155967 | 3175 | 1 | Addition of new WLAN interworking test case for RRC Connected Mode | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155968 | 3247 | 1 | Addition of new test case - WLAN Offload / T350 expiry | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155969 | 3248 | 1 | Addition of new test case - WLAN Offload / Offload Success / EUTRA RRC_Connected to/from WLAN (ANDSF and RAN rules co-existence) | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155970 | 3184 | 1 | Addition of new TC 7.1.7.1.8 SCE-L1 / DL-SCH transport block size selection / DCI format 1 / RA type 1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155971 | 3185 | 1 | Addition of new TC 7.1.7.1.9 SCE-L1 / DL-SCH transport block size selection / DCI format 1A / RA type 2 / Localised VRB | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155972 | 3186 | 1 | Addition of new TC 7.1.7.1.10 SCE-L1 / DL-SCH transport block size selection / DCI format 1A / RA type 2 / Distributed VRB | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155978 | 3165 | 1 | Corrections to LTE CSG Idle mode testcases | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155979 | 3182 | 1 | Correction to Test Case 6.3.4 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155980 | 3183 | 1 | Correction to Test Case 6.4.6 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155981 | 3201 | 1 | Update of RLC Test Case 7.2.2.5.1 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155983 | 3151 | 1 | Correction to eMDT test cases 8.6.8.x and 8.6.9.x | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155984 | 3176 | 1 | Optimization of EPS attach test case 9.2.1.1.13 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155985 | 3181 | 2 | Correction to Test Case 9.1.3.3 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155986 | 3200 | 1 | Correction to Rel-11 SIMTC test case 9.2.3.1.8b | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155987 | 3237 | 1 | Correction to GCF WI-082 EUTRA Testcase 9.1.5.1 | 12.7.0 | 12.8.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2015-12 | RAN#70 | R5-155988 | 3207 | 1 | Adding TC 13.1.19 and 13.1.20 for emergency call via CS domain | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155989 | 3208 | 1 | Addition of new applicability of Emergency call via CS domain TCs for IMS capable UE | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155991 | 3262 | - | Correction to EMM test case 9.3.1.4 for IMS enabled Ues | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-155992 | 3263 | - | Correction to ESM test case 10.5.3 for IMS enabled Ues | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156138 | 3225 | 2 | Extension of TC 8.5.4.1 for Multi PDN configuration | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156150 | 3222 | 1 | Correction to LTE-A rSRVCC test cases | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156152 | 3226 | 1 | Clarification to EMM test case 9.3.1.16 for IMS enabled UEs | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156153 | 3256 | 1 | Update of RLC test case 7.2.2.6 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156154 | 3257 | 1 | Update of RLC test case 7.2.2.7 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156155 | 3258 | 1 | Update of RLC test case 7.2.3.2 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156156 | 3259 | 1 | Update of RLC test case 7.2.3.10 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156157 | 3260 | 1 | Update of RLC test case 7.2.3.13 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2015-12 | RAN#70 | R5-156158 | 3261 | 1 | Update of RLC test case 7.2.3.15 for UE Cat 0 | 12.7.0 | 12.8.0 |
| 2016-03 | RAN#71 | R5-160075 | 3271 | - | Corrections to SCE-L1 test case 7.1.7.1.7 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160076 | 3272 | - | Corrections to SCE-L1 test case 7.1.7.1.8 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160078 | 3274 | - | Corrections to SCE-L1 test case 7.1.7.1.10 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160210 | 3283 | - | Correction to FDD-TDD CA test case 7.1.2.11.4 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160254 | 3284 | - | Corrections to the PIXIT item name of MFBI test cases | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160386 | 3304 | - | Correction to RRC CA test cases 8.2.4.16.x | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160478 | 3320 | - | Correction of EUTRA MAC UL MIMO test case 7.1.4.22 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160479 | 3321 | - | Correction to MDT test case 8.6.2.3 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160480 | 3322 | - | Correction to MDT test case 8.6.2.3a | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160526 | 3327 | - | Optimisation of Combined Attach test case 9.2.1.2.12 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160626 | 3333 | - | Adding a new TC ProSe Direct Communication Pre-configured authorisation UE is not served by E-UTRAN selection and re/selection of SyncRef UE | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160642 | 3344 | - | Correction to MAC test case 7.1.8.1 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160664 | 3348 | - | Correction to EUTRA RRC test case 8.5.4.1 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160715 | 3356 | - | Correction to LC MTC MAC test case 7.2.3.2 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160732 | 3281 | 1 | Correction to RFT-119 EUTRA Idle Mode Testcase 6.1.1.9 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160733 | 3282 | 1 | Correction to RFT-119 EUTRA Idle Mode Testcase 6.1.1.8 | 12.8.0 | 12.9.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-03 | RAN#71 | R5-160734 | 3305 | 1 | Correction to MAC test case 7.1.7.2.1 for LTE 64QAM UL | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160735 | 3280 | 1 | Correction to GCF WI-081 EUTRA RLC test case 7.2.3.15 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160736 | 3350 | 1 | Correction of Test case 8.6.9.1 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160737 | 3285 | 1 | Correction to EMM test case 9.2.3.4.1 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160739 | 3290 | 1 | Extension of EMM test cases 9.1.3.1 and 9.1.3.2 for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160740 | 3291 | 1 | Extension of EMM test cases 9.2.1.1.1, 9.2.1.1.1a and 9.2.1.1.1b for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160741 | 3292 | 1 | Extension of EMM test cases 9.2.1.1.7, 9.2.1.1.7a and 9.2.1.1.7b for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160742 | 3293 | 1 | Extension of EMM test cases 9.4.1 and 9.4.2 for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160743 | 3294 | 1 | Extension of EMM test cases 9.4.3 and 9.4.4 for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160745 | 3303 | 1 | Corrections to EMM test cases for Multi-PDN UE | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160746 | 3316 | 1 | Correction to Test Case 6.4.6 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160747 | 3332 | 1 | Correction to GCF WI-082 EUTRA EMM Testcase 9.2.1.2.3 with IMS enabled | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160748 | 3345 | 1 | Correction to EMM test case 9.3.1.17 for IMS-enabled UE | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160753 | 3357 | - | Correction to eMBMS-SC-CA test case 17.4.9.1 and 17.4.9.2 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160756 | 3359 | - | Corrections to LTE SSAC test cases 13.5.3 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160757 | 3360 | - | Corrections to LTE SSAC test case 13.5.3a | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160758 | 3297 | 1 | Correction of CS fallback emergency call procedure in TC 13.1.19 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160759 | 3265 | 1 | Correction to MBMS test case 17.4.3 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160769 | 3312 | 1 | Adding new test 19.1.1 for ProSe Direct Communication Transmission RRC_IDLE using resources on serving cells, with pre-configured authorisation | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160770 | 3313 | 1 | Adding new test 19.1.2 for ProSe Direct Communication Reception RRC_IDLE using the resources of the serving cell, with Pre-configured authorisation | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160771 | 3334 | 1 | Adding a new TC ProSe Direct Communication Pre-configured authorisation UE is not served by E-UTRAN selection and re/selection of SyncRef UE | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160772 | 3335 | 1 | Adding a new TC ProSe Direct Communication Pre-configured authorisation UE is communicating not on the serving cell | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160773 | 3336 | 1 | Adding a new TC ProSe Direct Communication Reception RRC_CONNECTED Pre-configured authorisation | 12.8.0 | 12.9.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-03 | RAN#71 | R5-160774 | 3337 | 1 | Adding a new TC ProSe Direct Communication Transmission RRC_CONNECTED Pre-configured authorisation | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160775 | 3338 | 1 | Adding a new TC ProSe Direct Discovery Announcing RRC_CONNECTED Pre-configured authorisation | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160776 | 3339 | 1 | Adding a new TC ProSe Direct Discovery Announcing Pre-configured authorisation RRC_IDLE | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160777 | 3340 | 1 | Adding a new TC ProSe Direct Discovery Monitoring Pre-configured authorisation | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160778 | 3341 | 1 | Removal of RRC ProSe TCs | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160783 | 3314 | 1 | New UEPCOP test case 9.2.3.1.1a Normal tracking area update / Accepted / PSM | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160785 | 3315 | 1 | New UEPCOP test case 9.2.3.1.5b Periodic tracking area update / Accepted / PSM / T3412 Extended Value | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160786 | 3266 | 1 | Addition of new SCE-L1 TC 7.1.7.1.11 DL-SCH transport block size selection / DCI format 2A / RA type 0 / Two transport blocks enabled / Transport block to codeword swap flag value set to '0' / 256QAM | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160787 | 3267 | 1 | Addition of new SCE-L1 TC 7.1.7.1.12 DL-SCH Transport Block Size selection / DCI format 2A / RA type 1 / Two transport blocks enabled / Transport block to codeword swap flag value set to '1' / 256QAM | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160788 | 3273 | 1 | Corrections to SCE-L1 test case 7.1.7.1.9 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160920 | 3295 | 1 | Update of SSAC test case 13.5.1a and removal of test case 13.5.1b | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160921 | 3296 | 1 | Update of SSAC test case 13.5.2a and removal of test case 13.5.2b | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160922 | 3289 | 2 | Extension of EMM test cases 9.1.2.3 and 9.1.2.4 for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160924 | 3279 | 1 | Correction to GCF WI-081 EUTRA MAC test case 7.1.4.7a | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160926 | 3301 | 1 | Correction to LTE IRAT CSG Test Case 6.3.4 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160932 | 3288 | 1 | Update of WLAN interworking test case 6.5.4 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160933 | 3318 | 1 | Merge of WLAN offload Idle mode test cases 6.5.1 in 6.5.6 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160934 | 3330 | 1 | Correction of parameters and message contents in test case 6.5.3 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160935 | 3331 | 1 | Correction of BackhaulRateULWAN parameters in test case 8.4.8.1 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160936 | 3349 | 1 | Correction of ChannelUtilizationWLAN parameters in test case 8.4.8.2 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160940 | 3302 | 1 | Add test case for Selection of ePDG | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160947 | 3361 | - | Extension of EMM test cases 9.2.1.1.19, 9.2.1.1.24, 9.2.1.1.25 and 9.2.1.1.26 for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160951 | 3307 | 1 | Correction to DC PDCP test case 7.3.7.1 | 12.8.0 | 12.9.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-03 | RAN#71 | R5-160953 | 3363 | - | Correction to Dual Connectivity test case 8.2.2.9.5, RRC connection reconfiguration / SCG change without handover / Split DRB modification within the same PSCell | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160954 | 3310 | 1 | Addition of test case 8.5.1.8.1 Dual Connectivity Radio link failure on PSCell / UE supports SCG DRB | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160955 | 3311 | 1 | Addition of test case 8.2.4.25.3 Dual Connectivity RRC connection reconfiguration / Intra-MeNB and SeNB Handover / Split DRB to Split DRB | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160956 | 3317 | 1 | Addition of Dual Connectivity MAC test cases for Dual Connectivity Power Headroom Report | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160957 | 3328 | 1 | New Dual Connectivity test case 7.3.7.2 for PDCP Data Recovery / Reconfiguration of Split DRB | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160958 | 3329 | 1 | New Dual Connectivity test case 7.3.7.3 for PDCP Data Recovery / Reconfiguration of Split DRB to MCG/SCG DRBs | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160959 | 3343 | 1 | Addition of Dual Connectivity PDCPre-establishment test cases | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160965 | 3325 | 1 | Extension of EMM test case 9.2.1.2.4a for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160966 | 3326 | 1 | Extension of EMM test case 9.2.3.2.25 for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160967 | 3268 | 1 | Addition of new SCE-L1 TC 8.3.1.29 Measurement configuration control and reporting / Intra E-UTRAN measurements / Event C1 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160968 | 3269 | 1 | Addition of new SCE-L1 TC 8.3.1.30 Measurement configuration control and reporting / Intra E-UTRAN measurements / Event C2 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160969 | 3270 | 1 | Addition of new SCE-L1 TC 8.3.1.31 Measurement configuration control and reporting / Intra E-UTRAN measurements / Periodic reporting / CSI-RSRP | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160984 | 3346 | 1 | Correction to EMM test case 9.2.1.1.28a | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160991 | 3362 | 1 | Handling of UTRAN Registration procedure for LTE-IRAT test cases | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-160999 | 3367 | - | Correction to LTE-A UL CA test cases 7.1.4.20.x | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-161090 | 3298 | 2 | Correction to LTE-IRAT testcase 9.2.3.1.6 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-161091 | 3342 | 2 | Moving ProSe security TCs to the PDCP section | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-161092 | 3364 | 1 | Extension of EMM test cases 9.2.1.2.1, 9.2.1.2.2, and 9.2.1.2.4 for Multi-PDN configuration | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-161119 | 3358 | 1 | Correction to eMDT test case 8.6.7.1 | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | R5-161120 | 3365 | 1 | Update of 3GPP/WLAN test case: WLAN Offload / T350 expiry | 12.8.0 | 12.9.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2016-03 | RAN#71 | R5-161121 | 3366 | 1 | Update of 3GPP/WLAN test case: WLAN Offload / Offload Success / EUTRA RRC_Connected to/from WLAN (ANDSF and RAN rules co-existence) | 12.8.0 | 12.9.0 |
| 2016-03 | RAN#71 | - | - | - | Upgraded to v13.0.0 with no change | 12.9.0 | 13.0.0 |
| 2016-06 | RAN#72 | R5-162060 | 3375 | - | Corrections to various WLAN Offload Idle test cases | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162061 | 3376 | - | Corrections to various WLAN Offload Connected test cases | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162062 | 3377 | - | Correction to test case 8.6.5.4 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162064 | 3378 | - | Add test case for Tunnel establishment | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162135 | 3383 | - | Correction to UEPCOP EMM test cases | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162136 | 3384 | - | Update test case 20.1 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162146 | 3386 | - | Correction to Dual Connectivity PDCP Test Cases 7.3.7.1 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162185 | 3392 | - | Correction to EUTRA eMDT TC 8.6.8.5 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162287 | 3398 | - | Correction to EMM test case 9.2.2.1.2 for IMS-enabled device | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162293 | 3402 | - | New eIMTA test case for DL-SCH data transfer | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162365 | 3405 | - | Introduction of Specific Message Content for Dual Connectivity test case 8.2.4.25.3, RRC connection reconfiguration / Intra-MeNB Handover / Split DRB to Split DRB | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162366 | 3406 | - | Correction to Dual Connectivity test case 8.2.2.9.5, RRC connection reconfiguration / SCG change without handover / Split DRB modification within the same PSCell | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162381 | 3417 | - | Correction to MDT test case 8.6.7.2 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162454 | 3428 | - | Addition of TC 8.2.2.9.3 RRC connection reconfiguration / SCG change without handover / SCG DRB to MCG DRB and SCG DRB modification | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162458 | 3432 | - | Correction to MeasObjectGERAN table in test case 8.6.7.2 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162462 | 3436 | - | Correction to test case 7.1.2.11.4 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162516 | 3438 | - | Addition of a new TC for SC-MCCH information acquisition UE power on | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162517 | 3439 | - | Addition of a new TC for SC-MCCH information acquisition cell reselection to a cell broadcasting SIB20 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162518 | 3440 | - | Addition of a new TC for SC-MCCH information acquisition UE handover to a cell broadcasting SIB20 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162520 | 3442 | - | Addition of a new TC for SC-MCCH information acquisition UE is not receiving SC-PTM data | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162521 | 3443 | - | Addition of a new TC for SC-PTM DRX operation / Parameters configured by RRC | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162524 | 3444 | - | Correction to test case 8.6.7.1/8.6.7.2 | 13.0.0 | 13.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2016-06 | RAN#72 | R5-162536 | 3445 | - | Correction to Dual connectivity PDCP test cases | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162674 | 3467 | - | Correction to EMM test case 9.1.2.5 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162679 | 3468 | - | Correction to EMM test case 9.1.2.7 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162696 | 3471 | - | Correction to GCF WI-82 9.2.3.1.15 and 9.2.3.1.15a with IMS enabled | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162699 | 3474 | - | Correction to Testcase 8.6.9.1 Connection Establishment Failure logging / Logging and reporting / Reporting at UTRAN Inter-RAT handover | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162714 | 3480 | - | Addition of a new TC for Cell reselection to intra-frequency cell to continue SC-PTM service reception / Single Frequency operation (inter-band neighbouring cell) | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162716 | 3482 | - | Addition of a new TC for Cell reselection to inter-band cell to start SC-PTM service reception | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162718 | 3483 | - | Corrections to the SCE-L1 TC of 7.1.7.1.11 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162719 | 3484 | - | Corrections to the SCE-L1 TC of 7.1.7.1.12 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162729 | 3490 | - | Correction to eMDT test cases 8.6.8.x and 8.6.9.x | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162732 | 3493 | - | Correction to MTC test case 10.5.4 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162741 | 3495 | - | Correction to LTE<->IRAT Emergency testcases 13.1.19 and 13.1.20 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162742 | 3496 | - | Correction to RRC CA test cases 8.2.4.16.1 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162770 | 3485 | 1 | Corrections to the Idle mode TC of 6.1.1.8 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162771 | 3487 | 1 | Corrections to the Idle mode TC of 6.1.1.9 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162772 | 3475 | 1 | Correction to Testcase 8.6.5.1a Radio Link Failure logging / Reporting at UTRAN Inter-RAT handover / PLMN list | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162773 | 3385 | 1 | Correction to Test Case 9.2.1.2.4 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162774 | 3399 | 1 | Correction to EMM test case 9.2.1.1.18 for Multi-PDN enabled device | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162775 | 3400 | 1 | Correction to EMM test case 9.2.1.1.2 for Multi-PDN enabled device | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162776 | 3401 | 1 | Correction to EMM test case 9.2.1.1.26 for Multi-PDN enabled device | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162777 | 3409 | 1 | Correction to EMM test cases 9.2.1.2.2 and 9.2.1.2.4 for Multi-PDN enabled UE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162778 | 3410 | 1 | Correction to EMM test case 9.2.1.2.4a for Multi-PDN enabled device | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162779 | 3411 | 1 | Correction to EMM test case 9.3.1.17 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162780 | 3412 | 1 | Correction to EMM test case 9.2.3.2.3 for IMS-enabled UE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162781 | 3413 | 1 | Correction to EMM test case 9.2.1.1.19 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162782 | 3414 | 1 | Correction to EMM test case 9.2.3.1.25 | 13.0.0 | 13.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-06 | RAN#72 | R5-162783 | 3449 | 1 | Correction to EMM test cases to refer the generic registration procedure steps | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162784 | 3462 | 1 | Correction to EMM test case 9.2.2.2.1 for Multi-PDN enabled UE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162785 | 3463 | 1 | Correction to EMM test case 9.2.3.1.5 for Multi-PDN enabled UE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162786 | 3464 | 1 | Correction to EMM test case 9.2.1.1.7c to refer the generic registration procedure steps | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162787 | 3492 | 1 | Correction of EMM test cases 9.2.1.1.1, 9.2.1.1.1a for Multi-PDN UE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162788 | 3491 | 1 | Correction of EMM test cases 9.2.1.2.1, 9.2.3.2.2 for Multi-PDN UE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162789 | 3418 | 1 | Correction to Rel-12 SSAC test cases | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162791 | 3497 | - | Correction to SRVCC Testcases 13.4.3.2, 13.4.3.14, 13.4.3.16 and 13.4.3.18 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162792 | 3473 | 1 | Correction to GCF WI-178 eMBMS testcases 17.4.5 and 17.4.6 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162799 | 3498 | - | Addition of New Test Case - Attach and Normal tracking area update Procedure / Success / With and without Idle eDRX parameters | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162900 | 3499 | - | Addition of New Test Case - Attach & Normal tracking area update Procedure / Success / With and without Idle eDRX and PSM parameters | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162905 | 3500 | - | Correction to FDD-TDD MAC CA test cases 7.1.3.11.x | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162910 | 3450 | 1 | Update of test 19.1.1 for ProSe Direct Communication Transmission RRC_IDLE using resources on serving cells, with pre-configured authorisation | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162911 | 3451 | 1 | Update of test case 19.1.2 for ProSe Direct Communication Reception RRC_IDLE using the resources of the serving cell, with Pre-configured authorisation | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162912 | 3452 | 1 | Update of TC 19.1.3 ProSe Direct Communication Transmission RRC_CONNECTED Pre-configured authorisation | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162913 | 3453 | 1 | Update of TC 19.1.4 ProSe Direct Communication Reception RRC_CONNECTED Pre-configured authorisation | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162914 | 3454 | 1 | Update of TC 19.1.5 ProSe Direct Communication Pre-configured authorisation UE is communicating not on the serving cell | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162915 | 3455 | 1 | Update of TC 19.1.6 ProSe Direct Communication Pre-configured authorisation UE out of coverage on the frequency used for sidelink communication | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162916 | 3456 | 1 | Update of TC 19.1.7 ProSe Direct Communication Pre-configured authorisation Selection and re/selection of SyncRef UE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162917 | 3457 | 1 | Update to TC 19.2.1 ProSe Direct Discovery Monitoring Pre-configured authorisation | 13.0.0 | 13.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-06 | RAN#72 | R5-162918 | 3458 | 1 | Update of TC 19.2.2 ProSe Direct Discovery Announcing Pre-configured authorisation RRC_IDLE | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162919 | 3459 | 1 | Update of TC 19.2.3 ProSe Direct Discovery Announcing RRC_CONNECTED Pre-configured authorisation | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162920 | 3488 | 1 | Correction to D2D ProSe PDCP test cases 7.3.8.1 and 7.3.8.2 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162921 | 3430 | 1 | Correction to TC 8.3.1.29 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162922 | 3431 | 1 | Correction to TC8.3.1.30 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-162923 | 3433 | 1 | Correction to TC8.3.1.31 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163002 | 3403 | 1 | New eIMTA test case for UL-SCH data transfer | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163006 | 3395 | 1 | Addition of New Test Case – 7.1.3.4a Correct HARQ process handling / DCCH and DTCH/ Enhanced Coverage | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163007 | 3447 | 1 | Addition of new eMTC test case for Correct HARQ process handling / Enhanced Coverage | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163008 | 3448 | 1 | Addition of new eMTC test case Correct HARQ process handling / Enhanced Coverage / CE Mode B | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163026 | 3407 | 1 | Correction to Dual Connectivity test case 8.5.1.8.1, Radio link failure on PSCell / UE supports SCG DRB | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163027 | 3408 | 1 | Introduction of Dual Connectivity test case 8.5.1.8.2, Radio link failure on PSCell / UE supports Split DRB | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163028 | 3423 | 1 | Add dual connectivity test case 8.2.4.25.4 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163029 | 3424 | 1 | Add dual connectivity test case 8.2.4.25.5 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163030 | 3425 | 1 | Add dual connectivity test case 8.2.4.25.6 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163031 | 3426 | 1 | Add dual connectivity test case 8.2.4.25.7 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163032 | 3429 | 1 | Addition of TC 8.2.2.9.4 RRC connection reconfiguration / SCG change without handover / Split DRB to MCG/SCG DRBs | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163033 | 3494 | 1 | Correction to Dual Connectivity PDCP Test Cases 7.3.7.2 and 7.3.7.3 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163039 | 3441 | 1 | Addition of a new TC for SC-MCCH information acquisition UE is receiving an SC-PTM service | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163040 | 3479 | 1 | Addition of a new TC for Cell reselection to intra-frequency cell to continue SC-PTM service reception | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163041 | 3481 | 1 | Addition of a new TC for Cell reselection to inter-frequency cell to start SC-PTM service reception | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163051 | 3470 | 1 | Correction to GCF WI-082 EUTRA EMM Testcase 9.2.1.2.3 with IMS enabled | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163054 | 3404 | 1 | Correction to LTE IRAT idle mode testcases (IMS over UTRA behaviour) | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163056 | 3502 | - | Addition of new test case 6.1.2.23 for MFBI enhancement | 13.0.0 | 13.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-06 | RAN#72 | R5-163057 | 3437 | 1 | Updates to TCs 7.1.3.11.4 and 7.1.3.11.5 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163058 | 3503 | - | Correction to EMM test case 9.2.1.1.30 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163059 | 3472 | 1 | Correction to EMM test case 9.2.1.1.28 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163060 | 3476 | 1 | Correction to IMS Emergency Call test case 11.2.7 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163062 | 3478 | 1 | Correction to CMAS test case 18.1.3 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163073 | 3486 | 1 | Correction to LTE-A CA 2UL test cases 7.1.2.11.x | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163074 | 3387 | 1 | Update dual connectivity test case 8.2.2.9.1 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163075 | 3388 | 1 | Update dual connectivity test case 8.2.2.9.2 | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163076 | 3427 | 1 | Addition of Dual Connectivity MAC test cases for Dual Connectivity Buffer Status Report | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163082 | 3461 | 1 | Addition of test case 8.2.2.10: eIMTA / RRC connection reconfiguration / Radio resource reconfiguration / Success | 13.0.0 | 13.1.0 |
| 2016-06 | RAN#72 | R5-163083 | 3465 | 1 | Addition of test case 8.2.2.26: eIMTA / RRC connection reconfiguration / Handover / Success | 13.0.0 | 13.1.0 |
| 2016-09 | RAN#73 | R5-165021 | 3506 | - | Correction to EMM test case 9.3.1.6 for Multi-PDN UEs | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165133 | 3515 | - | Addition of a new TC for Handover to inter-band cell to start SC-PTM service reception | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165332 | 3532 | - | Correction to GCF WI-177 EUTRA RRC testcase 8.6.4.3 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165339 | 3538 | - | Correction to LTE IRAT testcases 6.3.3 and 6.3.4 (IMS over UTRA behaviour) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165341 | 3539 | - | Correction to EMM test case 9.2.1.2.4 to resolve merging conflict of RAN5#71 CR's | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165461 | 3551 | - | Update of test case 19.1.2 for ProSe Direct Communication Reception RRC_IDLE using the resources of the serving cell, with Pre-configured authorisation | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165463 | 3553 | - | Update of TC 19.1.4 ProSe Direct Communication Reception RRC_CONNECTED Pre-configured authorisation | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165468 | 3558 | - | Update of TC 19.2.2 ProSe Direct Discovery Announcing Pre-configured authorisation RRC_IDLE | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165470 | 3560 | - | Removal of D2D TC 19.1.7 and redundant titles | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165539 | 3572 | - | Correction to Rel-10 MDT test case 8.6.3.1 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165556 | 3573 | - | Correction to Rel-11 eMDT test case 8.6.9.2 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165561 | 3578 | - | Corrections to IMS Emergency Call test case 11.2.7 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165727 | 3600 | - | Update dual connectivity test case 8.2.4.25.5 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165730 | 3601 | - | Update dual connectivity test case 8.2.4.25.6 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165738 | 3602 | - | Update dual connectivity test case 8.2.4.25.7 | 13.1.0 | 13.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2016-09 | RAN#73 | R5-165742 | 3604 | - | Corrections to EMM test cases for Multi-PDN UEs | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165757 | 3608 | - | Removing EMM test case 9.2.1.1.30 from TS 36.523-1 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165762 | 3609 | - | Correction to EMM test cases 9.2.1.1.1a for Multi-PDN UE | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165763 | 3610 | - | Correction to EMM test cases 9.2.1.2.1 for Multi-PDN UE | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165766 | 3611 | - | Correction to EMM test cases 9.2.3.2.2 for Multi-PDN UE | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165816 | 3620 | - | Correction to LTE IRAT testcases 6.4.6 (IMS over UTRA behaviour) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165871 | 3622 | - | Addition of New eDRX MAC test case for Long DRX cycle | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165881 | 3623 | - | Correction to GCF WI-082 EMM test case 9.2.1.1.11 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165895 | 3548 | 1 | Update of IDLE mode Cell selection test case 6.2.2.5 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165896 | 3563 | 1 | Correction to Idle mode test case 6.1.1.4a | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165898 | 3533 | 1 | Correction to LTE IRAT testcase 8.1.3.7 (IMS over UTRA behaviour) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165899 | 3534 | 1 | Correction to LTE IRAT testcase 8.5.2.1 (IMS over UTRA behaviour) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165904 | 3605 | 1 | Correction to eMDT testcase 8.6.6.5 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165905 | 3535 | 1 | Correction to LTE IRAT testcase 9.2.2.1.10 (IMS over UTRA behaviour) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165906 | 3536 | 1 | Correction to LTE IRAT testcase 9.2.3.1.6 (IMS over UTRA behaviour) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165907 | 3537 | 1 | Correction to LTE IRAT testcase 9.2.3.3.1 (IMS over UTRA behaviour) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165909 | 3598 | 1 | Correction to LTE<->GERAN EMM test case 9.2.3.4.1 for IMS-enabled device | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165910 | 3606 | 1 | Correction to SIMTC test case 9.2.1.1.27a | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165911 | 3624 | - | Adding reference to generic procedure for IMS over GERAN for Idle mode test cases | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165912 | 3625 | - | Correction to Rel-11 SIMTC test cases 9.2.1.1.27 and 9.2.3.1.8a to update test USIM contents | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165914 | 3540 | 1 | Correction to IMS emergency call test case 11.2.6 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165915 | 3574 | 1 | Correction to IMS emergency call test case 11.2.3 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165916 | 3575 | 1 | Correction to IMS emergency call test case 11.2.8 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165928 | 3524 | 1 | Corrections to eDRX TC 9.2.4.1.1 - Attach & Normal tracking area update Procedure / Success / without Idle eDRX parameters / With Idle eDRX parameters | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165929 | 3528 | 1 | Addition of new eDRX Test case 8.1.1.2a | 13.1.0 | 13.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-09 | RAN#73 | R5-165930 | 3529 | 1 | Addition of new eDRX Test case 9.2.4.1.3 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165953 | 3565 | 1 | Correction to Rel-12 LC-MTC test case 7.1.3.3a | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165961 | 3527 | 1 | Addition of new D2D Test case 7.3.8.3 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165962 | 3550 | 1 | Update of test 19.1.1 for ProSe Direct Communication Transmission RRC_IDLE using resources on serving cells, with pre-configured authorisation | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165963 | 3552 | 1 | Update of TC 19.1.3 ProSe Direct Communication Transmission RRC_CONNECTED Pre-configured authorisation | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165964 | 3554 | 1 | Update of TC 19.1.5 ProSe Direct Communication Pre-configured authorisation UE is communicating not on the serving cell | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165965 | 3555 | 1 | Update of TC 19.1.6 ProSe Direct Communication Pre-configured authorisation UE out of coverage on the frequency used for sidelink communication | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165966 | 3557 | 1 | Update to TC 19.2.1 ProSe Direct Discovery Monitoring Pre-configured authorisation | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165967 | 3559 | 1 | Update of TC 19.2.3 ProSe Direct Discovery Announcing RRC_CONNECTED Pre-configured authorisation | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165968 | 3614 | 1 | Correction to ProSe D2D test cases 7.3.8.x | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165969 | 3596 | 1 | New eIMTA CA test case for DL-SCH data transfer | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165970 | 3597 | 1 | New eIMTA CA test case for UL-SCH data transfer | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165972 | 3518 | 1 | Corrections to SCE-L1 test case 7.1.7.1.7, 7.1.7.1.8, 7.1.7.1.9, 7.1.7.1.10, 7.1.7.1.11 and 7.1.7.1.12 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165973 | 3599 | 1 | Update dual connectivity test case 8.2.4.25.4 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165974 | 3561 | 1 | Test sequence for Dual Connectivity test case 8.5.1.8.1, Radio link failure on PSCell / UE supports SCG DRB | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165975 | 3562 | 1 | Test sequence for Dual Connectivity test case 8.5.1.8.2, Radio link failure on PSCell / UE supports Split DRB | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-165999 | 3543 | 1 | Correction to the initial conditions in 8.2.2.9.3 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166201 | 3507 | 1 | Introduction of new TC 21.3.9 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166202 | 3508 | 2 | Introduction of new TC 21.3.10.1 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166203 | 3509 | 1 | Introduction of new TC 21.3.10.2 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166204 | 3510 | 2 | Introduction of new TC 21.3.11.1 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166205 | 3511 | 1 | Introduction of new TC 21.3.11.2 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166206 | 3512 | 2 | Introduction of new TC 21.3.12.1 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166207 | 3513 | 1 | Introduction of new TC 21.3.12.2 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166208 | 3514 | 1 | Addition of a new TC for Handover to inter-frequency cell to start SC-PTM service reception | 13.1.0 | 13.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2016-09 | RAN#73 | R5-166211 | 3516 | 1 | Addition of a new TC for Handover to intra-frequency cell to continue SC-PTM service reception | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166212 | 3517 | 1 | Addition of a new TC for Conditional retransmission of MBMS Interest Indication after handover | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166213 | 3519 | 1 | Corrections to SC-PTM test case 21.3.1 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166214 | 3521 | 1 | Addition of a new TC for MBMS Interest Indication retransmission after returning from cell not broadcasting SIB20 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166215 | 3522 | 1 | Addition of a new TC for MBMS Interest Indication after Radio Link Failure | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166216 | 3525 | 1 | Corrections to SC-PTM test case 21.3.2 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166217 | 3592 | 1 | Addition of a new test case 21.3.6 MBMS Interest Indication retransmission after returning from cell not broadcasting SIB15 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166222 | 3629 | - | Addition of new LWA Test case - LWA / WLAN Release / WLAN Association / EUTRA RRC_Connected to WLAN (Event W2) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166223 | 3630 | - | Addition of new LWA Test case - LWA / WLAN Release Success / EUTRA RRC_Connected from WLAN (Event W3) | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166225 | 3631 | - | Addition of new test case: NB-IoT / PLMN selection of RPLMN, HPLMN / EHPLMN, UPLMN and OPLMN / Automatic mode | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166226 | 3632 | - | Addition of new test case: NB-IoT / Cell selection / Qrxlevmin | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166229 | 3633 | - | Addition of reference RLC NB-IoT test case | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166247 | 3526 | 1 | Clarification for LTE-GERAN Idle Mode test case 6.2.2.2 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166248 | 3544 | 1 | Update test 6.1.2.19 for band 65 and higher | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166250 | 3618 | 1 | Update test 6.1.2.20 for band 65 and higher | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166251 | 3619 | 1 | Update test 6.1.2.21 for band 65 and higher | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166255 | 3576 | 1 | Correction to Multi-Layer test case 13.1.2a | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166262 | 3523 | 1 | Addition of New Test Case – 7.1.3.5a Correct HARQ process handling / CCCH/ Enhanced Coverage | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166264 | 3634 | - | Introduction of new eMTC Signalling test case 8.1.1.1a | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166265 | 3545 | 1 | Addition of New eMTC Test Case – 7.1.2.3a Correct selection of RACH parameters/ Preamble selected by MAC itself/ Contention based random access procedure/ Enhanced coverage | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166266 | 3593 | 1 | Addition of new eMTC idle test case for Cell selection / Qrxlevmin / Enhanced coverage | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166267 | 3595 | 1 | Addition of new eMTC idle test case for Cell reselection using Treselection / Enhanced coverage | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166268 | 3594 | 1 | Addition of new eMTC idle test case for Cell selection / Qqualmin / Enhanced coverage | 13.1.0 | 13.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-09 | RAN#73 | R5-166269 | 3607 | 1 | Update of MAC legacy UE Cat o test cases to expand applicability to UE Cat M1 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166270 | 3612 | 1 | New eMTC test case: 7.1.7.1.13 DL-SCH transport block size selection / DCI format 6-1A | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166271 | 3613 | 1 | New eMTC test case: 7.1.7.2.2 UL-SCH transport block size selection / DCI format 6-0A | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166275 | 3626 | 1 | Correction to Rel-11 SIMTC test cases 10.5.x to update test USIM contents | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166281 | 3564 | 1 | Update of CSG Testcase 8.3.4.5 | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166286 | 3635 | 1 | Addition of representative MAC NB-IoT test case | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166320 | 3628 | 2 | Addition of a new test case 22.3.3.2.1 Integrity protection / Ciphering and deciphering / Correct functionality of EPS AS and UP encryption algorithms / SNOW3G | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166321 | 3627 | 2 | Corrections to eDRX TC 9.2.4.1.2 - Attach & Normal tracking area update Procedure / Success / With and without Idle eDRX and PSM parameters | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166322 | 3579 | 2 | Update of Idle Mode Testcases | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166323 | 3617 | 2 | Correction of test case 6.1.2.23 for MFBI enhancement | 13.1.0 | 13.2.0 |
| 2016-09 | RAN#73 | R5-166324 | 3530 | 2 | Updates to test case 8.5.4.1 | 13.1.0 | 13.2.0 |
| 2016-12 | RAN#74 | R5-168073 | 3636 | - | Update of ProSe Direct Communication test case 19.1.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168074 | 3637 | - | Update of ProSe Direct Communication test case 19.1.2 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168075 | 3638 | - | Update of ProSe Direct Communication test case 19.1.3 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168076 | 3639 | - | Update of ProSe Direct Communication test case 19.1.4 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168077 | 3640 | - | Update of ProSe Direct Communication test case 19.1.5 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168078 | 3641 | - | Update of ProSe Direct Communication test case 19.1.6 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168080 | 3643 | - | Correction to eDRX RRC test case 8.1.1.2a | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168081 | 3644 | - | Correction to eDRX EMM test cases | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168137 | 3648 | - | Correction to Rel-11 eMDT test case 8.6.10.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168140 | 3649 | - | Correction to Rel-12 MFBI test case 6.1.2.23 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168162 | 3650 | - | Update the title of NB-IoT test case 22.2.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168163 | 3651 | - | Update the title of NB-IoT test case 22.2.4 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168167 | 3654 | - | New NB-IoT EMM-CIoT testcase: 22.5.12 - NB-IoT / EPS NAS integrity and encryption / ZUC | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168255 | 3662 | - | Correction to test cases 17.4.3, 17.4.4, 17.4.5 and 17.4.6 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168298 | 3665 | - | Introduction of new signalling EMM-CIoT test case 22.5.10 for category NB1 | 13.2.0 | 13.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-12 | RAN#74 | R5-168299 | 3666 | - | Introduction of new signalling EMM-CIoT test case 22.5.11 for category NB1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168320 | 3667 | - | Correction to EUTRA<>GERAN Idle Mode test case 6.2.3.27 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168347 | 3669 | - | New test NB-IoT 22.5.1 Authentication failures | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168356 | 3674 | - | Correction to EUTRA Transport block size selection test cases 7.1.7.x.x | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168359 | 3675 | - | Correction to EUTRA PDCP test case 7.3.5.3 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168361 | 3676 | - | Correction to Rel-12 LTE Cov Enh test case 7.1.4.24 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168364 | 3678 | - | Correction to Rel-13 eDRX test case 9.2.4.1.2 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168385 | 3680 | - | Correction to UEPCOP test cases 9.2.1.1.7c, 9.2.3.1.1.a and 9.2.3.1.5b | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168423 | 3683 | - | Correction to Rel-11 SIMTC test case 10.8.8 to update test USIM contents | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168434 | 3684 | - | Correction to IMS emergency call test case 11.2.10 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168436 | 3685 | - | Correction to reference to generic procedure for Redirection from GERAN to E-UTRA upon release of the CS connection in test 6.2.3.19 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168438 | 3686 | - | Editorial update on table numbering in LTE IRAT test case 8.5.2.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168440 | 3687 | - | Editorial update on UE configurations for SIMTC test cases 9.2.1.1.27 and 9.2.3.1.8a and Extended Access Class Barring test case 9.2.3.1.8b | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168441 | 3688 | - | Update on UE configurations for SIMTC test cases 10.5.1a, 10.5.1b and 10.5.4 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168479 | 3696 | - | Update of eMTC test case 7.1.4.24b | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168507 | 3702 | - | Corrections to RLC NB-IoT test case 22.3.2.2 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168520 | 3706 | - | Correction of missing TP in TC7.1.6.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168542 | 3713 | - | Correction of test case 7.1.3.16a | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168543 | 3714 | - | Correction of test case 7.1.4.28a | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168586 | 3722 | - | Update to MAC test cases 7.1.7.1.9 and 7.1.7.1.10 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168590 | 3723 | - | Addition of a new test case 22.3.1.3 Correct Handling of UL MAC PDU/Assignment/HARQ process/Padding | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168591 | 3724 | - | Addition of a new test case 22.3.2.3 AM RLC / In sequence delivery of upper layers PDUs/ Different numbers of length indicators | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168613 | 3726 | - | Update test case 8.2.4.25.4 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168617 | 3728 | - | Update test case 8.2.4.25.6 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168625 | 3729 | - | Update test case 8.2.4.25.7 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168700 | 3730 | - | New Dual Connectivity test case for PDCP reordering of Split DRB / Maximum re-ordering delay below t-Reordering | 13.2.0 | 13.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2016-12 | RAN#74 | R5-168707 | 3734 | - | Editorial correction to EMM test case 9.2.1.2.15 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168729 | 3735 | - | Correction to test case 6.4.6 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168772 | 3742 | - | Correction to MAC test case 7.1.1.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168781 | 3743 | - | Update of eMTC Test Case 7.1.2.3a | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168786 | 3744 | - | Addition of New NB-IoT MAC Test Case – 22.3.1.4: NB-IoT / Correct handling of MAC control information / Buffer status | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168868 | 3751 | - | Corrections to eMTC test case 7.1.3.4a | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168870 | 3753 | - | Corrections to eMTC test case 7.1.3.5a | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168966 | 3769 | - | Addition of New NB-IoT RRC Test Case – 22.4.7: NB-IoT / RRC connection release / Success with extendedWait / RRC connection establishment / Reject with extendedWait | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168969 | 3772 | - | Addition of New NB-IoT RRC Test Case – 22.4.11: NB-IoT / RRC connection release / Redirection to another NB-IoT frequency | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-168970 | 3773 | - | Addition of New NB-IoT RRC Test Case – 22.4.12: NB-IoT / RRC connection release / Redirection to another NB-IoT band | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169010 | 3653 | 1 | New NB-IoT RRC testcase: 22.4.13 - NB-IoT / UE capability transfer / Success | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169011 | 3656 | 1 | New NB-IoT Idle testcase: 22.2.8 - NB-IoT / Cell reselection in shared network environment. | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169015 | 3670 | 1 | New test NB-IoT 22.5.2 NAS security | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169016 | 3671 | 1 | New test NB-IoT 22.5.3 Detach | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169017 | 3672 | 1 | New test NB-IoT 22.5.4 Attach/Detach | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169020 | 3695 | 1 | Addition of new NB-IoT MAC test case 22.3.1.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169021 | 3701 | 1 | Addition of RLC NB-IoT test case 22.3.2.4 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169022 | 3718 | 1 | Addition of RLC NB-IoT test case 22.3.2.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169023 | 3710 | 1 | Introduction of new signalling EMM-CIoT test case 22.5.8 for category NB1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169024 | 3719 | 1 | Addition of new NB-IoT Test case for Paging for BCCH modification | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169025 | 3720 | 1 | Addition of new NB-IoT Test case "Paging for connection in idle mode / Multiple paging records" | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169026 | 3750 | 1 | Addition of new NB-IoT RLC test case 22.3.2.5 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169027 | 3757 | 1 | New test case 22.5.9 NB-IoT / UE in NB-S1 mode supporting CiOT Optimizations / Paging with not matching identity / Control Plane Service request Rejected (IMSI invalid / Illegal ME / EPS services not allowed / UE identity cannot be derived by the network | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169028 | 3758 | 1 | New test case 22.5.18 Attach & Normal tracking area update Procedure / Success / without Idle eDRX parameters / With Idle eDRX parameters/ With and without Idle eDRX and PSM parameters | 13.2.0 | 13.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2016-12 | RAN#74 | R5-169029 | 3768 | 1 | New test case 22.5.14 NB-IoT / Attach / Rejected / Tracking Area not allowed/Roaming not allowed in this tracking area// No suitable cells in tracking area | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169030 | 3696 | 1 | Update of eMTC test case 7.1.4.24b | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169031 | 3700 | 1 | Addition of MAC eMTC DRX test case | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169033 | 3717 | 1 | Correction to eMTC RRC test case 8.1.1.1a | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169036 | 3673 | 1 | Adding reference to generic procedure for IMS over GERAN for Idle Mode test cases | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169037 | 3739 | 1 | Correction to EUTRA Idle Mode CSG test case 6.3.4 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169038 | 3642 | 1 | Updates to test case 8.5.4.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169039 | 3752 | 1 | Correction to RRC test case 8.3.1.5 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169040 | 3682 | 1 | Adding reference to generic procedure for IMS over GERAN for EMM test cases | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169041 | 3645 | 1 | Correction to test case 11.2.6 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169042 | 3776 | - | Update to IMS Emergency Call over EPS Test case 11.2.8 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169043 | 3733 | 1 | Correction to IMS Emergency Call test case 11.2.7 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169048 | 3658 | 1 | Corrections to several SC-PTM test cases in section 21.3 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169051 | 3777 | - | Correction to SCM test case 13.5.4 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169056 | 3778 | - | Corrections to several SC-PTM test cases | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169075 | 3646 | 1 | Update test case 20.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169076 | 3647 | 1 | Update test case 20.2 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169077 | 3736 | 1 | Add test case for UE initiated disconnection | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169078 | 3740 | 1 | Add test case for ePDG initiated disconnection | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169110 | 3655 | 1 | Correction of test case 8.2.4.26 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169111 | 3689 | 1 | Addition of new eMDT2 testcase: Radio Link Failure logging / Logging and reporting / Dropped QCI | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169115 | 3681 | 1 | Correction to EUTRA RRC test case 8.5.4.1 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169117 | 3677 | 1 | Correction to Rel-11 eDDA test cases 8.2.2.6.x | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169118 | 3754 | 1 | Correction to EMM test case 9.2.3.3.3 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169119 | 3762 | 1 | Correction to IMS emergency call test cases 11.2.3 and 11.2.7 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169123 | 3760 | 1 | New test case 22.5.17 Attach Success /Normal tracking area update accepted / Periodic tracking area update T3412 Extended Value / PSM | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169131 | 3652 | 1 | New NB-IoT Idle testcase: NB-IoT / 22.2.5 - Cell reselection / Qhyst, Qoffset, Treselection and Cell-specific reselection parameters | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169132 | 3657 | 1 | New NB-IoT Idle testcase: 22.2.9 - NB-IoT / Inter-frequency cell reselection | 13.2.0 | 13.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2016-12 | RAN#74 | R5-169134 | 3775 | 1 | Addition of New NB-IoT NAS Test Case – NB-IoT / Attach Procedure / Success / Last visited TAI, TAI list and equivalent PLMN list handling | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169135 | 3661 | 1 | Addition of New NB-IoT Test Case – NB-IoT / Normal tracking area update / Rejected / EPS service not allowed /EPS services not allowed in this PLMN | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169138 | 3668 | 1 | New test 22.1.1 Control Plane CIoT EPS optimisation for EPS services | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169139 | 3691 | 1 | Addition of New NB-IoT Idle Mode Test Case - NB-IoT / Cell reselection using cell status and cell reservations / Access control class 0 to 9 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169140 | 3692 | 1 | Addition of New NB-IoT RRC Test Case - NB-IoT / RRC / Paging for notification of BCCH modification in idle mode / Direct indication for SI update | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169141 | 3693 | 1 | Addition of New NB-IoT Idle Mode Test Case – NB-IoT / Cell reselection using cell status and cell reservations / Access control class 11 to 15 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169142 | 3694 | 1 | Addition of New NB-IoT Test Case – NB-IoT / RRC connection establishment / Access Barring for UE with AC 0 to 9 / MO exception data / ab-Category a, b and c | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169143 | 3774 | 1 | Addition of New NB-IoT Test Case – NB-IoT / Attach Procedure / Success / List of equivalent PLMNs in the ATTACH ACCEPT message / Attach / Rejected / PLMN not allowed | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169145 | 3781 | - | Editorial CR updating test case title of NB-IoT MAC test case | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169146 | 3755 | 1 | Addition of new NB-IoT MAC test case 22.3.1.5 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169147 | 3756 | 1 | Addition of new NB-IoT MAC test case 22.3.1.6 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169151 | 3761 | 1 | Addition of new LWIP Test case - LWIP / WLAN Release / WLAN Association / EUTRA RRC_Connected to WLAN (Event W2) | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169152 | 3727 | 1 | Update test case 8.2.4.25.5 | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169156 | 3731 | 1 | New Dual Connectivity test case for PDCP reordering of Split DRB / t-Reordering timer operations | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169172 | 3690 | 1 | Addition of new test case: NB-IoT / PLMN selection / Periodic reselection / MinimumPeriodicSearchTimer | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169736 | 3663 | 2 | New NB-IoT EMM-CIoT testcase: 22.5.6 – NB-IOT / Attach Abnormal cases / Unsuccessful attach or Repeated rejects for network failures / Change of cell into a new tracking area / EPS services not allowed / Failure due to non integrity protection /UE initiate | 13.2.0 | 13.3.0 |
| 2016-12 | RAN#74 | R5-169737 | 3779 | 2 | Adding new NB-IoT EMM-CIoT testcase 22.5.7a: NB-IoT / Periodic tracking area update Accepted / Normal tracking area update List of equivalent PLMNs in the TRACKING AREA UPDATE ACCEPT message / Normal tracking area update Rejected (IMSI invalid / Illegal M | 13.2.0 | 13.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2016-12 | RAN#74 | R5-169738 | 3780 | 1 | Adding New NB-IoT EMM-CIoT testcase 22.5.7b: NB-IoT / Normal tracking area update Rejected (Tracking area not allowed / No suitable cells in tracking area / Roaming not allowed in this tracking area / Congestion) / UE initiated detach Abnormal case Chan | 13.2.0 | 13.3.0 |
| 2017-03 | RAN#75 | R5-170565 | 3786 | - | Corrections to GCF WI-257 MAC test case 22.3.1.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170566 | 3787 | - | Corrections to GCF WI-257 MAC test case 22.3.1.2 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170567 | 3788 | - | Corrections to GCF WI-257 MAC test case 22.3.1.3 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170568 | 3789 | - | Corrections to GCF WI-257 MAC test case 22.3.1.4 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170569 | 3790 | - | Corrections to GCF WI-257 MAC test case 22.3.1.5 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170570 | 3791 | - | Corrections to GCF WI-257 MAC test case 22.3.1.6 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170571 | 3792 | - | Corrections to GCF WI-257 RRC test case 22.4.6 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170576 | 3793 | - | Correction to GCF WI-254-A Idle test case 6.1.2.2c | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170577 | 3794 | - | Correction to GCF WI-254-A Idle test case 6.1.2.2d | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170578 | 3795 | - | Correction to GCF WI-254-A Idle test case 6.1.2.6a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170579 | 3796 | - | Updates to test case 8.5.4.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170582 | 3797 | - | Update of NB-IoT RRC Test Case 22.4.11 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170583 | 3798 | - | Update of NB-IoT RRC Test Case 22.4.12 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170607 | 3800 | - | Corrections to NB-IoT Idle Mode Test Case 22.2.7 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170608 | 3801 | - | Updates to NB-IoT RRC Access Barring Test case 22.4.8 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170682 | 3806 | - | Correction to GCF WI-254-A MAC test case 7.1.3.4a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170686 | 3807 | - | Add test case NB-IoT / Radio link failure / T301 expiry / T311 expiry | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170708 | 3812 | - | Modification of TC 22.4.1 to include Direct Indication Information message for eDRX | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170710 | 3813 | - | Addition of new test case for Cell reselection from cell in enhanced coverage to inter-frequency cell in normal coverage | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170717 | 3815 | - | Correction to LTE-IRAT testcase 9.2.3.1.6 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170745 | 3822 | - | Correction of TC 22.2.5 for supporting intra-frequency cell reselection only | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170768 | 3827 | - | Addition of New NB-IoT Test Case – NB-IoT / RRC connection establishment / Paging / Access Barring for UE with AC 0 to 9 / ab-Category a, b and c | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170770 | 3829 | - | Updates to NBIOT NAS TC 22.5.13 | 13.3.0 | 13.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-03 | RAN#75 | R5-170859 | 3833 | - | Corrections to eMTC test case 7.1.3.5a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170861 | 3834 | - | Update of eMTC Test Case 7.1.2.3a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170883 | 3838 | - | Correction to test case 6.2.2.5 to update conformance requirements | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170930 | 3850 | - | Correction to Idle Mode test case 6.1.2.14 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170931 | 3851 | - | Correction to eMBMS SC test case 17.4.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170933 | 3852 | - | Correction to IMS Emergency Call test case 11.2.7 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170962 | 3863 | - | Correction to PICS Parameter Conditions of NB-IoT testcase 22.4.13 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170966 | 3864 | - | Update the test scope of NB-IoT testcase 22.5.10 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-170969 | 3866 | - | Update the test scope of NB-IoT testcase 22.5.12 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171033 | 3871 | - | Corrections to NB-IoT test case 22.5.6 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171035 | 3872 | - | Corrections to NB-IoT test case 22.5.7a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171038 | 3874 | - | Corrections to NB-IoT test case 22.5.7b | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171039 | 3875 | - | Corrections to NB-IoT test case 22.5.8 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171110 | 3882 | - | Correction to Idle Mode Cell selection and reselection test cases to support Band > 64 - Part 2 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171114 | 3886 | - | Correction to RRC Intra E-UTRAN measurements test cases to support Band > 64 - Part 3 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171115 | 3887 | - | Correction to RRC Inter-RAT measurements test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171132 | 3898 | - | Update of NB-IoT TC 22.1.1 Control Plane CIoT EPS optimisation for EPS services | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171133 | 3899 | - | Update of NB-IoT TC 22.5.1 Authentication failures | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171135 | 3901 | - | Update of NB-IoT TC 22.5.3 detach | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171136 | 3902 | - | Update of NB-IoT TC 22.5.4 Attach-Detach | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171140 | 3903 | - | Correction to Multi-layer Call setup and RRC connection reconfiguration test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171142 | 3905 | - | Correction to Multi-layer Inter-system mobility packet test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171143 | 3906 | - | Correction to Multi-layer Inter-system mobility voice test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171144 | 3907 | - | Correction to RRC Inter-RAT Logged RLF test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171145 | 3908 | - | Correction to RRC Intra E-UTRAN measurements test cases to support Band > 64 - Part 2 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171147 | 3909 | - | Correction to RRC Measurements for self optimized networks test cases to support Band > 64 | 13.3.0 | 13.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-03 | RAN#75 | R5-171148 | 3910 | - | Correction to RRC Measurement for CSG, Hybrid and Open cells test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171150 | 3911 | - | Correction to MBMS test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171205 | 3915 | - | New test case 22.6.5, NB-IoT / UE requested PDN connectivity procedure not accepted / UE requested PDN connectivity accepted Dual priority T3396 override UE requested PDN connectivity accepted / Dual priority / T3346 override | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171207 | 3917 | - | Updates to test case 22.5.18 eDRX and PSM | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171306 | 3932 | - | Update RRC test case 8.5.1.4 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171307 | 3933 | - | Add test case NB-IoT / Radio link failure / RRC connection re-establishment reject | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171339 | 3938 | - | Correction to Idle Mode Cell reselection Rel-8 testcases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171340 | 3939 | - | Correction to Idle Mode Cell reselection Rel-9 testcases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171346 | 3940 | - | Addition of New NB-IoT Test Case – NB-IoT / RRC connection establishment / Paging / Access Barring for UE with AC 11 to 15 / ab-Category a, b and c | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171347 | 3941 | - | Addition of New NB-IoT / RRC connection establishment / Access Barring for UE with AC 11 to 15 / MO exception data / ab-Category a, b and c | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171363 | 3943 | - | Correction of test case 8.1.2.7 for Rel-8 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171367 | 3944 | - | Update NB-IoT test case 22.2.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171368 | 3945 | - | Correction of NB-IoT test case 22.2.4 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171405 | 3810 | 1 | Addition of new NB-IoT Test case for NB-IoT / Radio link failure / T310 expiry / Dedicated RLF timer (CP Clot) | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171406 | 3821 | 1 | Add test purpose in test case 22.2.9 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171407 | 3830 | 1 | Addition of new NBIOT TC 22.4.15 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171408 | 3835 | 1 | Modification of TC 22.4.2 to include Paging in Shared Network Environment | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171409 | 3854 | 1 | Correction to NB-IoT RLC test case 22.3.2.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171410 | 3855 | 1 | Correction to NB-IoT RLC test case 22.3.2.2 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171411 | 3856 | 1 | Correction to NB-IoT RLC test case 22.3.2.3 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171412 | 3857 | 1 | Correction to NB-IoT RLC test case 22.3.2.4 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171413 | 3858 | 1 | Correction to NB-IoT RLC test case 22.3.2.5 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171414 | 3876 | 1 | New NB-IoT test case for PLMN selection in Manual mode | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171415 | 3878 | 1 | New NB-IoT test case for NB-IoT / Integrity protection / Ciphering and deciphering / Correct functionality of EPS AS and UP encryption algorithms / AES | 13.3.0 | 13.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-03 | RAN#75 | R5-171416 | 3879 | 1 | New NB-IoT test case for NB-IoT / Integrity protection / Ciphering and deciphering / Correct functionality of EPS AS and UP encryption algorithms / ZUC | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171417 | 3900 | 1 | Update of NB-IoT TC 22.5.2 NAS Security | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171418 | 3914 | 1 | New test case 22.5.15, NB-IoT / Normal tracking area update / low priority override | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171419 | 3918 | 1 | New test case 22.6.1a, NB-IoT / UE routing of uplinks packets / Control Plane | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171420 | 3920 | 1 | Corrections to ESM-CIoT test case 22.5.14 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171423 | 3865 | 1 | Update the test scope of NB-IoT testcase 22.5.11 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171425 | 3818 | 1 | Addition of MAC eMTC transmission and reception test case | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171426 | 3819 | 1 | Addition of RRC eMTC test case for mobility enhancement | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171432 | 3844 | 1 | Correction to UTRAN->LTE Idle mode test cases for IMS-enabled UEs | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171433 | 3870 | 1 | Correction to LTE MFBI Test Case 6.2.3.34 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171434 | 3881 | 1 | Correction to idle mode PLMN selection test cases to support band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171435 | 3883 | 1 | Correction to MAC test cases test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171436 | 3935 | 1 | Correction to GCF WI-081 TCs 7.1.7.1.1, 7.1.7.1.2 to 7.1.7.1.6 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171437 | 3946 | - | Correction to GCF WI-254-A TC 7.1.4.3a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171439 | 3841 | 1 | Update RRC connection chapter 8.1.3 test cases for band 65 and higher | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171440 | 3889 | 1 | Correction to RRC Radio link failure test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171441 | 3885 | 1 | Correction to RRC Handover test cases to support Band > 64 - Part 2 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171442 | 3912 | 1 | Correction to RRC Radio Resource Reconfiguration test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171443 | 3888 | 1 | Correction to RRC MDT test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171444 | 3913 | 1 | Correction to RRC Logged Handover Failure test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171445 | 3919 | 1 | Correction to RRC Connection Establishment Failure test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171446 | 3936 | 1 | Correction to Rel-11 eMDT test case 8.6.9.2 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171447 | 3845 | 1 | Correction to EMM test case 9.2.3.2.1b | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171448 | 3846 | 1 | Correction to EUTRA EMM test case 9.2.3.3.3 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171449 | 3880 | 1 | Correction to UTRAN->LTE test cases 9.2.2.1.10 and 9.2.3.3.1 for IMS-enabled UEs | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171450 | 3890 | 1 | Correction to EMM test cases to support Band > 64 | 13.3.0 | 13.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2017-03 | RAN#75 | R5-171452 | 3891 | 1 | Correction to Emergency test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171453 | 3814 | 1 | Correction to LTE-IRAT IMS Emergency Call Testcases 13.1.19 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171502 | 3832 | 1 | D2D - Moving TC 7.3.8.3 to Section 19.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171503 | 3840 | 1 | Specific message contents introduction and test procedure correction for Dual Connectivity test case 8.5.1.8.1, Radio link failure on PSCell / UE supports SCG DRB | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171504 | 3842 | 1 | Specific message contents introduction and test procedure correction for Dual Connectivity test case 8.5.1.8.2, Radio link failure on PSCell / UE supports Split DRB | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171505 | 3862 | 1 | Addition of new eMDT2 testcase: Measurement / Latency metrics for UL PDCP Packet Delay per QCI | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171506 | 3803 | 1 | LAA/Common Control PDCCH Information/CC-RNTI | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171507 | 3868 | 1 | Addition of new test case 8.3.1.32 LAA RSSI measurement | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171533 | 3952 | - | Addition of RRC V2V test case for in coverage transmission | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171537 | 3892 | 1 | Correction to eMTC RRC test case 8.1.1.1a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171538 | 3894 | 1 | Update of legacy LTE MAC test cases for Cat M1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171539 | 3895 | 1 | Update of legacy LTE RRC test cases for Cat M1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171540 | 3897 | 1 | Update of legacy LTE emergency, ETWS and PWS test cases for Cat M1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171541 | 3893 | 2 | Update of legacy LTE idle mode test cases for Cat M1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171542 | 3896 | 2 | Update of legacy LTE EMM test cases for Cat M1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171547 | 3799 | 1 | Update of NB-IoT RRC Test Case 22.4.7 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171548 | 3809 | 1 | Addition of new NB-IoT Test case for NB-IoT / Radio link failure / T311 expiry / Dedicated RLF timer (UP ClIoT) | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171549 | 3811 | 1 | Addition of new NB-IoT Test case for NB-IoT / Radio link failure / Radio link recovery while T310 is running | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171550 | 3831 | 1 | Addition of new NBIOT TC 22.4.16 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171552 | 3837 | 1 | NB-IoT: Addition of new test case "NB-IoT / Cell reselection / MFBI" | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171553 | 3843 | 1 | NB-IoT: Addition of new test case "NB-IoT / PDCP re-establishment / stored UE AS context is used and drb-ContinueROHC is configured" | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171558 | 3930 | 1 | Corrections to GCF WI-257 PDCP test case 22.3.3.2 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171559 | 3916 | 1 | New test case 22.6.1, NB-IoT / UE routing of uplinks packets/UE requested PDN disconnect procedure accepted by the network | 13.3.0 | 13.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-03 | RAN#75 | R5-171560 | 3877 | 1 | New NB-IoT test case for Maintenance of PDCP sequence numbers / User plane / RLC AM | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171562 | 3953 | - | Addition of new eMTC testcase "DL-SCH transport block size selection / DCI format 6-1B" | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171563 | 3954 | - | Addition of new eMTC testcase "UL-SCH transport block size selection / DCI format 6-0B" | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171564 | 3860 | 1 | Correction to eMTC Idle Mode test case 6.1.2.6a | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171565 | 3922 | 1 | New Test case 23.1.1 for CIoT Optimization over Control Plane | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171567 | 3934 | 1 | Correction to Inter-RAT test case 6.2.1.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171568 | 3853 | 1 | Correction to RRC test case 8.5.4.1 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171570 | 3839 | 1 | Correction to Rel-11 eDDA test cases 8.2.2.6.3 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171571 | 3836 | 1 | Correction to USIM contents for Idle Mode test case 6.1.1.4 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171573 | 3804 | 1 | Corrections to several SC-PTM Service Continuity test cases, including support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171574 | 3927 | 1 | Corrections to several SC-MCCH Information Acquisition test cases, including support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171576 | 3949 | 1 | Correction to testcase 9.1.5.1: EMM Information procedure | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171585 | 3847 | 1 | NB-IoT : Addition of new test case "NB-IoT / PDCP discard" | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171587 | 3828 | 1 | Updates to NBIOT NAS TC 22.5.5 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171592 | 3904 | 2 | Correction to Multi-layer Intra-system mobility test cases to support Band > 64 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171951 | 3848 | 2 | NB-IoT: Correction of test case 22.2.3 | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171995 | 3947 | 2 | Correction to RRC Handover test cases to support Band > 64 - Part 1 (TCs 8.2.4.1 to 8.2.4.15a) | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171996 | 3948 | 1 | Correction to RRC Intra E-UTRAN measurements test cases to support Band > 64 - Part 1 (TCs 8.3.1.1 to 8.3.1.9a) | 13.3.0 | 13.4.0 |
| 2017-03 | RAN#75 | R5-171470 | 3950 | - | Addition of new UE Power Class 2 TC | 13.4.0 | 14.0.0 |
| 2017-03 | RAN#75 | R5-171533 | 3952 | - | Addition of RRC V2V test case for in coverage transmission | 13.4.0 | 14.0.0 |
| 2017-03 | RAN#75 | R5-171535 | 3951 | - | Addition of PDCP V2V test case | 13.4.0 | 14.0.0 |
| 2017-03 | RAN#75 | - | - | - | Correction of history table to indicate Rel-14 CRs | 14.0.0 | 14.0.1 |
| 2017-06 | RAN#76 | R5-172036 | 3960 | - | Correction to IMS Emergency test case 11.2.7 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172037 | 3961 | - | Correction to eMDT test cases 8.6.x.x | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172050 | 3966 | - | Editorial update to the title of test case 19.1.8 | 14.0.1 | 14.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-06 | RAN#76 | R5-172053 | 3967 | - | Corrections to GCF WI-257 MAC test case 22.3.1.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172056 | 3969 | - | Corrections to GCF WI-257 PDCP test case 22.3.3.6 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172057 | 3970 | - | Corrections to GCF WI-257 EMM test case 22.5.5 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172064 | 3974 | - | Correction to RRC Inter-RAT Logged RLF test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172065 | 3975 | - | Correction to MBMS test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172076 | 3976 | - | Correction to SC-PTM test case 21.3.6 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172090 | 3978 | - | Editorial correction to RRC test cases 8.1.1.1a and 8.1.2.13 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172099 | 3980 | - | Editorial correction to EMM test case 9.2.1.2.1c | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172130 | 3981 | - | Correction to Multi-layer Call setup and RRC connection reconfiguration test case 13.1.18 to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172141 | 3989 | - | Updates to manual CSG selection test cases | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172156 | 3990 | - | Removing TDD parts of D2D ProSe Direct Communication Test Cases | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172163 | 3991 | - | Corrections to NBIOT RRC ACB TC 22.4.5 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172164 | 3992 | - | Corrections to NBIOT RRC ACB TC 22.4.9 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172315 | 4010 | - | Update of NB-IoT TC 22.5.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172361 | 4014 | - | Correction to SC-PTM test case 21.3.11.1 to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172419 | 4018 | - | Addition of underlying sub-clause 22.4 RRC | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172442 | 4020 | - | Correction to xSRVCC Test Cases 13.4.3.14, 13.4.3.16 and 13.4.3.18 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172443 | 4021 | - | Correction to GCF WI-156 RRC Intra E-UTRAN measurements test cases to support Band > 64 – 8.3.1.13, 8.3.1.14 and 8.3.1.16 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172485 | 4035 | - | Correction to NB-IoT RLC test case 22.3.2.3 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172491 | 4039 | - | Correction to NB-IoT RLC test case 22.3.2.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172502 | 4045 | - | Correction to MAC eMTC transmission and reception test case | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172508 | 4048 | - | Correction to Dual Connectivity test case 8.2.4.25.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172781 | 4076 | - | Correction to EMM test case 9.2.3.2.1c | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172783 | 4077 | - | Correction to GCF WI-254-A eMTC MAC test case 7.1.3.4a | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172784 | 4078 | - | Correction to CA EUTRA<->UTRA Handover test cases 8.4.2.7.x | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172830 | 3987 | 1 | Correction to RRC Inter-RAT Logged RLF test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172831 | 3988 | 1 | Correction to RRC Inter-RAT Logged Handover Failure test cases to support Band > 64 | 14.0.1 | 14.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-06 | RAN#76 | R5-172832 | 4093 | - | Addition of eMTC capabilities check in test case 8.5.4.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172833 | 4094 | - | Correction to NB-IoT MAC test case 22.3.1.6 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172834 | 4095 | - | Correction to NB-IoT MAC test case 22.3.1.3 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172835 | 4096 | - | Correction to NB-IoT MAC test case 22.3.1.4 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172855 | 3993 | 1 | Correction to NBIOT NAS TC 22.5.16 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172856 | 3962 | 1 | Add test case NB-IoT / RRC Connection Establishment / Multi-Carrier | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172858 | 3964 | 1 | Add test case NB-IoT / RRC connection reconfiguration / SRB reconfiguration / Success | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172859 | 3965 | 1 | Update test case 22.4.19 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172860 | 3968 | 1 | Corrections to GCF WI-257 MAC test case 22.3.1.2 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172861 | 4001 | 1 | Corrections to GCF WI-257 EMM test case 22.5.8 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172862 | 4040 | 1 | Corrections to TC 22.5.4 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172863 | 4041 | 1 | Remove Multi-PLMN test for TC 22.5.6 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172864 | 4053 | 1 | Updates to NB-IoT test case 22.5.17 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172865 | 4054 | 1 | Updates to NB-IoT test case 22.5.18 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172866 | 4055 | 1 | Updates to NB-IoT test case 22.6.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172867 | 4056 | 1 | Updates to NB-IoT test case 22.6.1a | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172869 | 4070 | 1 | Correction to NB-IOT test case 22.4.7 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172881 | 4015 | 1 | Correction to GCF WI-254-A Rel-13 eMTC Idle Mode test case 6.1.2.2d | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172882 | 3977 | 1 | Correction to eMTC Idle Mode test case 6.1.2.6a | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172883 | 4017 | 1 | Update of CP-CIoT TC for LTE | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172884 | 4026 | 1 | Correction on RRC eMTC test case 8.2.4.27 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172885 | 4044 | 1 | Correction to MAC eMTC CeModeB HARQ process handling test case | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172886 | 4046 | 1 | Corrections to eMTC MAC TBS test case for "UL-SCH transport block size selection / DCI format 6-0B" | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172887 | 4093 | 1 | Addition on new eMTC ClIoT optimisation test case 23.2.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172899 | 4098 | - | Correction to GCF WI-081 TC 7.1.4.13 for Cat-M1 UE | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172901 | 4019 | 1 | Correction to RRC test case 8.5.4.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172902 | 3996 | 1 | Update 8.3.1.21 for Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172903 | 4003 | 1 | Update chapter 8.3.2 for Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172904 | 4092 | 1 | Correction to RRC Intra E-UTRAN measurements test cases to support Band > 64 - Part 2 | 14.0.1 | 14.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2017-06 | RAN#76 | R5-172905 | 3984 | 2 | Correction to RRC Inter-RAT handover UTRA to E-UTRA test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172906 | 3985 | 1 | Correction to RRC Inter-RAT mobility E-UTRA to GERAN test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172907 | 3986 | 2 | Correction to RRC Inter-RAT handover E-UTRA to and 1xRTT test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172908 | 3997 | 1 | Correction to RRC Logged Handover Failure test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172909 | 4024 | 1 | Correction to LTE Test Case 8.6.1.3 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172910 | 4079 | 1 | Correction to RRC Connection Establishment Failure test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172911 | 3958 | 1 | Correction to EMM test case 9.2.3.1.5a for Multi-PDN UE | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172912 | 4016 | 1 | Correction to EMM test case 9.2.3.1.23 for multi-PDN capable UE | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172913 | 4074 | 1 | Correction to EMM PSM test case 9.2.3.1.1a | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172914 | 3956 | 1 | Correction to Pre-registration at 1xRTT test case 13.4.4.2 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172915 | 4006 | 1 | Update test case 11.2.11 for Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172916 | 3982 | 1 | Correction to Multi-layer Inter-system mobility packet test case 13.4.2.2 to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172917 | 3983 | 2 | Correction to Multi-layer Inter-system mobility voice test cases to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172918 | 4011 | 1 | Update Inter-system mobility packet chapter 13.4.2 for Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172919 | 4012 | 1 | Update Inter-system mobility voice chapter 13.4.3 for Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172920 | 4002 | 1 | Correction of test case 20.2 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172925 | 4000 | 1 | Correction to LTE SIMTC Test Case 10.8.8 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172926 | 3963 | 2 | Add test case NB-IoT / RRC connection reconfiguration / Radio bearer establishment / Success / Dedicated bearer / ROHC configured under UP | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172948 | 4091 | 1 | Add test case Inter-frequency cell reselection / Extended frequency list Ericsson CR LTE_UTRA_IncMon-UEConTest | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172958 | 4069 | 1 | Change title of test case 8.2.4.25.6 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172959 | 4072 | 1 | Change title of test case 8.2.4.25.7 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172982 | 4025 | 1 | Correction on RRC V2V test case 24.1.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172991 | 4031 | 1 | Correction of NB-IoT test case 22.2.5 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-172992 | 4033 | 1 | Correction to NB-IoT RLC test case 22.3.2.2 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173004 | 3957 | 1 | Correction to (Cat-M1) eMTC MAC test case 7.1.7.2.2 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173007 | 4005 | 1 | Update Inter-RAT cell reselection chapter 6.2.3 for Band > 64 | 14.0.1 | 14.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2017-06 | RAN#76 | R5-173008 | 4004 | 1 | Update Inter-RAT PLMN selection chapter 6.2.1 for Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173009 | 4007 | 1 | Correction to RRC connection management procedures test case 8.1.3.7 to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173010 | 4008 | 1 | Correction to RRC Radio link failure test case 8.5.2.1 to support Band > 64 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173011 | 4090 | 1 | Correction to GCF WI-086 TC 8.1.3.6 for IMS disabled over UMTS | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173012 | 3959 | 1 | Correction to MDT test case 8.6.9.2 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173013 | 4097 | 1 | Corrections to PC2 Test Case 6.1.2.5a | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173017 | 4009 | 2 | Addition of new TC for reselection using Pcompensation | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173023 | 3972 | 1 | Corrections to GCF WI-081 RRC test case 8.1.2.7 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173043 | 4101 | 1 | Correction to LTE Test Case 8.5.4.1 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173044 | 4049 | 2 | Correction to Dual Connectivity test case 8.2.4.25.2 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173074 | 4042 | 2 | Corrections to TC 22.5.7a | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173075 | 4043 | 2 | Remove Multi-PLMN test for TC 22.5.7b | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173076 | 4071 | 1 | Corrections to NB-IoT test case 22.4.13 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173077 | 4086 | 2 | Correction to NB-IoT test case 22.5.14 | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173078 | 4099 | 1 | Correction to GCF WI-081 TC 8.1.1.2 for Cat-M1 UE | 14.0.1 | 14.1.0 |
| 2017-06 | RAN#76 | R5-173079 | 4100 | 2 | Correction to (Cat-M1) eMTC MAC test case 7.1.3.4a | 14.0.1 | 14.1.0 |
| 2017-09 | RAN#77 | R5-173530 | 4102 | - | Update test case 22.4.14 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173595 | 4106 | - | Correction to Multi layer Inter-system mobility voice test case 13.4.3.41 to support Band > 64 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173674 | 4113 | - | Updates to audit test case 8.5.4.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173679 | 4115 | - | Correction to RRC Connection Establishment Failure test case 8.6.8.6 to support Band > 64 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173742 | 4121 | - | Correction to NB-IoT Idle Mode testcase 22.2.9 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173745 | 4124 | - | Correction to NB-IoT testcase 22.2.6 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173746 | 4125 | - | Correction to NB-IOT testcase 22.5.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173808 | 4127 | - | Correction to GCF WI-257 NB-IoT test case 22.5.17 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173809 | 4128 | - | Correction to GCF WI-257 NB-IoT test case 22.5.18 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173811 | 4129 | - | Correction to GCF WI-254-A eMTC MAC test case 7.1.3.4a | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173832 | 4130 | - | Update idle mode test cases 6.2.3.6 for Band > 64 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173835 | 4132 | - | Correction to Rel-11 eMDT Inter-RAT E<>G test case 8.6.9.3 | 14.1.0 | 14.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-09 | RAN#77 | R5-173837 | 4134 | - | Correction to EMM test case 9.2.1.1.2a for IMS Enabled MultiPDN UE's | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173847 | 4138 | - | Add test case ClOT / RRC connection suspend-resume / Success / different cell | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173848 | 4139 | - | Add test case ClOT / RRC connection suspend-resume / Network reject / different cell | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173856 | 4142 | - | Addition of the new eCall over IMS Test Case-eCall Only mode/T3444/eCall inactivity procedure/Removal of eCall only restriction after an eCall over IMS | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173870 | 4144 | - | Correction to NB-IoT testcase 22.5.13 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173871 | 4145 | - | Correction to NB-IoT testcase 22.5.16 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173965 | 4147 | - | Update TC 22.4.22 to invoke generic procedure to establish radio bearers in UP | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-173967 | 4148 | - | In rlf-TimersAndConstants-r13 Mandatory IEs are added in Table 22.4.23.3.3-2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174001 | 4151 | - | Correction to (Cat-M1) eMTC MAC test case 7.1.3.5a | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174005 | 4152 | - | Correction to EMM test cases 9.3.1.4 and 9.3.1.5 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174010 | 4153 | - | Correction to (Cat-M1) eMTC MAC test case 7.1.6.1a | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174013 | 4155 | - | Correction to (Cat-M1) eMTC MAC test case 7.1.2.3a | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174014 | 4156 | - | Corrections to RRC test case 8.5.4.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174016 | 4158 | - | Correction to SRVCC test case 13.4.3.4 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174017 | 4159 | - | Correction to (Cat-M1) eMTC MAC test case 7.1.4.24b | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174072 | 4167 | - | Correction of NB-IoT test case 22.2.2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174075 | 4170 | - | Corrections to NBIOT NAS TC 22.5.5 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174087 | 4175 | - | Correction to MBMS testcase 17.2.2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174091 | 4177 | - | Editorial Changes to NB-IoT testcase titles | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174123 | 4179 | - | Corrections to LAA MAC test case | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174196 | 4184 | - | Correction to EMM test cases 9.2.1.1.20 and 9.2.3.1.22 for CAT-M1 UEs | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174292 | 4199 | - | Correction to GCF WI-257 NB-IoT test case 22.4.11 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174293 | 4200 | - | Corrections to test case 22.4.13 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174301 | 4201 | - | Corrections to NBIOT RRC TC 22.4.20 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174307 | 4205 | - | Correction to NB-IoT RLC test case 22.3.2.5 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174311 | 4207 | - | Corrections to NBIOT RRC TC 22.4.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174317 | 4211 | - | Corrections to NBIOT RRC TC 22.4.8 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174383 | 4216 | - | Updates to NB-IoT test case 22.5.15 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174384 | 4217 | - | Updates to NB-IoT test case 22.6.1 | 14.1.0 | 14.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-09 | RAN#77 | R5-174386 | 4219 | - | Correction to Multi-Layer procedures SRVCC test case 13.4.3.2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174388 | 4220 | - | Removal of Rel-12 DC test cases 8.2.2.9.4 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174405 | 4225 | - | Correction to NB-IoT RLC test cases | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174458 | 4112 | 1 | Corrections to GCF WI-257 PDCP test case 22.3.3.5 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174459 | 4120 | 1 | Update of NB-IoT TC 22.1.1 for APN Rate Control | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174460 | 4143 | 1 | Correction to NB-IoT testcase 22.5.4 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174462 | 4168 | 1 | Correction of NB-IoT test case 22.2.3 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174463 | 4169 | 1 | Corrections to NBIOT NAS TC 22.5.2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174464 | 4171 | 1 | Corrections to NBIOT NAS TC 22.5.6 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174465 | 4172 | 1 | Corrections to NBIOT NAS TC 22.5.8 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174466 | 4173 | 1 | Corrections to NBIOT NAS TC 22.5.18 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174467 | 4176 | 1 | Addition of updated NB-IoT testcase 22.4.9 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174469 | 4228 | - | Adding ESM-CIoT test case 22.6.2 - default EPS bearer context | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174471 | 4189 | 1 | Correction to GCF WI-257 NB-IoT test case 22.4.12 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174473 | 4229 | - | Adding ESM-CIoT test case 22.6.3 - default EPS bearer context | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174474 | 4202 | 1 | Corrections to NB-IoT MAC test case 22.3.1.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174475 | 4230 | - | Corrections to NBIOT RLC TC 22.3.2.3 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174476 | 4204 | 1 | Correction to NB-IoT RLC test case 22.3.2.4 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174477 | 4206 | 1 | Corrections to NB-IoT PDCP test case 22.3.3.6 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174481 | 4232 | - | Updating test case 22.5.14 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174482 | 4233 | - | Corrections to D2D ProSe PDCP test cases | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174485 | 4154 | 1 | Correction to EUTRA RLC test case 7.2.3.18 for CAT-M1 UE's | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174486 | 4150 | 1 | Correction to EUTRA RB generic test procedure clause 12.1.1 for PDCP SDU size | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174487 | 4178 | 1 | Addition of new CloT optimisation test case 23.1.2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174488 | 4180 | 1 | Update of CloT CP TC 23.1.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174489 | 4191 | 1 | Enabling eDRx Test Case 8.1.1.2a for CAT M1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174493 | 4116 | 1 | Correction to EUTRA test case 7.1.2.4 for execution on CAT-M1 UE's | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174503 | 4104 | 1 | Correction to Inter-RAT MFBI test case 6.2.3.35 to support Band > 64 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174504 | 4133 | 1 | Update idle mode test cases 6.3.3 and 6.4.1 for Band > 64 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174505 | 4131 | 1 | Correction of RRC UTRAN to E-UTRAN test cases 8.1.3.7 and 8.5.2.1 for Band > 64 | 14.1.0 | 14.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2017-09 | RAN#77 | R5-174506 | 4141 | 1 | Correction to LTE<>IRAT testcases for IMS disabled over UMTS | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174507 | 4182 | 1 | Correction to LTE<>IRAT testcase 8.1.3.6 for IMS disabled over UMTS | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174508 | 4183 | 1 | Correction to Radio Link Failure test cases to support Band > 64 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174509 | 4105 | 1 | Correction to EMM test case 9.2.1.1.7 to support Band > 64 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174510 | 4161 | 1 | Correction to EMM test case 9.2.3.1.6 for IMS Enabled Ues | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174512 | 4110 | 1 | Correction to Multi-Layer access control test case 13.5.6 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174513 | 4192 | 1 | Correction to LTE SSAC test case 13.5.3 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174514 | 4226 | 1 | Correction to LTE SCM test cases 13.5.4 and 13.5.6 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174515 | 4160 | 1 | Merging "MTSI over WLAN" test cases 20.1 and 20.2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174539 | 4181 | 1 | Addition of the new IMS eCall Test Case- eCall Only mode / T3445 / eCall inactivity procedure / Removal of eCall only restriction after a call to URI for test service | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174567 | 4111 | 1 | Corrections to test case 6.1.2.11a | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174568 | 4193 | 1 | Add test case Inter-band cell reselection / Extended frequency list | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174570 | 4194 | 1 | Add test case RRC connection release / Success / With extended priority information | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174572 | 4234 | - | New TBS test cases | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174574 | 4166 | 1 | Addition of new V2V Sidelink test case 24.1.9 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174575 | 4235 | - | Addition of new TC 7.1.12.1 "DataInactivityTimer expiry" | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174596 | 4118 | 1 | New ProSe Rel-13 TC 19.1.9 Isolated one-to-one direct communication MO 36523-1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174597 | 4119 | 1 | New ProSe Rel-13 TC 19.1.10 Isolated one-to-one direct communication MT 36523-1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174629 | 4236 | - | Correction on RRC V2X test case 7.3.9.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174630 | 4163 | 1 | Correction on RRC V2X test case 24.1.1 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174631 | 4164 | 1 | Addition of new V2X Sidelink test case 24.1.14 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174632 | 4165 | 1 | Addition of new V2X Sidelink test case 24.1.15 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174633 | 4196 | 1 | Addition of new V2X Sidelink test case 24.1.6 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174634 | 4214 | 1 | Addition of V2X test case 24.1.3 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174643 | 4195 | 1 | Corrections to NB-IoT "S1-U Only" Impacted Test Cases | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174644 | 4208 | 1 | Corrections to NBIOT RRC TC 22.4.4 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174645 | 4209 | 1 | Corrections to NBIOT RRC TC 22.4.5 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174646 | 4210 | 1 | Correction to NB-IOT test case 22.4.7 | 14.1.0 | 14.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2017-09 | RAN#77 | R5-174647 | 4231 | 1 | Corrections to NB-IoT test case 22.5.7b | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174648 | 4123 | 1 | Correction to NB-IoT testcase 22.2.5 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174650 | 4157 | 1 | Correction to (Cat-M1) eMTC RRC test case 8.2.4.27 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174651 | 4198 | 1 | Correction to RRC Measurement test cases 8.3.1.2x for CAT-M1 UEs | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174657 | 4197 | 1 | LWIP / WLAN Release Success / EUTRA RRC_Connected from WLAN (Event W3) | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-174668 | 4218 | 1 | Updates to NB-IoT test case 22.6.5 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-175222 | 4212 | 2 | Add V2V Sidelink Communication test case 24.1.2 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-175223 | 4213 | 2 | Add V2V Sidelink Communication test case 24.1.4 | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-175224 | 4221 | 2 | Update test cases to ensure the integrity protection of reject messages | 14.1.0 | 14.2.0 |
| 2017-09 | RAN#77 | R5-175225 | 4237 | 1 | Correction to SRVCC test case 13.4.3.5 | 14.1.0 | 14.2.0 |
| 2017-12 | RAN#78 | R5-176032 | 4239 | - | Correction to EMM test case 9.2.1.1.28a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176038 | 4240 | - | Update test case 8.1.3.5a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176043 | 4243 | - | Correction to test case 22.3.2.3 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176045 | 4245 | - | Updating test case 22.6.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176084 | 4257 | - | NB-IoT: Addition of new Test Purpose (2) to cover the inter-frequency case in "NB-IoT / Cell reselection / MFBI" | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176089 | 4258 | - | Correction to eMDT2 testcase 8.6.4.11 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176120 | 4260 | - | Removal of MDT test case 8.6.5.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176139 | 4262 | - | Merge of NB-IoT RLF test cases 22.4.19 and 22.4.22 - Part1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176140 | 4263 | - | Correction to NB-IoT test case 22.4.14 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176149 | 4265 | - | Correction to Idle mode test cases for LTE Bands>64 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176153 | 4268 | - | Correction to test case 13.4.2.5 for LTE Bands>64 in Packet Cell Change Order | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176172 | 4269 | - | Introduction of MAC reset / partial reset in 7.1.4.12a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176181 | 4272 | - | Correction to NB-IoT test case 22.5.18 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176314 | 4275 | - | Correction to NB-IoT RLC test case 22.3.2.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176323 | 4279 | - | Correction to NB-IoT EMM test case 22.5.16 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176343 | 4280 | - | Correction to NB-IoT test case 22.4.8 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176344 | 4281 | - | Correction to NB-IoT test case 22.4.9 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176476 | 4290 | - | Correction to Dual connectivity Radio link failure test case 8.5.1.8.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176478 | 4291 | - | Correction to Dual connectivity Radio link failure test case 8.5.1.8.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176580 | 4306 | - | Correction to INCMON test case 6.1.2.11a | 14.2.0 | 14.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-12 | RAN#78 | R5-176581 | 4307 | - | Correction to INCMON test case 6.1.2.5c | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176590 | 4309 | - | Correction to test case 8.5.4.1 to clarify reporting of ss-CCH-InterfHandl-r11 IE | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176592 | 4310 | - | Editorial correction to NB-IoT EMM test case 22.5.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176657 | 4319 | - | Correction to NB-IoT testcase 22.4.23 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176659 | 4321 | - | Correction to NB-IoT test case 22.3.1.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176665 | 4325 | - | Correction to NB-IoT test case 22.4.9 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176681 | 4329 | - | Correction to eMTC MAC test case 7.1.3.5a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176687 | 4332 | - | Correction to LTE RRC test case 8.1.2.8 for CAT-M1 UEs | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176688 | 4333 | - | Correction to RRC Measurement test cases 8.3.x.x for CAT-M1 UEs | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176690 | 4334 | - | Correction to ESM test cases 10.3.1. and 10.9.1 for Multi-PDN UEs | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176746 | 4340 | - | Updates to V2V test case 24.1.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176752 | 4344 | - | New eDECOR test case 9.2.3.1.1b | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176774 | 4345 | - | Corrections to V2X PDCP test case 7.3.9.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176775 | 4346 | - | Correction to SRVCC test cases 13.4.3.4 and 13.4.3.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176803 | 4351 | - | Correction to MAC test case 7.1.2.1 for CAT-M1 UEs | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176804 | 4352 | - | Correction to Multi-Layer procedures test case 13.2.1 for CAT-M1 UEs | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176807 | 4354 | - | Updates to NB-IoT test case 22.6.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176809 | 4355 | - | Correction to eMTC MAC test case 7.1.4a.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176810 | 4356 | - | Correction to eDRX RRC test case 8.1.1.2a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176873 | 4241 | 1 | Correction to test case 22.3.1.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176875 | 4244 | 1 | Updating test case 22.5.14 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176876 | 4246 | 1 | Updating test case 22.6.3 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176877 | 4261 | 1 | Corrections to NB-IoT test case 22.1.1 Module 3 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176878 | 4360 | - | Correction to NB-IoT test case 22.3.2.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176879 | 4277 | 1 | Correction to NBIOT EMM test case 22.5.7b | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176880 | 4278 | 1 | Correction to NB-IoT EMM test case 22.5.13 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176881 | 4286 | 1 | Editorial Update for missing references in specific message contents NB-IoT | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176882 | 4322 | 1 | Correction to NB-IoT test case 22.3.1.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176884 | 4353 | 1 | Updates to NB-IoT test case 22.6.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176885 | 4337 | 1 | Correction to NB-IoT Test Case 22.5.6 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176886 | 4361 | - | Updates to NB-IoT test case 22.2.9 | 14.2.0 | 14.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2017-12 | RAN#78 | R5-176890 | 4292 | 1 | Correction to MAC TBS 4Rx test case 7.1.7.1.12a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176891 | 4293 | 1 | Correction to MAC TBS 4Rx test case 7.1.7.1.6a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176893 | 4273 | 1 | Correction to LAA test case 7.1.11.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176894 | 4274 | 1 | Correction to test case 7.2.2.8 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176895 | 4331 | 1 | Correction to EUTRA RLC test case 7.2.3.10 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176896 | 4348 | 1 | Correction to eMTC RRC test case 8.2.4.27 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176897 | 4317 | 1 | Correction to 8.4.2.x testcases for IMS disabled over UMTS | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176898 | 4318 | 1 | Correction to LTE<>IRAT testcases for IMS disabled over UMTS | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176899 | 4358 | 1 | Corrections to MDT test cases for LTE Bands>64 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176900 | 4304 | 1 | Correction to EMM test case 9.2.3.1.6 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176901 | 4266 | 1 | Corrections to ePDG test cases | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176902 | 4267 | 1 | Corrections to CloT SMS test case 23.1.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176903 | 4285 | 1 | Adding missing referenced specs to the References section | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176904 | 4287 | 1 | Editorial Update for missing references in specific message contents CloT | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176905 | 4347 | 1 | Small update of CloT TC 23.1.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176909 | 4298 | 1 | Addition of new CA_enh_b5C_PUCCH test case 7.1.4.29.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176910 | 4299 | 1 | Addition of new CA_enh_b5C_PUCCH test case 7.1.4.29.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176913 | 4362 | - | Editorial correction of EUTRA MAC test case 7.1.4.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176942 | 4363 | - | Update to NB-IoT PDCP RoHC test case 22.3.3.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176951 | 4248 | 1 | Correction of the eCall over IMS Test Case 11.3.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176952 | 4249 | 1 | Correction of the eCall over IMS Test Case 11.3.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176953 | 4250 | 1 | Addition of the new eCall over IMS Test Case 11.3.3 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176954 | 4251 | 1 | Addition of the new eCall over IMS Test Case 11.3.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176955 | 4252 | 1 | Addition of the new eCall over IMS Test Case 11.3.6 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176956 | 4253 | 1 | Addition of the new eCall over IMS Test Case 11.3.7 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176957 | 4254 | 1 | Addition of the new eCall over IMS Test Case 11.3.8 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176959 | 4270 | 1 | Introduction of RRC connection reconfiguration / UE Assistance Information / Delay Budget Report T342 running in 8.2.2.6.5 | 14.2.0 | 14.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-12 | RAN#78 | R5-176960 | 4271 | 1 | Introduction of RRC connection reconfiguration / UE Assistance Information / Delay Budget Report setup and release in 8.2.2.6.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176963 | 4339 | 1 | Updates to V2V test case 24.1.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176967 | 4247 | 1 | Update of V2X Sidelink test case 24.1.6 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176968 | 4288 | 1 | Addition of V2X Sidelink Communication test case 24.1.16 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176970 | 4294 | 1 | Addition of new V2X Sidelink test case 24.1.7 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176971 | 4295 | 1 | Addition of new V2X Sidelink test case 24.1.8 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176972 | 4296 | 1 | Addition of new V2X Sidelink test case 24.1.10 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176973 | 4311 | 1 | Correction on V2X test case 24.1.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176974 | 4313 | 1 | Correction on V2X test case 24.1.9 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176975 | 4314 | 1 | Correction on V2X test case 24.1.14 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176976 | 4315 | 1 | Split V2X test case 24.1.15 to two separate test cases. | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176977 | 4316 | 1 | Addition of new V2X Sidelink test case 24.1.17 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176978 | 4341 | 1 | Updates to V2X test case 24.1.3 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176979 | 4342 | 1 | Addition of V2X test case 24.1.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176983 | 4289 | 1 | Addition of test case CA / RRC connection reconfiguration / SCell addition without UL / SRS configuration / Periodic / multi-SRS switching | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176984 | 4256 | 1 | Introduction of Correct selection of RACH parameters / Preamble selected by MAC itself / Contention based random access procedure for high speed scenario in 7.1.2.3b | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-176985 | 4255 | 1 | Introduction of Correct selection of RACH parameters / Random access preamble and PRACH resource explicitly signalled to the UE by RRC / Non-contention based random access procedure for high speed scenario in 7.1.2.1a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177042 | 4282 | 1 | New ProSe Rel-13 TC 19.2.6 Announcing UE procedure for group member discovery | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177043 | 4283 | 1 | New ProSe Rel-13 TC 19.2.7 Discoverer UE procedure for group member discovery | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177044 | 4284 | 1 | New ProSe Rel-13 TC 19.2.8 Discoveree UE procedure for group member discovery | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177051 | 4276 | 1 | Correction to NB-IoT EMM test case 22.5.7a | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177052 | 4323 | 1 | Correction to NB-IoT test case 22.4.4 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177054 | 4327 | 1 | Corrections to NBIOT NAS TC 22.5.6 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177055 | 4324 | 1 | Correction to NB-IoT test case 22.4.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177060 | 4305 | 1 | Correction to EUTRA MAC test case 7.1.2.4 for execution on CAT-M1 UEs | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177061 | 4357 | 1 | Correction to EMM test cases 9.3.1.4 and 9.3.1.5 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177078 | 4264 | 1 | Correction to GERAN specific messages for LTE Bands>64 | 14.2.0 | 14.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2017-12 | RAN#78 | R5-177082 | 4343 | 1 | New eDECOR test case 9.2.1.1.7d | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177110 | 4242 | 2 | Correction to test case 22.3.2.2 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177119 | 4320 | 2 | Correction to NB-IoT test case 22.3.1.1 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | R5-177120 | 4328 | 2 | Corrections to NBIOT NAS TC 22.5.8 | 14.2.0 | 14.3.0 |
| 2017-12 | RAN#78 | - | - | - | Administrative release upgrade to match the release of 3GPP TS 36.523-2 which was upgraded at RAN#78 to Rel-15 due to Rel-15 relevant CR(s) | 14.3.0 | 15.0.0 |
| 2018-03 | RAN#79 | R5-180263 | 4366 | - | Correction to SCM test cases 13.5.4, 13.5.5 and 13.5.6 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180359 | 4372 | - | Update UE/ USIM configuration for V2X test case 24.1.6 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180360 | 4373 | - | Update UE/ USIM configuration for V2X test case 24.1.7 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180375 | 4375 | - | Correction of IMS Emergency Call test case 11.2.3 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180432 | 4379 | - | Correction to MAC test case 7.1.2.9 for CAT-M1 UEs | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180447 | 4381 | - | Correction on V2X Sidelink test case 24.1.1 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180448 | 4382 | - | Correction on V2X Sidelink test case 7.3.9.1 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180450 | 4384 | - | Correction on V2X Sidelink test case 24.1.14 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180451 | 4385 | - | Correction on V2X Sidelink test case 24.1.15 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180452 | 4386 | - | Correction on V2X Sidelink test case 24.1.17 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180550 | 4398 | - | Correction to NB-IoT EMM test case 22.5.13 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180551 | 4399 | - | Correction to NB-IoT test case 22.6.3 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180552 | 4400 | - | Correction to LTE PDCP test case 7.3.6.1 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180625 | 4407 | - | Editorial correction to DC test case 8.2.2.9.2 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180721 | 4426 | - | Correction of Test case 8.5.4.1 for felCIC support | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180726 | 4429 | - | Correction to CA test cases (RRC Part 2) when executed using LAA band combination | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180728 | 4430 | - | Updates to IMS eCall test cases | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180731 | 4431 | - | Correction to CA test cases (RRC Part 3) when executed using LAA band combination | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-180899 | 4452 | - | Correction to 1xRTT MT call Test Cases | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181040 | 4461 | - | Clarifying the Test Loop Mode used in the NB-IoT test cases | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181120 | 4467 | - | Removing test case 22.4.17 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181144 | 4464 | 1 | Update of Transport block size selection (EUTRA) test cases 7.1.7.1.x | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181145 | 4406 | 1 | Updates to test cases 8.1.3.7 & 8.5.2.1 for Band>64 support | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181146 | 4468 | 1 | Correction to eCIC call Test Cases | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181148 | 4442 | 1 | Correction to Rel-11 eDDA test case 8.2.2.6.2 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181149 | 4465 | 1 | Correction to LTE<->IRAT testcases for IMS disabled over UMTS | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181150 | 4466 | 1 | Correction of Test Case 8.6.7.3 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181151 | 4446 | 1 | Updates to eDECOR test cases 9.2.1.1.7d and 9.2.3.1.1b | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181152 | 4451 | 1 | Correction to EMM test case 9.2.3.2.17 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181153 | 4455 | 1 | Correction to several EMM test cases for IMS disabled over UMTS | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181154 | 4435 | 1 | Updates to Multilayer test cases for Band>64 support | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181156 | 4470 | - | Correction to NB-IoT PDCP test case 22.3.3.6 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181157 | 4425 | 1 | Update of eMBMS SC Rel-11 test cases 17.4.x | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181158 | 4432 | 1 | Correction to NB-IoT test case 22.3.2.4 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181161 | 4393 | 1 | Correction to NB-IoT test case 22.2.4 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181198 | 4427 | 1 | Addition of the new eCall over IMS Test Case 11.3.4 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181199 | 4428 | 1 | Addition of the new eCall over IMS Test Case 8.2.4.28 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181213 | 4383 | 1 | Correction on V2X Sidelink test case 24.1.9 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181214 | 4448 | 1 | Updates to V2V test case 24.1.2 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181215 | 4449 | 1 | Updates to V2V test case 24.1.4 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181220 | 4374 | 1 | Update UE/ USIM configuration for V2X test case 24.1.8 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181221 | 4378 | 1 | Correction to V2X test case 24.1.10 | 15.0.0 | 15.1.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2018-03 | RAN#79 | R5-181222 | 4387 | 1 | Correction on V2X Sidelink test case 24.1.18 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181223 | 4388 | 1 | Addition of new V2X Sidelink test case 24.1.20 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181224 | 4454 | 1 | Addition of GNSS details for V2X test cases | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181227 | 4424 | 1 | Addition of the new Enhanced LAA test case 7.1.4.30: eLAA / Cross Carrier UL Scheduling for eLAA SCell | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181231 | 4423 | 1 | Update of Test case 8.5.4.1 with Cat-1bis capability check | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181232 | 4471 | - | Updates to V2X test case 24.1.3 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181233 | 4472 | - | Updates to V2X test case 24.1.5 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181275 | 4367 | 1 | Add test case for NB-IoT / Radio link failure / T301 expiry / T311 expiry / RRC connection re-establishment | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181276 | 4368 | 1 | Add test case for NB-IoT / Radio link failure / RRC connection re-establishment reject / RRC connection re-establishment | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181277 | 4389 | 1 | Correction to NB-IoT test case 22.4.13 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181279 | 4473 | - | Add test case for NB-IoT/Tracking area update/Inter-RAT change between NB-IOT and E-UTRA | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181281 | 4459 | 1 | New feMTC test case 8.2.2.6.6 RRC connection reconfiguration/ UE Assistance Information/ maximum PDSCH/PUSCH bandwidth preference | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181288 | 4474 | - | New test case 7.1.4.1a for Layer 2 Latency Reduction | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181289 | 4475 | - | New test case 7.1.4.2a for Layer 2 Latency Reduction | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181290 | 4476 | - | New test case 7.1.4.2b for Layer 2 Latency Reduction | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181291 | 4477 | - | New test case 7.1.4.11a for Layer 2 Latency Reduction | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181299 | 4376 | 1 | Correction to eMTC MAC test case 7.1.4a.1 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181300 | 4453 | 1 | Correction to GCF WI-081 test case 7.1.2.4 with Cat-M1 UE. | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181301 | 4413 | 1 | Correction to EMM test case 9.2.1.2.10 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181302 | 4443 | 1 | Correction to EMM test case 9.2.3.1.5a | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181303 | 4463 | 1 | Correction to IMS Emergency Call test case 11.2.12 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181304 | 4433 | 1 | Correction to NB-IoT test case 22.4.23 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181305 | 4434 | 1 | Correction to NBIOT TC 22.2.10 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181306 | 4458 | 1 | Correction to NB-IoT MAC test case 22.3.1.3 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181307 | 4469 | 1 | Corrections to NB-IoT "S1-U Only" Impacted Test Cases | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181310 | 4478 | - | Correction to NB-IoT test case 22.5.7b | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181315 | 4437 | 1 | LWA / WLAN Association Success / EUTRA RRC_Connected to WLAN (Event W1) | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181316 | 4438 | 1 | LWIP / WLAN Association Success / EUTRA RRC_Connected to WLAN (Event W1) | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181318 | 4422 | 1 | Addition of the new Enhanced LAA test case: eLAA / Logical channel prioritization handling / laa-UL-Allowed | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181319 | 4401 | 1 | Corrections to test case 24.1.16 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181320 | 4402 | 1 | Addition of V2X Sidelink Communication test case 24.1.19 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181329 | 4414 | 1 | Correction to EMM test case 9.2.3.1.1a | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181330 | 4460 | 1 | Correction to EUTRA Multi-Layer procedures test case 13.4.1.5 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181331 | 4462 | 1 | Adding clarification to EMM test case 9.1.5.1 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181338 | 4377 | 1 | Correction to RRC test case 8.1.1.2 for CAT-M1 UEs | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181352 | 4479 | - | Updates to NB-IoT test case 22.6.1 | 15.0.0 | 15.1.0 |
| 2018-03 | RAN#79 | R5-181354 | 4480 | - | Resubmission of Addition of the new eCall over IMS Test Case 11.3.7 | 15.0.0 | 15.1.0 |
| 2018-06 | RAN#80 | R5-182298 | 4483 | - | Updates to test case 6.2.3.19 for Band>64 support | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182299 | 4484 | - | Editorial updates to SPS test cases | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182300 | 4485 | - | Updates to some IMS eCall test cases for Band>64 support | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182322 | 4486 | - | Corrections for RRC Paging test case 8.1.1.7 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182342 | 4488 | - | Correction to test case 7.1.4.2a for Layer 2 Latency Reduction | 15.1.0 | 15.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2018-06 | RAN#80 | R5-182351 | 4491 | - | Corrections to AM RLC test case 7.2.3.10 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182359 | 4493 | - | Update of test case 8.5.4.1 to add DL Cat 20 capability check | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182377 | 4495 | - | Editorial: corrections of typos and styles following GNSS CR | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182455 | 4505 | - | Correction to CA test case 8.3.1.22.2 when executed using LAA band combination | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182456 | 4506 | - | Correction for LTE<->GERAN idle mode test Case 6.2.3.27 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182457 | 4507 | - | Correction to GCF WI-242 UEPCOP TCs 9.2.3.1.1a and 9.2.3.1.5b | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182458 | 4508 | - | Correction to IMS emergency call test case test case 11.2.8 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182459 | 4509 | - | Correction to GCF WI-242 UEPCOP TC 9.2.1.1.7c. | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182475 | 4510 | - | Corrections to V2X TC 24.1.16 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182476 | 4511 | - | Corrections to V2X Sidelink Communication test case 24.1.19 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182512 | 4512 | - | Correction of test case 6.1.2.5a | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182546 | 4516 | - | Addition of new LTE_VoLTE_ViLTE_enh test case: PUSCH Hopping / multi-subframe repetitions | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182549 | 4517 | - | Correction on V2X Sidelink test case 24.1.15 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182579 | 4524 | - | Correction to LTE-IRAT CSG test cases 6.3.3 and 6.3.4 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182580 | 4525 | - | Correction to LTE test case 9.2.1.1.7b | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182582 | 4527 | - | Correction to NB-IoT test case 22.5.14 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182584 | 4528 | - | Correction to NB-IoT MAC test case 22.3.1.3 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182616 | 4530 | - | Addition of test case for NB-IoT/RDS (new protocol of NON-IP transmission) between UE and SCEF | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182632 | 4535 | - | Correction to DC testcase 8.2.4.25.3 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182634 | 4536 | - | Correction to DC testcase 8.2.4.25.7 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182639 | 4540 | - | Addition of NB-IoT testcase NB-IoT / AM RLC / Receiver status triggers / Non-zero t-Reordering configured | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182640 | 4541 | - | Correction to NB-IoT testcase 22.4.13 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182657 | 4546 | - | Addition of SRS switching test case 8.2.2.5a.3 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182778 | 4553 | - | Introduction of MAC TC 7.1.4.32.4 for eLAA | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182799 | 4556 | - | Correction to test case 8.5.4.1 to update reporting of crs-InterfHandl-r11 IE | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182820 | 4559 | - | Editorial CR to update the IMS eCall test case 11.3.7 title | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182823 | 4560 | - | Correction to LTE MDT test case 8.6.2.3a | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182840 | 4566 | - | Removal of Enhanced LAA test case 7.1.4.30 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182900 | 4568 | - | Correction to Test case 9.2.3.1.23 for CAT-M1 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182907 | 4569 | - | Update of DL-SCH transport block size selection TCs 7.1.7.1.x for CAT1bis | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182909 | 4570 | - | Update of UL-SCH transport block size selection TC 7.1.7.2.1 for CAT1bis | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182955 | 4571 | - | Correction to EUTRA MAC test case 7.1.3.9 for CAT-M1 UEs | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182956 | 4572 | - | Correction to EUTRA RLC test case 7.2.3.21 for CAT-M1 UEs | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-182996 | 4576 | - | Correction to several LTE and LTE<->IRAT test cases for IMS disabled over UMTS | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183060 | 4580 | - | Update of test cases 6.2.3.1, 6.2.3.15, 6.2.3.17, 6.2.3.18, 6.2.3.34 to include Extended band support | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183061 | 4487 | 1 | Correction to test case 7.1.4.1a for Layer 2 Latency Reduction | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183062 | 4489 | 1 | Correction to test case 7.1.4.2b for Layer 2 Latency Reduction | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183063 | 4490 | 1 | Correction to test case 7.1.4.11a for Layer 2 Latency Reduction | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183064 | 4579 | 1 | Editorial corrections to TC 7.1.2.9 (alignment with PRD13) | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183065 | 4533 | 1 | Correction to DC testcase 8.2.4.25.1 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183066 | 4534 | 1 | Correction to DC testcase 8.2.4.25.2 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183067 | 4573 | 1 | Correction to EUTRA RRC test cases 8.3.1.11(a) for CAT-M1 UEs | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183068 | 4557 | 1 | Update of EMM test case 9.2.1.1.1a | 15.1.0 | 15.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2018-06 | RAN#80 | R5-183069 | 4492 | 1 | Correction to test case 10.7.4 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183172 | 4550 | 1 | Introduction of MAC TC 7.1.4.32.1 for eLAA | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183173 | 4551 | 1 | Introduction of MAC TC 7.1.4.32.2 for eLAA | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183174 | 4552 | 1 | Introduction of MAC TC 7.1.4.32.3 for eLAA | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183176 | 4514 | 1 | Addition of new LTE_VoLTE_ViLTE_enh test case: Correct HARQ process handling / Repetition with asynchronous PUSCH enhancement | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183177 | 4515 | 1 | Addition of new LTE_VoLTE_ViLTE_enh test case: MAC PDU header handling / Recommended bit rate | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183179 | 4544 | 1 | Addition of SRS switching test case 7.1.2.12 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183180 | 4545 | 1 | Addition of SRS switching test case 8.2.2.5a.2 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183181 | 4547 | 1 | Addition of SRS switching test case 8.2.2.5a.4 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183183 | 4518 | 1 | Addition of new V2X test case "V2X Uplink Communication / UE in RRC_Connected on an E-UTRAN cell / Utilisation of the UL SPS resources configured by eNB/ Transmission" | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183184 | 4519 | 1 | Addition of new V2X test case "V2X Downlink Communication / UE in IDLE or RRC_Connected on an E-UTRAN cell / UE receives the V2X data via MBMS" | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183185 | 4520 | 1 | Addition of new V2X test case "V2X Downlink Communication / UE in IDLE or RRC_Connected on an E-UTRAN cell / UE receives the V2X data via SC-PTM" | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183186 | 4521 | 1 | Addition of new V2X test case 24.2.1 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183187 | 4522 | 1 | Addition of new V2X test case 24.2.2 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183188 | 4523 | 1 | Addition of new V2X test case 24.2.3 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183189 | 4548 | 1 | New test case for V2X Sidelink CBR measurement and report | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183190 | 4549 | 1 | New test case for V2X Sidelink using Tx parameters based on measured CBR and PPPP | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183195 | 4502 | 1 | Correction to NB-IoT test case 22.4.20a | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183196 | 4531 | 1 | Addition of test case for NB-IoT/ UE in NB-S1 mode supporting control plane data back-off timer/ Service reject with extended wait time CP data/ Release with extended wait time CP data/ Attach accept with extended wait time CP data | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183197 | 4532 | 1 | Addition of test case for NB-IoT/APN rate control for MO exception data | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183198 | 4538 | 1 | Addition of testcase for NB-IoT / RACH Procedure / Contention free random access (CFRA) | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183199 | 4542 | 1 | Correction to NB-IoT testcase 22.4.19a | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183201 | 4567 | 1 | Update to feMTC TC 8.2.2.6.6 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183202 | 4513 | 1 | Correction of test cases 6.2.3.34, 6.2.3.35, 6.2.4.1, 6.2.4.2, 6.2.4.3, 6.2.4.4, 6.2.4.5, 6.2.4.6 and 6.2.4.7 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183204 | 4539 | 1 | Correction to NB-IoT testcase 22.3.2.5 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183205 | 4558 | 1 | Update of eMBMS test case 17.1.1 for UEs supporting AT command for eMBMS service activation | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183207 | 4503 | 1 | Correction to NB-IoT test case 22.1.1 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183208 | 4504 | 1 | Correction to NB-IoT test case 22.5.6 | 15.1.0 | 15.2.0 |
| 2018-06 | RAN#80 | R5-183246 | 4574 | 1 | Correction to EUTRA PDCP test case 7.3.5.4 for CAT-M1 UEs | 15.1.0 | 15.2.0 |
| 2018-09 | RAN#81 | R5-184091 | 4587 | - | Correction to NB-IoT test case 22.6.2 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184092 | 4588 | - | Correction to NB-IoT test case 22.6.3 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184093 | 4589 | - | Correction to NB-IoT test case 22.1.1 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184213 | 4593 | - | Removal of Testcase 8.2.2.6.4 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184214 | 4594 | - | Removal of Testcase 8.2.2.6.5 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184493 | 4599 | - | Correction of NB-IoT test case 22.5.20 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184494 | 4600 | - | Correction of NB-IoT test case 22.5.21 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184507 | 4606 | - | Correction to EMM TC 9.2.1.1.24 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184508 | 4607 | - | Correction to ESM TC 10.5.4 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184510 | 4608 | - | Correction to CSFB TC 13.1.12 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184551 | 4613 | - | Correction to MAC test cases with TB Size selection | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184631 | 4614 | - | Adding TC 13.1.21 for emergency call via CS domain | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184707 | 4618 | - | Update of EMM test case 9.2.1.1.1b | 15.2.0 | 15.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2018-09 | RAN#81 | R5-184708 | 4619 | - | Update of EMM test case 9.2.1.1.22 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184710 | 4621 | - | Update of eMBMS test cases for UEs supporting AT command for eMBMS service activation | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184726 | 4624 | - | Removal of 1xPre-Registration 8.4.7.x test cases | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184727 | 4625 | - | Removal of Multi-Layer 1xPre-Registration 13.4.4.x and 1xCSFB 13.1.xx test cases | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184778 | 4626 | - | Updates to Align the GNSS Moving Scenario Details with Other V2X Test Cases | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184786 | 4630 | - | Addition of new NB_IOTenh-UEConTest test case 22.3.1.9 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184793 | 4636 | - | Remove test step 0 in test case 24.1.15 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184794 | 4637 | - | Remove test step 0 in test case 24.1.18 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184795 | 4638 | - | Correction on V2X Sidelink test case 24.3.1 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184796 | 4639 | - | Update Table 24.3.3.3.3-1 in test case 24.3.3 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184854 | 4644 | - | Correction to NB-IoT testcase 22.3.2.2 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-184918 | 4645 | - | Correction to multi-layer test case 13.1.20 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185004 | 4598 | 1 | Correction to Idle mode Inter-RAT G<>E test case 6.2.3.21 to allow optional IMS registration on EUTRAN cell | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185006 | 4603 | 1 | Update of DL 256QAM TCs for high UE DL Categories | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185007 | 4604 | 1 | Correction to RRC TC 8.5.4.1 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185008 | 4582 | 1 | Correction to EMM test case 9.2.3.1.25 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185009 | 4610 | 1 | Correction to testcase 9.2.2.1.9 for CAT-M1 UEs | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185010 | 4620 | 1 | Update of EMM test case 9.2.3.2.17 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185012 | 4584 | 1 | Clarification for NB-IoT test case 22.3.1.1 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185013 | 4585 | 1 | Correction to NB-IoT test case 22.5.8 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185014 | 4586 | 1 | Correction to NB-IoT test case 22.5.14 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185015 | 4640 | 1 | Corrections to NBIOT NAS TC 22.5.7b | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185017 | 4648 | - | Correction to NB-IoT test cases 22.4.4, 22.4.8 and 22.4.9 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185018 | 4609 | 1 | Correction to NB-IoT test case 22.2.9 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185019 | 4622 | 1 | Update to NB-IOT test case 22.1.1 M2 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185020 | 4623 | 1 | Update to NB-IOT test case 22.3.1.2 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185021 | 4641 | 1 | Correction to NB-IoT testcase 22.3.3.5 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185105 | 4591 | 1 | Addition of Test Case: "LWA / T351 Expiry" to WLAN/3GPP Radio Level Integration and Interworking Enhancement Interworking Work Item | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185106 | 4592 | 1 | Correction of Test Cases 8.2.5.4 and 8.2.5.5 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185108 | 4616 | 1 | Correction to V2X test case 24.1.12 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185109 | 4617 | 1 | Correction to V2X test case 24.1.1, 24.1.3, 24.1.5, 24.1.6, 24.1.10 and 24.1.11 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185111 | 4649 | - | New test case for V2X Sidelink with SL SPS Transmission | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185112 | 4646 | 1 | Correction to V2X TC 24.1.16 & 24.1.19 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185114 | 4590 | 1 | Correction to eNB-IoT test case 22.3.2.7 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185115 | 4601 | 1 | Addition to NB-IoT testcase 22.3.1.6a | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185116 | 4629 | 1 | Addition of new NB_IOTenh-UEConTest test case 22.3.1.8 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185117 | 4631 | 1 | Addition of new NB_IOTenh-UEConTest test case 22.3.1.10 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185118 | 4632 | 1 | Addition of new NB_IOTenh-UEConTest test case 22.4.24 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185119 | 4633 | 1 | Addition of new NB_IOTenh-UEConTest test case 22.4.25 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185120 | 4643 | 1 | New test case for NB-IoT UM RLC | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185126 | 4597 | 1 | Correction to SSAC connected mode test cases 13.5.1a and 13.5.3a for IMS Enabled UE | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185135 | 4583 | 1 | Correction to 10.7.4 regarding CE mode | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185141 | 4647 | 1 | Correction to V2V TC 24.1.2 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185159 | 4611 | 1 | Correction to CAT-M1 Test case 8.2.4.27 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185160 | 4615 | 2 | Addition of new V2X test case 24.2.4 | 15.2.0 | 15.3.0 |
| 2018-09 | RAN#81 | R5-185169 | 4602 | 2 | Update of number of DL PDCP SDUs in test cases 7.1.7.1.x | 15.2.0 | 15.3.0 |
| 2018-12 | RAN#82 | R5-186458 | 4650 | - | Corrections to EMM test case 9.2.3.1.8b | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-186632 | 4651 | - | Correction to values for GNSS scenario #3 for V2X test cases | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-186766 | 4656 | - | Correction on V2X testcase 24.3.1 | 15.3.0 | 15.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2018-12 | RAN#82 | R5-186775 | 4661 | - | Addition of new LTE_UDC-UEConTest test case 8.4.2.29 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-186796 | 4664 | - | Correction to NB-IoT test case 22.4.19a | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-186800 | 4666 | - | Correction to NB-IoT test case 22.3.3.5 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-186908 | 4671 | - | Correction to LTE<->GERAN idle mode test case 6.2.3.30 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-186985 | 4675 | - | Correction to SSAC connected mode test case 13.5.2a | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-186986 | 4676 | - | Correction to NB-IoT test case 22.3.1.8 and 22.4.24 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187000 | 4679 | - | Correction to NB-IoT Test case 22.4.25 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187119 | 4680 | - | Correction to test case 8.2.4.1 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187120 | 4681 | - | Correction to test case 8.2.4.2 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187121 | 4682 | - | Correction to test case 8.2.4.5 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187125 | 4686 | - | Correction to test case 8.3.1.8 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187127 | 4688 | - | Correction to test case 8.3.1.11 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187128 | 4689 | - | Correction to test case 9.2.2.1.9 for CAT-M UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187157 | 4690 | - | Correction to RLC test case 7.2.3.13 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187178 | 4692 | - | Removal of feMTC test case 8.2.2.6.6 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187184 | 4693 | - | Correction to V2V TC 24.1.4 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187198 | 4696 | - | Correction to GCF WI-086 EUTRA EPC Testcases 9.2.1.2.1b and 9.2.1.2.1c | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187544 | 4703 | - | Correction to test case 8.2.4.27 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187545 | 4704 | - | Correction to test case 7.1.7.1.9 and 7.1.7.1.10 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187554 | 4707 | - | Removal of Multi-Layer eHRPD test cases 13.4.4.2 and 13.4.4.3 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187634 | 4701 | 1 | Correction to test case 7.1.2.12 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187635 | 4706 | 1 | Update eLAA test case 7.1.4.31 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187636 | 4685 | 1 | Correction to test cases 8.3.1.10, 8.3.1.11a, 8.3.1.15 and 8.3.1.16 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187637 | 4687 | 1 | Correction to test case 8.3.1.9 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187641 | 4674 | 1 | Addition of specific RDS message contents for NB-IoT test case 22.5.19 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187642 | 4678 | 1 | Correction to NB-IoT test case 22.3.2.6 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187644 | 4691 | 1 | New feMTC test case 21.2.2 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187647 | 4694 | 1 | Correction of LWA Test Case 8.2.5.8 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187648 | 4695 | 1 | Corrections to LWA TC 8.2.5.7 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187649 | 4697 | 1 | Correction of LWA Test Case 8.2.5.4 and LWIP 8.2.5.5 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187650 | 4698 | 1 | Corrections to LWA/LWIP Test Cases 8.2.5.1, 8.2.5.2, 8.2.5.6 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187654 | 4708 | - | Correction to eNB-IoT test case 22.3.2.7 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187656 | 4710 | - | Updates to V2X test case 24.3.3 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187731 | 4711 | - | Removal of Testcase 7.1.4.36 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187733 | 4653 | 1 | Correction on V2X testcase 24.3.2 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187734 | 4709 | 1 | Correction to V2X test case 24.1.13 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187735 | 4658 | 1 | Addition of new LTE_UDC-UEConTest test case 7.3.10.1 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187736 | 4659 | 1 | Addition of new LTE_UDC-UEConTest test case 7.3.10.2 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187737 | 4660 | 1 | Addition of new LTE_UDC-UEConTest test case 7.3.10.3 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187738 | 4662 | 1 | Addition of new LTE_UDC-UEConTest test case 8.5.1.9 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187741 | 4654 | 1 | Introduction of RRC TC QoE Measurement Collection in 8.3.5.1 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187742 | 4655 | 1 | Introduction of RRC TC Qoemtsi Measurement Collection in 8.3.5.2 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187765 | 4702 | 1 | New Test Case in section 10.2 of TS 36.523-1 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187768 | 4672 | 1 | Update of Test case 8.5.4.1 with UE DL and UL Cat 22,23,24,25,26 capability check | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187769 | 4683 | 1 | Correction to test case 8.2.4.7 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187770 | 4684 | 1 | Correction to test case 8.2.4.8 for CAT-M1 UEs | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187771 | 4705 | 1 | Correction to 8.3.1.x measurement TCs with Cat-M1 device. | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187772 | 4673 | 1 | Correction to SRVCC test cases for IMS Reregistration over UTRAN | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-187773 | 4665 | 1 | Correction to NB-IoT test case 22.4.22 | 15.3.0 | 15.4.0 |
| 2018-12 | RAN#82 | R5-188200 | 4677 | 1 | Correction to NB-IoT Test case 22.3.1.9 | 15.3.0 | 15.4.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2018-12 | RAN#82 | R5-188201 | 4670 | 2 | Correction to eMDT2 test case 8.6.1.3 | 15.3.0 | 15.4.0 |
| 2019-03 | RAN#83 | R5-191067 | 4713 | - | New test case for UL-SCH transport block size selection for DCI format 0 and 256QAM UL | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-191103 | 4721 | - | Update to IMS eCall test case 11.3.2 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-191104 | 4722 | - | Update to IMS eCall test case 11.3.6 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-191230 | 4729 | - | Corrections to test case 11.2.7 regarding IMS emergency registration | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-191369 | 4735 | - | Correction to test case 9.2.1.1.24 for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-191551 | 4743 | - | Correction to NBIOT test case 22.4.19a | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-191834 | 4751 | - | Correction to MDT test case 8.6.2.12 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192070 | 4760 | - | Update to EMM test case 9.2.3.2.17 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192232 | 4767 | - | Correction to CAT-M1 Test cases | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192261 | 4727 | 1 | Update to eLAA test cases 7.1.4.31 and 7.1.4.32.x | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192262 | 4755 | 1 | Corrections to LTE RRC test case 8.1.2.9 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192263 | 4756 | 1 | Correction to EMM TC 9.2.2.1.9 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192264 | 4726 | 1 | Correction to test case 10.2.2 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192265 | 4741 | 1 | Corrections to test case 11.2.8 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192266 | 4768 | - | Correction to NB-IoT test case 22.5.21 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192267 | 4742 | 1 | Correction to NB-IoT test case 22.5.20 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192345 | 4714 | 1 | Corrections to test case 8.2.5.6 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192346 | 4766 | 1 | Correction of test case 8.2.5.1 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192347 | 4737 | 1 | Correction to WI-282 V2X TC 24.1.19 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192348 | 4761 | 1 | Update of RRC TC QoE Measurement Collection in 8.3.5.1 and 8.3.5.2 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192349 | 4745 | 1 | Completion of UDC TC 7.3.10.1 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192350 | 4746 | 1 | Completion of UDC TC 7.3.10.2 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192351 | 4747 | 1 | Completion of UDC TC 7.3.10.3 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192352 | 4748 | 1 | Completion of UDC TC 8.2.4.29 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192353 | 4749 | 1 | Completion of UDC TC 8.5.1.9 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192354 | 4715 | 1 | Introduction of TC Bluetooth measurement collection in LTE Immediate MDT | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192355 | 4716 | 1 | Introduction of TC WLAN measurement collection in LTE Immediate MDT | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192356 | 4717 | 1 | Introduction of TC Bluetooth measurement collection in LTE Logged MDT | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192357 | 4718 | 1 | Introduction of TC WLAN measurement collection in LTE Logged MDT | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192358 | 4719 | 1 | Introduction of TC Bluetooth measurement collection in Logged Radio Link Failure | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192359 | 4720 | 1 | Introduction of TC WLAN measurement collection in Logged Radio Link Failure | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192361 | 4757 | 1 | New feMTC test case 21.3.13 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192362 | 4758 | 1 | New feMTC test case 21.1.6 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192714 | 4734 | 1 | Correction to 6.1.1.1 and 6.1.1.1b test cases for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192716 | 4730 | 1 | Correction to eMTC test case 7.1.3.4a | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192717 | 4731 | 1 | Correction to 7.x test cases for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192718 | 4725 | 1 | Update of UE capability test case 8.5.4.1 for UTRA RATs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192719 | 4732 | 1 | Correction to test case 8.2.4.4 for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192720 | 4740 | 1 | Update to measurement reporting test cases with FGI 25 for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192721 | 4736 | 1 | Correction to test case 9.2.2.1.6 for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192722 | 4752 | 1 | Update to EMM test case 9.2.1.1.26 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192723 | 4733 | 1 | Correction to test case 13.4.1.5 for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192724 | 4762 | 1 | Correction to test case 13.2.1 for CAT-M1 UEs | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192725 | 4723 | 2 | Correction to LTE<->IRAT test case 6.2.3.6 for optional IMS Registration behaviour | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192730 | 4739 | 1 | Updating 8.5.4.1 to check FGI 103 and 104 | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192731 | 4763 | 1 | New feMTC test case SC-MCCH information acquisition / Enhanced Coverage / Paging precedence | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192732 | 4765 | 1 | New feMTC test case Cell reselection to inter-frequency cell using QoffsetSCPTM / Enhanced Coverage | 15.4.0 | 15.5.0 |
| 2019-03 | RAN#83 | R5-192814 | 4769 | 1 | Correction to testcase 9.2.3.1.27 for Cat M1 Ues | 15.4.0 | 15.5.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2019-03 | RAN#83 | - | - | - | Administrative release upgrade to match the release of TS 36.523-2 and TS 36.523-3 which were upgraded at RAN#83 to Rel-16 due to Rel-16 relevant CR(s) | 15.5.0 | 16.0.0 |
| 2019-06 | RAN#84 | R5-193997 | 4784 | - | Correction to LTE audit test case 8.5.4.1 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-193998 | 4785 | - | Correction to EPC NAS test case 9.2.3.1.25 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-193999 | 4786 | - | Correction to EPC NAS test case 10.7.4 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194084 | 4788 | - | Update of UE capability test case 8.5.4.1 for Aerial vehicle UE | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194244 | 4791 | - | Correction to NBIOT test case 22.3.1.7 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194246 | 4792 | - | Correction to NBIOT test case 22.2.5 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194248 | 4793 | - | Correction to NBIOT test case 22.4.4 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194249 | 4794 | - | Correction to NBIOT test case 22.4.5 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194250 | 4795 | - | Correction to NBIOT test case 22.4.23 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194274 | 4801 | - | New feMTC test case 7.1.3.6a | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194601 | 4813 | - | Correction to NBIOT test case 22.5.5, 22.5.8 and 22.5.13 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194734 | 4819 | - | Resubmission of Correction to LAA test case 7.1.11.1 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194735 | 4820 | - | Resubmission of New test case for UL-SCH transport block size selection for DCI format 0 and 256QAM UL | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194765 | 4800 | 1 | Correction to test case 10.8.7 for CAT-M1 UEs | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194772 | 4770 | 1 | Introduction of new Event H1 measurement and reporting test case for Aerial UE | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194773 | 4771 | 1 | Introduction of new Event H2 measurement and reporting test case for Aerial UE | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194774 | 4778 | 1 | Addition of new Aerial vehicle Event A4 measurement reporting test case | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194775 | 4779 | 1 | Addition of new Aerial vehicle Event A5 measurement reporting test case | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194776 | 4804 | 1 | Addition of new Aerial vehicle Event A3 measurement reporting test case | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194777 | 4805 | 1 | Addition of new Aerial vehicle flight path information reporting test case | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194778 | 4806 | 1 | Adding a new clause for Aerial Vehicle test cases | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194860 | 4821 | - | New MAC test case for DL-SCH transport block size selection / DCI format 6-1A for UE Category M2 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194861 | 4822 | - | New MAC test case for DL-SCH transport block size selection / DCI format 6-1B for UE Category M2 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194862 | 4823 | - | New MAC test case for UL-SCH transport block size selection / DCI format 6-0A for UE Category M2 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194863 | 4824 | - | New MAC test case for UL-SCH transport block size selection / DCI format 6-0B for UE Category M2 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194864 | 4825 | - | Update of MAC test case 7.1.7.2.2 for extended max UL TBS for UE Category M1 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194865 | 4826 | - | Update of MAC test case 7.1.7.2.3 for extended max UL TBS for UE Category M1 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194886 | 4816 | 1 | Update to WLAN measurement collection in Logged Radio Link Failure | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194887 | 4817 | 1 | Update to WLAN measurement collection in LTE Immediate MDT | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-194888 | 4818 | 1 | Update to WLAN measurement collection in LTE Logged MDT | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-195204 | 4809 | 1 | Addition of idle mode measurement testcase with measurement info from measIdleConfig and SIB5 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-195205 | 4812 | 1 | Addition of idle mode measurement testcase with measurement info from measIdleConfig | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-195206 | 4815 | 1 | Addition of idle mode measurement testcase without capability information | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-195310 | 4827 | - | Correction to test case 7.2.3.10 and 7.2.3.13 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-195312 | 4798 | 1 | Update to EMM test case 9.2.1.1.26 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | R5-195313 | 4796 | 1 | Correction to NB-IoT test case 22.5.20 | 16.0.0 | 16.1.0 |
| 2019-06 | RAN#84 | RP-191441 | 4828 | - | Updating 8.5.4.1 to check FGI 103 and 104 | 16.0.0 | 16.1.0 |
| 2019-09 | RAN#85 | R5-195829 | 4830 | - | Correction to test case 7.1.3.3a for CAT-M1 UE | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-195983 | 4833 | - | Update to WLAN measurement collection in Logged Radio Link Failure | 16.1.0 | 16.2.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2019-09 | RAN#85 | R5-195984 | 4834 | - | Update to WLAN measurement collection in LTE Immediate MDT | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-195985 | 4835 | - | Update to WLAN measurement collection in LTE Logged MDT | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-195992 | 4840 | - | Correction to NB-IoT test case 22.1.1 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196007 | 4844 | - | Correction to NB-IoT test case 22.2.1 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196015 | 4846 | - | Addition of new Aerial vehicle Event A3 Inter-frequency measurement reporting TC 8.9.4a | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196019 | 4848 | - | Update of IMS eCall test cases 11.3.2, 11.3.3 and 11.3.6 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196206 | 4854 | - | Correction to NBIOT testcase 22.2.2 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196207 | 4855 | - | Correction to NBIOT testcase 22.2.4 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196208 | 4856 | - | Correction to NBIOT testcase 22.2.5 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196209 | 4857 | - | Correction to NBIOT testcase 22.4.5 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196210 | 4858 | - | Correction to NBIOT testcase 22.5.7b | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196211 | 4859 | - | Correction to NBIOT R14 test case 22.4.24 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196279 | 4861 | - | Correction to test case 8.2.2.6.2 for Cat-M1 device | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196770 | 4865 | - | Update of Aerial vehicle Event A4 and Event A5 measurement reporting TCs 8.9.5 and 8.9.6 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196775 | 4866 | - | Corrected PLMNs in IMS emergency test cases | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196972 | 4841 | 1 | Correction to CIoT test case 23.1.2 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196973 | 4852 | 1 | Removal of NB-IoT test case 22.5.19 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196974 | 4860 | 1 | Correction to NBIOT testcase 22.5.21 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196975 | 4853 | 1 | Correction to test case 10.5.1b | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-196979 | 4867 | - | Updating 8.5.4.1 to remove transient period for FGI 103 and 104 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197177 | 4832 | 1 | Modification of simulated aerial heights for aerial testing with GNSS | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197179 | 4847 | 1 | Addition of new Aerial vehicle Event A4 Inter-frequency measurement reporting TC 8.9.5a | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197181 | 4863 | 1 | Addition of SCell in dormant state | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197182 | 4864 | 1 | Modification of SCell in dormant state | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197239 | 4845 | 1 | Correction to NB-IoT test case 22.5.17 | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197252 | 4836 | 1 | Update to Bluetooth measurement collection in Logged Radio Link Failure | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197253 | 4849 | 1 | Update to Bluetooth measurement collection in LTE Immediate MDT | 16.1.0 | 16.2.0 |
| 2019-09 | RAN#85 | R5-197254 | 4850 | 1 | Update to Bluetooth measurement collection in LTE Logged MDT | 16.1.0 | 16.2.0 |
| 2019-12 | RAN#86 | R5-197901 | 4872 | - | Correction to ESM test case 10.8.7 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198002 | 4876 | - | Correction the test purpose of LTE UDC TC 7.3.10.2 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198037 | 4877 | - | Update to NAS test case 9.2.2.1.4 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198065 | 4878 | - | Addition of UTC time reset to aerial test cases | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198068 | 4879 | - | Correction to MDT test case 8.6.4.13 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198069 | 4880 | - | Correction to MDT test case 8.6.1.5 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198070 | 4881 | - | Correction to MDT test case 8.6.2.15 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198246 | 4888 | - | Correction to NBIOT testcase 22.3.1.8 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198249 | 4889 | - | Correction to NBIOT testcase 22.3.2.7 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198359 | 4892 | - | Correction to Test cases 7.2.3.21 and 7.3.5.3 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198433 | 4893 | - | Modification of TC 8.9.1 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198841 | 4887 | 1 | Correction to LTE testcases 6.1.2.7, 6.1.2.7a and 6.1.2.16 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198842 | 4882 | 1 | Correction of RRC testcase 8.5.4.1 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198843 | 4883 | 1 | Correction of EMM testcase 9.2.1.1.26 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-198998 | 4891 | 1 | Addition of SCell in activated state. | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199001 | 4874 | 2 | Introduction of new test case 8.6.8.7 Connection Establishment Failure logging / Logging and reporting / Bluetooth measurement collection | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199004 | 4869 | 1 | Addition of 7.1.2.13 PUCCH SCell Maintenance of uplink time alignment | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199005 | 4870 | 1 | Addition of 7.1.3.17 PUCCH SCell Correct HARQ process handling | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199006 | 4871 | 1 | Addition of 7.1.9.2 PUCCH SCell Activation and Deactivation of Scells | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199009 | 4894 | 1 | Corrections to CA Band Combination Capability Signalling test cases 8.5.4.2 and 8.5.4.3 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199010 | 4885 | 1 | Update to EMM testcase 9.2.1.2.14 | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199012 | 4896 | - | Correction to NB-IoT test case 22.5.17 | 16.2.0 | 16.3.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|--|-------------|-------------|
| 2019-12 | RAN#86 | R5-199081 | 4875 | 4 | Introduction of new test case 8.6.8.8 Connection Establishment Failure logging / Logging and reporting / WLAN measurement collection | 16.2.0 | 16.3.0 |
| 2019-12 | RAN#86 | R5-199100 | 4884 | 2 | Correction to NB-IoT test case 22.5.18 | 16.2.0 | 16.3.0 |
| 2020-03 | RAN#87 | R5-200222 | 4899 | - | Correction to test case 8.2.4.3 for CAT-M1 UEs | 16.3.0 | 16.4.0 |
| 2020-03 | RAN#87 | R5-200638 | 4902 | - | Corrections to LTE 256 QAM MAC Test Case | 16.3.0 | 16.4.0 |
| 2020-03 | RAN#87 | R5-201016 | 4900 | 1 | Update to Aerial vehicle test cases | 16.3.0 | 16.4.0 |
| 2020-03 | RAN#87 | R5-201099 | 4903 | 1 | Update of RRC Idle mode test cases to handle IMS Re-registration | 16.3.0 | 16.4.0 |
| 2020-03 | RAN#87 | R5-201111 | 4901 | 1 | Update of MDT test cases to handle IMS Re-registration | 16.3.0 | 16.4.0 |
| 2020-03 | RAN#87 | R5-201172 | 4904 | 1 | Addition of a new test case of SIP registration via a new P-CSCF address discovery | 16.3.0 | 16.4.0 |
| 2020-03 | RAN#87 | R5-201205 | 4898 | 1 | Correction to NBIOT testcase 22.5.7b | 16.3.0 | 16.4.0 |
| 2020-06 | RAN#88 | R5-201583 | 4907 | - | Correction to LTE test case 9.2.1.1.7b | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-201584 | 4908 | - | Updates to SMS over SGs test cases 11.1.5 and 11.1.6 | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-201762 | 4909 | - | Specific message content update to NB-IoT test case 22.5.17 | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-202179 | 4924 | - | Editorial update to EMM test case 9.2.1.1.1a | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-202181 | 4925 | - | Editorial update to EMM test case 9.3.1.4 | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-202182 | 4926 | - | Editorial update to NB-IoT test case 22.3.2.4 | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-202233 | 4927 | - | Correction to NB-IoT test case 22.3.1.8 | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-202234 | 4928 | - | Correction to NB-IoT test case 22.4.14 | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203050 | 4914 | 1 | Addition of 7.1.3.22 Correct DL HARQ handling with short processing time | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203051 | 4915 | 1 | Addition of 7.1.4.37 Correct UL HARQ handling with short processing time | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203052 | 4917 | 1 | Addition of 7.1.4.39 Correct UL assignment with DMRS sharing for short TTI | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203053 | 4919 | 1 | Addition of 7.1.4.41 HARQ sharing between PUSCH and sPUSCH | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203054 | 4921 | 1 | Addition of 8.2.2.12 Aperiodic SRS for short TTI | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203058 | 4922 | 1 | Addition of new TC 23.1.3 CIoT Optimization / Control Plane / EDT | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203060 | 4934 | 1 | Addition of new RRC TC for checking extended / spare field handling in SI | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203061 | 4932 | 1 | Correction to LTE test case 8.2.4.1 for CAT-M1 UEs | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203062 | 4933 | 1 | Correction to LTE test case 8.2.4.5 for Cat-M1 UEs | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203064 | 4931 | 1 | Correction to LTE test case 13.3.1.3 for CAT-M1 UEs | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203065 | 4906 | 1 | Correction to LTE Aerial UE test cases 8.9.4a and 8.9.5a | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203066 | 4929 | 1 | Correction to NB-IoT test case 22.4.5 | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203067 | 4935 | 1 | Addition of new NB-IoT RRC TC for checking extended / spare field handling in SI | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203080 | 4910 | 1 | Addition of 7.1.3.18 Correct DL HARQ handling for short TTI | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203081 | 4911 | 1 | Addition of 7.1.3.19 HARQ sharing between PDSCH and sPDSCH | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203082 | 4912 | 1 | Addition of 7.1.3.20 Multiplexing of sPDCCH and sPDSCH | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203083 | 4913 | 1 | Addition of 7.1.3.21 Correct DL assignment with DMRS sharing for short TTI | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203084 | 4916 | 1 | Addition of 7.1.4.38 Correct UL HARQ handling for short TTI | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203085 | 4918 | 1 | Addition of 7.1.4.40 Scheduling requests on sPUCCH | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203086 | 4920 | 1 | Addition of 8.2.2.11 Aperiodic SRS with short processing time | 16.4.0 | 16.5.0 |
| 2020-06 | RAN#88 | R5-203116 | 4905 | 2 | Correction to LTE TC 8.3.3.1-LTE CGI | 16.4.0 | 16.5.0 |
| 2020-09 | RAN#89 | R5-203545 | 4941 | - | Correction to SC-PTM test case 21.2.1 | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-203809 | 4945 | - | Correction to RRC measurement testcase 8.3.1.11 for measGapConfig for CAT-M1 | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-203812 | 4946 | - | Correction RRC idle mode test cases 6.1.1.x | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-203924 | 4949 | - | Update of message contents for UL transmission test cases for sTTI and short processing time | 16.5.0 | 16.6.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2020-09 | RAN#89 | R5-203925 | 4950 | - | Correction to derivation path for SRS transmission test cases for sTTI and short processing time | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204252 | 4955 | - | Editorial update to EMM test case 9.2.1.1.7b | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204300 | 4957 | - | Update of MDT test cases to handle IMS Re-registration | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204339 | 4958 | - | Correction to MDT test case 8.6.4.13 | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204340 | 4959 | - | Correction to MDT test case 8.6.8.8 | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204345 | 4960 | - | Correction to 9.x test cases to handle IMS Re-registration (moving between HPLMN and VPLMN) | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204494 | 4948 | 1 | Update of test description for DL transmission test cases for sTTI and short processing time | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204497 | 4951 | 1 | Addition of NB-IoT R15 testcase 22.3.2.8 NB-IoT / UM RLC / Correct use of sequence numbering / Concatenation, segmentation and reassembly / Duplicate detection | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204498 | 4952 | 1 | Addition of NB-IoT R15 testcase 22.4.27 NB-IoT / RRC connection establishment / Access barring enhancement | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204500 | 4937 | 1 | Addition of new test case to test Paging with DRX and WUS in enhanced coverage | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204501 | 4938 | 1 | Addition of new test case to test Paging with eDRX and WUS in enhanced coverage | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204502 | 4939 | 1 | Addition of new test case to test CE-level based access barring | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204503 | 4953 | 1 | Addition of new TC 23.2.4 CIoT Optimization / User Plane / EDT | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204522 | 4942 | 1 | Update of TC 9.2.1.1.28b | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204523 | 4947 | 1 | Addition of new NAS test case to test handling of extended octets | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204524 | 4956 | 1 | Update of EMM test cases to handle IMS Re-registration | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204525 | 4936 | 1 | Correction to EPC IMS TC 13.1.19-wait for UE IMS de-register | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204526 | 4943 | 1 | Modification and editorial changes to NB-IoT TC 22.4.26 | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204527 | 4944 | 1 | Correction to NB-IoT test case 22.4.5 | 16.5.0 | 16.6.0 |
| 2020-09 | RAN#89 | R5-204528 | 4954 | 1 | Updates to legacy TCs for feMTC | 16.5.0 | 16.6.0 |
| 2020-12 | RAN#90 | R5-205179 | 4964 | - | Correction to LTE testcases 9.2.3.1.4 and 9.2.3.2.13 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-205218 | 4967 | - | Restoration of wrongly implemented parts of T2 of Table 6.3.4.3.2-1 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-205344 | 4970 | - | Corrections to EMM Test Cases 9.2.1.1.28b and 9.2.1.2.1d | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-205668 | 4976 | - | Correction to NB-IoT UE Capability transfer test case 22.4.13 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-205760 | 4977 | - | Addition of NB-IoT R15 testcase 22.3.1.11 NB-IoT / Scheduling Request / Without HARQ ACK | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-205762 | 4978 | - | Correction to DCI format for sTTI test cases | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-205861 | 4981 | - | Correction to NB-IoT test case 22.5.21 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-205867 | 4982 | - | Update of test case 11.2.7 to handle IMS Re-registration | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206052 | 4984 | - | Correction to LTE RLC test cases 7.2.3.10 and 7.2.3.13 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206058 | 4985 | - | Addition of new eMTC4 TC 7.1.4.14a Correct HARQ process handling / feedback for UL data | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206281 | 4963 | 1 | New TC 13.1.22 MCPTT / Attach / Call setup CO | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206387 | 4979 | 1 | Introduction of sTTI related definitions and abbreviations | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206389 | 4968 | 1 | Addition of new NB-IoT test case 22.2.11 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206390 | 4969 | 1 | Addition of new NB-IoT test case 22.2.12 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206401 | 4986 | 1 | New testcase for ethernet header compression and decompression for eutran | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206433 | 4961 | 1 | Update applicability of RRC 8.1.2.15 to Rel-15 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206434 | 4974 | 1 | Correction to LTE testcase 11.2.6 to handle IMS Re-Registration | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206435 | 4962 | 1 | Update applicability of NB-IoT RRC 22.4.26 to Rel-15 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206436 | 4965 | 1 | Correction to NBIOT testcase 22.5.20 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206437 | 4966 | 1 | Correction to NBIOT testcase 22.2.5 | 16.6.0 | 16.7.0 |
| 2020-12 | RAN#90 | R5-206438 | 4975 | 1 | Correction to NB-IoT test cases | 16.6.0 | 16.7.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2021-03 | RAN#91 | R5-210042 | 4987 | - | Editorial TC BT measurement collection in Immediate MDT to the correct subclause | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210043 | 4988 | - | Editorial TC BT measurement collection in Logged MDT to the correct subclause | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210044 | 4989 | - | Editorial TC BT measurement collection in RLF logging to the correct subclause | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210045 | 4990 | - | Editorial TC WLAN measurement collection in RLF logging to the correct subclause | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210046 | 4991 | - | Editorial TC BT measurement collection in CEF logging to the correct subclause | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210047 | 4992 | - | Editorial TC WLAN measurement collection in CEF logging to the correct subclause | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210681 | 5006 | - | Correction to LTE TC 6.1.1.2a | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210683 | 5008 | - | Addition of LTE TC 6.1.1.6b | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210684 | 5009 | - | Correction to LTE TC 6.1.2.3 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-210685 | 5010 | - | Correction to LTE TC 6.1.2.12 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211341 | 4995 | 1 | Editorial updates of TS 36.523-1 Section 6 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211342 | 5007 | 1 | Correction to LTE TC 6.1.1.6a | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211343 | 4996 | 1 | Editorial updates of TS 36.523-1 Section 7.1 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211344 | 4997 | 1 | Editorial updates of TS 36.523-1 Sections 8.1 and 8.2 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211345 | 5011 | 1 | Correction to LTE test case 8.2.4.1 for CAT-M mode UEs | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211346 | 4998 | 1 | Editorial updates of TS 36.523-1 Section 8.3 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211347 | 4999 | 1 | Editorial updates of TS 36.523-1 Section 8.4 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211348 | 5000 | 1 | Editorial updates of TS 36.523-1 Section 9 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211349 | 5001 | 1 | Editorial updates of TS 36.523-1 Sections 10 to 13 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211350 | 5002 | 1 | Editorial updates of TS 36.523-1 Sections 15, 17 and 19 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211452 | 5012 | 1 | Addition of E-UTRAN TC 8.2.4.30.1 DAPS handover | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211509 | 4993 | 1 | Update of TC WLAN measurement collection in Immediate MDT for specific sys infos | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211510 | 4994 | 1 | Update of TC WLAN measurement collection in Logged MDT for specific sys infos | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211511 | 5013 | 1 | Correction to Test Case 10.2.2 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211512 | 5004 | 1 | Update to TC 13.1.22 MCPTT / Attach / Call setup CO | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211513 | 5003 | 1 | Editorial updates of TS 36.523-1 Sections 22 and 24 | 16.7.0 | 16.8.0 |
| 2021-03 | RAN#91 | R5-211514 | 5005 | 1 | Adding specs to References in TS 36.523-1 | 16.7.0 | 16.8.0 |
| 2021-06 | RAN#92 | R5-212439 | 5017 | - | Correction to LTE TC 6.1.1.2a-Automatic PLMN selection | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-212440 | 5018 | - | Correction to LTE TC 6.1.1.6a-User PLMN selection | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-212683 | 5021 | - | Add test case 7.3.5.6 | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-212888 | 5022 | - | Correction and reallocation of NB-IoT test case for WUS / DRX | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-212889 | 5023 | - | Correction and reallocation of NB-IoT test case for WUS / eDRX | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-213023 | 5024 | - | Correction to NB-IoT test case 22.3.2.8 | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-213426 | 5016 | 1 | Correction to handling of LTE MAC PDU on DL SCH with reserved value for LCID | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-213547 | 5015 | 1 | Addition of new NB-IoT test case 22.4.14a | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-213550 | 5014 | 1 | Addition of LTE TC 8.2.4.31.1 Conditional handover Success | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-213551 | 5019 | 1 | Addition of LTE TC 8.2.4.31.2-CHO modify CHO configuration | 16.8.0 | 16.9.0 |
| 2021-06 | RAN#92 | R5-213649 | 5025 | 1 | Correction of limited service IMS emergency call test cases | 16.8.0 | 16.9.0 |
| 2021-09 | RAN#93 | R5-214438 | 5027 | - | Correction to LTE testcase 7.2.2.8 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-214439 | 5028 | - | Correction to NBIOT testcase 22.5.21 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-214459 | 5029 | - | Update Test Cases 8.1.1.8 and 8.1.1.9 to specify PowerBoost for WUS configuration | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-214517 | 5030 | - | Update NB-IoT test case 22.2.4 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-214518 | 5031 | - | Update NB-IoT test case 22.2.5 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-214585 | 5034 | - | Correction to EUTRA RRC test case 8.6.4.5 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215042 | 5040 | - | Update NB-IoT test case 22.2.9 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215050 | 5042 | - | Update NB-IoT test case 22.3.1.1 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215053 | 5043 | - | Update NB-IoT test case 22.3.1.6 and 22.3.1.6a for TDD | 16.9.0 | 16.10.0 |

| Date | TSG # | TSG Doc. | CR | Rev | Subject/Comment | Version Old | Version New |
|---------|--------|-----------|------|-----|---|-------------|-------------|
| 2021-09 | RAN#93 | R5-215054 | 5044 | - | Update NB-IoT test case 22.3.1.7 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215118 | 5045 | - | Update NB-IoT test case 22.3.1.8 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215120 | 5046 | - | Correction to NB-IoT test case 22.3.2.8 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215125 | 5048 | - | Update NB-IoT test case 22.4.4 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215126 | 5049 | - | Update NB-IoT test case 22.4.5 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215127 | 5050 | - | Update NB-IoT test case 22.4.6 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215155 | 5052 | - | Update NB-IoT test case 22.4.8 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215156 | 5053 | - | Update NB-IoT test case 22.4.9 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215157 | 5054 | - | Update NB-IoT test case 22.4.26 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-215724 | 5041 | 1 | Addition of new NB-IoT test case for NB-IoT / RACH Procedure / Non-anchor carrier / Preamble format 2 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216245 | 5047 | 1 | Update NB-IoT test case 22.4.1 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216246 | 5055 | 1 | Update NB-IoT test case 22.4.13 for Rel-15 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216247 | 5056 | 1 | Update NB-IoT test case 22.5.8 for TDD | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216248 | 5026 | 1 | Update test case 7.3.5.6 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216249 | 5032 | 1 | Add new TC 8.2.4.30.4 Inter Frequency DAPS handover | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216250 | 5033 | 1 | Update on TC 8.2.4.30.1 intra-frequency DAPS handover | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216251 | 5035 | 1 | Addition of LTE TC 8.2.4.31.3-Conditional handover Failure | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216252 | 5036 | 1 | Addition of new test case 8.2.4.30.2 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216253 | 5037 | 1 | Addition of new test case 8.2.4.30.3 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216254 | 5038 | 1 | Addition of new test case 8.2.4.30.5 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216255 | 5039 | 1 | Addition of new test case 8.2.4.30.6 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216281 | 5051 | 1 | Addition of Rel-16 RACS RRC test case 8.5.5.1 | 16.9.0 | 16.10.0 |
| 2021-09 | RAN#93 | R5-216337 | 5057 | 1 | Correction to LTE Idle mode TC 6.1.2.13 for CAT-M1 | 16.9.0 | 16.10.0 |
| 2021-12 | RAN#94 | R5-216563 | 5059 | - | Update of test case 8.2.4.30.2 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-216564 | 5060 | - | Update of test case 8.2.4.30.5 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-216800 | 5061 | - | Add test case 7.3.5.7 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217868 | 5063 | 1 | Addition of new TC 7.1.3.23 Enhanced Coverage / DL Flexible starting PRB | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217869 | 5064 | 1 | Addition of new TC 7.1.4.42 Enhanced Coverage / UL Flexible starting PRB | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217871 | 5062 | 1 | Update test case 7.3.5.6 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217903 | 5070 | 1 | Update of UE capability test case 8.5.4.1 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217904 | 5071 | 1 | Update of RACS test case 8.5.5.1 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217956 | 5066 | 1 | Correction to NB-IoT test case 22.4.27 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217957 | 5067 | 1 | Update NB-IoT test case 22.4.13 for Rel-15 | 16.10.0 | 16.11.0 |
| 2021-12 | RAN#94 | R5-217958 | 5068 | 1 | Update NB-IoT / Cell reselection / MFBI for NS_04 NB-IoT in North America | 16.10.0 | 16.11.0 |
| 2022-12 | RAN#98 | R5-225985 | 5123 | - | Removal of technical content in 36.523-1 v16.11.0 and substitution with pointer to the next Release | 16.11.0 | 16.12.0 |

History

| Document history | | |
|-------------------------|----------------|-------------|
| V16.5.0 | October 2020 | Publication |
| V16.6.0 | November 2020 | Publication |
| V16.7.0 | February 2021 | Publication |
| V16.8.0 | June 2021 | Publication |
| V16.9.0 | September 2021 | Publication |
| V16.10.0 | December 2021 | Publication |
| V16.11.0 | March 2022 | Publication |
| V16.12.0 | January 2023 | Publication |